#### **Building Condition Assessment Survey 2023-2024**

#### **Mechanical Inspection**

Asset:	P.S. 67 - BRONX, 2024 MOHEGAN AVENUE, BRON	IX, NY, 10460			
Inspection Id	Inspection Type		Time In	Last Edited	
3320	MECHANICAL		2024-02-16 07:13AM	2024-03-26 11:58AN	
et Data					
Question		Answer			
Have any Syste	ms/Major Building Components been upgraded?	Systems:	DX Split System for Health Clin	ic	
		Years:	2023		
		Systems:	IDF Room - Dedicated A/C Equi	pment (DX Split	
			System)		
		Years:	2021		
		Systems:	Kitchen - Gas System: Shut-Off		
			Drip Traps; Terminal Unit Therm	ostatic Traps; Boiler	
			Safety Valves		
		Years:	2020	<b>T</b> 1	
		Systems:	Domestic Hot Water Remote Storage Tank		
		Years:	2019		
		Systems:	Unit Ventilators; Climate Control	•	
			(except pneumatic tubing); MER Condensate Piping (~80%)	Steam and	
		Years:	2017		
		Systems:	Student Fixtures - Toilets (~60%)	Urinals (~60%)	
		Systems.	Lavatory/Sinks (~60%)	, erinais ( 0070),	
		Years:	2015		
		Systems:	MDF Room - Dedicated A/C Equ	ipment (DX Split	
		·	System)		
		Years:	2014		
Are there fuel t	anks?	Yes			
	bove ground tanks	2			
Total capac	ity of all above ground tanks in gal.	15,000			
	elow ground tanks	0			
-	ity of all below ground tanks in gal.	0			
Total # of wate	r main service entries to the asset	4			
MERs/Fan Roo	oms Locations		- North Mechanical Area, South M	,	
		North Bul	lkhead Fan Room, South Bulkhead	Fan Room;	

# Are there any spaces with Missing or Defective CO Detectors?

Location(s)	Kitchen
Are there any Painted/Obstructed Sprinkler Heads?	No
Are there any Emergency Stop Switches with Missing Hammers?	No components

#### **Priority Condition**

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
		Description	Anecteu	Description	Notifieu	Title	mage
No condi	tion recorded						
Inspection	l						
Question	I			Response			
Mechani	cal						
AIR C	ONDITIONING			Inspected			
Chill	ed Water System			Does not	exist		
Cond	lenser Water Distrik	oution: Piping, Pumps and Auxiliaries		Does not	exist		
Cooli	ng Coil in Ductwor	k		Does not	exist		
Cooli	ng Tower			Does not	exist		
DX S	plit System			Inspected			
Ind	oor Unit			Inspected			
С	ondition			1- Good			
	Deficiency			No deficio	encies recorded		
Ou	tdoor Unit			Inspected			
C	ondition			1- Good			

Penthouse Gravity Roof Tank Room

Yes

## Building Condition Assessment Survey 2023-2024

Response

#### **Mechanical Inspection**

Question

	response
AIR CONDITIONING	
DX Split System	
Outdoor Unit	
Deficiency	No deficiencies recorded
Dry Cooler	Does not exist
Packaged / Rooftop Unit	Does not exist
Packaged Terminal A/C	Does not exist
Refrigerant Leak Detection System	Does not exist
Refrigerant Piping	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Return Fan	Does not exist
CENTRAL ACID WASTE NEUTRALIZING TANK	Does not exist
CLIMATE CONTROL SYSTEM	Inspected
BMS	Inspected
Instance	Throughout except 1st Floor Lower Level Gymnasium,
mstanov	Multipurpose Rooms; Rooms
	516A, 516B, 516C, 516D; 5th Floor Gymnasium
Instance Condition	4- Between Fair and Poor
Instance Quantity	1
Instance Quantity Uom	EACH
Building Area Covered by Operational System	0-20%
Installation Year	2017
Source of Installation Year	Custodial Staff
Deficiency	DEFECTIVE SYSTEM
Deficiency Location/Instance	Throughout except 1st Floor Lower Level Gymnasium,
·	Multipurpose Rooms; Rooms
	516A, 516B, 516C, 516D; 5th Floor Gymnasium
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Pneumatic System	Does not exist
Hybrid System	Does not exist
Electric System	Does not exist
COMPACTOR	Does not exist
CONVEYING	Inspected
Dumbwaiter	Does not exist
Elevator	Does not exist
Escalator	Does not exist
Non-auditorium Handicap Lift - Vertical	Does not exist
Non-auditorium Handicap Lift - Stair	Does not exist
Ash Hoist	Inspected
Condition	4- Between Fair and Poor
Are all the existing ash hoists operable?	No
Deficiency	No deficiencies recorded
Sidewalk Elevator	Does not exist
DOMESTIC WATER SYSTEM	Inspected
	Inspected
Domestic Cold Water System	
Domestic Cold Water System Gravity System	Inspected
Gravity System	Inspected Does not exist
Gravity System Supply Pump	Does not exist
Gravity System	-

## **Building Condition Assessment Survey 2023-2024**

#### **Mechanical Inspection**

tion	Response
MESTIC WATER SYSTEM	
omestic Cold Water System	
Water Service	
Instance	Boiler Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Deficiency	WATER MAIN:MISSING BACKFLOW PREVENTION DEVICE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Boiler Room; North and South Mechanical Areas - Crawlspace
Instance Condition	3- Fair
Instance Quantity	3
Instance Quantity Uom	EACH
Deficiency	WATER MAIN:MISSING BACKFLOW PREVENTION DEVICE
Deficiency Location/Instance	Boiler Room; North and South Mechanical Areas - Crawlspace
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	INSTALL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
omestic Hot Water System	Inspected
Domestic Hot Water Remote Storage Tank	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Domestic Water Heat Exchanger	Does not exist
Electric Domestic Water Heater	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Gas Fired Domestic Water Heater	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	RayPak
EquipmentId	N/A
Capacity/Size Quantity	264
Capacity/Size UOM	MBH Input
Capacity/Size 2 Quantity	0
Capacity/Size 2 UOM	Gallons
Source of Capacity/Size	Documented
Installation Year	2007
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Oil Fired Domestic Water Heater	Does not exist
Heat Pump Domestic Water Heater	Does not exist

## **Building Condition Assessment Survey 2023-2024**

#### Mechanical Inspection

uestion	Response
DOMESTIC WATER SYSTEM	
Domestic Water Distribution Piping	
Condition	3- Fair
Deficiency	No deficiencies recorded
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected
Interior Storm Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sewage/Waste/Vent Piping	Inspected
Condition	3- Fair
Deficiency	SEWAGE/WASTE PIPING:DEFECTIVE/LEAKS
Deficiency Location/Instance	5th Floor Boy's Toilet Room
Deficiency Quantity	10
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Sewage Ejector Pump	Does not exist
Sump Pump	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist
TXTURES	Inspected
Staff And Other	Inspected
Janitor Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF
Dentency	VALVE,ETC.)
Deficiency Location/Instance	1st Floor Staff Toilet Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Toilet	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE FLUSHOMETER VALVE
Deficiency Location/Instance	1st Floor Staff Toilet Room
Deficiency Quantity	
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Urinal	Inspected
Condition	3- Fair
	No deficiencies recorded
Deficiency	
Student Drinking Fountain	Inspected
Drinking Fountain Condition	Inspected 2- Between Good and Fair

## **Building Condition Assessment Survey 2023-2024**

#### **Mechanical Inspection**

Question	Response
FIXTURES	
Student	
Drinking Fountain	
Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF VALVE,ETC.)
Deficiency Location/Instance	Near Stair "H/4"
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lavatory/Sink	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Locker Room Shower	Does not exist
Sink And Fountain Combo Unit	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Urinal	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
GAS FIRED FURNACE	Does not exist
GAS SERVICE	Inspected
Gas Distribution Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Gas Meter Room Exhaust Fan	Does not exist
Gas Meter Room Vent	Does not exist
Gas Pressure Booster	Does not exist
CO/Gas Leak Detection	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Installation Year	1998
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
HEATING	Inspected
Heating Coil In Ductwork	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Hydronic Heating	Does not exist
Radiator/Convector/Fin Tube	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Steam Heating	Inspected
F&T/Steam Drip Trap	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
MER Steam and Condensate Piping	Inspected

## **Building Condition Assessment Survey 2023-2024**

#### **Mechanical Inspection**

ucui Inspeciion	A
stion	Response
CATING	
team Heating	
MER Steam and Condensate Piping	
Condition	1- Good
Deficiency	No deficiencies recorded
Steam Condensate Return Piping	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE/LEAKS
Deficiency Location/Instance	Near Oil Tank Room
Deficiency Quantity	10
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Condensate Return Pumping System	Inspected
Condition	4- Between Fair and Poor
Deficiency	DEFECTIVE TANK
Deficiency Location/Instance	Near Oil Tank Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE CONTROLS
Deficiency Location/Instance	Near Oil Tank Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Piping	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE/LEAKS
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	20
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Terminal Unit Thermostatic Trap	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
team supplied by External Sources	Does not exist
nit Heater/Cabinet Heater	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE
Deficiency Location/Instance	Kitchen
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

## **Building Condition Assessment Survey 2023-2024**

#### **Mechanical Inspection**

estion	Response	
IEATING		
Unit Heater/Cabinet Heater		
Violations	No violations recorded	
EATING PLANT	Inspected	
Instance on Basement	Inspected	
Is there a water meter on the boiler make-up water piping?	Yes	
Observed Operational?	No	
Burner Manufacturer	Gordon Piatt	
Burner Model	N/A	
Burner Type	Oil	
Heating Plant Oil Number	2	
Boiler Auxiliaries		
Instance on Basement	Inspected	
Boiler Auxiliary Piping		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler Emergency Stop Switch		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler Feedwater System		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler Feedwater Treatment(Automatic)		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler Flue Exhaust		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler Make-up Water Backflow Preventer		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler Room Steam And Condensate Piping		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	DAMAGED/MISSING INSULATION	
Deficiency Location/Instance	Boiler Room	
Deficiency Quantity	30	
Quantity Uom	L.F.	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Boiler Safety Valve		
Instance on Basement	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Boiler System		

## **Building Condition Assessment Survey 2023-2024**

#### **Mechanical Inspection**

tion	Response	
ATING PLANT		
ioiler System		
Coal-fired Boiler		
Instance on Basement	Does not exist	
Hot Water Boiler		
Instance on Basement	Does not exist	
Modular Boiler		
Instance on Basement	Does not exist	
Steam Boiler		
Instance on Basement	Inspected	
Instance on Basement	Inspected	
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity	6,014	
Instance Quantity Uom	MBH NET	
Cast Iron Boiler?	No	
Manufacturer	A. L. Eastmond & Sons Inc.	
EquipmentId	7369-01	
Capacity/Size Quantity	6014	
Capacity/Size UOM	MBH Net	
Source of Capacity/Size	Documented	
Installation Year	1998	
Source of Installation Year	Documented	
Deficiency	LEAKY/PLUGGED TUBES	
Deficiency Quantity	1	
Quantity Uom Potential Action	EACH	
	REPLACE PRIORITY 3	
Urgency of Action Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Deficiency Deficiency Quantity	DAMAGED REFRACTORY 30	
Quantity Uom	S.F.	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity	6,014	
Instance Quantity Uom	MBH NET	
Cast Iron Boiler?	No	
Manufacturer	A. L. Eastmond & Sons Inc.	
EquipmentId	7369-02	
Capacity/Size Quantity	6014	
Capacity/Size UOM	MBH Net	
Source of Capacity/Size	Documented	
Installation Year	1998	
Source of Installation Year	Documented	
Deficiency	LEAKY/PLUGGED TUBES	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action Purpose of Action	PRIORITY 3 LEVEL 2	
PURDOSE OF A CHOR		

## **Building Condition Assessment Survey 2023-2024**

#### **Mechanical Inspection**

estion	Response
EATING PLANT	
Boiler System	
Steam Boiler	
Deficiency	DAMAGED REFRACTORY
Deficiency Quantity	30
Quantity Uom	S.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fuel System	
Instance on Basement	Inspected
Boiler Fresh Air Louver/Damper	
Instance on Basement	Inspected
Instance Condition	3- Fair
Туре	Automatic
Deficiency	No deficiencies recorded
Burner/Burner Control Panel	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	BURNER CONTROL PANEL: DEFECTIVE OPACITY SENSOR
Deficiency Location/Instance	Boiler Room @ Boilers #1,#2
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fuel Oil Storage/Supply System	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	FUEL OIL TRANSFER PUMP:DEFECTIVE
Deficiency Location/Instance	Near Oil Tank Room (bearing)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	FUEL OIL LEVEL GAUGE:DEFECTIVE
Deficiency Location/Instance	Near Oil Tank Room (1 of 2)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Gas Trains And Vent At The Boiler	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	NOT IN USE
Deficiency Location/Instance	Boiler Room @ Boilers #1, #2
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1

## **Building Condition Assessment Survey 2023-2024**

#### **Mechanical Inspection**

uestion		Response	
	G PLANT	Response	
Fuel Sy			
	rains And Vent At The Boiler		
Gasi	Purpose of Action	LEVEL 1	
	Violations	No violations recorded	
Fnelosod	IDF Room	Inspected	
Elicioseu	Instance on Room 402D	Inspected	
Dedicat	red A/C Equipment	inspected	
Deuleat	Instance on Room 402D	Inspected	
	Instance Condition	1- Good	
	Deficiency	No deficiencies recorded	
KITCHE		Inspected	
MICHE	Instance on 1st Floor	Inspected	
CO Det		inspected	
CO Dei	Instance on 1st Floor	Inspected	
	Instance Condition	4- Between Fair and Poor	
	Deficiency	DEFECTIVE/MISSING	
	Deficiency Location/Instance	Kitchen	
	Deficiency Quantity	1	
	Quantity Uom	EACH	
	Potential Action	MAINTENANCE	
	Urgency of Action	PRIORITY 5	
	Purpose of Action	LEVEL 6	
	Violations	No violations recorded	
Gas Sys	tem		
	Instance on 1st Floor	Inspected	
	Instance Condition	2- Between Good and Fair	
	Deficiency	No deficiencies recorded	
Grease	T <u>rap</u>		
	Instance on 1st Floor	Inspected	
	Instance Condition	2- Between Good and Fair	
	Deficiency	No deficiencies recorded	
Hood			
	Instance on 1st Floor	Inspected	
	Instance Condition	3- Fair	
	Deficiency	No deficiencies recorded	
Hood E	xhaust Ductwork		
	Instance on 1st Floor	Inspected	
	Instance Condition	3- Fair	
	Deficiency	No deficiencies recorded	
Hood E	xhaust Fan		
	Instance on 1st Floor	Inspected	
	Instance Condition	4- Between Fair and Poor	
	Deficiency	DEFECTIVE	
	Deficiency Location/Instance	Kitchen	
	Deficiency Quantity	1	
	Quantity Uom	EACH	
	Potential Action	MAINTENANCE	
	Urgency of Action	PRIORITY 3	
	Purpose of Action	LEVEL 2	
	Violations	No violations recorded	
Hood F	ire Suppression System		
	Instance on 1st Floor	Does not exist	
Hot Wa	ter Temperature Booster		

## **Building Condition Assessment Survey 2023-2024**

#### **Mechanical Inspection**

unieu Inspeciion		110
uestion	Response	
KITCHEN		
Kitchen Sink		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	Missing Air Gap	
Deficiency Location/Instance	Kitchen	
Deficiency Quantity	3	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
MDF Room	Inspected	
Instance on Room inside Room 310	Inspected	
Dedicated A/C Equipment		
Instance on Room inside Room 310	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Inspected	
Instance on Room 508, 510	Inspected	
Alternative Use	Yes	
Acid Waste Neutralizing Tank		
Instance on Room 508, 510	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
CO Detector		
Instance on Room 508, 510	Not required	
Emergency Shower		
Instance on Room 508, 510	Does not exist	
Eye Wash		
Instance on Room 508, 510	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Hood Exhaust Ductwork		
Instance on Room 508, 510	Does not exist	
Hood Exhaust Fan		
Instance on Room 508, 510	Does not exist	
Fixed Laboratory Hood		
Instance on Room 508, 510	Does not exist	
Laboratory Sink	In one - star d	
Instance on Room 508, 510	Inspected 2- Between Good and Fair	
Instance Condition		
Deficiency	No deficiencies recorded	
Make-up Air Unit		
Instance on Poor 509 510	Does not exist	
Instance on Room 508, 510	Does not exist	
SCIENCE PREP ROOM	Inspected	
SCIENCE PREP ROOM Instance on Room 509	Inspected Inspected	
SCIENCE PREP ROOM Instance on Room 509 Alternative Use	Inspected	
SCIENCE PREP ROOM Instance on Room 509 Alternative Use Acid Waste Neutralizing Tank	Inspected Inspected Yes	
SCIENCE PREP ROOM Instance on Room 509 Alternative Use Acid Waste Neutralizing Tank Instance on Room 509	Inspected Inspected Yes Inspected	
SCIENCE PREP ROOM Instance on Room 509 Alternative Use Acid Waste Neutralizing Tank	Inspected Inspected Yes	

## **Building Condition Assessment Survey 2023-2024**

#### Mechanical Inspection

anical Inspection		<b>XU6</b>
uestion	Response	
SCIENCE PREP ROOM		
CO Detector		
Instance on Room 509	Not required	
Emergency Shower		
Instance on Room 509	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Eye Wash		
Instance on Room 509	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Hood Exhaust Ductwork		
Instance on Room 509	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Hood Exhaust Fan		
Instance on Room 509	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fixed Laboratory Hood		
Instance on Room 509	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Laboratory Sink		
Instance on Room 509	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Make-up Air Unit		
Instance on Room 509	Does not exist	
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Does not exist	
SWIMMING POOL	Does not exist	
VENTILATION	Inspected	
Is the building Mechanically ventilated?	Yes	
Exhaust Fan	Inspected	
Condition	2- Between Good and Fair	
Approximate Total # of Fans	1-25	
Deficiency	No deficiencies recorded	
Heating And Ventilating Unit	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Metal Ductwork	Inspected	
Condition	3- Fair	
Are there any uninsulated ductwork by design in Mechanical rooms?	Yes	
Are there chain operated dampers?	No	
Deficiency	No deficiencies recorded	
Supply Fan	Does not exist	
Unit Ventilator	Inspected	
Condition	1- Good	
Deficiency	DEFECTIVE	
Deficiency Location/Instance	North Multipurpose Room, Cafeteria	
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	REPAIR	
Urgency of Action	PRIORITY 3	

## **Building Condition Assessment Survey 2023-2024**

#### Mechanical Inspection

Question

VENTILATION

Unit Ventilator Violations

Response

No violations recorded