Building Condition Assessment Survey 2023-2024

Electrical Inspection X068

Asset:	P.S. 68 - BRONX, 4011 MONTICELLO AVENUE, BRONX, NY, 10466		
Inspection Id	Inspection Type	Time In	Last Edited
2140	ELECTRICAL	2024-01-04 07:38AM	2024-01-30 09:01AM
_			

4	SS	et	$\boldsymbol{\nu}$	at	a	

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Security Lighting
	Years: 2022
	Systems: Partial Molded Case Circuit Breaker Panel Boards
	Years: 2019, 2018, 2010, 2006
	Systems: Partial Emergency Lighting (Battery Pack)
	Years: 2017, 2012
	Systems: Exit Lights (Battery Pack), Gymnasium (LED Lighting), Retrofitted LED Lighting (Classrooms 309, 313), Telephone System
	Years: 2017
	Systems: Auditorium (House Lighting, Dimming System, Partia Theater Lighting), Intrusion Alarm System (Infrared Sensors), Cafeteria (Recessed Fluorescent Lighting)
	Years: 2015
	Systems: Intercom (Elevator), Fire Alarm System (Elevator Recall)
	Years: 2013
	Systems: Interior Fluorescent Lighting, Auditorium (Local Sound System, Projection System), Public Address System (Master Clock, Clocks)
	Years: 2011
	Systems: Partial Service Switch, Switchboard
	Years: 2010
	Systems: Fire Alarm System (Electronic Sub-Panel), Fan

Shutdown Controls

Years: 2007

Systems: Intrusion Alarm System

1999 Years:

Fire Alarm System (Remote Annunciator Panel) Systems:

Years:

Systems: Emergency Light/Exit Panel

Years:

Below Ground

Yes

Yes

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Does Interactive Whiteboard (IWB) Exist?

Water Penetration In Electrical Room?

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in	No
your building?	

Priority Condition

Type of Service

Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
No	Water Penetration in Electrical Room	Water leaks from steam pipe valve.	Electrical Equipment	Electrical Room inside Boiler Room	Anthony Rauschenb erg	Fireman	

Inspection

Question	Response	
Electrical		

Question	Response
ATHLETIC FIELD	Does not exist
AUDITORIUM	Inspected
Instance on Basement	Inspected
House Lighting	mspected
Instance on Basement	Inspected
Does a Chandelier Exist?	No
	NO
Lighting Fixture - Fluorescent Instance on Basement	Inspected
	nispected
Pendant Mounted	
Instance on Basement	Does not exist
Surface Mounted	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Basement	Does not exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not exist
Lighting Fixture - LED	
Instance on Basement	Does not exist
Local Sound System	2000 100 4.110.
Instance on Basement	Inspected
Instance Condition	3- Fair
Installation Year	2011
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	1.0 40.00.00.00
Instance on Basement	Inspected
Instance Condition	3- Fair
Is the projector on a cart or installed on the ceiling?	Ceiling
Deficiency	No deficiencies recorded
	No deficiencies recorded
Theater Lighting System Instance on Basement	Inomostod
	Inspected
Dimming System	T 1
Instance on Basement	Inspected
Instance Condition	4- Between Fair and Poor
Deficiency	DIMMING RACK/LIGHT CONSOLE NOT OPERATIONAL
Deficiency Quantity	1 FACU
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Theater Lighting	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	28
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1

ical Inspection	
uestion	Response
AUDITORIUM	
Theater Lighting System	
Theater Lighting	
Purpose of Action	LEVEL 2
Violations	No violations recorded
CAFETERIA	Inspected
Instance on Basement	Inspected
Lighting	
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	1
Instance on Basement	Does not exist
Surface Mounted	2000 100 01100
Instance on Basement	Does not exist
	DOGS HOL CAISE
Recessed Mounted Instance on Basement	Inchected
Instance on Basement Instance Condition	Inspected 3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Basement	Does not exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not exist
Lighting Fixture - LED	
Instance on Basement	Does not exist
Local Sound System	
Instance on Basement	Inspected
Instance Condition	5- Poor
Installation Year	1973
Source of Installation Year	Documented
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Projection System	
Instance on Basement	Does not exist
Theater Lighting System	
Instance on Basement	Does not exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
	3- Fair
Condition	
Deficiency Operatity	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	11 FACH
Quantity Uom	EACH
Potential Action	REPLACE BALLAST

Building Condition Assessment Survey 2023-2024

	_
estion	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Inspected
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	44
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	46
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	Does not exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not exist
Recessed Mounted	Does not exist
OMPUTER LAB	Inspected
Instance on Room 214	Inspected
Power Panel?	Yes
Lighting	
Instance on Room 214	Inspected
Lighting Fixture - Fluorescent	1
Instance on Room 214	Inspected
Pendant Mounted	пърсска
Instance on Room 214	Inspected
Instance Condition	3- Fair
	No deficiencies recorded
Deficiency	No deliciencies recorded
Surface Mounted	
Instance on Room 214	Does not exist
Recessed Mounted	
Instance on Room 214	Does not exist
Lighting Fixture - HID	
Instance on Room 214	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 214	Does not exist

rical Inspection	D	X06
Duestion	Response	
COMPUTER LAB		
Lighting		
Lighting Fixture - LED Instance on Room 214	Does not exist	
	Does not exist	
Raceway With Receptacles Instance on Room 214	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
<u> </u>		
GYMNASIUM	Inspected	
Instance on 1st Floor	Inspected	
Lighting	Y 4 1	
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent	B	
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	5- Poor	
Installation Year	1973	
Source of Installation Year	Documented Company of the Company of	
Deficiency Deficiency Quantity	AMPLIFIER NOT OPERATIONAL	
Quantity Uom	1 EACH	
Potential Action	REPLACE SYSTEM	
Urgency of Action	PRIORITY 2	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Projection System	140 violations recorded	
Instance on 1st Floor	Does not exist	
Scoreboard	DOGS HOT CAIST	
Instance on 1st Floor	Does not exist	
Theater Lighting System	Does not exist	
Instance on 1st Floor	Does not exist	
KITCHEN	Inspected	
Instance on Basement	Inspected	
	inspecieu	
Lighting Instance on Basement	Inspected	
	nispecieu	
Lighting Fixture - Fluorescent Instance on Basement	Increated	
	Inspected	
Pendant Mounted	Toward 1	
Instance on Basement	Inspected	

Building Condition Assessment Survey 2023-2024

Duestion	Response	
KITCHEN	·	
Lighting		
Lighting Fixture - Fluorescent		
Pendant Mounted		
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Basement	Does not exist	
Recessed Mounted		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on Basement	Does not exist	
Lighting Fixture - Incandescent		
Instance on Basement	Does not exist	
Lighting Fixture - LED		
Instance on Basement	Does not exist	
LIBRARY	Inspected	
Instance on Room 372	Inspected	
Lighting		
Instance on Room 372	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 372	Inspected	
Pendant Mounted		
Instance on Room 372	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 372	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Room 372	Does not exist	·

Does not exist

Inspected

No deficiencies recorded

Inspected

3- Fair

Instance on Room 372

Instance on Room 372

Instance on Room 372

Instance on Room 372

Instance Condition
Deficiency

Lighting Fixture - Incandescent
Instance on Room 372

Lighting Fixture - LED

Raceway With Receptacles

Projection System

MULTIPURPOSE ROOM SCIENCE DEMO ROOM

SCIENCE PREP ROOM

TOILET ROOM - STAFF

SWIMMING POOL

LOCKER ROOM

SCIENCE LAB

Building Condition Assessment Survey 2023-2024

ciricai Inspection	Αυυο
Question	Response
TOILET ROOM - STAFF	
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
	Does not exist
Lighting Fixture - HID	
Lighting Fixture - Incandescent	Inspected Does not exist
Pendant Mounted	
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	Does not exist
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Inspected
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	Does not exist
Accessed Montica	DOGS HOL CAIST

Building Condition Assessment Survey 2023-2024

Response
Does not exist
Inspected
3- Fair
No deficiencies recorded
Does not exist
Does not exist
Inspected
3- Fair
No deficiencies recorded
Inspected
Inspected
2- Between Good and Fair
No deficiencies recorded
Inspected 3- Fair
No deficiencies recorded
Inspected
Inspected
2- Between Good and Fair
No deficiencies recorded
Does not exist
Does not exist
Inspected
Inspected
3- Fair
No deficiencies recorded
Does not exist
Inspected
3- Fair
No deficiencies recorded
Inspected
3- Fair
No deficiencies recorded
Inspected
3- Fair
No deficiencies recorded
Inspected
3- Fair
No deficiencies recorded
Does not exist
Does not exist
Inspected 2- Between Good and Fair
No deficiencies recorded
Does not exist Inspected
Inspected 3- Fair
No deficiencies recorded
No deficiencies recorded Does not exist
DOES HOLEKIST
Inspected
Inspected Inspected

Building Condition Assessment Survey 2023-2024

uestion	Response	
FIRE ALARM SYSTEM	T. C.	
Main Panel		
Bell At Panel		
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Does not exist	
Fire Alarm Control Panel (Standard)	Inspected	
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	ACME	
EquipmentId	Fire Alarm Control Panel	
Installation Year	1973	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Boiler Room	
Deficiency Quantity	78,000	
Quantity Uom	S.F.	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Sub-Panel	Inspected	
Bell At Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Boiler Room	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	General Electric	
Model	EST 2	
EquipmentId	Damper Control Panel	
Installation Year	2007	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Inspected	
Instance	Mechanical Room 291	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	ACME	
EquipmentId	Heat Detection Control Board	
Installation Year	1973	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Mechanical Room 291	
Deficiency Quantity	78,000	
Quantity Uom	S.F.	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
r dipose of riedon		

Boiler Room

Instance

Jugation	Dogwongo	
Question	Response	
FIRE ALARM SYSTEM		
Sub-Panel		
Fire Alarm Control Panel (Standard)	4 F :	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	ACME	
EquipmentId	Sprinkler Alarm Control Board	
Installation Year	1973	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Boiler Room	
Deficiency Quantity	78,000	
Quantity Uom	S.F.	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	ACME	
EquipmentId	Smoke Detection Control Board	
Installation Year	1973	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Boiler Room	
Deficiency Quantity	78,000	
Quantity Uom	S.F.	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	ACME	
EquipmentId	Heat Detection Control Board	
Installation Year	1973	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Boiler Room	
Deficiency Quantity	78,000	
Quantity Uom	S.F.	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Printer	Does not exist	

Building Condition Assessment Survey 2023-2024

Question	Response	
FIRE ALARM SYSTEM		
Remote Annunciator		
Punch Register	Does not exist	
Sprinkler Flow/Air Pressure Switch	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Tamper Flow Switch/Chain	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
GROUNDING SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
INTERCOM SYSTEM	Inspected	
Elevator	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Holding Area	Does not exist	
LAN	Inspected	
	Inspected	
Local Distribution Frame (I/LDF) Condition	3- Fair	
Deficiency	No deficiencies recorded	
Main Equipment Rack (MDF)	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
	Does not exist	
LIGHTNING PROTECTION		
MOTOR CONTROLLER	Inspected	
MOTOR CONTROL CENTER	Inspected Boiler Room	
Instance	3- Fair	
Instance Condition		
Instance Quantity	1 FACH	
Instance Quantity Uom	EACH	
Manufacturer	Royal Switchboard	
EquipmentId	N/A	
Capacity/Size Quantity	200	
Capacity/Size UOM Capacity/Size 2 Quantity	Amps 1	
Capacity/Size 2 Quantity Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Inspector Estimate	
Installation Year	1973	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Boiler Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
MOTOR STARTER/CONTACTOR	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
	Does not exist	
Variable Frequency Drive	Boos not exist	
Variable Frequency Drive PANEL BOARD	Inspected	

Condition

3- Fair

Building Condition Assessment Survey 2023-2024

uestion	Response
PANEL BOARD	•
Fused Disconnect Switch Type	
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room, Room B71, Electrical Room
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	1 moughout the building
Quantity Uom	EACH PEN AGE LINGDADE
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	Main Office - Room 212
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	N/A
Installation Year	1973
Source of Installation Year	Documented
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Main Office - Room 212
Deficiency Quantity	78,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded

Inspected

SECURITY

Electrical Inspection	X068

uestion	Response
SECURITY	
IPDVS/CCTV System	Does not exist
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office - Room 113
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 50P
Installation Year	1999
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
SERVICE SWITCH	Inspected
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
	Royal Switchboard Co.
Manufacturer	Lighting
EquipmentId Capacity/Size Quantity	1200
Capacity/Size Quantity Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1973
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Siemens
EquipmentId	Main Service Switch
	2000
Capacity/Size Quantity Capacity/Size UOM	Amps

Building Condition Assessment Survey 2023-2024

ciricai Inspection		74000
Question	Response	
SERVICE SWITCH		
Source of Capacity/Size	Nameplate	
Installation Year	2010	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Room B71	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Royal Switchboard Co.	
	N/A	
EquipmentId Capacity/Size Quantity	1200	
Capacity/Size Quantity Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	1973	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Room B71	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
SWITCHBOARD	Inspected	
Number of Spares	0	
Fused Disconnect Switch Type	Inspected	
Instance	Electrical Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Royal Switchboard Co.	
EquipmentId	N/A	
Capacity/Size Quantity	1200	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	2	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Nameplate	
Installation Year	1973	
Source of Installation Year	Documented Previous No. 100 Previous Pr	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	Electrical Room	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Siemens	
EquipmentId	N/A	
Capacity/Size Quantity	2000	
Capacity/Size Quantity	2000	

Building Condition Assessment Survey 2023-2024

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Room B71
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Royal Switchboard Co.
EquipmentId	N/A
Capacity/Size Quantity	1200
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	1973
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Room B71
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not exist