### **Building Condition Assessment Survey 2023-2024**

Asset:	P.S. 71 - BR	ONX, 3040 ROBERTS AVENU	E, BRONX, NY,	10461			
Inspection Id	Inspection Ty	ре			Time	In	Last Edited
1016	MECHANICA	AL			2023-	-11-15 08:42AN	1 2023-12-21 08:52AN
set Data							
Question				Answer			
Have any Syst	ems/Major Build	ling Components been upgraded?		Systems:	MDF Room -	Dedicated A/C	Equipment (DX Split
	-				•	iler Safety Valve	s
				Years:	2019		
				Systems:	Sump Pump (	(1 of 2)	
				Years:	2018	_	
				Systems:		sure Booster Syst	tem
				Years:	2017		
				Systems:			perature Control
							p Traps; Terminal Unit ondensate Return
							oilets, Urinals; Kitchen -
							erature Booster, Kitchen
					Sinks	filot water remp	eratare Booster, Riterien
				Years:	2016		
				Systems:	CO/Gas Leak	Detection	
				Years:	2014		
Are there fuel	tanks?			Yes			
Total # of	above ground tar	nks		1			
Total capa	city of all above	ground tanks in gal.		8,500			
	below ground tar			0			
-		ground tanks in gal.		0			
		entries to the asset		2			
MERs/Fan Ro	oms Locations						Gymnasium Fan
And theme only	ana aga with Mig	aina an Dafaatiyya CO Dataatana?		Room, Pe No	enthouse - Tank	Room	
		sing or Defective CO Detectors? ted Sprinkler Heads?		Yes			
Location(s)	I anneu/Obstruct	icu spinikier freads:			Storage Room	(nainted 1)	
	Emergency Ston	Switches with Missing Hammers?		No compo	-	(punited, 1)	
iority Condi		ownered what thissing Hammers.			, nonto		
•	lority	Condition	Component	Location	Person(s)	Person(s)	Photo
	tegory	Description	Affected	Description	Notified	Title	Image
No condition r	recorded						
nspection							
Question				Response	•		
Mechanical							
AIR CONDITIONING				Does not	exist		
CENTRAL ACID WASTE NEUTRALIZING TANK				Does not	exist		
CLIMATE	CONTROL SYS	STEM		Inspected			
BMS				Does not			
Pneumati	- · ·			Inspected			
-	nstance			Througho	out		
-	nstance Conditio			3- Fair			
I	nstance Quantity			1			

Instance Quantity Uom

Deficiency Quantity

Quantity Uom

Potential Action

Urgency of Action

Deficiency Location/Instance

Deficiency

Building Area Covered by Operational System

EACH

1

EACH

81-100%

Corridor near room 300

MAINTENANCE

PRIORITY 3

DEFECTIVE TERMINAL UNIT CONTROL VALVE

## **Building Condition Assessment Survey 2023-2024**

### **Mechanical Inspection**

unicui Inspeciion	Λυ
uestion	Response
CLIMATE CONTROL SYSTEM	
Pneumatic System	
Purpose of Action	LEVEL 2
Violations	No violations recorded
Hybrid System	Does not exist
Electric System	Does not exist
COMPACTOR	Does not exist
CONVEYING	Does not exist
	Inspected
DOMESTIC WATER SYSTEM	Inspected
Domestic Cold Water System	Inspected
Gravity System	Does not exist
Supply Pump	Inaccessible
Roof Tank	
Pressure Booster System	Inspected
Electric Pressure Booster System	Inspected
Instance	Boiler Room 1- Good
Instance Condition	
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Allen-Bradley
EquipmentId	N/A
Capacity/Size Quantity	2
Capacity/Size UOM	Total # Pumps
Capacity/Size 2 Quantity	10
Capacity/Size 2 UOM	Total Pumps HP
Source of Capacity/Size	Documented 2017
Installation Year Source of Installation Year	2017 Custodial Staff
	No deficiencies recorded
Deficiency	
Hydraulic/Pneumatic Booster System	Inspected
Water Pressure Booster - Compressor	Inspected 3- Fair
Condition	
Deficiency	NOT IN USE
Deficiency Location/Instance Deficiency Quantity	Boiler Room
	1
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action Violations	LEVEL 1 No violations recorded
Pressure Booster Pump	Inspected 2 Feite
Condition	3- Fair
Deficiency	NOT IN USE
Deficiency Location/Instance Deficiency Quantity	Boiler Room
Quantity Uom Potential Action	EACH
	NO ACTION
Urgency of Action Purpose of Action	PRIORITY 1 LEVEL 1
-	LEVEL I No violations recorded
Violations	INO VIOIALIONS RECORDED
Violations	
Domestic Cold Water Tank	Inspected
Domestic Cold Water Tank Condition	Inspected 3- Fair
Domestic Cold Water Tank	Inspected

### **Building Condition Assessment Survey 2023-2024**

### **Mechanical Inspection**

icui Inspeciion	
tion	Response
MESTIC WATER SYSTEM	
Oomestic Cold Water System	
Pressure Booster System	
Hydraulic/Pneumatic Booster System	
Domestic Cold Water Tank	
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
Water Service	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	2
Instance Quantity Uom	EACH
Deficiency	WATER MAIN: MISSING BACKFLOW PREVENTION
,	DEVICE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	INSTALL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
omestic Hot Water System	Inspected
Domestic Hot Water Remote Storage Tank	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Domestic Water Heat Exchanger	Does not exist
Electric Domestic Water Heater	Does not exist
Gas Fired Domestic Water Heater	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	RayPak
EquipmentId	N/A
Capacity/Size Quantity	264
Capacity/Size UOM	MBH Input
Capacity/Size 2 Quantity	0
Capacity/Size 2 UOM	Gallons
Source of Capacity/Size	Documented
Installation Year	1990
Source of Installation Year	Inspector Estimate
Deficiency	No deficiencies recorded
Oil Fired Domestic Water Heater	Does not exist
Heat Pump Domestic Water Heater	Does not exist
omestic Water Distribution Piping	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE DOMESTIC HOT WATER CIRCULATING PUMP
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uam	EACH
Quantity Uom	
Potential Action	MAINTENANCE
	MAINTENANCE PRIORITY 3

## **Building Condition Assessment Survey 2023-2024**

### Mechanical Inspection

	Αυ
uestion	Response
DOMESTIC WATER SYSTEM	
Domestic Water Distribution Piping	
Violations	No violations recorded
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected
Interior Storm Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sewage/Waste/Vent Piping	Inspected
Condition	3- Fair
Deficiency	INTERIOR FLOOR DRAIN: DEFECTIVE
Deficiency Location/Instance	Janitor's Closet Room 416
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	SEWAGE/WASTE PIPING:DEFECTIVE/LEAKS
Deficiency Location/Instance	5th Floor - Girl's Toilet Room, Staff Toilet Room
Deficiency Quantity	20
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Sewage Ejector Pump	Does not exist
Sump Pump	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist
TIXTURES	Inspected
Staff And Other	Inspected
Janitor Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Urinal	Does not exist
Student	Inspected
Drinking Fountain	Inspected
Condition	3- Fair
Deficiency	CRACKED/PHYSICAL DAMAGE
Deficiency Location/Instance	Corridor near Room 300
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF
,	VALVE,ETC.)

## **Building Condition Assessment Survey 2023-2024**

### **Mechanical Inspection**

uestion	Response
FIXTURES	
Student	
Drinking Fountain	
Deficiency Location/Instance Deficiency Quantity	Corridor near Room 409 1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lavatory/Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Locker Room Shower	Does not exist
Sink And Fountain Combo Unit	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	2- Between Good and Fair
	No deficiencies recorded
Deficiency	Inspected
Urinal Condition	
	2- Between Good and Fair
Deficiency	No deficiencies recorded
GAS FIRED FURNACE	Does not exist
GAS SERVICE	Inspected
Gas Distribution Piping	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Gas Meter Room Exhaust Fan	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Gas Meter Room Vent	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Gas Pressure Booster	Does not exist
CO/Gas Leak Detection	Inspected
Instance	Basement - Boiler Room, Gas Meter Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Installation Year	2014
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
HEATING	Inspected
Heating Coil In Ductwork	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Hydronic Heating	Does not exist
Radiator/Convector/Fin Tube	Inspected
Condition	3- Fair
Deficiency	AUXILIARY (VALVE, VENT): DEFECTIVE
Deficiency Location/Instance	4th Floor Stair "D"
Deficiency Quantity	1

## **Building Condition Assessment Survey 2023-2024**

### **Mechanical Inspection**

inicui Inspeciion		Λ
estion	Response	
EATING		
Radiator/Convector/Fin Tube		
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Steam Heating	Inspected	
F&T/Steam Drip Trap	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
MER Steam and Condensate Piping	Inspected	
Condition	3- Fair	
Deficiency	DEFECTIVE VALVE	
Deficiency Location/Instance	Boiler Room Mechanical Area	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Steam Condensate Return Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Steam Condensate Return Pumping System	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Steam Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Terminal Unit Thermostatic Trap	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Steam supplied by External Sources	Does not exist	
Unit Heater/Cabinet Heater	Does not exist	
EATING PLANT	Inspected	
Instance on Basement	Inspected	
Is there a water meter on the boiler make-up water piping?	Yes	
Observed Operational?	No	
Burner Manufacturer	Industrial Combustion	
Burner Model	DLG-105P	
Burner Type	Dual Fuel (Gas/Oil)	
Heating Plant Oil Number	2	
Boiler Auxiliaries		
Instance on Basement	Inspected	
Boiler Auxiliary Piping		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler Emergency Stop Switch		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler Feedwater System		
	Increated	
Instance on Basement	Inspected 3- Fair	
Instance Condition	5- Fair	

### **Building Condition Assessment Survey 2023-2024**

### **Mechanical Inspection**

estion	Response
EATING PLANT	A
Boiler Auxiliaries	
Boiler Feedwater System	
Deficiency	FEEDWATER TANK:DEFECTIVE TANK AUXILIARIES(AUTO FEEDWATER VALVE, LOW LEVEL CUT OFF,ETC)
Deficiency Location/Instance	Boiler Room (defective gauge)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Boiler Feedwater Treatment(Automatic)	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Flue Exhaust	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Make-up Water Backflow Preventer	
Instance on Basement	Inspected
Instance Condition	5- Poor
Deficiency	DEFECTIVE RPZ
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Boiler Room Steam And Condensate Piping	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Safety Valve	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Boiler System	
Instance on Basement	Inspected
Coal-fired Boiler	
Instance on Basement	Does not exist
Hot Water Boiler	
Instance on Basement	Does not exist
Modular Boiler	
Instance on Basement	Does not exist
Steam Boiler	
Instance on Basement	Inspected
Instance on Basement	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	6,498
Instance Quantity Uom	MBH NET

### **Building Condition Assessment Survey 2023-2024**

### **Mechanical Inspection**

stion		Response	
EATING			
Boiler Sys			
Steam B			
_	Cast Iron Boiler?	No	
	Manufacturer	A. L. Eastmond & Sons Inc.	
	EquipmentId	6223-01	
	Capacity/Size Quantity	6498	
	Capacity/Size UOM	MBH Net	
	Source of Capacity/Size	Documented	
	Installation Year	1998	
-	Source of Installation Year	Documented	
Γ	Deficiency	DAMAGED REFRACTORY	
	Deficiency Quantity	30	
	Quantity Uom	S.F.	
	Potential Action	REPLACE	
	Urgency of Action	PRIORITY 3	
	Purpose of Action	LEVEL 2	
	Violations	No violations recorded	
I	Instance	Boiler Room	
Ī	Instance Condition	3- Fair	
-	Instance Quantity	6,498	
-		MBH NET	
_	Instance Quantity Uom		
-	Cast Iron Boiler?	No	
	Manufacturer	A. L. Eastmond & Sons Inc.	
	EquipmentId	6223-02	
	Capacity/Size Quantity	6498	
	Capacity/Size UOM	MBH Net	
	Source of Capacity/Size	Documented	
	Installation Year	1998	
-	Source of Installation Year	Documented	
	Deficiency	No deficiencies recorded	
Fuel Syste			
	Instance on Basement	Inspected	
Boiler F	Fresh Air Louver/Damper		
I	Instance on Basement	Inspected	
I	Instance Condition	3- Fair	
T	Гуре	Automatic	
Γ	Deficiency	No deficiencies recorded	
Burner/	/Burner Control Panel		
Ī	Instance on Basement	Inspected	
Ţ	Instance Condition	3- Fair	
_	Deficiency	No deficiencies recorded	
	l Storage/Supply System	T (1	
_	Instance on Basement	Inspected	
-	Instance Condition	3- Fair	
I	Deficiency	No deficiencies recorded	
Gas Tra	ins And Vent At The Boiler		
I	Instance on Basement	Inspected	
I	Instance Condition	3- Fair	
Γ	Deficiency	No deficiencies recorded	
	DF Room	Inspected	
-	Instance on Room 252		
I	Instance on Room 352	Inspected	
 Dedicated	Instance on Room 352 IA/C Equipment Instance on Room 352	Inspected	

## **Building Condition Assessment Survey 2023-2024**

### **Mechanical Inspection**

lestion		Response	
	IDE D	Response	
	IDF Room		
Dedica	ted A/C Equipment	DOEGNOTEVICT	
	Deficiency	DOES NOT EXIST	
	Deficiency Location/Instance Deficiency Quantity	Room 352	
	• • •	EACH	
	Quantity Uom Potential Action	INSTALL	
	Urgency of Action	PRIORITY 3	
	Purpose of Action	LEVEL 2	
	Violations	No violations recorded	
KITCHE		Inspected	
	Instance on 1st Floor	Inspected	
CO De			
	Instance on 1st Floor	Inspected	
	Instance Condition	1- Good	
	Deficiency	No deficiencies recorded	
Gas Sy	stem		
	Instance on 1st Floor	Does not exist	
Grease	T <u>rap</u>		
	Instance on 1st Floor	Inspected	
	Instance Condition	2- Between Good and Fair	
	Deficiency	No deficiencies recorded	
Hood			
	Instance on 1st Floor	Inspected	
	Instance Condition	3- Fair	
	Deficiency	No deficiencies recorded	
Hood F	Exhaust Ductwork		
	Instance on 1st Floor	Inspected	
	Instance Condition	4- Between Fair and Poor	
	Deficiency	DEFECTIVE/DETERIORATED	
	Deficiency Location/Instance	Building exterior by playground	
	Deficiency Quantity	30	
	Quantity Uom	L.F.	
	Potential Action	REPLACE	
	Urgency of Action	PRIORITY 3	
	Purpose of Action	LEVEL 2	
	Violations	No violations recorded	
Hood E	Exhaust Fan		
	Instance on 1st Floor	Inspected	
	Instance Condition	3- Fair	
	Deficiency	No deficiencies recorded	
Hood F	Fire Suppression System		
11000 1	Instance on 1st Floor	Inspected	
	Instance Condition	3- Fair	
	Deficiency	No deficiencies recorded	
H-4 W/		No deficicités récorded	
HOT Wa	ater Temperature Booster	Increated	
		Inspected 2- Between Good and Fair	
	Instance Condition		
	Deficiency	No deficiencies recorded	
Kitcher			
	Instance on 1st Floor	Inspected	
	Instance Condition	2- Between Good and Fair	
	Deficiency	No deficiencies recorded	
MDF Ro	om	Inspected	
	Instance on Room 218	Inspected	

# NYC Department of Education Building Condition Assessment Survey 2023-2024

### **Mechanical Inspection**

	Αυ/Ι
Question	Response
MDF Room	
Dedicated A/C Equipment	
Instance on Room 218	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
SCIENCE DEMO ROOM	Inspected
Instance on Rooms 207, 414, 502, 504	Inspected
Alternative Use	No
Acid Waste Neutralizing Tank	110
Instance on Rooms 207, 414, 502, 504	Does not exist
CO Detector	
Instance on Rooms 207, 414, 502, 504	Not required
Emergency Shower	
Instance on Rooms 207, 414, 502, 504	Does not exist
Eye Wash	
Instance on Rooms 207, 414, 502, 504	Does not exist
Hood Exhaust Ductwork	
Instance on Rooms 207, 414, 502, 504	Does not exist
Hood Exhaust Fan	
Instance on Rooms 207, 414, 502, 504	Does not exist
Fixed Laboratory Hood	
Instance on Rooms 207, 414, 502, 504	Does not exist
Laboratory Sink	
Instance on Rooms 207, 414, 502, 504	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Make-up Air Unit Instance on Rooms 207, 414, 502, 504	Does not exist
SCIENCE LAB	Does not exist
SCIENCE PREP ROOM	Does not exist
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected
Dry Sprinkler Alarm Valve Assembly	Does not exist
Wet Sprinkler Alarm Valve Assembly	Does not exist
Fire Booster Pump Assembly	Does not exist
Roof Tank	Does not exist
Siamese Connection	Does not exist
Sprinkler Head	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Basement Storage Room (painted, 1)
Deficiency Quantity	
Quantity Uom Potential Action	EACH REPLACE
	REPLACE PRIORITY 5
Urgency of Action Purpose of Action	LEVEL 6
Violations	No violations recorded
Sprinkler Piping	Inspected 3- Fair
Condition	
Deficiency	No deficiencies recorded
Standpipe System	Does not exist
Water Gong	Does not exist
SWIMMING POOL	Does not exist
VENTILATION	Inspected
Is the building Mechanically ventilated?	Partial
Exhaust Fan	Inspected

## **Building Condition Assessment Survey 2023-2024**

#### **Mechanical Inspection**

anical Inspection		X071
uestion	Response	
VENTILATION		
Exhaust Fan		
Condition	3- Fair	
Approximate Total # of Fans	1-25	
Deficiency	No deficiencies recorded	
Heating And Ventilating Unit	Does not exist	
Metal Ductwork	Inspected	
Condition	3- Fair	
Are there any uninsulated ductwork by design in Mechanical rooms?	Yes	
Are there chain operated dampers?	Yes	
Deficiency	No deficiencies recorded	
Supply Fan	Inspected	
Condition	3- Fair	
Approximate Total # of Fans	1-5	
Deficiency	No deficiencies recorded	
Unit Ventilator	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	