# **Building Condition Assessment Survey 2023-2024**

**Mechanical Inspection** X080

Asset:	I.S. 80/P.S. 280 - BRONX, 149 EAST MOSHOLU PARKWAY NORTH, BRONX, NY, 10467		
Inspection Id	Inspection Type	Time In	Last Edited
4436	MECHANICAL	2024-04-02 07:12AM	2024-04-23 05:15PM

4430 MECHANICAL	2024-04-02 U/:12AM 2024-04-23 U3:15P
eet Data	
Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: F&T/Steam Drip Traps; Terminal Unit Thermostatic Traps; Steam Condensate Return Pumping System; Boiler Safety Valves (3 of 6); Exhaust Fans (~50%)
	Years: 2020
	Systems: DX Split Systems for Auditorium, Cafeteria and 5th
	Floor Gymnasium (15 of 20)
	Years: 2019
	Systems: Kitchen - Grease Trap (1 of 2); Toilet Room Fixtures (~20%)
	Years: 2016.
	Systems: Climate Control System - Pneumatic System: Temperature Control Thermostats; DX Split Systems for Nurses Office 280, Administration Suite 323 (2 of 20)
	Years: 2015
	Systems: Elevator (1 of 2); DX Split System for Elevator  Machine Room (1 of 20); MDF Room - Dedicated A/C  Equipment (1 of 2, DX Split System)
	Years: 2014
	Systems: Toilet Room Fixtures (~75%)
	Years: 2013
Are there fuel tanks?	Yes
Total # of above ground tanks	2
Total capacity of all above ground tanks in gal.	18.000
Total # of below ground tanks	0
Total capacity of all below ground tanks in gal.	0
Total # of water main service entries to the asset	3
MERs/Fan Rooms Locations	Basement - West Mechanical Area, Boiler Room Mechanical Area; 5th Floor - Gymnasium Fan Room
Are there any spaces with Missing or Defective CO Detectors?	Yes
Location(s)	Kitchen, Science Lab
Are there any Painted/Obstructed Sprinkler Heads?	Yes
Location(s)	Basement - Paint Storage Room, Fire Extinguishers Storage Room; Room 202 (painted, 10)
Are there any Emergency Stop Switches with Missing Hammers?	No components

Priority Co	ondition						
Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No	Defective CO/Gas Leak Detection	Fault Signal At Panels	CO/Gas Leak Detection	Boiler Room, Custodians Office	Carlos Entriano	Fireman	
Yes	Other	Defective (1)	Science Lab - Eye Wash	Room 314A	Carlos Entriano	Fireman	

#### **Building Condition Assessment Survey 2023-2024**

#### Mechanical Inspection X080

No Defective Boiler Water Column Assembly: Steam Boiler Boiler Room / Carlos Fireman Safety Auxiliary Sight Glass is leaking Boiler #2 Entriano



Inspection
------------

estion	Response
echanical	
AIR CONDITIONING	Inspected
Chilled Water System	Does not exist
Condenser Water Distribution: Piping, Pumps and Auxiliaries	Does not exist
Cooling Coil in Ductwork	Does not exist
Cooling Tower	Does not exist
DX Split System	Inspected
Indoor Unit	Inspected
Condition	1- Good
Deficiency	OVER 5 TONS:DEFECTIVE
Deficiency Location/Instance	Nurses Office 280, 5th Floor Gymnasium
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Outdoor Unit	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Dry Cooler	Does not exist
Packaged / Rooftop Unit	Inspected
Instance	Building Addition - Roof
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	York
EquipmentId	AC-1
Capacity/Size Quantity	11
Capacity/Size UOM	Tons
Source of Capacity/Size	Inspector Estimate
Installation Year	1999
Source of Installation Year	Documented
Source of Heating	Gas
Refrigerant Type	R-22
Deficiency	No deficiencies recorded
Instance	Building Addition - Roof
Instance Condition	3- Fair
Instance Quantity	4
Instance Quantity Uom	EACH
Manufacturer	York
EquipmentId	AC-2, AC-3, AC- 5, AC-7
Capacity/Size Quantity	9
Capacity/Size UOM	Tons
Source of Capacity/Size	Inspector Estimate
Installation Year	1999
Source of Installation Year	Documented
Source of Heating	Gas

#### **Building Condition Assessment Survey 2023-2024**

hanical Inspection		X080
Question	Response	
AIR CONDITIONING		
Packaged / Rooftop Unit		
Refrigerant Type	R-22	
Deficiency	No deficiencies recorded	
Instance	Building Addition - Roof	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	York	
EquipmentId	AC-4	
Capacity/Size Quantity	13	
Capacity/Size UOM	Tons	
Source of Capacity/Size	Inspector Estimate	
Installation Year	1999	
Source of Installation Year	Documented	
Source of Heating	Gas	
Refrigerant Type	R-22	
Deficiency	No deficiencies recorded	
Instance	Building Addition - Roof	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	York	
EquipmentId	AC-6	
Capacity/Size Quantity	20	
Capacity/Size UOM	Tons	
Source of Capacity/Size	Inspector Estimate	

Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
CLIMATE CONTROL SYSTEM	Inspected
BMS	Inspected
Instance	Building Addition - Throughout
Instance Condition	4- Between Fair and Poor
Instance Quantity	1
Instance Quantity Uom	EACH
Building Area Covered by Operational System	0-20%

EACH

NO ACTION

**Deficiency Quantity** Quantity Uom

Potential Action

Mechanical Inspection	X080

uestion	Response	
CLIMATE CONTROL SYSTEM		
BMS		
Installation Year	1999	
Source of Installation Year	Documented	
Deficiency	DEFECTIVE SYSTEM	
Deficiency Location/Instance	Building Addition - Throughout	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPAIR	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Pneumatic System	Inspected	
Instance	Original Building - Throughout	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Building Area Covered by Operational System	81-100%	
Deficiency	No deficiencies recorded	
Hybrid System	Does not exist	
Electric System	Does not exist	
COMPACTOR	Does not exist	
CONVEYING	Inspected	
Dumbwaiter	Does not exist	
Elevator	Inspected	
Condition	2- Between Good and Fair	
Are all the existing elevators operable?	Yes	
Deficiency	No deficiencies recorded	
Escalator	Does not exist	
Non-auditorium Handicap Lift - Vertical	Does not exist	
Non-auditorium Handicap Lift - Stair	Does not exist	
Ash Hoist	Does not exist	
Sidewalk Elevator	Does not exist	
DOMESTIC WATER SYSTEM	Inspected	
Domestic Cold Water System	Inspected	
Gravity System	Does not exist	
Pressure Booster System	Inspected	
Electric Pressure Booster System	Inspected	
Instance	Boiler Room Mechanical Area	
Instance Condition	3- Fair	
Instance Quantity		
	1 EACH	
Instance Quantity Uom		
Manufacturer	SyncroFlo	
EquipmentId	N/A	
Capacity/Size Quantity	3	
Capacity/Size UOM	Total # Pumps	
Capacity/Size 2 Quantity	8	
Capacity/Size 2 UOM	Total Pumps HP	
Source of Capacity/Size	Documented	
Installation Year	1999	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Hydraulic/Pneumatic Booster System	Does not exist	
Water Service	Inspected	
Water Service Instance	Inspected Boiler Room, Boiler Room Mechanical Area	

estion	Response
DOMESTIC WATER SYSTEM	псэронэс
Domestic Cold Water System Water Service	
Instance Condition	3- Fair
Instance Quantity	3
	EACH
Instance Quantity Uom	
Deficiency	No deficiencies recorded
Domestic Hot Water System	Inspected
Domestic Hot Water Remote Storage Tank	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Domestic Water Heat Exchanger	Does not exist
Electric Domestic Water Heater	Does not exist
Gas Fired Domestic Water Heater	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Rheem / Ruud
EquipmentId	N/A
Capacity/Size Quantity	264
Capacity/Size UOM	MBH Input
Capacity/Size 2 Quantity	0
Capacity/Size 2 UOM	Gallons
Source of Capacity/Size	Documented
Installation Year	2010
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Oil Fired Domestic Water Heater	Does not exist
Heat Pump Domestic Water Heater	Does not exist
Domestic Water Distribution Piping	Inspected
Condition	3- Fair
Deficiency	DAMAGED/MISSING INSULATION
Deficiency Location/Instance	Near Room 513
Deficiency Quantity	60
Quantity Uom	L.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
RAIN/WASTE/VENT AND STORM SYSTEM	Inspected
Interior Storm Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sewage/Waste/Vent Piping	Inspected
Condition	3- Fair
Deficiency	SEWAGE/WASTE PIPING:DEFECTIVE/LEAKS
Deficiency Location/Instance	Kitchen
Deficiency Quantity	10
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Sewage Ejector Pump	Does not exist

#### **Building Condition Assessment Survey 2023-2024**

Mechanical Inspection X080

uestion	Response
DRAIN/WASTE/VENT AND STORM SYSTEM	
Sump Pump	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE
Deficiency Location/Instance	Boiler Room (2 of 6)
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist
FIXTURES	Inspected
Staff And Other	Inspected
Janitor Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Urinal	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Student	Inspected
Drinking Fountain	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF
Deficiency	VALVE,ETC.)
Deficiency Location/Instance	Corridor near Room 512
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lavatory/Sink	Inspected
Condition	2- Between Good and Fair
Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF
,	VALVE,ETC.)
Deficiency Location/Instance	Boy's Toilet Room 209A
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Locker Room Shower	Inspected
Instance on Stair "F/3"	Inaccessible
Sink And Fountain Combo Unit	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Toilet	Inspected

Mechanical Inspection		X080
0	D	

Question	Response	
FIXTURES		
Student		
Toilet		
Condition	2- Between Good and Fair	
Deficiency	CLOGGED/LEAKING	
Deficiency Location/Instance	Boy's Toilet Room 209A	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Urinal	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
GAS FIRED FURNACE	Does not exist	
GAS SERVICE	Inspected	
Gas Distribution Piping	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Gas Meter Room Exhaust Fan	Does not exist	
Gas Meter Room Vent	Inspected 3- Fair	
Condition		
Deficiency	No deficiencies recorded	
Gas Pressure Booster	Does not exist	
CO/Gas Leak Detection	Inspected C. M. C.	
Instance	Basement - Boiler Room, Gas Meter Room	
Instance Condition	4- Between Fair and Poor	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Installation Year	1999	
Source of Installation Year	Documented	
Deficiency	DEFECTIVE CONTROL PANEL	
Deficiency Location/Instance	Boiler Room, Custodian's Office	
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	REPAIR	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
HEATING	Inspected	
Heating Coil In Ductwork	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hydronic Heating	Does not exist	
Radiator/Convector/Fin Tube	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Steam Heating	Inspected	
F&T/Steam Drip Trap	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
MER Steam and Condensate Piping	Inspected	
Condition	3- Fair	
Deficiency	DAMAGED/MISSING INSULATION	
Deficiency	DAMAGED/MISSING INSULATION	

Mechanical Inspection	X080_

	<b>D</b>
estion	Response
EATING	
Steam Heating	
MER Steam and Condensate Piping	
Deficiency Location/Instance	Basement - West Mechanical Area
Deficiency Quantity	60
Quantity Uom	L.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Condensate Return Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Steam Condensate Return Pumping System	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Steam Piping	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE/LEAKS
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	10
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
	Inspected
Terminal Unit Thermostatic Trap	<del>-</del>
Condition	1- Good
Deficiency	No deficiencies recorded
Steam supplied by External Sources	Does not exist
Unit Heater/Cabinet Heater	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EATING PLANT	Inspected
Instance on Basement	Inspected
Is there a water meter on the boiler make-up water piping?	Yes
Observed Operational?	No
Burner Manufacturer	KEWANEE
Burner Model	250-KFC7.5 - 1152- GO2
Burner Type	Oil
Heating Plant Oil Number	2
Boiler Auxiliaries	
Instance on Basement	Inspected
Boiler Auxiliary Piping	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	DEFECTIVE BOILER AUTOMATIC FEEDWATER VALVE
Deficiency Location/Instance	Boiler Room @ Boiler #1
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded

stion	Response
EATING PLANT	
Boiler Auxiliaries	
Boiler Emergency Stop Switch	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Feedwater System	
Instance on Basement	Inspected
Instance Condition	4- Between Fair and Poor
Deficiency	FEEDWATER TANK:DEFECTIVE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	FEEDWATER TANK:DAMAGED/MISSING INSULATION
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	160
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Boiler Feedwater Treatment(Automatic)	140 Violations recorded
Instance on Basement	Turnerated
	Inspected 4- Between Fair and Poor
Instance Condition	
Deficiency	DEFECTIVE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3 LEVEL 2
Purpose of Action	: :
Violations	No violations recorded
Boiler Flue Exhaust	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Make-up Water Backflow Preventer	
Instance on Basement	Inspected
Instance Condition	4- Between Fair and Poor
Deficiency	DEFECTIVE RPZ
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Boiler Room Steam And Condensate Piping	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded

Question	Response
HEATING PLANT	•
Boiler Auxiliaries	
Boiler Safety Valve	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Boiler System	
Instance on Basement	Inspected
Coal-fired Boiler	•
Instance on Basement	Does not exist
Hot Water Boiler	
Instance on Basement	Does not exist
Modular Boiler	
Instance on Basement	Does not exist
Steam Boiler	
Instance on Basement	Inspected
Instance on Basement	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	6,498
Instance Quantity Uom	MBH NET
Cast Iron Boiler?	No
Manufacturer	Kewanee Boiler Corporation
EquipmentId	7281-01
Capacity/Size Quantity	8369
Capacity/Size UOM	MBH Gross
Source of Capacity/Size	Documented
Installation Year	1999
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	6,498
Instance Quantity Uom	MBH NET
Cast Iron Boiler?	No
Manufacturer	Kewanee Boiler Corporation
EquipmentId	7281-02
Capacity/Size Quantity	8369
Capacity/Size UOM	MBH Gross
Source of Capacity/Size	Documented 1999
Installation Year Source of Installation Year	Documented
Deficiency	DEFECTIVE SAFETY AUXILIARY: LOW-WATER CUT-OFF.
Beneficiency	WATER COLUMN ASSEMBLY
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Deficiency	LEAKY/PLUGGED TUBES
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

anical Inspection		X08
uestion	Response	
HEATING PLANT		
Boiler System		
Steam Boiler		
Violations	No violations recorded	
Fuel System		
Instance on Basement	Inspected	
Boiler Fresh Air Louver/Damper		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Туре	Automatic	
Deficiency	No deficiencies recorded	
Burner/Burner Control Panel		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fuel Oil Storage/Supply System	The deficiencies recorded	
Instance on Basement	Inspected	
Instance on Basement Instance Condition	3- Fair	
,		
Deficiency	No deficiencies recorded	
Gas Trains And Vent At The Boiler		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	NOT IN USE	
Deficiency Location/Instance	Boiler Room @ Boilers #1, #2	
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	NO ACTION	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 1	
Violations	No violations recorded	
Enclosed IDF Room	Inspected	
Instance on Building Addition - Room 282	Inspected	
Instance on Original Building - Room 353	Inspected	
Dedicated A/C Equipment		
Instance on Building Addition - Room 282	Inspected	
Instance Condition	4- Between Fair and Poor	
Deficiency	DEFECTIVE	
Deficiency Location/Instance	Building Addition - Room 282	
Deficiency Quantity	building Addition - Room 282	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance on Original Building - Room 353	Inspected	
Instance Condition	4- Between Fair and Poor	
Deficiency	DOES NOT EXIST	
Deficiency Location/Instance	Original Building - Room 353	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	INSTALL	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
KITCHEN	Inspected	

#### **Building Condition Assessment Survey 2023-2024**

uestion	Response	
	Кезропос	
KITCHEN Instance on 1st Floor	Inspected	
Instance on 1st Floor CO Detector	Inspected	
Instance on 1st Floor	Inspected	
Instance Condition	4- Between Fair and Poor	
Deficiency	DEFECTIVE/MISSING	
Deficiency Location/Instance	Kitchen	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Gas System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Grease Trap		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Hood		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hood Exhaust Ductwork		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hood Exhaust Fan		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hood Fire Suppression System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hot Water Temperature Booster		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Kitchen Sink		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
MDF Room	Inspected	
Instance on Original Building - Room 331	Inspected	
	nispecieu	
Dedicated A/C Equipment  Instance on Original Puilding Poom 221	Inspected	
Instance on Original Building - Room 331	Inspected 3- Fair	
Instance Condition		
Deficiency	DEFECTIVE	

**EACH** 

MAINTENANCE

Original Building - Room 331 (Dx Split System, 1 of 2)

Deficiency Location/Instance

Deficiency Quantity Quantity Uom

Potential Action

#### **Building Condition Assessment Survey 2023-2024**

IORITY 3 VEL 2 violations recorded es not exist pected pected pected  pected  Gair deficiencies recorded  Detween Fair and Poor FECTIVE/MISSING Dom 314A  CH
VEL 2 violations recorded es not exist pected pected pected  Fair deficiencies recorded  Between Fair and Poor FECTIVE/MISSING om 314A
VEL 2 violations recorded es not exist pected pected pected  Fair deficiencies recorded  Between Fair and Poor FECTIVE/MISSING om 314A
violations recorded es not exist pected pected  pected  fair deficiencies recorded  Between Fair and Poor FECTIVE/MISSING om 314A
pected pected  pected  pected  Fair  deficiencies recorded  pected  Between Fair and Poor  FECTIVE/MISSING  om 314A
pected  pected  pected  Fair  deficiencies recorded  pected  Between Fair and Poor  FECTIVE/MISSING  om 314A
pected Fair deficiencies recorded  pected  Between Fair and Poor FECTIVE/MISSING om 314A
pected Fair  deficiencies recorded  pected  Between Fair and Poor  FECTIVE/MISSING  om 314A
pected Fair  deficiencies recorded  pected  Between Fair and Poor  FECTIVE/MISSING  om 314A
Pair deficiencies recorded  pected Between Fair and Poor FECTIVE/MISSING om 314A
Pair deficiencies recorded  pected Between Fair and Poor FECTIVE/MISSING om 314A
pected Between Fair and Poor FECTIVE/MISSING om 314A
pected Between Fair and Poor FECTIVE/MISSING om 314A
Between Fair and Poor FECTIVE/MISSING om 314A
Between Fair and Poor FECTIVE/MISSING om 314A
Between Fair and Poor FECTIVE/MISSING om 314A
om 314A
CH
СП
CII
AINTENANCE
IORITY 5
VEL 6
violations recorded
es not exist
pected
Between Fair and Poor
FECTIVE
om 314A
СН
AINTENANCE
IORITY 5
VEL 6
violations recorded
es not exist
es not exist
es not exist

Inspected 3- Fair

Does not exist

Inspected

Inspected

Inspected 3- Fair

Yes

No deficiencies recorded

Instance on Room 314A

Instance on Room 314A

Instance on Room 314

Alternative Use

Instance Condition

Acid Waste Neutralizing Tank
Instance on Room 314

Instance Condition
Deficiency

Make-up Air Unit

SCIENCE PREP ROOM

Mechanical Inspection	X080
Question	Response

Question	Response
SCIENCE PREP ROOM	-
Acid Waste Neutralizing Tank	
Deficiency	No deficiencies recorded
CO Detector	
Instance on Room 314	Not required
Emergency Shower	1
Instance on Room 314	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Eye Wash	The deficiences recorded
Instance on Room 314	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
	No deficiencies recorded
Hood Exhaust Ductwork	Turnis de d
Instance on Room 314	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Hood Exhaust Fan	
Instance on Room 314	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Fixed Laboratory Hood	
Instance on Room 314	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Laboratory Sink	
Instance on Room 314	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Make-up Air Unit	
Instance on Room 314	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected
	Does not exist
Dry Sprinkler Alarm Valve Assembly  Wet Sprinkler Alarm Valve Assembly	Does not exist
Wet Sprinkler Alarm Valve Assembly Fire Booster Pump Assembly	Does not exist
Roof Tank	Does not exist
Siamese Connection	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
	Inspected
Sprinkler Head Condition	3- Fair
Deficiency Leastien/Instance	DEFECTIVE/DETERIORATED  Programment
Deficiency Location/Instance	Basement - Paint Storage Room, Fire Extinguishers Storage Room; Room 202 (painted, 10)
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
	Inspected
Sprinkler Piping Condition	2- Between Good and Fair
	No deficiencies recorded
Deficiency	no deficiencies recorded

# **Building Condition Assessment Survey 2023-2024**

Mechanical Inspection X080

unicul Inspection		11000
uestion	Response	
SPRINKLERS, STANDPIPE, FIRE SYSTEM		
Standpipe System	Inspected	
Hose Valve Assembly	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Piping	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Water Gong	Does not exist	
SWIMMING POOL	Does not exist	
VENTILATION	Inspected	
Is the building Mechanically ventilated?	Yes	
Exhaust Fan	Inspected	
Condition	2- Between Good and Fair	
Approximate Total # of Fans	1-25	
Deficiency	No deficiencies recorded	
Heating And Ventilating Unit	Does not exist	
Metal Ductwork	Inspected	
Condition	3- Fair	
Are there any uninsulated ductwork by design in Mechanical rooms?	Yes	
Are there chain operated dampers?	No	
Deficiency	DEFECTIVE REGISTER/DIFFUSER	
Deficiency Location/Instance	Boy's Toilet Room 512A	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Supply Fan	Inspected	
Condition	3- Fair	
Approximate Total # of Fans	1-5	
Deficiency	No deficiencies recorded	
Unit Ventilator	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	