Building Condition Assessment Survey 2023-2024

Electrical Inspection X085

Asse	et:	P.S. 85 - BRONX, 2400 MARION AVENUE, BRONX, NY, 10458					
Insp	ection Id	Inspection Type	Time In	Last Edited			
	2239	ELECTRICAL	2024-01-08 08:28AM	2024-01-30 10:56AM			

4sset	Data
0	uestion

Have any Systems/Major Building Components been upgraded?

Answer Systems: Partial LED Lighting in the Corridors and some

Classrooms 1st Floor and Level B

2023 Years:

Systems: Fire Alarm System (Printer)

Years: 2022

Systems: Partial Molded Case Circuit Breaker Panel Board

2021, 2010, 2001, 1998 Years: Security Lights, LAN Systems:

2021 Years:

Systems: LED Lighting (Cafeteria, Multipurpose Room,

Kitchen), Auditorium (Local Sound System, Projection

System)

2019 Years:

Systems: Exit Lights (Battery Packs)

Years: 2018

Systems: Exit/Emergency Lights

Years:

Gymnasium LED Lighting, Telephone System Systems: Years:

Systems: Fire Alarm System Except Tamper Switch/Chain and

Printer 2011 Years:

Systems: Most Motor Starters, Partial Fused Disconnect Type

Panel Boards

Years: 2010 Library Systems:

Years:

Public Address System, Local Sound System Except Systems:

Auditorium, Emergency Lights/Exit Lights Panel,

Partial Service Switch

1998 Years:

Systems: Interior Fluorescent and Incandescent Lighting

Years: Below Ground

Yes

No

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Does Interactive Whiteboard (IWB) Exist?

Water Penetration In Electrical Room?

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in	No
your building?	

Priority Condition

Type of Service

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
Yes	Fire Alarm System - Components Not Operational	Fire Alarm Air Pressure Switch is out of Order.	Fire Alarm System - Sprinkler Flow/Air Pressure Switch	Cellar - Boiler Room	Rayniel Rosado	Fireman	No Photo Taken
Yes	Intercom - Not Operational	Intercom stations are out of order.	Intercom System - Holding/Fire Rescue Area	Rooms: 119, 219, 319, 419 and Main Office	Rayniel Rosado	Fireman	No Photo Taken

Building Condition Assessment Survey 2023-2024

Electric	al Inspection						X085
Yes	Exposed Electrical Wires	Outlet in the Kitchen completely destroyed and electrical wires are exposed from the box.	Electrical Outlet	Kitchen	Rayniel Rosado	Fireman	
Yes	Emergency Lighting - Not Operational	Emergency Light Fixtures are out of order.	Emergency Lighting	Throughout the Building	Rayniel Rosado	Fireman	No Photo Taken
No	Grounding System - Defective	Grounding System Completely Detached by Contractors from the Water Main Pipe.	Grounding System	Cellar - Boiler Room	Rayniel Rosado	Fireman	

pection	
Question	Response
Electrical	
ATHLETIC FIELD	Does not exist
AUDITORIUM	Inspected
Instance on 1st Floor	Inspected
House Lighting	
Instance on 1st Floor	Inspected
Does a Chandelier Exist?	Yes
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	56
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected

Building Condition Assessment Survey 2023-2024

Electrical InspectionX085QuestionResponse

Question	Response
AUDITORIUM	
Local Sound System	
Instance Condition	2- Between Good and Fair
Installation Year	2019
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Is the projector on a cart or installed on the ceiling?	Ceiling
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Does not exist
Theater Lighting	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	29
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
CAFETERIA	Inspected
Instance on Basement	Inspected
Lighting	
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Does not exist
Lighting Fixture - HID	
Instance on Basement	Does not exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not exist
Lighting Fixture - LED	
Instance on Basement	Inspected
Pendant Mounted	
Instance on Basement	Does not exist
Surface Mounted	
Instance on Basement	Does not exist
Recessed Mounted	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Local Sound System	1 to deficiences recorded
Instance on Basement	Inspected
Instance Condition	3- Fair
Installation Year	1998
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Cafeteria-Basement
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE

Building Condition Assessment Survey 2023-2024

estion	Response	
AFETERIA		
Local Sound System		
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Projection System		
Instance on Basement	Does not exist	
Theater Lighting System		
Instance on Basement	Does not exist	
LASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	3- Fair	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Deficiency Quantity	578	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Surface Mounted	Inspected	
Condition	3- Fair	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Deficiency Quantity	94	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Recessed Mounted	Inspected	
Condition	3- Fair	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Deficiency Quantity	24	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Inspected	
Pendant Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Does not exist	
Recessed Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - LED	Inspected	
	Inspected	
Pendant Mounted Condition	1- Good	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected 1- Good	

Building Condition Assessment Survey 2023-2024

Response
No deficiencies recorded
Does not exist
Inspected
Inspected
Yes
Inspected
Inspected
Inspected
3- Fair
LIGHTING FIXTURE BEYOND USEFUL LIFE
12
EACH
REPLACE-UPGRADE
PRIORITY 1
LEVEL 2
No violations recorded
Does not exist

Building Condition Assessment Survey 2023-2024

Electrical Inspection	X085
Question	Response

rieui Inspection		11005
Question	Response	
GYMNASIUM		
Lighting		
Lighting Fixture - LED		
Surface Mounted		
Instance on 3rd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 3rd Floor	Does not exist	
Local Sound System		
Instance on 3rd Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	1998	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Gymnasium-3rd Floor	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Projection System		
Instance on 3rd Floor	Does not exist	
Scoreboard		
Instance on 3rd Floor	Does not exist	
Theater Lighting System		
Instance on 3rd Floor	Does not exist	
KITCHEN	Inspected	
Instance on Basement	Inspected	
Lighting		
Instance on Basement	Inspected	
Lighting Fixture - Fluorescent		
Instance on Basement	Does not exist	
Lighting Fixture - HID		
Instance on Basement	Does not exist	
Lighting Fixture - Incandescent		
Instance on Basement	Does not exist	
Lighting Fixture - LED		
Instance on Basement	Inspected	
Pendant Mounted		
Instance on Basement	Does not exist	
Surface Mounted		
Instance on Basement	Does not exist	
Recessed Mounted		
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
LIBRARY	Inspected	
Instance on Room 118	Inspected	
Lighting	<u>F</u>	
Instance on Room 118	Inspected	
Lighting Fixture - Fluorescent	1	
Instance on Room 118	Inspected	
mounted on recom 110		

Building Condition Assessment Survey 2023-2024

rical Inspection		X08
euestion	Response	
LIBRARY		
Lighting		
Lighting Fixture - Fluorescent		
Pendant Mounted		
Instance on Room 118	Does not exist	
Surface Mounted		
Instance on Room 118	Does not exist	
Recessed Mounted		
Instance on Room 118	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on Room 118	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 118	Does not exist	
Lighting Fixture - LED		
Instance on Room 118	Inspected	
Pendant Mounted	•	
Instance on Room 118	Does not exist	
Surface Mounted		
Instance on Room 118	Does not exist	
Recessed Mounted		
Instance on Room 118	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Raceway With Receptacles		
Instance on Room 118	Does not exist	
Projection System		
Instance on Room 118	Does not exist	
LOCKER ROOM	Does not exist	
MULTIPURPOSE ROOM	Inspected	
Instance on Basement - North	Inspected	
	nispected	
Lighting Instance on Basement - North	Inspected	
	nispected	
Lighting Fixture - Fluorescent Instance on Basement - North	Does not exist	
Lighting Fixture - HID	Does not exist	
Instance on Basement - North	Does not exist	
	Does not exist	
Lighting Fixture - Incandescent	Description in the second	
Instance on Basement - North	Does not exist	
Lighting Fixture - LED	Lucrostad	
Instance on Basement - North	Inspected	
Pendant Mounted	D	
Instance on Basement - North	Does not exist	
Surface Mounted		
Instance on Basement - North	Does not exist	
Recessed Mounted	T 1	
Instance on Basement - North	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Local Sound System		
Instance on Basement - North	Inspected	
Instance Condition	3- Fair	
Installation Year	1998	

Building Condition Assessment Survey 2023-2024

Question	Response
MULTIPURPOSE ROOM	
Local Sound System	
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Multipurpose Room-Basement - North
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Projection System	
Instance on Basement - North	Does not exist
Theater Lighting System	
Instance on Basement - North	Does not exist
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Does not exist
SCIENCE PREP ROOM	Does not exist
SWIMMING POOL	Does not exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	30
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2

Building Condition Assessment Survey 2023-2024

rical Inspection	X08:
Question	Response
TOILET ROOM - STUDENT	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Violations	No violations recorded
Surface Mounted	Does not exist
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	5- Poor
Deficiency	BELL TRANSFORMER PANEL NOT OPERATIONAL
Deficiency Location/Instance Deficiency Quantity	Electrical Room
Quantity Uom	EACH
Potential Action	REPLACE PANEL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	4- Between Fair and Poor
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	27
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Non Battery Pack	Does not exist
EXIT/EMERGENCY LIGHT	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
FIRE ALARM SYSTEM	Inspected
Bell/Horn	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Deficiency	no deficiencies recorded

Building Condition Assessment Survey 2023-2024

cui Inspection		2100
estion	Response	
TRE ALARM SYSTEM		
Manual Pull Station	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
CO Detector	Does not exist	
Heat Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Elevator Recall	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Magnetic Door Holder/Contactor	Does not exist	
Fused Cutout Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Inspected	
Bell At Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	General Electric	
Model	EST 2	
EquipmentId	Fire Alarm Control Panel	
Installation Year	2011	
Source of Installation Year	Custodial Staff	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel	Does not exist	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
	Does not exist	
Punch Register		
Sprinkler Flow/Air Pressure Switch Condition	Inspected 4- Between Fair and Poor	

Building Condition Assessment Survey 2023-2024

iricui Inspection	AUUS
Question	Response
FIRE ALARM SYSTEM	
Sprinkler Flow/Air Pressure Switch	
Deficiency Location/Instance	Cellar - Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Tamper Flow Switch/Chain	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	5- Poor
Deficiency	DETACHED GROUND CONDUCTOR
Deficiency Location/Instance	Cellar - Boiler Room
Deficiency Quantity	
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
INTERCOM SYSTEM	Inspected
Elevator	Inspected 3- Fair
Condition	
Deficiency	No deficiencies recorded
Holding Area	Inspected
Condition	5- Poor
Deficiency	INTERCOM CABINET NOT OPERATIONAL
Deficiency Location/Instance	Rooms: 119, 219, 319, 419 and Main Office
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not exist
MOTOR CONTROLLER	Inspected
	Does not exist
MOTOR CONTROL CENTER	Inspected
MOTOR STARTER/CONTACTOR Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Cellar - Boiler and Fan Rooms

Building Condition Assessment Survey 2023-2024

ricui Inspection		11003
Question	Response	
PANEL BOARD		
Fused Disconnect Switch Type		
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Fused Knife Switch Type	Does not exist	
Fused Toggle Switch Type	Inspected	
Condition	3- Fair	
Deficiency	PANEL BOARD BEYOND USEFUL LIFE	
Deficiency Location/Instance	Cellar - Electrical Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Molded Case Circuit Breaker Type	Inspected	
Condition	3- Fair	
Deficiency	PANEL BOARD BEYOND USEFUL LIFE	
Deficiency Location/Instance	Throughout the Building	
Deficiency Quantity	17	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations		
	No violations recorded	
PUBLIC ADDRESS SYSTEM	Inspected	
Instance	Room 226	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Rauland TC2100	
Installation Year	1998	
Source of Installation Year	Custodial Staff	
Deficiency	CLOCK NOT OPERATIONAL	
Deficiency Location/Instance	Throughout the Building	
Deficiency Quantity	16	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
SECURITY	Inspected	
IPDVS/CCTV System	Does not exist	
Intrusion Alarm System	Inspected	
Central Control Panel	Inspected	
Instance	Electrical Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	4140 XMPT2	
Installation Year	1993	
Source of Installation Year	Documented	

Building Condition Assessment Survey 2023-2024

Response
BEYOND USEFUL LIFE
Electrical Room
1
EACH
REPLACE
PRIORITY 1
LEVEL 3
No violations recorded
Inspected
3- Fair
No deficiencies recorded
Inspected
3- Fair
No deficiencies recorded
Inspected
3- Fair
No deficiencies recorded
Inspected
3- Fair
No deficiencies recorded
Inspected
2- Between Good and Fair
LIGHTING FIXTURE BALLAST DEFECTIVE
Perimeter of the Building
5
EACH
REPLACE BALLAST
PRIORITY 3
LEVEL 3
No violations recorded
Inspected
Electrical Room
3- Fair
1
EACH
Metropolitan
2000A M. SERV. SW. 1600A FU
1600
Amps
Fuse Size
1974
Documented
BEYOND USEFUL LIFE
Electrical Room
1
EACH
EACH REPLACE
PRIORITY 1
LEVEL 2
No violations recorded
Inspected
1

Building Condition Assessment Survey 2023-2024

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Metropolitan Electric
EquipmentId	N/A
Capacity/Size Quantity	1600
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	3
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Fuse Size
Installation Year	1974
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not exist