### **Building Condition Assessment Survey 2023-2024**

### **Electrical Inspection**

	ONX, 3530 KINGS COLI	LUL I LACE, DRUN			-	
Inspection Id Inspection Ty				Time		Last Edited
3524 ELECTRICAI				2024	-02-27 01:00PM	2024-05-14 02:29PM
sset Data						
Question			Answer			
Have any Systems/Major Build	ing Components been upgrad	ed?	Systems:		ight/Exit Light Pa	nel
			Years:	2022, 1993		
			Systems:		mergency Lights, I	Emergency Light
			Years:	(Battery Pack 2022	()	
			Systems:		Local Sound Syste	em, Partial Theater
			Systems		tem, Projection Sy	
			Years:	2020		,
			Systems:	Security Ligh	nting	
			Years:	2019		
			Systems:	Partial Molde	ed Case Circuit Bro	eaker Panel Board
			Years:	2017, 2011, 2		
			Systems:		•	l Control Panel, Partial
			Years:	Remote Annu 2017	inciator)	
			Systems:		tina	
			Years:	2014	ting	
			Systems:		ystem (Strobe for A	Annex)
			Years:	2010	ystelli (Subbe for 7	(linex)
			Systems:		rm System	
			Years:	1995	5	
Type of Service			Below G			
Does Interactive Whiteboard (I	WB) Exist?		Yes			
Water Penetration In Electrical	Room?		No			
DEDICATED INTERCOM	IS IN FIRE RESCUE AR	EAS				
Question				Response		
Are there any Life Rescue As your building?	ssistance Areas, Fire Rescue A	reas, and/or Holding Roon	ms in	No		
Priority Condition						
Exist Priority	Condition	Component	Location	Dorson(s)	<b>D</b> owgon(g)	Photo
Last Year? Category	Description	Component Affected	Description	Person(s) Notified	· · · ·	Image
No condition recorded						
Inspection						
Question			Response	e		
Electrical						
ATHLETIC FIELD			Does not	exist		
AUDITORIUM			Inspected	l		
Instance on 1st Fl	oor		Inspected	l		
House Lighting						
Instance on 1st Flo			Inspected	l		
Does a Chandelier			Yes			
Lighting Fixture - Fluor			T c c	1		
Instance on 1st Fl	oor		Inspected	L		
Pendant Mounted			Incored	1		
Instance on 1st Flo			Inspected	en Good and Fa		
Instance Condition	n					
Deficiency			No defici	encies recorded		
Surface Mounted						
T · · · · · · ·			<b>T</b>			
Instance on 1st Flu Instance Condition			Inspected	en Good and Fa		

BCAS Partners Version 2.0 (P)

## **Building Condition Assessment Survey 2023-2024**

estion	Response	
UDITORIUM		
House Lighting		
Lighting Fixture - Fluorescent		
Surface Mounted		
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent Instance on 1st Floor	Does not exist	
	Does not exist	
Lighting Fixture - LED	Descend suist	
Instance on 1st Floor	Does not exist	
Local Sound System	T ( 1	
Instance on 1st Floor		
Instance Condition	2- Between Good and Fair	
Installation Year Source of Installation Year	2020 Documented	
	No deficiencies recorded	
Deficiency	No deficiencies recorded	
Projection System	T ( 1	
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Is the projector on a cart or installed on the ceiling?	Ceiling	
Deficiency	No deficiencies recorded	
Theater Lighting System		
Instance on 1st Floor	Inspected	
Dimming System		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Theater Lighting		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Deficiency Quantity	22	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
AFETERIA	Inspected	
Instance on 1st Floor	Inspected	
Lighting	-	
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent	-	
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		

## **Building Condition Assessment Survey 2023-2024**

lestion	Response	
CAFETERIA	Response	
Lighting		
Lighting Fixture - Fluorescent		
Recessed Mounted		
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Does not exist	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	5- Poor	
Installation Year	1963	
Source of Installation Year	Documented	
Deficiency	AMPLIFIER NOT OPERATIONAL	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE SYSTEM	
Urgency of Action	PRIORITY 2	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Projection System		
Instance on 1st Floor	Does not exist	
Theater Lighting System		
Instance on 1st Floor	Does not exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier Exist?	Yes	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Does not exist	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - LED	Does not exist	
COMPUTER LAB	Inspected	
Instance on Room 309		
	Inspected	
Power Panel?	Yes	
Lighting		

## **Building Condition Assessment Survey 2023-2024**

### Electrical Inspection

rical Inspection		X094
Question	Response	
COMPUTER LAB		
Lighting		
Lighting Fixture - Fluorescent		
Instance on Room 309	Inspected	
Pendant Mounted		
Instance on Room 309	Inspected	
Instance Condition	2- Between Good and Fair	-
Deficiency	No deficiencies recorded	-
Surface Mounted		
Instance on Room 309	Does not exist	
Recessed Mounted		
Instance on Room 309	Does not exist	
Lighting Fixture - HID		
Instance on Room 309	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 309	Does not exist	
Lighting Fixture - LED		
Instance on Room 309	Does not exist	
Raceway With Receptacles	Does not exist	
Instance on Room 309	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
GYMNASIUM	Inspected	
Instance on 3rd Floor	Inspected	
Lighting	Tecnootod	
Instance on 3rd Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 3rd Floor	Does not exist	
Lighting Fixture - HID		
Instance on 3rd Floor	Does not exist	
Lighting Fixture - Incandescent		-
Instance on 3rd Floor	Does not exist	
Lighting Fixture - LED		
Instance on 3rd Floor	Inspected	
Pendant Mounted		
Instance on 3rd Floor	Does not exist	
Surface Mounted		
Instance on 3rd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 3rd Floor	Does not exist	
Local Sound System		
Instance on 3rd Floor	Inspected	
Instance Condition	5- Poor	
Installation Year	1963	
Source of Installation Year	Documented	
Deficiency	AMPLIFIER NOT OPERATIONAL	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE SYSTEM	
Urgency of Action	PRIORITY 2	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	

## **Building Condition Assessment Survey 2023-2024**

uestion	Response	
GYMNASIUM	ľ	
Projection System		
Instance on 3rd Floor	Does not exist	
Scoreboard		
Instance on 3rd Floor	Does not exist	
Theater Lighting System		
Instance on 3rd Floor	Does not exist	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
Lighting	*	
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted	1	
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
	DOES HOLEXIST	
Lighting Fixture - HID Instance on 1st Floor	Does not exist	
	Does not exist	
Lighting Fixture - Incandescent	Doog not griet	
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED	<b>D</b>	
Instance on 1st Floor	Does not exist	
LIBRARY	Inspected	
Instance on 2nd Floor	Inspected	
Lighting		
Instance on 2nd Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 2nd Floor	Inspected	
Pendant Mounted		
Instance on 2nd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on 2nd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 2nd Floor	Does not exist	
Lighting Fixture - HID		
Instance on 2nd Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 2nd Floor	Inspected	
Pendant Mounted		
Instance on 2nd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on 2nd Floor	Does not exist	
Recessed Mounted	DOUS HOUCKIST	

## **Building Condition Assessment Survey 2023-2024**

### Electrical Inspection

	A09
Response	
Inspected	
2- Between Good and Fair	
No deficiencies recorded	
Does not exist	
Inspected	
3- Fair	
No deficiencies recorded	
Does not exist	
Inspected	
Inspected	
Yes	
Inspected	
Inspected	
Does not exist	
Inspected	
2- Between Good and Fair	
No deficiencies recorded	
Does not exist	
Does not exist	
Does not exist	
Does not exist	
*	
-	
No deficiencies recorded	
No deficiencies recorded           Does not exist           Does not exist	
	Inspected 2- Between Good and Fair No deficiencies recorded Does not exist Inspected 3- Fair No deficiencies recorded Does not exist Inspected Inspected Yes Inspected Does not exist Does not exist

## **Building Condition Assessment Survey 2023-2024**

### Electrical Inspection

rical Inspection	Χι
uestion	Response
TOILET ROOM - STAFF	
Lighting	
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
	Does not exist
Recessed Mounted	Does not exist
Lighting Fixture - HID	
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
	Inspected
EMERGENCY LIGHTING	
Battery Pack Condition	Inspected 1- Good
	FIXTURE LAMP NOT OPERATIONAL
Deficiency	
Deficiency Location/Instance Deficiency Quantity	Gymnasium 2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance Deficiency Quantity	Gymnasium
Quantity Uom	1 EACH
Potential Action	EACH REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Non Battery Pack	Inspected 3- Fair
Condition	
Deficiency EXIT/EMERGENCY LIGHT	No deficiencies recorded Inspected

# NYC Department of Education Building Condition Assessment Survey 2023-2024

### Electrical Inspection

ricai Inspection		AUS
uestion	Response	
EXIT/EMERGENCY LIGHT		
Deficiency	No deficiencies recorded	
FIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Does not exist	
Duct Smoke Detector	Does not exist	
Area Smoke Detector	Does not exist	
CO Detector	Does not exist	
Heat Detector	Does not exist	
Elevator Recall	Does not exist	
Magnetic Door Holder/Contactor	Does not exist	
Fused Cutout Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Inspected	
Bell At Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Does not exist	
Fire Alarm Control Panel (Standard)	Inspected	
Instance	Basement	
Instance Condition	3- Fair	
Instance Quantity	1	
	EACH	
Instance Quantity Uom		
Manufacturer	Faraday	
EquipmentId	Fire Alarm Panel 1963	
Installation Year Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Basement	
Deficiency Quantity	69,000	
Quantity Uom	S.F.	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Sub-Panel	Does not exist	
Remote Annunciator	Does not exist	
Sprinkler Flow/Air Pressure Switch	Does not exist	
Tamper Flow Switch/Chain	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
GROUNDING SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
	Does not exist	
INTERCOM SYSTEM	Does not exist	

## **Building Condition Assessment Survey 2023-2024**

uestion	Response
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not exist
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	MOTOR STARTER NOT OPERATIONAL
Deficiency Location/Instance	Boiler Room (Sump Pump)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Variable Frequency Drive	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	
	No violations recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	9
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Computer Lab 309, 2nd Floor by Stair E
Deficiency Quantity	2

## **Building Condition Assessment Survey 2023-2024**

### **Electrical Inspection**

icui inspection		110
estion	Response	
PANEL BOARD		
Molded Case Circuit Breaker Type		
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 2	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
UBLIC ADDRESS SYSTEM	Inspected	
Instance	General Office - Room 225	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	N/A	
Installation Year	1963	
Source of Installation Year	Documented	
Deficiency	CLOCK NOT OPERATIONAL	
Deficiency Location/Instance	Classrooms and Corridors	
Deficiency Quantity	10	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	General Office - Room 225	
Deficiency Quantity	69,000	
Quantity Uom	S.F.	
Potential Action	REPLACE	
Urgency of Action Purpose of Action	PRIORITY 1 LEVEL 2	
Violations	No violations recorded	
	Inspected Does not exist	
IPDVS/CCTV System	Inspected	
Intrusion Alarm System Central Control Panel	Inspected	
Instance	Electrical Room	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Vista 128BPT	
Installation Year	2017	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Infrared Sensor	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
	Inspected	
Panic Switch		
Condition	3-Fair	
Deficiency	No deficiencies recorded	
Remote Annunciator	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Siren/Strobe	Inspected	
Condition	3- Fair	

## **Building Condition Assessment Survey 2023-2024**

uestion		Response	
SECURI	TV		
	ion Alarm System		
	/Strobe		
Sirei	Deficiency	No deficiencies recorded	
Lightin	ng - Security	Inspected	
Cond		2- Between Good and Fair	
Colla	Deficiency	No deficiencies recorded	
	•		
SERVIC	E SWITCH	Inspected	
	Instance	Electrical Meter Room	
	Instance Condition	3- Fair	
	Instance Quantity	1	
	Instance Quantity Uom	EACH	
	Manufacturer	Empire Switchboard	
	EquipmentId	1600A Service SW (1200A KPR Fused)	
	Capacity/Size Quantity	1200	
	Capacity/Size UOM	Amps	
	Source of Capacity/Size	Fuse Size	
	Installation Year	1963	
	Source of Installation Year	Documented	
	Deficiency	BEYOND USEFUL LIFE	
	Deficiency Location/Instance	Electrical Meter Room	
	Deficiency Quantity	1	
	Quantity Uom	EACH	
	Potential Action	REPLACE	
	Urgency of Action	PRIORITY 1	
	Purpose of Action	LEVEL 2	
	Violations	No violations recorded	
	Instance	Electrical Meter Room	
	Instance Condition	3- Fair	
	Instance Quantity	1	
	Instance Quantity Uom	EACH	
	Manufacturer	General Electric	
	EquipmentId	Main Mini School Service Switch	
	Capacity/Size Quantity	600	
	Capacity/Size UOM	Amps	
	Source of Capacity/Size	Nameplate	
	Installation Year	2004	
	Source of Installation Year	Inspector Estimate	
	Deficiency	No deficiencies recorded	
WITCH	HBOARD	Inspected	
	er of Spares	0	
	Disconnect Switch Type	Inspected	
I useu	Instance	Electrical Room	
	Instance Condition	3- Fair	
	Instance Quantity	1	
		EACH	
	Instance Quantity Uom		
	Manufacturer	Empire Switchboard	
	EquipmentId Capacity/Size Quantity	Main Distribution Panel 1200	
	Capacity/Size UOM	Amps Total	
	Capacity/Size 2 Quantity	Amps Total 2	
	Capacity/Size 2 UOM	Z Section(s)	
	Source of Capacity/Size	Service Switch Fuse Size	
	Installation Year	1963	
	Source of Installation Year	Documented	
	Deficiency	BEYOND USEFUL LIFE	

## **Building Condition Assessment Survey 2023-2024**

### **Electrical Inspection**

uestion	Response	
SWITCHBOARD		
Fused Disconnect Switch Type		
Deficiency Location/Instance	Electrical Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Fused Knife Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Does not exist	
FELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
<b>FDANSEODMED</b>	Does not exist	

TRANSFORMER

Does not exist