Building Condition Assessment Survey 2023-2024

	nspection	Z 2021 HH I MAN AVEN	THE PRONV NV	10463			X0
Asset: Inspection		X, 3961 HILLMAN AVE	NUE, BRONA, NY	, 10403	Time 1	ĺn	Last Edited
	Id Inspection Type 533 ELECTRICAL					02-27 09:16AN	
	333 ELECTRICAL				2024-	02-27 09.10AF	VI 2024-03-22 02.30FIVI
Question				A == ======			
		2 4 1 1 10		Answer	Dublic Address	s System (Cloc	lza)
Have any S	Systems/Major Building (Components been upgraded?		Systems:		s system (Cloc	KS)
				Years:	2024	Admona Crystam	(Amulifica)
				Systems:	LAN, Public A	Address System	(Ampimer)
				Years:	2022	ED I infetio	
				Systems:	Exit Lights, Ll	ED Lignting	
				Years:	2020	un Strataun (Imfu	anad Canaan)
				Systems:		m System (Infra	ared Sensor)
				Years:	2019	. C::4-1-11	M-14-4 C Circuit
				Systems:			Molded Case Circuit lotor Starters, Security
				Years:	2011, 2007		
				Systems:	Pendant Fluor	escent Lighting	, Surface Fluorescent
					Lighting		
				Years:	2011, 2003		
				Systems:	Signal/Bell Sy System, IPDV System, Emery Telephone Sys Panel Board, I	rstem, Fire Alar (S/CCTV System gency Generator (stem, Fused Dis (Recessed Fluore	Room 2002, Auxiliary m System, Public Address m, Intrusion Alarm or Set, Intercom System, econnect Switch Type escent Lighting, Science fariable Frequency Drives
				Years:	2011	1 ,	1 3
				Systems:	(Local Sound Grounding Sys	System), Incan	ighting), Gymnasiums descent Lighting, Partial
				Years:	2007		
				Systems:	HID Lighting		
				Years:	2003		
Type of Se				Below Gro	ound		
	active Whiteboard (IWB)			Yes			
	etration In Electrical Room		C	No			
Question	I ED INTERCOMS II	N FIRE RESCUE AREA		D	Response		
	e any Life Rescue Assista	nce Areas, Fire Rescue Areas	s. and/or Holding Root		es es		
your buil			, and of Heranig Heer				
		ole in all of these spaces for u	se during a fire?	Υ	les .		
Are a	ll dedicated intercoms op	perational?		Y	/es		
iority Con	dition						
xist ast Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
l'es .	Emergency Lighting - Not Operational	N/A	Emergency Lighting	Throughout the Building	Sean O'Donogh ue	Fireman	No Photo Taken
	Fire Alarm System - Defective	System in Trouble	Fire Alarm System	Main Entrance Lobby	Sean O'Donogh ue	Fireman	No Photo Taken
nspection					uc		
Question				Response			
Electrical							
				D (iat		
АТПІ Б	TIC FIELD			Does not e	XISL		

Electrical Inspection	A095

estion	Response
UDITORIUM	
Instance on 1st Floor	Inspected
House Lighting	
Instance on 1st Floor	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Inspected
Pendant Mounted	•
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	Does not const.
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	Does not exist
Instance on 1st Floor	Does not exist
Local Sound System	DOCS HOL CAISE
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Installation Year	2007
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Does not exist
Theater Lighting System	
Instance on 1st Floor	Inspected
Dimming System	•
Instance on 1st Floor	Inspected
Instance Condition	4- Between Fair and Poor
Deficiency	DIMMING RACK/LIGHT CONSOLE NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Theater Lighting	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
AFETERIA	Inspected

Building Condition Assessment Survey 2023-2024

uestion	Response	
CAFETERIA		
Instance on Basement - North	Inspected	
Instance on Basement - South	Inspected	
Lighting	1	
Instance on Basement - North	Inspected	
Instance on Basement - South	Inspected	
Lighting Fixture - Fluorescent	1	
Instance on Basement - North	Inspected	
Instance on Basement - South	Inspected	
Pendant Mounted		
Instance on Basement - North	Does not exist	
Instance on Basement - South	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	TVO deficiences recorded	
Instance on Basement - North	Does not exist	
Instance on Basement - North	Does not exist Does not exist	
-	Does not exist	
Recessed Mounted	Turnested	
Instance on Basement - North	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Basement - South	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on Basement - North	Does not exist	
Instance on Basement - South	Does not exist	
Lighting Fixture - Incandescent		
Instance on Basement - North	Does not exist	
Instance on Basement - South	Does not exist	
Lighting Fixture - LED		
Instance on Basement - North	Does not exist	
Instance on Basement - South	Does not exist	
Local Sound System		
Instance on Basement - North	Inspected	
Instance Condition	3- Fair	
Installation Year	2011	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance on Basement - South	Inspected	
Instance Condition	3- Fair	
Installation Year	2011	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Basement - North	Does not exist	
Instance on Basement - South	Does not exist	
Theater Lighting System		
Instance on Basement - North	Does not exist	
Instance on Basement - South	Does not exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier Exist?	No	

Building Condition Assessment Survey 2023-2024

uestion	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
	3- Fair
Condition	
Deficiency Deficiency Quantity	LIGHTING FIXTURE BALLAST DEFECTIVE
	15
Quantity Uom Potential Action	EACH
	REPLACE BALLAST
Urgency of Action	PRIORITY 3 LEVEL 2
Purpose of Action	
Violations	No violations recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Does not exist
Recessed Mounted	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
COMPUTER LAB	Inspected
Instance on Room 320	Inspected
Power Panel?	*
	Yes
Lighting Instance on Room 320	Lucusotad
	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 320	Inspected
Pendant Mounted	
Instance on Room 320	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 320	Does not exist
Recessed Mounted	
Instance on Room 320	Does not exist
Lighting Fixture - HID	
Instance on Room 320	Does not exist

Electrical Inspection	X095

Question	Response	
COMPUTER LAB		
Lighting		
Lighting Fixture - Incandescent		
Instance on Room 320	Does not exist	
Lighting Fixture - LED		
Instance on Room 320	Does not exist	
Raceway With Receptacles		
Instance on Room 320	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
GYMNASIUM	Inspected	
Instance on 3rd Floor	Inspected	
Instance on 4th Floor	Inspected	
Lighting		
Instance on 3rd Floor	Inspected	
Instance on 4th Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 3rd Floor	Inspected	
Instance on 4th Floor	Inspected	
Pendant Mounted		
Instance on 3rd Floor	Does not exist	
Instance on 4th Floor	Does not exist	
Surface Mounted		
Instance on 3rd Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on 4th Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 3rd Floor	Does not exist	
Instance on 4th Floor	Does not exist	
Lighting Fixture - HID		
Instance on 3rd Floor	Does not exist	
Instance on 4th Floor	Inspected	
Pendant Mounted	1	
Instance on 4th Floor	Does not exist	
Surface Mounted		
Instance on 4th Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 4th Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 3rd Floor	Does not exist	
Instance on 4th Floor	Does not exist	
Lighting Fixture - LED	2000 100 01110	
Instance on 3rd Floor	Does not exist	
Instance on 4th Floor	Does not exist	
Local Sound System	Does not only	
Instance on 3rd Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	2007	
Source of Installation Year	Documented	

Electrical Inspection	on .	
Question	Resnanse	

Question	Response	
GYMNASIUM	•	
Local Sound System		
Deficiency	No deficiencies recorded	
Instance on 4th Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	2007	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 3rd Floor	Does not exist	
Instance on 4th Floor	Does not exist	
Scoreboard		
Instance on 3rd Floor	Does not exist	
Instance on 4th Floor	Does not exist	
Theater Lighting System		
Instance on 3rd Floor	Does not exist	
Instance on 4th Floor	Does not exist	
KITCHEN	Inspected	
Instance on Basement	Inspected	
Lighting	inspected	
Instance on Basement	Inspected	
Lighting Fixture - Fluorescent	nispected	
Instance on Basement	Inspected	
Pendant Mounted	nispected	
Instance on Basement	Does not exist	
Surface Mounted	Does not exist	
Instance on Basement	Does not exist	
Recessed Mounted	Does not exist	
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
	No deficielles recorded	
Lighting Fixture - HID Instance on Basement	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
	Does not exist	
Instance on Basement	Does not exist	
Lighting Fixture - LED	Dana and ania	
Instance on Basement	Does not exist	
LIBRARY	Inspected	
Instance on Room 2002	Inspected	
Instance on Room 308	Inspected	
Lighting		
Instance on Room 2002	Inspected	
Instance on Room 308	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 2002	Inspected	
Instance on Room 308	Inspected	
Pendant Mounted		
Instance on Room 2002	Does not exist	
Instance on Room 308	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 2002	Does not exist	·
Instance on Room 308	Does not exist	

Electrical Inspection	A095

2		
Question	Response	
LIBRARY		
Lighting		
Lighting Fixture - Fluorescent		
Recessed Mounted		
Instance on Room 2002	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 308	Does not exist	
Lighting Fixture - HID		
Instance on Room 2002	Does not exist	
Instance on Room 308	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 2002	Does not exist	
Instance on Room 308	Does not exist	
Lighting Fixture - LED		
Instance on Room 2002	Does not exist	
Instance on Room 308	Does not exist	
Raceway With Receptacles		
Instance on Room 2002	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 308	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Room 2002	Does not exist	
Instance on Room 308	Does not exist	
LOCKER ROOM	Does not exist	
MULTIPURPOSE ROOM	Does not exist	
	Does not exist	
SCIENCE DEMO ROOM		
SCIENCE LAB	Inspected	
Instance on Room 3018	Inspected	
Power Panel?	Yes	
Alternative Use	Yes	
Instance on Rooms 4012, 4020	Inspected	
Power Panel?	Yes	
Alternative Use	No	
Lighting		
Instance on Room 3018	Inspected	
Instance on Rooms 4012, 4020	Inspected	
Lighting Fixture - Fluorescent		
Instance on Rooms 4012, 4020	Inspected	
Instance on Room 3018	Inspected	
Pendant Mounted		
Instance on Rooms 4012, 4020	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 3018	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Rooms 4012, 4020	Does not exist	
Instance on Room 3018	Inspected	

Building Condition Assessment Survey 2023-2024

Question	Response	
	кезропяс	
SCIENCE LAB		
Lighting Lighting Fixture - Fluorescent		
Surface Mounted		
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
<u> </u>	No deficiencies recorded	
Recessed Mounted	D	
Instance on Rooms 4012, 4020	Does not exist	
Instance on Room 3018	Does not exist	
Lighting Fixture - HID		
Instance on Rooms 4012, 4020	Does not exist	
Instance on Room 3018	Does not exist	
Lighting Fixture - Incandescent		
Instance on Rooms 4012, 4020	Inspected	
Instance on Room 3018	Does not exist	
Pendant Mounted		
Instance on Rooms 4012, 4020	Does not exist	
Surface Mounted		
Instance on Rooms 4012, 4020	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Rooms 4012, 4020	Does not exist	
Lighting Fixture - LED		
Instance on Rooms 4012, 4020	Does not exist	
Instance on Room 3018	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Room 3018	Does not exist	
Instance on Rooms 4012, 4020	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power		
Instance on Room 3018	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 4012, 4020	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Power Supply	tvo deficiencies recorded	
Instance on Room 3018	Does not exist	
Instance on Rooms 4012, 4020	Does not exist Does not exist	
	DOES HOLCAIST	
Projection System Instance on Room 3018	Does not exist	
Instance on Room 3018 Instance on Rooms 4012, 4020	Does not exist Does not exist	
SCIENCE PREP ROOM	Inspected	
Instance on Room 3012	Inspected	
Power Panel?	No	
Alternative Use	Yes	
Instance on Room 4018	Inspected	
Power Panel?	No	
Alternative Use	No	

Inspected

Lighting

Instance on Room 3012

Building Condition Assessment Survey 2023-2024

X095

Electrical Inspection

Instance on Room 4018

Instance on Room 3012

Instance on Room 4018

Instance on Room 3012

Instance Condition

Deficiency

Emergency Shut-Off Power

Surface Mounted

Condition
Deficiency

Emergency Gas Shut-Off Valve
Instance on Room 3012

tem impresses		110.
uestion	Response	
SCIENCE PREP ROOM		
Lighting		
Instance on Room 4018	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 4018	Inspected	
Instance on Room 3012	Inspected	
Pendant Mounted		
Instance on Room 4018	Does not exist	
Instance on Room 3012	Does not exist	
Surface Mounted		
Instance on Room 4018	Does not exist	
Instance on Room 3012	Does not exist	
Recessed Mounted		
Instance on Room 4018	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 3012	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on Room 4018	Does not exist	
Instance on Room 3012	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 4018	Does not exist	
Instance on Room 3012	Does not exist	
Lighting Fixture - LED		

Does not exist

Does not exist

Does not exist

No deficiencies recorded

Inspected

Inspected

Inspected

No deficiencies recorded

3- Fair

3- Fair

Building Condition Assessment Survey 2023-2024

4		
Question	Response	
TOILET ROOM - STAFF		
Lighting		
Lighting Fixture - Fluorescent		
Recessed Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected 3- Fair	
Condition		
Deficiency	No deficiencies recorded	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	
EMERGENCY GENERATOR SET	Inspected	
Automatic Transfer Switch (ATS)	Inspected	
Instance	Basement - ATS Room	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	ASCO	
EquipmentId	ATS-1 EMDB	
Capacity/Size Quantity	800	
Capacity/Size UOM	Amps	
Source of Capacity/Size Installation Year	Nameplate 2011	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Basement - ATS Room	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
	EACH	
Instance Quantity Uom	ASCO	
Manufacturer	ASCO Fire Alarm Automatic Transfer Switch	
EquipmentId Capacity/Size Quantity	Fire Alarm Automatic Transfer Switch	
Capacity/Size Quantity Capacity/Size UOM	Amps	
Source of Capacity/Size	Amps Nameplate	
Installation Year	2011	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	

Building Condition Assessment Survey 2023-2024

Inspected Basement - Generator Room 2- Between Good and Fair	
Basement - Generator Room 2- Between Good and Fair	
2- Between Good and Fair	
1	
EACH	
SENS	
Battery Charger	
10	
AmpsDC	
24	
VDC	
Nameplate	
Inspected	
4	
Inspected	
Basement - ATS Room	
2- Between Good and Fair	
1	
EACH	
Electrotech	
1	
2011	
Documented	
No deficiencies recorded	
Does not exist	
-	
•	
•	
*	
Does not exist	
Inspected	
Inspected	
	10 AmpsDC 24 VDC Nameplate 2011 Documented No deficiencies recorded Inspected 4 Inspected Basement - ATS Room 2- Between Good and Fair 1 EACH Electrotech EMDB 800 Amps Total 1 Section(s) Inspector Estimate 2011 Documented No deficiencies recorded Does not exist Inspected Basement - Generator Room 2- Between Good and Fair 1 EACH Caterpillar Emergency Generator 313 kVA 250 kW 869 Amps Nameplate 2011 Documented No deficiencies recorded

Building Condition Assessment Survey 2023-2024

		71075
Question	Response	
EMERGENCY LIGHTING		
Battery Pack		
Deficiency	FIXTURE NOT OPERATIONAL	
Deficiency Location/Instance	Throughout the Building	
Deficiency Quantity	40	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Non Battery Pack	Inspected	
Condition	4- Between Fair and Poor	
Deficiency	FIXTURE LAMP NOT OPERATIONAL	
Deficiency Location/Instance	3rd Floor Gymnasium	
Deficiency Quantity	12	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
EXIT LIGHT	Inspected	
Battery Pack	Inspected	
Condition	1- Good	
Deficiency	FIXTURE NOT OPERATIONAL	
Deficiency Location/Instance	Corridor near Room B003	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPAIR	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Non Battery Pack	Does not exist	
EXIT/EMERGENCY LIGHT	Does not exist	
FIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	2- Between Good and Fair	
	No deficiencies recorded	
Deficiency		
Fan Shutdown Control	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
CO Detector	Does not exist	
Heat Detector	Inspected	
Condition	2- Between Good and Fair	

Building Condition Assessment Survey 2023-2024

•		
estion	Response	
TIRE ALARM SYSTEM		
Heat Detector		
Deficiency	No deficiencies recorded	
Elevator Recall	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Magnetic Door Holder/Contactor	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fused Cutout Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Inspected	
Instance	Boiler Room	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Ademco	
EquipmentId	DACT	
Installation Year	2011	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Main Panel	Inspected	
Bell At Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Edwards System Technology	
Model	EST 2	
EquipmentId	Fire Alarm Control Panel	
Installation Year	2011	
Source of Installation Year	Documented	
Deficiency	SYSTEM DEFECTIVE	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPAIR SYSTEM	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel	Does not exist	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	5- Poor	
Deficiency	PRINTER NOT OPERATIONAL	
Deficiency Location/Instance	Custodian's Office - Room 163	
Deficiency Quantity	1	

Electrical Inspection	X	X095	
0 "	n.		

Question	Response
FIRE ALARM SYSTEM	
Remote Annunciator	
Printer	
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Punch Register	Does not exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Inspected
Elevator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Holding Area	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	General Office - Room 252
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantry	1

Building Condition Assessment Survey 2023-2024

AU
Response
EACH
Plena Mixer Amplifier
2011
Documented
No deficiencies recorded
Inspected
Inspected
3- Fair
2011
Documented
No deficiencies recorded
Inspected
Inspected
Custodian's Office - Room 163
3- Fair
1
EACH
Vista 128BPT
2011
Documented
No deficiencies recorded
Inspected
3- Fair
SENSOR NOT OPERATIONAL
Main Entrance Lobby 1
EACH
REPLACE
PRIORITY 4
LEVEL 3
No violations recorded
Inspected
3- Fair
No deficiencies recorded
Inspected
3- Fair
No deficiencies recorded
Inspected
3- Fair
No deficiencies recorded
Inspected
2- Between Good and Fair
LIGHTING FIXTURE BALLAST DEFECTIVE
Building Perimeters
6
EACH
REPLACE BALLAST
PRIORITY 3
LEVEL 3
No violations recorded
Inspected

Electrical Inspection	X095

Question		Response
SERVIC	E SWITCH	
	Instance Quantity	1
	Instance Quantity Uom	EACH
	Manufacturer	Galaxy Switchgear
	EquipmentId	N/A
	Capacity/Size Quantity	2500
	Capacity/Size UOM	Amps
	Source of Capacity/Size	Nameplate
	Installation Year	2007
	Source of Installation Year	Documented
	Deficiency	No deficiencies recorded
	Instance	Building Addition - Room B015
	Instance Condition	2- Between Good and Fair
	Instance Quantity	1
	Instance Quantity Uom	EACH
	Manufacturer	Electrotech
	EquipmentId	Main Service Switchboard 4000A SS#1
	Capacity/Size Quantity	4000
	Capacity/Size UOM	Amps
	Source of Capacity/Size	Nameplate
	Installation Year	2011
	Source of Installation Year	Documented
-	Deficiency	No deficiencies recorded
	HBOARD	Inspected
	er of Spares	28
Fused 1	Disconnect Switch Type	Inspected
	Instance	Building Addition - Room B015
	Instance Condition	2- Between Good and Fair
	Instance Quantity	1
	Instance Quantity Uom	EACH
	Manufacturer	Electrotech
	EquipmentId	Section 3, 4, 5, 6
	Capacity/Size Quantity	1600
	Capacity/Size UOM	Amps Total
	Capacity/Size 2 Quantity	4 Section(s)
	Capacity/Size 2 UOM Source of Capacity/Size	Switchboard Mains Size
	Installation Year	2011
	Source of Installation Year	Documented
	Deficiency	No deficiencies recorded
	Instance	Penthouse Electrical Room
	Instance Condition	2- Between Good and Fair
	Instance Quantity	1
	Instance Quantity Instance Quantity Uom	EACH
		Electrotech
	Manufacturer	HDB
	EquipmentId Capacity/Size Quantity	2000
	Capacity/Size UOM	Amps Total
	Capacity/Size 2 Quantity	2
	Capacity/Size 2 UOM	Section(s)
	Source of Capacity/Size	Nameplate
	Installation Year	2011
	Source of Installation Year	Documented
	Deficiency	No deficiencies recorded
	Instance	Original Building - Electrical Room
	Instance Condition	2- Between Good and Fair

Building Condition Assessment Survey 2023-2024

		120/0
Question	Response	
SWITCHBOARD		
Fused Disconnect Switch Type		
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Galaxy Switchgear	
EquipmentId	N/A	
Capacity/Size Quantity	2500	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	4	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Service Switch Size	
Installation Year	2007	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fused Knife Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Does not exist	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
TRANSFORMER	Does not exist	