Asset:	P.S. 97 - BRONX	, 2500 FISH AVENUE	BRONX, NY, 10469	)			
Inspection Id	Inspection Type				Time In		Last Edited
1378	ELECTRICAL				2023-12	-01 08:59AM	1 2023-12-18 02:58PM
set Data							
Question				Answer			
Have any Systems/Major Building Components been upgraded?		?	Systems:	Intrusion Alarm	System (New	Wing)	
, ,	, .	1 10		Years:	2023		
				Systems:	Security Lights		
				Years:	2021, 2014, 200	8	
				Systems:	Partial Molded O	Case Circuit B	reaker Panel Boards
				Years:	2021, 2008, 200	1, 1999	
Type of Service		Foriet?		Years: Systems: Years: Systems: Years: Systems: Years: Systems: Years: Below Gr	System, Auxilian Emergency Ligh Frequency Drive System, Gymnas Protection Syste System, Elevato 2021 Library (Racewa 2010 Multipurpose Ro 2008 Emergency Ligh 2001 Interior Fluoresc 2000	ry Signal/Bell tts, Most Exit tts, Most Moto sium, Cafeteri m, Grounding r Intercom, La ty with Recep toom (Local So t/Exit Panel	Lights, Variable or Starters, Telephone a, Kitchen, Lightning s System, Public Address AN tacles)
Does Interactiv	e Whiteboard (IWB)	Exist?		Yes			
	on In Electrical Roon			No			
	) INTERCOMS IN	N FIRE RESCUE ARE	AS				
Question	. I :£. D A	A Eine D A	4/ II-14: D		Response		
your building		nce Areas, Fire Rescue Are	as, and/or Holding Roor	ns in	Yes		
		le in all of these spaces for	use during a fire?		Yes		
	edicated intercoms ope				Yes		
iority Condit	ion						
	ority	Condition	Component	Location	Person(s)	Person(s)	Photo
	egory	Description	Affected	Description		Title	Image
No condition re	ecorded						
spection							
				D			
Question				Response	<del></del>		
Electrical					• .		
ATHLETIC				Does not			
AUDITORIU	UM			Does not			
CAFETERIA	A			Inspected			
In	stance on 1st Floor			Inspected			
Lighting_							
	stance on 1st Floor			Inspected	<u> </u>		
	Fixture - Fluorescen	it					
	stance on 1st Floor			Does not	exist		
	Fixture - HID						
	stance on 1st Floor			Does not	exist		
	Fixture - Incandesce	ent					
In	stance on 1st Floor			Does not	exist		

Duestion	Response	
CAFETERIA	Tespons.	
Lighting		
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted	1	
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Installation Year	2021	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 1st Floor	Does not exist	
Theater Lighting System		
Instance on 1st Floor	Does not exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected Inspected	
Pendant Mounted	1- Good	
Condition		
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected 1- Good	
Condition	No deficiencies recorded	
Deficiency	Inspected	
Recessed Mounted	1- Good	
Condition		
Deficiency	No deficiencies recorded	
COMPUTER LAB	Does not exist	
GYMNASIUM	Inspected	
Instance on 3rd Floor	Inspected	
Lighting		
Instance on 3rd Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 3rd Floor	Does not exist	
Lighting Fixture - HID		

Duestion	Response	
	response	
GYMNASIUM		
Lighting Lighting Fixture - Incandescent		
Instance on 3rd Floor	Does not exist	
Lighting Fixture - LED	Does not exist	
Instance on 3rd Floor	Inspected	
	inspected	
Pendant Mounted	Door not aviat	
Instance on 3rd Floor	Does not exist	
Surface Mounted	Y 1	
Instance on 3rd Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 3rd Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Local Sound System		
Instance on 3rd Floor	Inspected	
Instance Condition	1- Good	
Installation Year	2021	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 3rd Floor	Inspected	
Instance Condition	1- Good	
Is the projector on a cart or installed on the ceiling?	Ceiling	
Deficiency	No deficiencies recorded	
Scoreboard		
Instance on 3rd Floor	Does not exist	
Theater Lighting System		
Instance on 3rd Floor	Inspected	
Dimming System		
Instance on 3rd Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Theater Lighting		
Instance on 3rd Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
Lighting		
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted	Порессей	
Instance on 1st Floor	Does not exist	

#### **Building Condition Assessment Survey 2023-2024**

Question	Response	
KITCHEN		
Lighting		
Lighting Fixture - LED		
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
LIBRARY	Inspected	
Instance on Room 215	Inaccessible	
LOCKER ROOM	Does not exist	
MULTIPURPOSE ROOM	Inspected	
Instance on 1st Floor	Inspected	
Lighting Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Instance on 1st Floor	Inconnected	
Pendant Mounted	Inspected	
Instance on 1st Floor	Does not exist	
Surface Mounted	Does not exist	
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	No deficiencies recorded	
-	Dogs not exist	
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID	Does not exist	
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent Instance on 1st Floor	Does not exist	
	Does not exist	
Lighting Fixture - LED  Instance on 1st Floor	Does not exist	
	Does not exist	
Local Sound System Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	2008	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 1st Floor	Does not exist	
Theater Lighting System		
Instance on 1st Floor	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Inspected	
Instance on Room 431	Inspected	
Power Panel?	No	
Alternative Use		
	No	
Lighting Instance on Room 431	Inspected	
Lighting Fixture - Fluorescent	nispecieu	
Instance on Room 431	Does not exist	
Lighting Fixture - HID	DOCS HOT CYIST	

**Lighting Fixture - Incandescent** 

Electrical Inspection	X097
Question	Response

Question	Response
SCIENCE LAB	
Lighting	
Lighting Fixture - Incandescent	
Instance on Room 431	Does not exist
Lighting Fixture - LED	
Instance on Room 431	Inspected
Pendant Mounted	
Instance on Room 431	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 431	Does not exist
Recessed Mounted	
Instance on Room 431	Does not exist
Emergency Gas Shut-Off Valve	
Instance on Room 431	Does not exist
Emergency Shut-Off Power	
Instance on Room 431	Does not exist
Power Supply	
Instance on Room 431	Does not exist
Projection System	
Instance on Room 431	Does not exist
SCIENCE PREP ROOM	Does not exist
SWIMMING POOL	Does not exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Does not exist
Recessed Mounted	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not exist
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Does not exist

### **Building Condition Assessment Survey 2023-2024**

icui inspection		AU9
uestion	Response	
TOILET ROOM - STUDENT		
Lighting		
Lighting Fixture - LED		
Surface Mounted	Does not exist	
Recessed Mounted	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	
	Does not exist	
EMERGENCY GENERATOR SET		
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EMERGENCY LIGHTING	Inspected	
Battery Pack	Inspected	
Condition	1- Good	
Deficiency	BATTERY NOT OPERATIONAL	
Deficiency Location/Instance	Unit #2	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE BATTERY	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 4	
Violations	35591730r	
Non Battery Pack	Does not exist	
EXIT LIGHT	Inspected	
Battery Pack	Inspected	
Condition	1- Good	
Deficiency	FIXTURE NOT OPERATIONAL	
Deficiency Location/Instance	Staircase C/1	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPAIR	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 4	
Violations	35591730r	
Non Battery Pack	Does not exist	
EXIT/EMERGENCY LIGHT	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
FIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Manual Pull Station Condition	1- Good	
	No deficiencies recorded	
Deficiency		
Fan Shutdown Control	Inspected	

### **Building Condition Assessment Survey 2023-2024**

ent inspection		1107
estion	Response	
FIRE ALARM SYSTEM		
Fan Shutdown Control		
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
CO Detector	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Heat Detector	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Elevator Recall	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Magnetic Door Holder/Contactor	Does not exist	
Fused Cutout Panel	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Inspected	
Bell At Panel	Does not exist	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	1- Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Edwards System Technology	
Model	EST 3	
EquipmentId	Fire Alarm Control Panel	
Installation Year	2021	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Exit 1 Vestibule	
Instance Condition	1- Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Edwards System Technology	
Model	EST 3	
EquipmentId	Fire Alarm Control Panel	
Installation Year	2021	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel	Does not exist	
Remote Annunciator	Inspected	<u></u>
Display Monitor	Does not exist	
Panel	Inspected	
Condition	1- Good	_
Deficiency	No deficiencies recorded	
	Inspected	
Printer	nispected	

### **Building Condition Assessment Survey 2023-2024**

uestion	Response
FIRE ALARM SYSTEM	
Remote Annunciator	
Printer	
Deficiency	No deficiencies recorded
Punch Register	Does not exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
NTERCOM SYSTEM	Inspected
Elevator	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Holding Area	Does not exist
	Inspected
LAN Local Distribution Frame (I/LDF)	Inspected
Condition Condition	1- Good
Deficiency	No deficiencies recorded
<u> </u>	
Main Equipment Rack (MDF) Condition	Inspected 1- Good
	No deficiencies recorded
Deficiency	
LIGHTNING PROTECTION	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Variable Frequency Drive	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Does not exist
Fused Knife Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Corridor near Rooms 307, 207, Multipurpose Room, Boiler Room
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Old Electrical Room
Deficiency Quantity	1

### **Building Condition Assessment Survey 2023-2024**

Question	Response
PANEL BOARD	
Fused Toggle Switch Type	
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Inspected
Condition	1- Good
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Multipurpose Room, Corridor near Room 207, 307
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	MDF Room 507
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Bogen Multicom - 2000
Installation Year	2021
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Condition	1- Good
Installation Year	2021
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office - Room 100
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128B
Installation Year	2000
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Custodian's Office - Room 124
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista 128BPT
Installation Year	2023
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	2- Between Good and Fair
	2 Detritor Good and I an

Question	Response
SECURITY	
Intrusion Alarm System	
Panic Switch	
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	
	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	1- Good
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Old Building Roof
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Violations	No violations recorded
Deficiency	TIME CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Room 356
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Violations	No violations recorded
SERVICE SWITCH	Inspected
Instance	Electrical Room 025
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	Main Service Switchboard
Capacity/Size Quantity	2000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2021
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room 025
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
	Main Service Switchboard
EquipmentId Capacity/Size Quantity	1200
Capacity/Size Quantity  Capacity/Size UOM	Amps
Source of Capacity/Size	Amps Nameplate
Installation Year	2021
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room 025 1- Good

### **Building Condition Assessment Survey 2023-2024**

и інѕресион		AUX
tion	Response	
RVICE SWITCH		
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Electrotech	
EquipmentId	Fire Pump	
Capacity/Size Quantity	800	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	2021	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Electrical Room - Old Building	
Instance Condition	3- Fair	
Instance Condition  Instance Quantity		
	1 EACH	
Instance Quantity Uom		
Manufacturer	Federal Pacific Electric	
EquipmentId	Lights	
Capacity/Size Quantity	600	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	1960	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room - Old Building	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	Electrical Room - Old Building	
Instance Condition	3- Fair	
Instance Quantity	1	_
Instance Quantity Uom	EACH	
Manufacturer	Federal Pacific Electric	
EquipmentId	Power	
Capacity/Size Quantity	600	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	1960	-
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room - Old Building	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance Instance Condition	Electrical Room - Old Building	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Arrow Hart	
EquipmentId	Service SW for Kitchen Panel	
Capacity/Size Quantity	400	

Duestion	Response	
SERVICE SWITCH		
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	1960	
Source of Installation Year	Inspector Estimate	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room - Old Building	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
SWITCHBOARD	Inspected	
Number of Spares	8	
Fused Disconnect Switch Type	Inspected	
Instance	Electrical Room 505	
Instance Condition	1- Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Electrotech	
EquipmentId	RDP	
Capacity/Size Quantity	3000	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	2	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Nameplate	
Installation Year	2021	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Electrical Room 025	
Instance Condition	1- Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Electrotech	
EquipmentId	Main Service Switchboard	
Capacity/Size Quantity	2000	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	2	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Nameplate	
Installation Year	2021	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Electrical Room - Old Building	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Electric Switchboard	
EquipmentId	N/A	
Capacity/Size Quantity	800	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	3	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Nameplate	
Installation Year	1960	
Source of Installation Year	Documented	

# **Building Condition Assessment Survey 2023-2024**

euestion	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room - Old Building
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
TRANSFORMER	Does not exist