Building Condition Assessment Survey 2023-2024

Mechanical Inspection

Asset:	P.S. 199 - BRONX, 1449 SHAKESPEARE AVENUE, I	BRONX, NY, 10452		
Inspection Id	Inspection Type		Time In	Last Edited
3636	MECHANICAL		2024-03-01 07:07AM	2024-04-19 10:43AN
set Data				
Question		Answer		
Have any Syste	ms/Major Building Components been upgraded?	Systems:	Boilers #1, #2 re-tubed, Boiler Fr	resh Air
		Years:	Louver/Dampers 2023	
		Systems:	Boiler Feedwater Treatment(Aut	amatic): Fixtures
		Systems.	Toilets, Urinals	Sinanc), Fixtures -
		Years:	2022	
		Systems:	F&T/Steam Drip Traps; Termina	l Unit Thermostatic
		2	Traps; Steam Condensate Return	
		Years:	2021	
		Systems:	CO/Gas Leak Detection	
		Years:	2019	
		Systems:	Climate Control System - Pneum	atic System: PRV
			Station; DX Split Systems and E	lectric Domestic Water
			Heater for Clinic; MDF Room D	
			Equipment: Room 426M (DX Sp	olit System)
		Years:	2018 Con Final Domestic Water Hoste	w Daward's Hat Water
		Systems:	Gas Fired Domestic Water Heate Remote Storage Tank	r; Domestic Hot water
		Years:	2017	
	Systems:	Climate Control System - Electri	c System: MDF Room	
		Systems	- Dedicated A/C Equipment: Roc	•
			System)	
		Years:	2015	
Are there fuel t	anks?	Yes		
Total # of a	bove ground tanks	1		
-	ity of all above ground tanks in gal.	7,500		
	elow ground tanks	0		
	ity of all below ground tanks in gal.	0		
	r main service entries to the asset	2		
MERs/Fan Roo			- MER, Mechanical Area	
	paces with Missing or Defective CO Detectors?	No		
-	Painted/Obstructed Sprinkler Heads?	Yes		
Location(s)		Basement Room,	Mechanical Area - Storage Room	next to Paint
			om - Work Shop (painted, 5)	
Are there any F	mergency Stop Switches with Missing Hammers?	No compo		

Priority Condition

Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
No	Defective Boiler Safety Auxiliary	(3)	Boiler Safety Valve	Boiler Room @ Boilers #1, #2	Roman Roque	Fireman	

spection		
Question	Response	
Mechanical		
AIR CONDITIONING	Inspected	
Chilled Water System	Does not exist	
Condenser Water Distribution: Piping, Pumps and Auxiliaries	Does not exist	
Cooling Coil in Ductwork	Does not exist	



NYC Department of Education Building Condition Assessment Survey 2023-2024

Mechanical Inspection

unicui Inspeciion	
uestion	Response
AIR CONDITIONING	
Cooling Tower	Does not exist
DX Split System	Inspected
Indoor Unit	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Outdoor Unit	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Dry Cooler	Does not exist
Packaged / Rooftop Unit	Does not exist
Packaged Terminal A/C	Does not exist
Refrigerant Leak Detection System	Does not exist
Refrigerant Piping	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Return Fan	Does not exist
CENTRAL ACID WASTE NEUTRALIZING TANK	Does not exist
CLIMATE CONTROL SYSTEM	Inspected
BMS	Does not exist
Pneumatic System	Inspected
Instance	Throughout
Instance Condition	3- Fair
Instance Quantity	1
	EACH
Instance Quantity Uom Building Area Covered by Operational System	81-100%
Deficiency	No deficiencies recorded
Hybrid System	Does not exist Inspected
Electric System Instance	Throughout (Heat Timer System)
Instance Condition	2- Between Good and Fair
Instance Quantity	1 EACH
Instance Quantity Uom	
Building Area Covered by Operational System	81-100%
Deficiency	No deficiencies recorded
COMPACTOR	Does not exist
CONVEYING	Does not exist
DOMESTIC WATER SYSTEM	Inspected
Domestic Cold Water System	Inspected
Gravity System	Does not exist
Pressure Booster System	Does not exist
Water Service	Inspected
Instance	Basement - Mechanical Area, Boiler Room
Instance Condition	3- Fair
Instance Quantity	2
Instance Quantity Uom	EACH
Deficiency	WATER MAIN: MISSING BACKFLOW PREVENTION DEVICE
Deficiency Location/Instance	Basement - Mechanical Area, Boiler Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	INSTALL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

unicui Inspection	ΛΙ
lestion	Response
DOMESTIC WATER SYSTEM	
Domestic Cold Water System	
Water Service	
Violations	No violations recorded
Domestic Hot Water System	Inspected
Domestic Hot Water Remote Storage Tank	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Domestic Water Heat Exchanger	Inspected
Condition	3- Fair
Deficiency	NOT IN USE
Deficiency Location/Instance	Basement Mechanical Area
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
Electric Domestic Water Heater	Inspected
Condition	2- Between Good and Fair
Deficiency	NOT IN USE
Deficiency Location/Instance	Basement Mechanical Area (1 of 3)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
Gas Fired Domestic Water Heater	Inspected
Instance	Boiler Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Lochinvar
EquipmentId	N/A
Capacity/Size Quantity	315
Capacity/Size UOM	MBH Input
Capacity/Size 2 Quantity Capacity/Size 2 UOM	0 Gallons
Source of Capacity/Size	Documented
Installation Year	2017
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Oil Fired Domestic Water Heater	Does not exist
Heat Pump Domestic Water Heater	Does not exist
Domestic Water Distribution Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected
Interior Storm Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sewage/Waste/Vent Piping	Inspected
	-
Condition	3- Fair

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

Response
Does not exist
Inspected
3- Fair
No deficiencies recorded
Does not exist
Inspected
Inspected
Inspected
3- Fair
No deficiencies recorded
Inspected
3- Fair
DEFECTIVE AUXILIARY (FAUCET, SHUT OFF VALVE,ETC.)
3rd Floor Staff Toilet Room
1
EACH
MAINTENANCE
PRIORITY 3
LEVEL 2
No violations recorded
Inspected
1- Good
No deficiencies recorded
Does not exist
Inspected
Inspected
3- Fair
No deficiencies recorded
Inspected
3- Fair
DEFECTIVE AUXILIARY (FAUCET, SHUT OFF VALVE,ETC.)
2nd and 3rd Floor Boy's Toilet Rooms, 2nd Floor Girl's Toilet
Room
3
EACH
MAINTENANCE
PRIORITY 3
LEVEL 2
No violations recorded
Does not exist
Inspected
3- Fair
No deficiencies recorded
Inspected
1- Good
No deficiencies recorded
Inspected
1- Good
No deficiencies recorded
No deficiencies recorded Does not exist

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

	Λ104
Question	Response
GAS SERVICE	
Gas Distribution Piping	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Gas Meter Room Exhaust Fan	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Gas Meter Room Vent	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Gas Pressure Booster	Inspected
Instance	Gas Meter Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Eclipse
EquipmentId	N/A
Capacity/Size Quantity	18000
Capacity/Size UOM	SCFH
Source of Capacity/Size	Documented
Installation Year	1997
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
CO/Gas Leak Detection	Inspected
Instance	Boiler Room, Gas M eter Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Installation Year	2019
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
HEATING	Inspected
Heating Coil In Ductwork	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Hydronic Heating	Does not exist
Radiator/Convector/Fin Tube	Inspected
Condition	3- Fair
Deficiency	AUXILIARY (VALVE, VENT): DEFECTIVE
Deficiency Location/Instance	Near Room 325; Staircase "EF/3"
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
	Inspected
Steam Heating	Inspected
F&T/Steam Drip Trap	
Condition	1- Good
Deficiency	No deficiencies recorded
MER Steam and Condensate Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Steam Condensate Return Piping	Inspected

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

estion	Response
IEATING	
Steam Heating	
Steam Condensate Return Piping	
Deficiency	DEFECTIVE/LEAKS
Deficiency Location/Instance	Boiler Room near Boiler #2; Basement - near Paint Room, under
	Auditorium
Deficiency Quantity	30
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Condensate Return Pumping System	Inspected
Condition	2- Between Good and Fair
Deficiency	DEFECTIVE CONTROLS
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Piping	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE/LEAKS
Deficiency Location/Instance	Boiler Room near Boiler #1,
Deficiency Quantity	30
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Terminal Unit Thermostatic Trap	Inspected
Condition	1- Good
Deficiency	DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Rooms 117A, 322, 419A, 423,425 and other locations
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam supplied by External Sources	Does not exist
Unit Heater/Cabinet Heater	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
IEATING PLANT	Inspected
Instance on Basement	Inspected
Is there a water meter on the boiler make-up water piping?	Yes
Observed Operational?	Yes
Burner Manufacturer	Gordon-Piatt
Burner Model	F14.9-GO-30
Burner Type	Dual Fuel (Gas/Oil)
Heating Plant Oil Number	2
Boiler Auxiliaries	
Instance on Basement	Inspected

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

stion	Response
EATING PLANT	
Boiler Auxiliaries	
Boiler Auxiliary Piping	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	DEFECTIVE BOILER AUTOMATIC FEEDWATER VALVE
Deficiency Location/Instance	Boiler Room @ Boiler #2
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE BLOWDOWN PIPING
Deficiency Location/Instance Deficiency Quantity	Boiler Room @ Boilers #1,#2 (corroded)
• • •	2
Quantity Uom Potential Action	EACH MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 4
Violations	39023469M
Boiler Emergency Stop Switch	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Feedwater System	<u> </u>
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Feedwater Treatment(Automatic)	
Instance on Basement	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Boiler Flue Exhaust	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Make-up Water Backflow Preventer	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Room Steam And Condensate Piping	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Safety Valve	
Instance on Basement	Inspected
Instance Condition	5- Poor
Deficiency	DEFECTIVE
Deficiency Location/Instance	Boiler Room @ Boilers #1,#2
Deficiency Quantity	3
	EACH
Quantity Uom	
Quantity Uom Potential Action Urgency of Action	REPLACE PRIORITY 5

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

estion	Response	
	Response	
EATING PLANT		
Boiler Auxiliaries		
Boiler Safety Valve Violations	No violations recorded	
	No violations recorded	
Boiler System Instance on Basement	Y	
	Inspected	
Coal-fired Boiler		
Instance on Basement	Does not exist	
Hot Water Boiler		
Instance on Basement	Does not exist	
Modular Boiler		
Instance on Basement	Does not exist	
Steam Boiler		
Instance on Basement	Inspected	
Instance on Basement	Inspected	
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity	5.198	
Instance Quantity Uom	MBH NET	
Cast Iron Boiler?	No	
Manufacturer	A. L. Eastmond & Sons Inc.	
EquipmentId	6503-01	
Capacity/Size Quantity	5198	
Capacity/Size UOM	MBH Net	
Source of Capacity/Size	Documented	
Installation Year	1997	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity	5,198	
Instance Quantity Uom	MBH NET	
Cast Iron Boiler?	No	
Manufacturer	A. L. Eastmond & Sons Inc.	
EquipmentId	6503-02	
Capacity/Size Quantity	5198	
Capacity/Size UOM	MBH Net	
Source of Capacity/Size	Documented	
Installation Year	1997	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fuel System		
Instance on Basement	Inspected	
Boiler Fresh Air Louver/Damper	•	
Instance on Basement	Inspected	
Instance Condition	1- Good	
Туре	Automatic	
Deficiency	No deficiencies recorded	
Burner/Burner Control Panel		
Instance on Basement	Inspected	
	Inspected 3- Fair	
Instance Condition		
Deficiency	No deficiencies recorded	
Fuel Oil Storage/Supply System		
Instance on Basement	Inspected	
Instance Condition	3- Fair	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

uostie-	Inspection	Dosponso	
uestion		Response	
	IG PLANT		
Fuel Sy			
Fuel	Oil Storage/Supply System Deficiency	No deficiencies recorded	
<u> </u>	-	No deficiencies recorded	
Gas I	Frains And Vent At The Boiler	Inspected	
	Instance Condition	3- Fair	
	Deficiency	No deficiencies recorded	
	IDF Room	Does not exist	
KITCHE		Inspected	
	Instance on 1st Floor	Inspected	
CO Det			
	Instance on 1st Floor	Not required	
Gas Sy		Does not exist	
<u> </u>	Instance on 1st Floor	Does not exist	
Grease	Irap Instance on 1st Floor	Inspected	
	Instance Condition	3- Fair	
	Deficiency	No deficiencies recorded	
Hood	Deficiency	No deficielles recorded	
Hood	Instance on 1st Floor	Inspected	
	Instance Condition	3- Fair	
	Deficiency	No deficiencies recorded	
Head E	Exhaust Ductwork	No deficiencies recorded	
Hood F	Instance on 1st Floor	Inspected	
	Instance Condition	3- Fair	
	Deficiency	No deficiencies recorded	
Hood F	Exhaust Fan	No deficicles recorded	
HOOU P	Instance on 1st Floor	Inspected	
	Instance Condition	3- Fair	
	Deficiency	No deficiencies recorded	
Hood F	Fire Suppression System	No deficicies recorded	
HOOU F	Instance on 1st Floor	Does not exist	
Hot We	ater Temperature Booster		
1101 111	Instance on 1st Floor	Does not exist	
Kitchei	n Sink		
	Instance on 1st Floor	Inspected	
	Instance Condition	3- Fair	
	Deficiency	Missing Air Gap	
	Deficiency Location/Instance	Kitchen	
	Deficiency Quantity	1	
	Quantity Uom	EACH	
	Potential Action	MAINTENANCE	
	Urgency of Action	PRIORITY 3	
	Purpose of Action	LEVEL 2	
	Violations	No violations recorded	
MDF Ro		Inspected	
	Instance on Room 355	Inspected	
	Instance on Room 426M	Inspected	
Dedica	ted A/C Equipment		
	Instance on Room 355	Inspected	
	Instance Condition	2- Between Good and Fair	
	Deficiency	No deficiencies recorded	
	Instance on Room 426M	Inspected	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

anical Inspection	ΔΙ
uestion	Response
MDF Room	
Dedicated A/C Equipment	
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Does not exist
	Does not exist
SCIENCE PREP ROOM	
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected
Dry Sprinkler Alarm Valve Assembly	Does not exist Does not exist
Wet Sprinkler Alarm Valve Assembly	Does not exist
Fire Booster Pump Assembly	Does not exist
Roof Tank Siamese Connection	Does not exist
	Inspected
Sprinkler Head Condition	3- Fair
	DEFECTIVE/DETERIORATED
Deficiency Deficiency Location/Instance	
Denciency Location/Instance	Basement Mechanical Area - Storage Room next to Paint Room, Boiler Room - Work Shop (painted, 5)
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
	Inspected
Sprinkler Piping Condition	3- Fair
Deficiency	No deficiencies recorded
	Does not exist
Standpipe System	Does not exist
Water Gong	Does not exist
SWIMMING POOL	
VENTILATION	Inspected
Is the building Mechanically ventilated?	Partial
Exhaust Fan	Inspected
Condition	3- Fair
Approximate Total # of Fans	1-25
Deficiency	No deficiencies recorded
Heating And Ventilating Unit	Does not exist
Metal Ductwork	Inspected
Condition	3- Fair
Are there any uninsulated ductwork by design in Mechanical rooms?	Yes
Are there chain operated dampers?	No
Deficiency	No deficiencies recorded
Supply Fan	Inspected
Condition	3- Fair
	1-5
Approximate Total # of Fans	No deficiencies recorded
Deficiency	
Deficiency Unit Ventilator	Inspected
Deficiency Unit Ventilator Condition	3- Fair
Deficiency Unit Ventilator Condition Deficiency	3- Fair DEFECTIVE MOTOR
Deficiency Unit Ventilator Condition Deficiency Deficiency Deficiency Deficiency Deficiency	3- Fair DEFECTIVE MOTOR Rooms 320, 322, 423
Deficiency Unit Ventilator Condition Deficiency Deficiency Location/Instance Deficiency Quantity	3- Fair DEFECTIVE MOTOR Rooms 320, 322, 423 3
Deficiency Unit Ventilator Condition Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom	3- Fair DEFECTIVE MOTOR Rooms 320, 322, 423 3 EACH
Deficiency Unit Ventilator Condition Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action	3- Fair DEFECTIVE MOTOR Rooms 320, 322, 423 3 EACH MAINTENANCE
Deficiency Unit Ventilator Condition Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom	3- Fair DEFECTIVE MOTOR Rooms 320, 322, 423 3 EACH

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

Question

VENTILATION

Unit Ventilator Violations Response

No violations recorded