Building Condition Assessment Survey 2023-2024

sset Data		pe			Time In	Last Edited
sset Data						
	1633 ELECTRICAL				2023-12-12 08:46AM	2024-06-13 09:24A
•						
Question				Answer		
Have any S	Systems/Major Build	ing Components been upgraded?		Systems:	Most Molded Case Circuit Bre	aker Panel Board
				Years:	2023, 2020, 2018, 2009, 1985	
				Systems:	Auditorium (LED Lighting)	
				Years:	2023	
				Systems:		
				Years:	2020	. 10 .
				Systems:	IPDVS/CCTV System	Sound Systems,
				Years:	2019	r: 1.: \ N .: 1
				Systems:	Variable Frequency Drive	Lighting), Partial
				Years:	2018	
				Systems:	Lightning Protection	
				Years:	2017	ii CtI1
				Systems:	Interior Lighting (Except Addit Library, Health Clinic LED Lip Pack Exit Lights, Partial Batter Lights, Non-Battery Type Eme Telephone System	ghts), Partial Battery ry Type Emergency
				Years:	2016	
				Systems:	Fire Alarm System (Remote Ar	nnunciator Panel)
				Years:	2012	
				Systems:	Computer Lab, Library	
				Years:	2011	
				Systems:	Auditorium (Projection System System), Partial Motor Starters	
				Years:	2010	1 T D 1D 1
				Systems:	Partial Fused Disconnect Switch	en Type Panel Boards
				Years:	2009	: Lighting)
				Systems: Years:	Building Addition (Fluorescent 2007	Lighting)
				Systems:		
				Years:	2006, 1995	
				Systems:	Fire Alarm System, Intercom (Elevator)
				Years:	2005	
				Systems:		inel
				Years:	2004	
				Systems:	Intrusion Alarm System	
				Years:	2002	
Type of Se	ervice			Below Gr	round	
	ractive Whiteboard (I'	WB) Exist?		Yes		
Water Pend	etration In Electrical	Room?		No		
	TED INTERCOM	IS IN FIRE RESCUE AREA	S			
Question					Response	
Are there your buil		sistance Areas, Fire Rescue Areas	, and/or Holding Roor	ns in	No	
-	_					
iority Con		C P2	<u> </u>	τ	n () n ()	DI 4
	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Person(s) Notified Title	Photo Image

Building Condition Assessment Survey 2023-2024

Electrica	al Inspection							X113
No	Fire Alarm System - Components Not Operational	N/A	Fire Alarm System - Area Smoke Detector	Staircase B/Bulkhead	Ramon Cruz	Fireman	FIRE ALARM	SYSTEM CONTRACTOR OF THE PARTY
Yes	Emergency Lighting - Not Operational	N/A	Emergency Lighting	Throughout the Building	Carlos Carrera	Custodian	No Photo Taken	
Yes	Intercom - Not Operational	N/A	Intercom System - Elevator	Elevator Device ID: 2P10750	Carlos Carrera	Custodian	No Photo Taken	
Yes	Fire Alarm System - Components Not Operational	N/A	Fire Alarm System - Magnetic Door Holder/Contac tor	Corridor near Rooms 347B, 368	Carlos Carrera	Custodian	No Photo Taken	
Inspect	ion							
Quest	tion			Response				
Electi								
	HLETIC FIELD			Does not e	exist			
	DITORIUM			Inspected				
AU	Instance on 1st Floor			Inspected				
H	ouse Lighting			шореской				
	Instance on 1st Floor			Inspected				
	Does a Chandelier Exi	ist?		No				
	Lighting Fixture - Fluoresce	nt						
	Instance on 1st Floor			Inspected				
	Pendant Mounted							
	Instance on 1st Floor			Does not e	exist			
	Surface Mounted							
	Instance on 1st Floor			Inspected				
	Instance Condition			2- Betwee	n Good and F	air		
	Deficiency			No deficie	ncies recorde	d		
	Recessed Mounted							
	Instance on 1st Floor			Inspected				
	Instance Condition			2- Betwee	n Good and F	air		
	Deficiency			No deficie	encies recorde	d		
	Lighting Fixture - HID							
	Instance on 1st Floor			Does not e	exist			
	Lighting Fixture - Incandesc	ent						
	Instance on 1st Floor			Inspected				
	Pendant Mounted							
	Instance on 1st Floor			Inspected				
	Instance Condition			3- Fair				
	Deficiency				G FIXTURE	BEYOND USE	FUL LIFE	
	Deficiency Quantity	7		4				
	Quantity Uom Potential Action			EACH PEDLACI	E-UPGRADE			
	Urgency of Action			PRIORIT				
	Purpose of Action			LEVEL 2	. 1			
	Violations				ons recorded			
	Surface Mounted			1.0 violati				
	Instance on 1st Floor			Does not e	exist			
	Recessed Mounted							
	Instance on 1st Floor			Does not e				

Building Condition Assessment Survey 2023-2024

Electrical Inspection	A113

uestion	Response
AUDITORIUM	
House Lighting	
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Installation Year	2019
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Is the projector on a cart or installed on the ceiling?	Ceiling
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Inspected
Instance Condition	5- Poor
Deficiency	DIMMING RACK/LIGHT CONSOLE NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Theater Lighting	
Instance on 1st Floor	Inspected
Instance Condition	4- Between Fair and Poor
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	68
Quantity Uom	EACH REPLACE
Potential Action	PRIORITY 3
Urgency of Action	PRIORITY 3 LEVEL 2
Purpose of Action Violations	No violations recorded
CAFETERIA	Inspected
Instance on 1st Floor	Inspected
Instance on 2nd Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Instance on 2nd Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Instance on 2nd Floor	Inspected
Pendant Mounted	

Building Condition Assessment Survey 2023-2024

icai Inspection		XII
estion	Response	
CAFETERIA		
Lighting		
Lighting Fixture - Fluorescent		
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Instance on 2nd Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Instance on 2nd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on 2nd Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Instance on 2nd Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Instance on 2nd Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Does not exist	
Instance on 2nd Floor	Does not exist	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Installation Year	2019	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance on 2nd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Installation Year	2019	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 1st Floor	Does not exist	
Instance on 2nd Floor	Does not exist	
Theater Lighting System		
Instance on 1st Floor	Does not exist	
Instance on 2nd Floor	Does not exist	
LASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	3- Fair	

Building Condition Assessment Survey 2023-2024

inea inspection	-	2113
Question	Response	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE		
Lighting		
Lighting Fixture - Fluorescent		
Recessed Mounted		
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - Incandescent Lighting Fixture - LED	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Does not exist	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
COMPUTER LAB	Inspected	
Instance on Room 156	Inspected	
Power Panel?	Yes	
Lighting		
Instance on Room 156	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 156	Inspected	
Pendant Mounted		
Instance on Room 156	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 156	Does not exist	
Recessed Mounted		
Instance on Room 156	Does not exist	
Lighting Fixture - HID		
Instance on Room 156	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 156	Does not exist	
Lighting Fixture - LED		
Instance on Room 156	Does not exist	
Raceway With Receptacles		
Instance on Room 156	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
GYMNASIUM	Inspected	
Instance on 3rd Floor - East, 3rd Floor - West	Inspected	
Lighting	Inconceted	
Instance on 3rd Floor - East, 3rd Floor - West	Inspected	
Lighting Fixture - Fluorescent	D	
Instance on 3rd Floor - East, 3rd Floor - West	Does not exist	
Lighting Fixture - HID		
Instance on 3rd Floor - East, 3rd Floor - West	Does not exist	
Lighting Fixture - Incandescent		
Instance on 3rd Floor - East, 3rd Floor - West	Does not exist	
Lighting Fixture - LED		
Instance on 3rd Floor - East, 3rd Floor - West	Inspected	
Pendant Mounted		
Instance on 3rd Floor - East, 3rd Floor - West	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE	

Building Condition Assessment Survey 2023-2024

estion	Response	
GYMNASIUM	-	
Lighting		
Lighting Fixture - LED		
Pendant Mounted		
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	REPLACE BALLAST	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Surface Mounted		
Instance on 3rd Floor - East, 3rd Floor - West	Does not exist	
Recessed Mounted		
Instance on 3rd Floor - East, 3rd Floor - West	Does not exist	
Local Sound System		
Instance on 3rd Floor - East, 3rd Floor - West	Inspected	
Instance Condition	2- Between Good and Fair	
Installation Year	2019	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 3rd Floor - East, 3rd Floor - West	Does not exist	
Scoreboard		
Instance on 3rd Floor - East, 3rd Floor - West	Does not exist	
Theater Lighting System		
Instance on 3rd Floor - East, 3rd Floor - West	Does not exist	
KITCHEN	Inspected	
Instance on 1st Floor, 2nd Floor	Inspected	
Lighting	-	
Instance on 1st Floor, 2nd Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor, 2nd Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor, 2nd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on 1st Floor, 2nd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	110 deficiences recorded	
Instance on 1st Floor, 2nd Floor	Does not exist	
Lighting Fixture - HID	DOCS HOT CAIST	
	Doos mot aviat	
Instance on 1st Floor, 2nd Floor	Does not exist	
Lighting Fixture - Incandescent	Description of the second	
Instance on 1st Floor, 2nd Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor, 2nd Floor	Does not exist	
JIBRARY	Inspected	
Instance on Room 152	Inspected	
Lighting		
Instance on Room 152	Inspected	
Lighting Fixture - Fluorescent		

Building Condition Assessment Survey 2023-2024

ricui Inspection	Λ
euestion	Response
LIBRARY	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Instance on Room 152	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 152	Does not exist
Recessed Mounted	
Instance on Room 152	Does not exist
Lighting Fixture - HID	
Instance on Room 152	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 152	Does not exist
Lighting Fixture - LED	
Instance on Room 152	Does not exist
Raceway With Receptacles	
Instance on Room 152	Does not exist
Projection System	
Instance on Room 152	Does not exist
LOCKER ROOM	Inspected
Instance on Room 228B	Inspected
Alternative Use	Yes
Instance on Room 228A	Inspected
Alternative Use	Yes
Lighting	100
Instance on Room 228B	Inspected
Instance on Room 228A	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 228B	Inspected
Instance on Room 228A	Inspected
Pendant Mounted	шорочно
Instance on Room 228B	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 228A	Does not exist
Surface Mounted	DOCS HOL CAISE
Instance on Room 228B	Does not exist
Instance on Room 228A	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
	No deficiencies recorded
Recessed Mounted	Discount with
Instance on Room 228B	Does not exist
Instance on Room 228A	Does not exist
Lighting Fixture - HID	December 11
Instance on Room 228B	Does not exist
Instance on Room 228A	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 228B	Does not exist
Instance on Room 228A	Does not exist
Lighting Fixture - LED	
Instance on Room 228B	Does not exist

Building Condition Assessment Survey 2023-2024

Electrical Inspection	X113

Response	
Does not exist	
Does not exist	
Inspected	
-	
Yes	
T 1	
Inspected	
Y 4 1	
Inspected	
*	
_	
No deficiencies recorded	
Does not exist	
Does not exist	
Does not exist	
Does not exist	
Does not exist	
Does not exist	
Does not exist	
Does not exist	
Does not exist	
Does not exist	
Inspected	
3- Fair	
No deficiencies recorded	
Does not exist	
Does not exist	
Does not exist	
Does not exist	
Does not exist	
	Does not exist Inspected Inspected No Yes Inspected No Yes Inspected Inspect

Building Condition Assessment Survey 2023-2024

iricai Inspection		AIIS
Question	Response	
SCIENCE DEMO ROOM		
Projection System		
Instance on Room 254	Does not exist	
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Inspected	
Instance on Room 252	Inspected	
Power Panel?	No	
Alternative Use	Yes	
Lighting		
Instance on Room 252	Inspected	
Lighting Fixture - Fluorescent	<u> </u>	
Instance on Room 252	Inspected	
Pendant Mounted	<u> </u>	
Instance on Room 252	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 252	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Room 252	Does not exist	
Lighting Fixture - HID		
Instance on Room 252	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 252	Does not exist	
Lighting Fixture - LED		
Instance on Room 252	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Room 252	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power		
Instance on Room 252	Does not exist	
Power Supply		
Instance on Room 252	Does not exist	
SWIMMING POOL	Does not exist	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	

Building Condition Assessment Survey 2023-2024

*		
Question	Response	
TOILET ROOM - STUDENT		
Lighting		
Lighting Fixture - Fluorescent		
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Does not exist	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	
EMERGENCY GENERATOR SET	Does not exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected 3- Fair	
Condition		
Deficiency	No deficiencies recorded	
EMERGENCY LIGHTING	Inspected	
Battery Pack	Inspected	
Condition	4- Between Fair and Poor	
Deficiency	BATTERY NOT OPERATIONAL	
Deficiency Location/Instance Deficiency Quantity	Throughout the Building 16	
Quantity Uom	EACH	
Potential Action	REPLACE BATTERY	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	35671882X	
Deficiency	FIXTURE NOT OPERATIONAL	
Deficiency Location/Instance	East Gymnasium	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 4	
Violations	35671882X	
Non Battery Pack	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
EXIT LIGHT	Inspected	
Battery Pack	Inspected	
Condition	2- Between Good and Fair	
Deficiency	FIXTURE NOT OPERATIONAL	
Deficiency Location/Instance	Auditorium Stage	
Deficiency Quantity	1	

Building Condition Assessment Survey 2023-2024

cui Inspection	All
estion	Response
EXIT LIGHT	
Battery Pack	
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 4
Violations	35671882X
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT/EMERGENCY LIGHT	Does not exist
TIRE ALARM SYSTEM	Inspected
Bell/Horn	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	3- Fair
Deficiency	DETECTOR NOT OPERATIONAL
Deficiency Location/Instance	Staircase B/Bulkhead
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	12136078X
CO Detector	Does not exist
Heat Detector	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Elevator Recall	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Magnetic Door Holder/Contactor	Inspected
Condition	3- Fair
Deficiency	CONTACTOR NOT OPERATIONAL
Deficiency Location/Instance	Corridor near Rooms 347B, 368
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	12136078X
Fused Cutout Panel	Inspected

Building Condition Assessment Survey 2023-2024

uestion	Response
	Кезронзе
FIRE ALARM SYSTEM Fused Cutout Panel	
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Notifier
Model	NFS - 640
EquipmentId	Interior Fire Alarm System
Installation Year	2005
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not exist
Sub-Panel	Does not exist
Remote Annunciator	Inspected
Display Monitor	Does not exist
Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	5- Poor
Deficiency	PRINTER NOT OPERATIONAL
Deficiency Location/Instance	Custodian's Office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Punch Register	Does not exist
Sprinkler Flow/Air Pressure Switch	Inspected 3- Fair
Condition	
Deficiency The Garden Control of the	No deficiencies recorded
Tamper Flow Switch/Chain Condition	Inspected 3- Fair
	No deficiencies recorded
Deficiency	
GROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
NTERCOM SYSTEM	Inspected
Elevator	Inspected
Condition	4- Between Fair and Poor
Deficiency	INTERCOM CABINET NOT OPERATIONAL
Deficiency Location/Instance	Elevator Device ID: 2P10750
Deficiency Quantity	1 EACH
Quantity Uom Potential Action	EACH

Building Condition Assessment Survey 2023-2024

*	
Question	Response
INTERCOM SYSTEM	
Elevator	
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Holding Area	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Inaccessible
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
PANEL BOARD	Inspected
Fused Disconnect Switch Type Condition	Inspected 3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance Deficiency Quantity	Boiler Room, Electrical Room, Basment
	5 FACH
Quantity Uom Potential Action	EACH REPLACE-UPGRADE
	PRIORITY 1
Urgency of Action Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type Condition	Inspected 3- Fair
Deficiency Deficiency Location/Instance	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Quantity	Electrical Room
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
	Inspected
Molded Case Circuit Breaker Type Condition	2- Between Good and Fair
Deficiency Deficiency Location/Instance	PANEL BOARD BEYOND USEFUL LIFE Outside Electrical Room
Deficiency Quantity	Outside Electrical Room 1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
i otelitiai Aetioii	PRIORITY 1
Urgancy of Action	FRIVALLE
Urgency of Action	
Urgency of Action Purpose of Action Violations	LEVEL 2 No violations recorded

Building Condition Assessment Survey 2023-2024

	pection		
Question		Response	
PUBLIC A	DDRESS SYSTEM		
	Instance	General Office - Room 131	
	Instance Condition	2- Between Good and Fair	
	Instance Quantity	1	
	Instance Quantity Uom	EACH	
	Model	Telecor II	
	Installation Year	2019	
	Source of Installation Year	Documented	
	Deficiency	No deficiencies recorded	
SECURIT	Y	Inspected	
IPDVS/C	CCTV System	Inspected	
Conditi	on	2- Between Good and Fair	
	Installation Year	2019	
	Source of Installation Year	Documented	
	Deficiency	No deficiencies recorded	
Intrusion	Alarm System	Inspected	
Centra	l Control Panel	Inspected	
	Instance	Fireman's Office Room B53	
	Instance Condition	3- Fair	
	Instance Quantity	1	
	Instance Quantity Uom	EACH	
	Model	Vista - 128B	
	Installation Year	2002	
	Source of Installation Year	Documented	
	Deficiency	No deficiencies recorded	
	d Sensor	Inspected	
Cond	ition	3- Fair	
	Deficiency	No deficiencies recorded	
Panic S		Inspected	
Cond		3- Fair	
	Deficiency	No deficiencies recorded	
	e Annunciator	Inspected	
Cond		3- Fair	
	Deficiency	No deficiencies recorded	
Siren/S		Inspected	
Cond		3- Fair	
	Deficiency	No deficiencies recorded	
Lighting	- Security	Inaccessible	
SERVICE	SWITCH	Inspected	
	Instance	Basement - Electrical Room	
	Instance Condition	3- Fair	
	Instance Quantity	1	
	Instance Quantity Uom	EACH	
	Manufacturer	Federal Pacific Electric	
	EquipmentId	Distribution Switchboard 'A'	
	Capacity/Size Quantity	1600	
	Capacity/Size UOM	Amps	
	Source of Capacity/Size	Nameplate	
	Installation Year	1970	
5	Source of Installation Year	Documented	
	Deficiency	BEYOND USEFUL LIFE	
	Deficiency Location/Instance	Basement - Electrical Room	
	Deficiency Quantity	1	
	Quantity Uom	EACH	
	Potential Action	REPLACE	

Building Condition Assessment Survey 2023-2024

rical Inspection	XII
Question	Response
SERVICE SWITCH	
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Basement - Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Federal Pacific Electric
EquipmentId	Distribution Switchboard 'B'
Capacity/Size Quantity	1600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1970
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance Deficiency Quantity	Basement - Electrical Room
	1
Quantity Uom	EACH DEDLACE
Potential Action	REPLACE DRIGHTY 1
Urgency of Action Purpose of Action	PRIORITY 1 LEVEL 2
Violations	
	No violations recorded
SWITCHBOARD	Inspected
Number of Spares	1
Fused Disconnect Switch Type	Inspected
Instance	Basement - Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Federal Pacific Electric
EquipmentId	N/A
Capacity/Size Quantity	1600
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate 1970
Installation Year Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Basement - Electrical Room
Deficiency Quantity	Basement - Electrical Room
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Basement - Electrical Room
	3- Fair
Instance Condition	
Instance Quantity	1 FACU
Instance Quantity Uom	EACH
Manufacturer	Federal Pacific Electric
EquipmentId	N/A
Capacity/Size Quantity	1600
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	2

Building Condition Assessment Survey 2023-2024

uestion	Response	
SWITCHBOARD		
Fused Disconnect Switch Type		
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Nameplate	
Installation Year	1970	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Basement - Electrical Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Fused Knife Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Does not exist	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	2- Between Good and Fair	<u> </u>
Deficiency	No deficiencies recorded	
TRANSFORMER	Does not exist	