### **Building Condition Assessment Survey 2023-2024**

**Electrical Inspection** X115

Asset:	I.S. 399 (OLD X HS/115) - BRONX, 120 EAST 184 STREET, BRONX, NY, 10468		
Inspection Id	Inspection Type	Time In	Last Edited
2375	ELECTRICAL	2024-01-12 07:49AM	2024-02-29 01:10PM

#### Asset Data

Question	Answer	
Have any Systems/Major Building Components been upgraded?	Systems:	IPDVS/CCTV System
	Years:	2023
	Systems:	Emergency Lighting (Battery Pack), Exit Lights (Battery Pack), LED Lighting (Auditorium, Staircases)
	Years: Systems:	2022 Fire Alarm System (Printer), Public Address System,
	Systems.	Local Sound System  Local Sound System
	Years:	2019
	Systems:	Intercom System (Elevator), LAN, Telephone System,
		Lighting - Security
	Years:	2018

Systems: Auditorium (Theatre Lighting System), Gymnasium (LED Lighting)

Years: 2015

Systems: Most Molded Case Circuit Breaker Panel Board

2014, 2007, 2000, 1990 Years:

Systems: Library Years:

Swimming Pool, Locker Room, Variable Frequency Systems: Drive

2013 Years:

Systems: Auditorium (Projection System)

Years:

Fire Alarm System, Lightning Protection Systems:

Years:

Systems:

Science Rooms, Surface Fluorescent Lighting,

Recessed Fluorescent Lighting, Auditorium

(Retrofitted Fluorescent Lighting), Retrofitted Pendant Fluorescent, Pendant Fluorescent Lighting (Kitchen,

Cafeteria)

Years:

Service Switch, Switchboard, Emergency Light/Exit Systems:

Light Panel 2000

Years:

Below Ground

Yes No

#### DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Does Interactive Whiteboard (IWB) Exist?

Water Penetration In Electrical Room?

DEDICATED INTERCOMS IN FIRE RESCUE AREAS	
Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in	No
your building?	

#### **Priority Condition**

Type of Service

Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
Yes	Grounding System - Defective	Grounding Bar connector completely detached from the water pipe.	Grounding System	Basement - Pool mechanical area	Raoul Velazquez	Fireman	

### **Building Condition Assessment Survey 2023-2024**

### **Electrical Inspection**

X115 Yes Fire Alarm System -Fire Alarm Sprinkler Flow Fire Alarm Basement -Raoul Fireman Components Not switch is deteriorated due System -Pool Velazquez Operational to chemicals in the room. Sprinkler Mechanical Flow/Air Area Pressure Switch Inspection Question Response Electrical Does not exist ATHLETIC FIELD AUDITORIUM Inspected Instance on 1st Floor Inspected **House Lighting** Instance on 1st Floor Inspected Does a Chandelier Exist? No **Lighting Fixture - Fluorescent** Instance on 1st Floor Inspected **Pendant Mounted** Instance on 1st Floor Does not exist **Surface Mounted** Instance on 1st Floor Inspected Instance Condition 3- Fair Deficiency No deficiencies recorded Recessed Mounted Instance on 1st Floor Does not exist Lighting Fixture - HID Instance on 1st Floor Does not exist **Lighting Fixture - Incandescent** Does not exist Instance on 1st Floor Lighting Fixture - LED Instance on 1st Floor Inspected

Pendant Mounted

Instance on 1st Floor Inspected 1- Good Instance Condition

Deficiency No deficiencies recorded **Surface Mounted** 

Instance on 1st Floor Does not exist

Recessed Mounted Instance on 1st Floor Inspected 1- Good

Instance Condition Deficiency No deficiencies recorded

**Local Sound System** Instance on 1st Floor Inspected

Instance Condition 2- Between Good and Fair 2019

Installation Year Source of Installation Year Documented

Deficiency No deficiencies recorded

**Projection System** Instance on 1st Floor

Instance Condition 3- Fair Is the projector on a cart or installed on the ceiling? Ceiling

Deficiency No deficiencies recorded Theater Lighting System

Instance on 1st Floor Inspected **Dimming System** 

Inspected

## **Building Condition Assessment Survey 2023-2024**

incui mspecuon		AIIS
Question	Response	
AUDITORIUM		
Theater Lighting System		
Dimming System		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Theater Lighting		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
CAFETERIA	Inspected	
Instance on 5th Floor	Inspected	
Lighting	1	
Instance on 5th Floor	Inspected	
Lighting Fixture - Fluorescent	1	
Instance on 5th Floor	Inspected	
Pendant Mounted	1	
Instance on 5th Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	1.0 442.14.14.14.14.14.14.14.14.14.14.14.14.14.	
Instance on 5th Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	100 deficiences recorded	
Instance on 5th Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
<u>-</u>	ivo deficiencies recorded	
Lighting Fixture - HID  Instance on 5th Floor	Does not exist	
	Does not exist	
Lighting Fixture - Incandescent  Instance on 5th Floor	Does not exist	
	Does not exist	
Lighting Fixture - LED  Instance on 5th Floor	December with	
	Does not exist	
Local Sound System  Instance on 5th Floor	Improposed	
Instance Condition	Inspected 2- Between Good and Fair	
Installation Year	2019	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System	1 to delicionetes recorded	
Instance on 5th Floor	Does not exist	
Theater Lighting System	Does not caus	
Instance on 5th Floor	Does not exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
	Inspected	
Lighting Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	3- Fair	
	No deficiencies recorded	
Deficiency	ino deliciencies recorded	

## **Building Condition Assessment Survey 2023-2024**

uestion	Resnance	
	Response	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE		
Lighting		
Lighting Fixture - Fluorescent		
Recessed Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
COMPUTER LAB	Does not exist	
GYMNASIUM	Inspected	
Instance on Basement	Inspected	
Lighting		
Instance on Basement	Inspected	
Lighting Fixture - Fluorescent		
Instance on Basement	Does not exist	
Lighting Fixture - HID		
Instance on Basement	Does not exist	
Lighting Fixture - Incandescent		
Instance on Basement	Does not exist	
Lighting Fixture - LED		
Instance on Basement	Inspected	
Pendant Mounted		
Instance on Basement	Does not exist	
Surface Mounted		
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE	
Deficiency Quantity	7	
Quantity Uom	EACH	
Potential Action	REPLACE BALLAST	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Recessed Mounted		
Instance on Basement	Does not exist	
Local Sound System		
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Installation Year	2019	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Basement	Does not exist	
Scoreboard		
Instance on Basement	Inspected	
Instance Condition	5- Poor	
Deficiency	NOT OPERATIONAL	
Deficiency Quantity	1	

# **Building Condition Assessment Survey 2023-2024**

Electrical Inspection	X115
Question	Response

incui inspection	Allo
Question	Response
GYMNASIUM	
Scoreboard	
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Theater Lighting System	
Instance on Basement	Does not exist
KITCHEN	Inspected
Instance on 5th Floor	Inspected
Lighting	
Instance on 5th Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 5th Floor	Inspected
Pendant Mounted	
Instance on 5th Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 5th Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	10 40100101010 10001400
Instance on 5th Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	No deficiencies recorded
Instance on 5th Floor	Does not exist
	Does not exist
Lighting Fixture - Incandescent  Instance on 5th Floor	Does not exist
-	Does not exist
Lighting Fixture - LED	Decreased society
Instance on 5th Floor	Does not exist
LIBRARY	Inspected
Instance on Room 112	Inspected
Lighting	
Instance on Room 112	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 112	Inspected
Pendant Mounted	
Instance on Room 112	Does not exist
Surface Mounted	
Instance on Room 112	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	
Instance on Room 112	Inspected
Instance Condition	2- Between Good and Fair

## **Building Condition Assessment Survey 2023-2024**

icui mspeciion		7111
uestion	Response	
LIBRARY		
Lighting		
Lighting Fixture - Fluorescent		-
Recessed Mounted		
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE	
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	REPLACE BALLAST	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Lighting Fixture - HID		
Instance on Room 112	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 112	Does not exist	
Lighting Fixture - LED		
Instance on Room 112	Does not exist	
Raceway With Receptacles		
Instance on Room 112	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Projection System	Two deficiencies recorded	
Instance on Room 112	Does not exist	
LOCKER ROOM	Inspected	
Instance on Basement - Boys, Basement - Girls	Inspected	
Alternative Use	No	
Lighting		
Instance on Basement - Boys, Basement - Girls	Inspected	
Lighting Fixture - Fluorescent		
Instance on Basement - Boys, Basement - Girls	Inspected	
Pendant Mounted		
Instance on Basement - Boys, Basement - Girls	Does not exist	
Surface Mounted		
Instance on Basement - Boys, Basement - Girls	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Basement - Boys, Basement - Girls	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE	
Deficiency Quantity	7	
Quantity Uom	EACH	
Potential Action	REPLACE BALLAST	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Lighting Fixture - HID		
Instance on Basement - Boys, Basement - Girls	Does not exist	
	DOG HOL CAISE	
Lighting Fixture - Incandescent	Door not aviet	
Instance on Basement - Boys, Basement - Girls	Does not exist	
Lighting Fixture - LED	<b>D</b>	
Lighting Fixture - LED  Instance on Basement - Boys, Basement - Girls  MULTIPURPOSE ROOM	Does not exist  Does not exist	

## **Building Condition Assessment Survey 2023-2024**

Electrical Inspection	X115

		7111
uestion	Response	
SCIENCE LAB	Inspected	
Instance on Room 307	Inspected	
Power Panel?	No	
Alternative Use	No	
Lighting		
Instance on Room 307	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 307	Inspected	
Pendant Mounted		
Instance on Room 307	Inspected	
Instance Condition	3- Fair	-
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 307	Does not exist	
Recessed Mounted		
Instance on Room 307	Does not exist	
Lighting Fixture - HID		
Instance on Room 307	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 307	Does not exist	
Lighting Fixture - LED	2000 1100 011100	
Instance on Room 307	Does not exist	
Emergency Gas Shut-Off Valve	2000 1100 011100	
Instance on Room 307	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power		
Instance on Room 307	Does not exist	
Power Supply		
Instance on Room 307	Inspected	
Instructor Unit	<u> </u>	
Instance on Room 307	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Meter Demonstration Unit		
Instance on Room 307	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Student Unit		
Instance on Room 307	Does not exist	
Projection System	2000 1100 011100	
Instance on Room 307	Does not exist	
SCIENCE PREP ROOM	Inspected	
Instance on Room 322A	Inspected	
Power Panel?		
	No	
Alternative Use	Yes	
Instance on Room 408A	Inspected	
Power Panel?	No	
Alternative Use	Yes	
Instance on Room 409	Inspected	
Power Panel?	Yes	
Alternative Use	Yes	
Instance on Room 314A	Inaccessible	

## **Building Condition Assessment Survey 2023-2024**

Electrical Inspection	All5	
Question	Response	

Question	Response
SCIENCE PREP ROOM	
Instance on Rooms: 204, 411	Inspected
Power Panel?	No
Alternative Use	Yes
Lighting	
Instance on Room 322A	Inspected
Instance on Room 408A	Inspected
Instance on Room 409	Inspected
Instance on Rooms: 204, 411	Inspected
Lighting Fixture - Fluorescent	•
Instance on Room 322A	Inspected
Instance on Room 408A	Inspected
Instance on Room 409	Inspected
Instance on Rooms: 204, 411	Inspected
Pendant Mounted	•
Instance on Room 322A	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 408A	Does not exist
Instance on Room 409	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Rooms: 204, 411	Does not exist
Surface Mounted	
Instance on Room 322A	Does not exist
Instance on Room 408A	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 409	Does not exist
Instance on Rooms: 204, 411	Does not exist
Recessed Mounted	
Instance on Room 322A	Does not exist
Instance on Room 408A	Does not exist
Instance on Room 409	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Rooms: 204, 411	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - HID	
Instance on Room 322A	Does not exist
Instance on Room 408A	Does not exist
Instance on Room 409	Does not exist
Instance on Rooms: 204, 411	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 322A	Does not exist
Instance on Room 408A	Does not exist
Instance on Room 409	Does not exist

## **Building Condition Assessment Survey 2023-2024**

······································		2111.
uestion	Response	
SCIENCE PREP ROOM		
Lighting		
Lighting Fixture - Incandescent		
Instance on Rooms: 204, 411	Does not exist	
Lighting Fixture - LED		
Instance on Room 322A	Does not exist	
Instance on Room 408A	Does not exist	
Instance on Room 409	Does not exist	
Instance on Rooms: 204, 411	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Room 322A	Does not exist	
Instance on Room 408A	Does not exist	
Instance on Room 409	Does not exist	
Instance on Rooms: 204, 411	Does not exist	
Emergency Shut-Off Power		
Instance on Room 322A	Does not exist	
Instance on Room 408A	Does not exist	
Instance on Room 409	Does not exist	
Instance on Rooms: 204, 411	Does not exist	
Power Supply		
Instance on Room 322A	Does not exist	
Instance on Room 408A	Does not exist	
Instance on Room 409	Does not exist	
Instance on Rooms: 204, 411	Does not exist	
SWIMMING POOL	Inspected	
Instance on Basement		
Lighting	Inspected	
Instance on Basement	Inspected	
Lighting Fixture - Fluorescent	nispected	
Instance on Basement	Inspected	
Pendant Mounted	inspected	
Instance on Basement	Does not exist	
Surface Mounted	BOGS HOL CAISU	
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Tu	
Instance on Basement	Inspected  2- Between Good and Fair	
Instance Condition	No deficiencies recorded	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on Basement	Does not exist	
Lighting Fixture - Incandescent		
Instance on Basement	Does not exist	
Lighting Fixture - LED		
Instance on Basement	Inspected	
Pendant Mounted		
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Basement	Does not exist	
Recessed Mounted		<del></del>
	Does not exist	<del></del>

## **Building Condition Assessment Survey 2023-2024**

rical Inspection		XIII
euestion	Response	
SWIMMING POOL		
Local Sound System		
Instance on Basement	Does not exist	
Scoreboard		
Instance on Basement	Does not exist	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Does not exist	
Recessed Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
FOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Does not exist	
Recessed Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	
	Does not exist	
EMERGENCY GENERATOR SET		
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EMERGENCY LIGHTING	Inspected	
Battery Pack	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Non Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EXIT LIGHT	Inspected	
Battery Pack	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Non Battery Pack	Does not exist	
EXIT/EMERGENCY LIGHT	Does not exist	
FIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Strobe	Inspected	

## **Building Condition Assessment Survey 2023-2024**

eui Inspection		7411
estion	Response	
IRE ALARM SYSTEM		
Strobe		
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
CO Detector	Does not exist	
Heat Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Elevator Recall	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Magnetic Door Holder/Contactor	Does not exist	
Fused Cutout Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Inspected	
Bell At Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Notifier	
Model	N/A	
EquipmentId	Fire Alarm Control Panel	
Installation Year	2010	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel	Does not exist	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Punch Register	Does not exist	

## **Building Condition Assessment Survey 2023-2024**

anca inspection	Allo
Question	Response
FIRE ALARM SYSTEM	
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	4- Between Fair and Poor
Deficiency	SWITCH NOT OPERATIONAL
Deficiency Location/Instance	Basement - Swimming Pool Mechanical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Tamper Flow Switch/Chain	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	4- Between Fair and Poor
Deficiency	DETACHED GROUND CONDUCTOR
Deficiency Location/Instance	Basement - Swimming Pool Mechanical Area
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
INTERCOM SYSTEM	Inspected
Elevator	Inspected 1- Good
Condition	
Deficiency	No deficiencies recorded
Holding Area	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
•	Inspected
Variable Frequency Drive  Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Does not exist
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	2- Between Good and Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Gymnasium, Rooms: 120, 408 and 409

## **Building Condition Assessment Survey 2023-2024**

cui Inspection	Ai
estion	Response
ANEL BOARD	
Molded Case Circuit Breaker Type	
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	CIRCUIT BREAKER NOT OPERATIONAL
Deficiency Location/Instance	Lower Gymnasium
Deficiency Quantity	22
Quantity Uom	EACH
Potential Action	REPLACE CIRCUIT BREAKER
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	Main Office - Room 116
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Bogen Multicom - 2000
Installation Year	2019
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<u>-</u>	Inspected
ECURITY INDIVISION OF THE PROPERTY OF THE PROP	Inspected
IPDVS/CCTV System Condition	1- Good
Installation Year	2023
Source of Installation Year	Documented
Deficiency	CAMERA NOT OPERATIONAL
Deficiency Location/Instance	Corridor: 1st, 3rd and 4th Floors
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
Intrusion Alarm System	Inspected Inspected
Central Control Panel	
Instance	Custodian's Office
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	4140 XMPT
Installation Year	1995
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Custodian's Office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 3
Violations	No violations recorded
Infrared Sensor	Inspected

## **Building Condition Assessment Survey 2023-2024**

<del></del>

# **Building Condition Assessment Survey 2023-2024**

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Swimming Pool - Mechanical Area
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	General Electric
EquipmentId	N/A
Capacity/Size Quantity	1200
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	2000
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
TRANSFORMER	Does not exist