Building Condition Assessment Survey 2023-2024

Electrical Inspection

Asset:	I.S. 117 - BRONX, 1865 MORRIS AVENUE, BRONX, NY, 10453		
Inspection Id	Inspection Type	Time In	Last Edited
1527	ELECTRICAL	2023-12-08 08:53AM	2024-06-12 10:33AM
sset Data			

Question Answer Systems: LAN Have any Systems/Major Building Components been upgraded? 2023 Years: Systems: Service Switch 2021, 1991 Years: Systems: Transformer 2021 Years: Systems: Exit Light Years: 2020, 2018 Systems: Auditorium (Local Sound System, Projection System) 2020 Years: Molded Case Circuit Breaker Type Panelboard Systems: 2018, 2015, 2007, 2000, 1998, 1991 Years: Systems: Science Lab and Prep Rooms (Except Lighting) Years: 2018 Partial Battery Park Type Emergency Lights Systems: (Auditorium, Gymnasium) Years: 2017 Public Address System Systems: 2016 Years: Security Lighting Systems: Years: 2015, 1991 4th Floor Gymnasium (Scoreboard) Systems: 2015 Years: Systems: Interior Fluorescent Lighting, Auditorium and Gymnasium LED Lighting, Intrusion Alarm System (Central Control Panel, Partial Remote Annunciator) Years: 2014 Systems: IPDVS/CCTV System 2013 Years: Systems: Telephone System Years: 2009 Systems: Switchboard, Fire Alarm System, Intrusion Alarm System (Except Central Control Panel, Partial Remote Annunciator), Auxiliary Signal/Bell System, Most Motor Starters, Emergency Light/Exit Light Panel, Auditorium (Theater Lights) Years: 1991 Below Ground Type of Service Does Interactive Whiteboard (IWB) Exist? Yes Water Penetration In Electrical Room? No **DEDICATED INTERCOMS IN FIRE RESCUE AREAS** Question Response Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in Yes your building? Are dedicated intercoms available in all of these spaces for use during a fire? No Which spaces do not have dedicated intercoms? Rooms 411, 311, 211 **Priority Condition** Exist Priority Condition Component Location Person(s) Person(s) Photo Last Year? Category Description Affected Description Notified Title Image

Building Condition Assessment Survey 2023-2024

Electrical Inspection

Yes	Fire Alarm System - Components Not Operational	N/A	Fire Alarm System - Magnetic Door Holder/Contac tor	Corridor near Room 125 and 2nd Floor Corridor	Alcindo Fernandes	Fireman	No Photo Taken
Yes	Fire Alarm System - Defective	N/A	Fire Alarm System	Boiler Room	Alcindo Fernandes	Fireman	No Photo Taken
Yes Inspect	Fire Alarm System - Defective	Sub Panels Visual Alarm Panel, Sprinkler Alarm and Smoke Detection Panel are in Trouble.	Fire Alarm System - Sub Panel	Boiler Room	Alcindo Fernandes	Fireman	
Ques				Response			
	trical			Каронас			
	HLETIC FIELD			Does not e	exist		
AU	DITORIUM			Inspected			
	Instance on 1st Floor			Inspected			
H	Iouse Lighting						

MIORICIM .		
Instance on 1st Floor	Inspected	
ouse Lighting		
Instance on 1st Floor	Inspected	
Does a Chandelier Exist?	Yes	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		

Building Condition Assessment Survey 2023-2024

Electrical Inspection

		АП
uestion	Response	
AUDITORIUM		
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Installation Year	2020	
Source of Installation Year	Custodial Staff	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Is the projector on a cart or installed on the ceiling?	Ceiling	
Deficiency	No deficiencies recorded	
Theater Lighting System		
Instance on 1st Floor	Inspected	
Dimming System	A	
Instance on 1st Floor	Does not exist	
Theater Lighting		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Deficiency Quantity	41	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
CAFETERIA	Inspected	
Instance on Basement	Inspected	
Lighting		
Instance on Basement	Inspected	
Lighting Fixture - Fluorescent		
Instance on Basement	Inspected	
Pendant Mounted	*	
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
	Incompated	
Instance on Basement	Inspected 2- Between Good and Fair	
Instance Condition		
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Basement	Does not exist	
Lighting Fixture - HID		
Instance on Basement	Does not exist	
Lighting Fixture - Incandescent		
Instance on Basement	Does not exist	
Lighting Fixture - LED		
Instance on Basement	Does not exist	
Local Sound System		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Installation Year	1991	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

rical Inspection	Al
Question	Response
CAFETERIA	
Local Sound System	
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Projection System	
Instance on Basement	Does not exist
Theater Lighting System	
Instance on Basement	Does not exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
COMPUTER LAB	Does not exist
GYMNASIUM	Inspected
Instance on 3rd Floor	Inspected
Instance on 4th Floor	Inspected
Lighting	
Instance on 3rd Floor	Inspected
Instance on 4th Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 3rd Floor	Does not exist
Instance on 4th Floor	Does not exist
Lighting Fixture - HID	
Instance on 3rd Floor	Does not exist
Instance on 4th Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 3rd Floor	Does not exist

Building Condition Assessment Survey 2023-2024

estion	Response
YMNASIUM	•
Lighting	
Lighting Fixture - Incandescent	
Instance on 4th Floor	Does not exist
Lighting Fixture - LED	
Instance on 3rd Floor	Inspected
Instance on 4th Floor	Inspected
Pendant Mounted	
Instance on 3rd Floor	Does not exist
Instance on 4th Floor	Does not exist
Surface Mounted	
Instance on 3rd Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	11
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on 4th Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3 LEVEL 2
Purpose of Action Violations	LEVEL 2 No violations recorded
	No violations recorded
Recessed Mounted	Does not exist
Instance on 3rd Floor	
Instance on 4th Floor	Does not exist
Local Sound System	Turner et al.
Instance on 3rd Floor	Inspected 3- Fair
Instance Condition Installation Year	1991
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Gymnasium-3rd Floor
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on 4th Floor	Inspected
Instance Condition	3- Fair
Installation Year	1991
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Gymnasium-4th Floor
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action Purpose of Action	PRIORITY 1
	LEVEL 2

Building Condition Assessment Survey 2023-2024

Juestion	Response	
GYMNASIUM		
Local Sound System		
Violations	No violations recorded	
Projection System		
Instance on 3rd Floor	Does not exist	
Instance on 4th Floor	Does not exist	
Scoreboard		
Instance on 3rd Floor	Does not exist	
Instance on 4th Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Theater Lighting System		
Instance on 3rd Floor	Does not exist	
Instance on 4th Floor	Does not exist	
KITCHEN	Inspected	
Instance on Basement	Inspected	
Lighting	*	
Instance on Basement	Inspected	
Lighting Fixture - Fluorescent		
Instance on Basement	Inspected	
Pendant Mounted	A	
Instance on Basement	Does not exist	
Surface Mounted		
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on Basement	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Instance on Basement	Does not exist	
Lighting Fixture - LED		
Instance on Basement	Does not exist	
LIBRARY	Inspected	
Instance on Room 315	Inspected	
	hispected	
Lighting Instance on Room 315	Inspected	
Lighting Fixture - Fluorescent	hispeeted	
Instance on Room 315	Inspected	
Pendant Mounted	hispected	
Instance on Room 315	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
	No deficicies recorded	
Surface Mounted Instance on Room 315	Does not exist	
	Does not exist	
Recessed Mounted	Doos not evict	
Instance on Room 315	Does not exist	
Lighting Fixture - HID	Door not eviat	
Instance on Room 315	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 315	Does not exist	

Building Condition Assessment Survey 2023-2024

Duestion	Response	
LIBRARY	Ксэронэс	
Lighting Fixture - LED		
Instance on Room 315	Does not exist	
Raceway With Receptacles		
Instance on Room 315	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Room 315	Does not exist	
LOCKER ROOM	Inspected	
Instance on 4th Floor - Boys, 3rd Floor - Girls	Inaccessible	
MULTIPURPOSE ROOM	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Inspected	
Instance on Rooms 221, 319, 419	Inspected	
Power Panel?	Yes	
Alternative Use	No	
Lighting		
Instance on Rooms 221, 319, 419	Inspected	
Lighting Fixture - Fluorescent	Turner et el	
Instance on Rooms 221, 319, 419	Inspected	
Pendant Mounted	Tu un este d	
Instance on Rooms 221, 319, 419	Inspected 2- Between Good and Fair	
Instance Condition	No deficiencies recorded	
Deficiency	No deficiencies recorded	
Surface Mounted	Does not exist	
Instance on Rooms 221, 319, 419		
Recessed Mounted Instance on Rooms 221, 319, 419	Does not exist	
	Does not exist	
Lighting Fixture - HID Instance on Rooms 221, 319, 419	Does not exist	
Lighting Fixture - Incandescent Instance on Rooms 221, 319, 419	Inspected	
Pendant Mounted	inspected	
Instance on Rooms 221, 319, 419	Does not exist	
Surface Mounted		
Instance on Rooms 221, 319, 419	Inspected	
Instance Condition	3- Fair	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Deficiency Quantity	6	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Recessed Mounted		
Instance on Rooms 221, 319, 419	Does not exist	
Lighting Fixture - LED		
Instance on Rooms 221, 319, 419	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Rooms 221, 319, 419	Does not exist	
Emergency Shut-Off Power		
Instance on Rooms 221, 319, 419	Inspected	

Building Condition Assessment Survey 2023-2024

Desmonae	X11
Response	
1 Good	
No deliciencies recorded	
Inspected	
Inspected	
Inspected	
-	
Insuranted	
No deficiencies recorded	
Does not exist	
Inspected	
No	
No	
Inspected	
Inspected	
Inspected	
2- Between Good and Fair	
No deficiencies recorded	
Does not exist	
Does not exist	
Does not exist	
Does not exist	
Does not evist	
Does not exist	
Inspected	
Doos not avist	
Inspected	
Inspected	
Inspected Inspected	
	No No Inspected Inspected Inspected 2- Between Good and Fair No deficiencies recorded Does not exist Does not exist <

Building Condition Assessment Survey 2023-2024

Electrical Inspection

trical Inspection	XI
Question	Response
TOILET ROOM - STAFF	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
	Inspected
EMERGENCY LIGHT/EXIT LIGHT PANEL	3- Fair
Condition	
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance Deficiency Quantity	Gymnasiums 7
Quantity Uom	7 EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 4
Violations	35654604L
Totatons	35557695L
EXIT LIGHT	Inspected
	Inspected
Battery Pack Condition	1- Good
Deficiency	No deficiencies recorded
Non Battery Pack	Does not exist
A STATE AND A STATE AN	

NYC Department of Education Building Condition Assessment Survey 2023-2024

Electrical Inspection

icui Inspeciion	ΛΙ
estion	Response
TRE ALARM SYSTEM	Inspected
Bell/Horn	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	3- Fair
Deficiency	PULL STATION COVER IS MISSING
Deficiency Location/Instance	Corridor near Rooms 323, 423, Auditorium Stage
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	INSTALL COVER
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fan Shutdown Control	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected 3- Fair
Condition	
Deficiency	No deficiencies recorded
CO Detector	Does not exist
Heat Detector	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Elevator Recall	Does not exist
Magnetic Door Holder/Contactor	Inspected
Condition	5- Poor
Deficiency	CONTACTOR NOT OPERATIONAL
Deficiency Location/Instance	Corridor near Rooms 125 and 2nd Floor Corridor
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
	Inspected
Fused Cutout Panel Condition	3- Fair
	No deficiencies recorded
Deficiency	
Fire Alarm Digital Communicator	Does not exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Boiler Room
Instance Condition	4- Between Fair and Poor
Instance Quantity	1
	EACH
Instance Quantity Uom	
Manufacturer	Fire Control Instruments

Building Condition Assessment Survey 2023-2024

Electrical Inspection

ui Inspection		
stion	Response	
RE ALARM SYSTEM		
Main Panel		
Fire Alarm Control Panel (Electronic)		
Model	BMFC-6	
EquipmentId	Fire Alarm Panel	
Installation Year	1991	
Source of Installation Year	Documented	
Deficiency	SYSTEM DEFECTIVE	
Deficiency Quantity	115,000	
Quantity Uom	S.F.	
Potential Action	REPLACE SYSTEM	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	E631265	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel	Inspected	
Bell At Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Boiler Room	
Instance Condition	4- Between Fair and Poor	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Fire Control Instruments	
Model	BMFC-6	
EquipmentId	Visual Alarm Panel	
Installation Year	1991	
Source of Installation Year	Documented	
Deficiency	PANEL DEFECTIVE	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPAIR	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	E631265	
Instance	Boiler Room	
Instance Condition	4- Between Fair and Poor	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Fire Control Instruments	
Model	BMFC-6	
EquipmentId	Sprinkler Alarm	
Installation Year	1991	
Source of Installation Year	Documented	
Deficiency	PANEL DEFECTIVE	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPAIR	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	E631265	
Instance	Boiler Room	
Instance Condition	4- Between Fair and Poor	
Instance Quantity	1	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

iestion	Response	
FIRE ALARM SYSTEM		
Sub-Panel		
Fire Alarm Control Panel (Electronic)		
Manufacturer	Fire Control Instruments	
Model	BMFC-6	
EquipmentId	Smoke Detection Panel	
Installation Year	1991	
Source of Installation Year	Documented	
Deficiency	PANEL DEFECTIVE	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPAIR	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	E631265	
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Fire Control Instruments	
Model	BMFC-6	
EquipmentId	Smoke Detection Panel	
Installation Year	1991	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Does not exist	
Printer	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Punch Register	Does not exist	
Sprinkler Flow/Air Pressure Switch	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Tamper Flow Switch/Chain	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
GROUNDING SYSTEM	Inspected	
Condition	3- Fair	
	No deficiencies recorded	
Deficiency		
NTERCOM SYSTEM	Does not exist	
LAN	Inspected	
Local Distribution Frame (I/LDF)	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Main Equipment Rack (MDF)	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
	Does not exist	
LIGHTNING PROTECTION		
LIGHTNING PROTECTION MOTOR CONTROLLER	Inspected	
LIGHTNING PROTECTION MOTOR CONTROLLER MOTOR CONTROL CENTER	Inspected Does not exist	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

	ΛΙ
estion	Response
10TOR CONTROLLER	
MOTOR STARTER/CONTACTOR	
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not exist
ANEL BOARD	Inspected
Fused Disconnect Switch Type	Does not exist
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
UBLIC ADDRESS SYSTEM	Inspected
Instance	General Office - Room 209
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Biamp MPA250
Installation Year	2016
Source of Installation Year	Documented
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Corridors
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
ECURITY	Inspected
IPDVS/CCTV System	Inspected 2- Between Good and Fair
Condition	
Installation Year	
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office - Room 102
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista 128BPT
Installation Year	2014
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected

Building Condition Assessment Survey 2023-2024

uestion		Response
SECURITY	/	
	Alarm System	
Siren/St	•	
Condit		3- Fair
Ī	Deficiency	No deficiencies recorded
Lighting -	-	Inspected
Conditio		3- Fair
-	Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
1	Deficiency Location/Instance	Building Perimeters
	Deficiency Quantity	14
	Quantity Uom	EACH
	Potential Action	REPLACE-UPGRADE
	Urgency of Action	PRIORITY 1
	Purpose of Action	LEVEL 3
	Violations	No violations recorded
SERVICE S	SWITCH	Inspected
-	nstance	Electrical Room
-	nstance Condition	1- Good
-	nstance Quantity	1
-		EACH
-	nstance Quantity Uom	
	Manufacturer	Square D
	EquipmentId	89L - Solar Generator Disconnect Switch 1 400
	Capacity/Size Quantity	
	Capacity/Size UOM Source of Capacity/Size	Amps Nameplate
-	nstallation Year	2021
	Source of Installation Year	Documented
-	Deficiency	No deficiencies recorded
-	nstance	Electrical Room
-	Instance Condition	3- Fair
	nstance Quantity	
-		l EACH
-	nstance Quantity Uom	
	Manufacturer	Siemens
	EquipmentId	Service Disconnect
	Capacity/Size Quantity Capacity/Size UOM	2000
	Source of Capacity/Size	Amps Nameplate
-	installation Year	1991
	Source of Installation Year	Documented
-	Deficiency	No deficiencies recorded
SWITCHB		Inspected
		2
Number of	-	Z Inspected
-	connect Switch Type	Electrical Room
-	nstance Condition	3- Fair
-		
-	nstance Quantity	
-	nstance Quantity Uom	EACH
	Manufacturer	Siemens
	EquipmentId	N/A
	Capacity/Size Quantity	2000
	Capacity/Size UOM	Amps Total
	Capacity/Size 2 Quantity	
	Capacity/Size 2 UOM	Section(s)
-	Source of Capacity/Size	Service Switch Size
	nstallation Year Source of Installation Year	Documented

Building Condition Assessment Survey 2023-2024

Electrical Inspection

uestion	Response	
SWITCHBOARD		
Fused Disconnect Switch Type		
Deficiency	No deficiencies recorded	
Fused Knife Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Does not exist	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
TRANSFORMER	Inspected	
Instance	Electrical Room	
Instance Condition	1- Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Hammond	
EquipmentId	N/A	
Capacity/Size Quantity	150	
Capacity/Size UOM	kVA	
Source of Capacity/Size	Nameplate	
Installation Year	2021	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	