Building Condition Assessment Survey 2023-2024

Mechanical Inspection X118

Asset:	I.S. 118 - BRONX, 577 EAST 179 STREET, BRONX, NY, 10457		
Inspection Id	Inspection Type	Time In	Last Edited
1759	MECHANICAL	2023-12-18 07:51AM	2024-01-10 12:30PM
1 1 D . 1 .			

Asset Data Question Answer Fixtures - Toilets (~70%); Boiler Fresh Air Systems: Have any Systems/Major Building Components been upgraded? Louver/Dampers Years: Systems: Steam Condensate Return Pumping System; CO/Gas Leak Detection System Years: Water Service refurbished (1 of 2) Systems: Years: Systems: Gas Fired Domestic Water Heater; Domestic Hot Water Remote Storage Tank Years: 2019 Electric Domestic Water Heater for Kitchen Systems: Years: Systems: Fixtures - Toilets (~30%); Terminal Unit Thermostatic Traps (~90%) Years: 2016 Sprinkler Heads (~50%); Sump Pumps (2 of 4)

Systems:

Years:

Are there fuel tanks? Yes Total # of above ground tanks Total capacity of all above ground tanks in gal. 5,000 0 Total # of below ground tanks Total capacity of all below ground tanks in gal. 0 Total # of water main service entries to the asset

MERs/Fan Rooms Locations Basement Mechanical Area; Cafeteria - MER

Are there any spaces with Missing or Defective CO Detectors? No Are there any Painted/Obstructed Sprinkler Heads? Location(s)

Basement - Storage Rooms; Rooms 107, 109, 227, 233, 423

(painted, 40) Are there any Emergency Stop Switches with Missing Hammers? No components

Priority Condition

Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
No	Defective Boiler Safety Auxiliary	Defective Water Column's Try Cock	Steam Boiler	Boiler Room / Boiler #1	zaheer Kalamadee n	Custodian	

Inspection	
Question	Response
Mechanical	
AIR CONDITIONING	Inspected
Chilled Water System	Does not exist
Condenser Water Distribution: Piping, Pumps and Auxiliaries	Does not exist
Cooling Coil in Ductwork	Does not exist
Cooling Tower	Does not exist
DX Split System	Inspected
Indoor Unit	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded

Building Condition Assessment Survey 2023-2024

unicui inspecuon	Allo
Question	Response
AIR CONDITIONING	
DX Split System	
Outdoor Unit	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Dry Cooler	Does not exist
Packaged / Rooftop Unit	Does not exist
Packaged Terminal A/C	Does not exist
Refrigerant Leak Detection System	Does not exist
Refrigerant Piping	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Return Fan	Does not exist
CENTRAL ACID WASTE NEUTRALIZING TANK	Does not exist
CLIMATE CONTROL SYSTEM	Inspected
BMS	Does not exist
Pneumatic System	Does not exist
Hybrid System	Does not exist
Electric System	Inspected
Instance	Throughout (Heat Timer System)
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Building Area Covered by Operational System	81-100%
Deficiency	No deficiencies recorded
Instance	Cafeteria, Multi-Purpose Room, Gymnasiums, Auditorium
	(Supply Fans preheat/re-heat coils controls)
Instance Condition	4- Between Fair and Poor
Instance Quantity	1
Instance Quantity Uom	EACH
Building Area Covered by Operational System	0-20%
Deficiency	DEFECTIVE TEMPERATURE CONTROL ZONE VALVE
Deficiency Location/Instance	Basement Mechanical Area; Cafeteria - MER
Deficiency Quantity	12
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
COMPACTOR	Does not exist
CONVEYING	Inspected
Dumbwaiter	Does not exist
Elevator	Inspected
Condition	3- Fair
Are all the existing elevators operable?	Yes
Deficiency	No deficiencies recorded
Escalator	Does not exist
Non-auditorium Handicap Lift - Vertical	Does not exist
Non-auditorium Handicap Lift - Stair	Does not exist
Ash Hoist	Does not exist
Sidewalk Elevator	Does not exist
DOMESTIC WATER SYSTEM	Inspected
Domestic Cold Water System	Inspected
Gravity System	Does not exist
Pressure Booster System	Does not exist

Building Condition Assessment Survey 2023-2024

Response
Inspected
Basement Mechanical Area
3- Fair
1
EACH
WATER MAIN:MISSING BACKFLOW PREVENTION DEVICE
Basement Mechanical Area
1
EACH
INSTALL
PRIORITY 3
LEVEL 2
No violations recorded
Boiler Room
2- Between Good and Fair
1
EACH
WATER MAIN:MISSING BACKFLOW PREVENTION
DEVICE
Boiler Room
1 Digit
EACH INSTALL
PRIORITY 3 LEVEL 2
No violations recorded
Inspected
Inspected
1- Good
No deficiencies recorded
Inspected
3- Fair
NOT IN USE
Basement - Crawlspace
1
EACH
NO ACTION
PRIORITY 1
LEVEL 1
No violations recorded
Inspected
2- Between Good and Fair
No deficiencies recorded
Inspected
Boiler Room
1- Good
1
EACH
Lochinvar
Lochinvar N/A
N/A 500
500

Building Condition Assessment Survey 2023-2024

unicui Inspection		XIIO
uestion	Response	
DOMESTIC WATER SYSTEM		
Domestic Hot Water System		
Gas Fired Domestic Water Heater		
Capacity/Size 2 Quantity	0	
Capacity/Size 2 UOM	Gallons	
Source of Capacity/Size	Documented	
Installation Year	2019	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Oil Fired Domestic Water Heater	Does not exist	
Heat Pump Domestic Water Heater	Does not exist	
Domestic Water Distribution Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected	
Interior Storm Piping	Inspected	
Condition	3- Fair	
	No deficiencies recorded	
Deficiency		
Sewage/Waste/Vent Piping	Inspected 3- Fair	
Condition		
Deficiency	SEWAGE/WASTE PIPING:DEFECTIVE/LEAKS	
Deficiency Location/Instance	Basement Mechanical Area	
Deficiency Quantity	10	
Quantity Uom	L.F.	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Deficiency	SEWAGE/WASTE PIPING:DEFECTIVE VALVE	
Deficiency Location/Instance	Boiler Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Sewage Ejector Pump	Does not exist	
Sump Pump	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist	
FIXTURES	Inspected	
Staff And Other	Inspected	
Janitor Sink	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lavatory/Sink	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Toilet	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Urinal	Does not exist	
Student	Inspected	
Stutent	пореска	

Building Condition Assessment Survey 2023-2024

inical Inspection	Al
nestion	Response
FIXTURES	
Student	
Drinking Fountain	
Condition	3- Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Locker Room Shower	Inspected
Instance on 4th Floor	Inaccessible
Sink And Fountain Combo Unit	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
	Inspected
Toilet	
Condition	1- Good
Deficiency	No deficiencies recorded
Urinal	Inspected
Condition	3- Fair
Deficiency	CRACKED/PHYSICAL DAMAGE
Deficiency Location/Instance	1st Floor Boy's Toilet Room
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
GAS FIRED FURNACE	Does not exist
GAS SERVICE	Inspected
Gas Distribution Piping	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Gas Meter Room Exhaust Fan	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Gas Meter Room Vent	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Gas Pressure Booster	Inspected
Instance	Basement - Gas Meter Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
	Eclipse
Manufacturer	N/A
EquipmentId	
Capacity/Size Quantity	18000
Capacity/Size UOM	SCFH Decomposited
Source of Capacity/Size Installation Year	Documented 2003
Installation Year Source of Installation Year	Documented
Deficiency	No deficiencies recorded
CO/Gas Leak Detection	Inspected
Instance	Basement - Gas Meter Room, Boiler Room
Instance Condition	1- Good

Building Condition Assessment Survey 2023-2024

estion	Response
GAS SERVICE	
CO/Gas Leak Detection	T. OV
Instance Quantity Uom	EACH
Installation Year	2021
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
EATING	Inspected
Heating Coil In Ductwork	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Hydronic Heating	Does not exist
Radiator/Convector/Fin Tube	Inspected
Condition	3- Fair
Deficiency	AUXILIARY (VALVE, VENT): DEFECTIVE
Deficiency Location/Instance	Stairs "F/2", "F/4", and other locations
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	RADIATOR/CONVECTOR:MISSING GUARD/SHIELD
Deficiency Location/Instance	Rooms 207, 406, 420, 427, 428, 430
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Heating	Inspected
F&T/Steam Drip Trap	Inspected
Condition	5- Poor
Deficiency	DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Basement Mechanical Area; Cafeteria - MER and other locations
Deficiency Quantity	40
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
MER Steam and Condensate Piping	Inspected
Condition	2- Between Good and Fair
Deficiency	DEFECTIVE/LEAKS
•	
Deficiency Location/Instance Deficiency Quantity	Basement Mechanical Area 10
	L.F.
Quantity Uom	
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Condensate Return Piping	Inspected
Condition	3- Fair
Deficiency	DAMAGED/MISSING INSULATION
Deficiency Location/Instance	Basement Mechanical Area
Deficiency Quantity	40
Quantity Uom	L.F.

Building Condition Assessment Survey 2023-2024

unicui Inspection		
uestion	Response	
HEATING		
Steam Heating		
Steam Condensate Return Piping		
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Steam Condensate Return Pumping System	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Steam Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Terminal Unit Thermostatic Trap	Inspected	
Condition	2- Between Good and Fair	
	DEFECTIVE/DETERIORATED	
Deficiency Deficiency Location/Instance	Various Locations	
Deficiency Quantity	various Locations 20	
Quantity Uom	EACH DEPLACE	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Steam supplied by External Sources	Does not exist	
Unit Heater/Cabinet Heater	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
HEATING PLANT	Inspected	
Instance on Basement	Inspected	
Is there a water meter on the boiler make-up water piping?	Yes	
Observed Operational?	No	
Burner Manufacturer	John Zink Company	
Burner Model	FL 12.1-160-50	
Burner Type	Dual Fuel (Gas/Oil)	
Heating Plant Oil Number	2	
Boiler Auxiliaries		
Instance on Basement	Inspected	
Boiler Auxiliary Piping		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	DEFECTIVE BLOWDOWN PIPING	
Deficiency Location/Instance	Boiler Room @ Boilers #1, #2	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
	LEVEL 2	
Purpose of Action		
Violations	No violations recorded	
Boiler Emergency Stop Switch	T 1	
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler Feedwater System		
Instance on Basement	Inspected	
	3- Fair	

Building Condition Assessment Survey 2023-2024

X118

Question	Response	
HEATING PLANT		
Boiler Auxiliaries		

ATING PLANT	
oiler Auxiliaries	
Boiler Feedwater System	
Deficiency	No deficiencies recorded
Boiler Feedwater Treatment(Automatic)	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Flue Exhaust	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Make-up Water Backflow Preventer	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Room Steam And Condensate Piping	110 401101010101010101
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
-	No deficiences recorded
Boiler Safety Valve Instance on Basement	Inspected
	3- Fair
Instance Condition	
Deficiency	No deficiencies recorded
piler System	
Instance on Basement	Inspected
Coal-fired Boiler	
Instance on Basement	Does not exist
Hot Water Boiler	
Instance on Basement	Does not exist
Modular Boiler	
Instance on Basement	Does not exist
Steam Boiler	
Instance on Basement	Inspected
Instance on Basement	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	4,299
Instance Quantity Uom	MBH NET
Cast Iron Boiler?	No
Manufacturer	A. L. Eastmond & Sons Inc.
EquipmentId	6082-01
Capacity/Size Quantity	4299
Capacity/Size UOM	MBH Net
Source of Capacity/Size	Documented
Installation Year	2003
Source of Installation Year	Documented
Deficiency	DEFECTIVE SAFETY AUXILIARY: LOW-WATER CUT-OFF, WATER COLUMN ASSEMBLY
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded

Building Condition Assessment Survey 2023-2024

Mechanical Inspection	Allō

uestion	Response	
HEATING PLANT		
Boiler System		
Steam Boiler		
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity	4,299	
Instance Quantity Uom	MBH NET	
Cast Iron Boiler?	No	
Manufacturer	A. L. Eastmond & Sons Inc.	
EquipmentId	6082-02	
Capacity/Size Quantity	4299 MDH N	
Capacity/Size UOM Source of Capacity/Size	MBH Net Documented	
Installation Year	2003	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fuel System		
Instance on Basement	Inspected	
Boiler Fresh Air Louver/Damper		
Instance on Basement	Inspected	
Instance Condition	1- Good	
Туре	Automatic	
Deficiency	No deficiencies recorded	
Burner/Burner Control Panel		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fuel Oil Storage/Supply System		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Gas Trains And Vent At The Boiler	No deficiences recorded	
Instance on Basement	Inspected	
Instance Condition	3- Fair	
	No deficiencies recorded	
Deficiency		
Enclosed IDF Room	Inspected	
Instance on Room 406	Inspected	
Dedicated A/C Equipment		
Instance on Room 406	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
KITCHEN	Inspected	
Instance on Basement	Inspected	
CO Detector		
Instance on Basement	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Gas System		
Instance on Basement	Does not exist	
Grease Trap		
Instance on Basement	Inspected	
Instance Condition	3- Fair	

Building Condition Assessment Survey 2023-2024

иниси твресион		
duestion	Response	
KITCHEN		
Hood		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hood Exhaust Ductwork		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hood Exhaust Fan		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hood Fire Suppression System		
Instance on Basement	Does not exist	
Hot Water Temperature Booster		
Instance on Basement	Does not exist	
Kitchen Sink		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
MDF Room	Inspected	
Instance on Room 225A	Inspected	
Dedicated A/C Equipment	•	
Instance on Room 225A	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
SCIENCE DEMO ROOM	Inspected	
Instance on Room 423	Inspected	
Alternative Use	Yes	
Acid Waste Neutralizing Tank	165	
Instance on Room 423	Does not exist	
CO Detector	2000 100 0.1100	
Instance on Room 423	Not required	
Emergency Shower	1	
Instance on Room 423	Does not exist	
Eye Wash		
Instance on Room 423	Does not exist	
Hood Exhaust Ductwork		
Instance on Room 423	Does not exist	
Hood Exhaust Fan		
Instance on Room 423	Does not exist	
Fixed Laboratory Hood		
Instance on Room 423	Does not exist	
Laboratory Sink		
Instance on Room 423	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Make-up Air Unit		
Instance on Room 423	Does not exist	
SCIENCE LAB	Inspected	
Instance on Room 419	Inspected	
Alternative Use	No	
Acid Waste Neutralizing Tank	110	

Building Condition Assessment Survey 2023-2024

	111
uestion	Response
SCIENCE LAB	
Acid Waste Neutralizing Tank	
Instance on Room 419	Does not exist
CO Detector	
Instance on Room 419	Not required
Emergency Shower	1
Instance on Room 419	Does not exist
Eye Wash	Does not const
Instance on Room 419	Does not exist
Hood Exhaust Ductwork	
Instance on Room 419	Does not exist
Hood Exhaust Fan	DOG NOT CALST
Instance on Room 419	Does not exist
	DOGS HOL CAISE
Fixed Laboratory Hood Instance on Room 419	Does not exist
	Does not exist
Laboratory Sink Instance on Room 419	
	Inspected 3- Fair
Instance Condition	
Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF
Deficient Leading Action	VALVE,ETC.) Room 419
Deficiency Location/Instance Deficiency Quantity	4 4
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
	140 VIOIALIOIIS IECOIAEA
Make-up Air Unit Instance on Room 419	Does not exist
SCIENCE PREP ROOM	Inspected
Instance on Room 414	Inaccessible
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected
Dry Sprinkler Alarm Valve Assembly	Does not exist
Wet Sprinkler Alarm Valve Assembly	Does not exist
Fire Booster Pump Assembly	Does not exist
Roof Tank	Does not exist
Siamese Connection	Does not exist
Sprinkler Head	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Basement - Storage Rooms; Rooms 107, 109, 227, 233, 423
	(painted, 40)
Deficiency Quantity	40
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Sprinkler Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Standpipe System	Does not exist
	Does not exist
Water Gong	Does not exist
Water Gong SWIMMING POOL	Does not exist

Building Condition Assessment Survey 2023-2024

estion	Response
ENTILATION	
Exhaust Fan	Inspected
Condition	3- Fair
Approximate Total # of Fans	1-25
Deficiency	No deficiencies recorded
Heating And Ventilating Unit	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Metal Ductwork	Inspected
Condition	3- Fair
Are there any uninsulated ductwork by design in Mechanical rooms?	Yes
Are there chain operated dampers?	No
Deficiency	DEFECTIVE REGISTER/DIFFUSER
Deficiency Location/Instance	Gymnasiums
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Supply Fan	Inspected
Condition	3- Fair
Approximate Total # of Fans	1-5
Deficiency	No deficiencies recorded
Unit Ventilator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded