#### **Building Condition Assessment Survey 2023-2024**

Electrical In	spection	X126
Asset:	P.S. 126 (ECF) - BRONX, 175 WEST 166 STREET, BRONX, NY, 10452	

Inspection Id	Inspection Type		Time In	Last Edited
3865	ELECTRICAL		2024-03-11 08:02AM	2024-04-04 02:17PM
sset Data				
Question		Answer		
Have any Syste	ms/Major Building Components been upgraded?	Systems:	IPDVS/CCTV System, Most Sec	curity Lights
		Years:	2023	
		Systems:	Public Address System (Amplific	er)
		Years:	2022	
		Systems:	Partial Molded Case Circuit Brea	aker Type Panel Board
		Years:	2021, 2014, 2000, 1999	
		Systems:	Partial Fused Disconnect Switch	oard
		Years:	2018	
		Systems:	Emergency Light/Exit Light Pane	el, Partial Emergency
			Lighting (Battery Pack), Telepho	ne System, LAN
		Years:	2016	
		Systems:	Interior Lighting, Local Sound S	ystem, Auditorium
			(Projection System)	
		Years:	2015	

Systems: Computer Lab (Raceways with Receptacles)
Years: 2014

Systems: Public Address System (Tuner) Years: 2003

Systems: Intrusion Alarm System Years: 1999

Below Ground Yes No

#### DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Does Interactive Whiteboard (IWB) Exist?

Water Penetration In Electrical Room?

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in	No
your building?	

#### **Priority Condition**

Type of Service

Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
Yes	Emergency Lighting - Not Operational	70% of the Batteries are not Operational.	Emergency Lighting	Throughout the Building	Alberto Hernandez	Handyman	No Photo Taken

#### Inspection

estion	Response	
etrical		
THLETIC FIELD	Does not exist	
UDITORIUM	Inspected	
Instance on 1st Floor	Inspected	
House Lighting		
Instance on 1st Floor	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		

### **Building Condition Assessment Survey 2023-2024**

Electrical Inspection	<b>y</b>	X126
0 4:	n.	

estion	Response
LUDITORIUM	
House Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	Descript mist
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Installation Year	2015
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Is the projector on a cart or installed on the ceiling?	Ceiling
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Does not exist
Theater Lighting	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	66
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
CAFETERIA	Inspected
Instance on 1st Floor - Large	Inspected
Instance on 1st Floor - Small	Inspected
Lighting	
Instance on 1st Floor - Large	Inspected
Instance on 1st Floor - Small	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor - Large	Does not exist
Instance on 1st Floor - Small	Inspected

### **Building Condition Assessment Survey 2023-2024**

Electrical InspectionX126QuestionResponse

	n	
Question	Response	
CAFETERIA		
Lighting		
Lighting Fixture - Fluorescent		
Pendant Mounted		
Instance on 1st Floor - Small	Does not exist	
Surface Mounted		
Instance on 1st Floor - Small	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor - Small	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor - Large	Does not exist	
Instance on 1st Floor - Small	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor - Large	Does not exist	
Instance on 1st Floor - Small	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor - Large	Inspected	
Instance on 1st Floor - Small	Does not exist	
Pendant Mounted		
Instance on 1st Floor - Large	Does not exist	
Surface Mounted		
Instance on 1st Floor - Large	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor - Large	Does not exist	
Local Sound System		
Instance on 1st Floor - Large	Inspected	
Instance Condition	2- Between Good and Fair	
Installation Year	2015	
Source of Installation Year	Custodial Staff	
Deficiency	No deficiencies recorded	
Instance on 1st Floor - Small	Does not exist	
Projection System		
Instance on 1st Floor - Large	Does not exist	
Instance on 1st Floor - Small	Does not exist	
Theater Lighting System		
Instance on 1st Floor - Large	Does not exist	
Instance on 1st Floor - Small	Does not exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	

### **Building Condition Assessment Survey 2023-2024**

ctrical inspection		X126
Question	Response	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE		
Lighting		
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
COMPUTER LAB	Inspected	
Instance on Room 240	Inspected	
Power Panel?	Yes	
Lighting		
Instance on Room 240	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 240	Inspected	
Pendant Mounted		
Instance on Room 240	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 240	Does not exist	
Recessed Mounted		
Instance on Room 240	Does not exist	
Lighting Fixture - HID		
Instance on Room 240	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 240	Does not exist	
Lighting Fixture - LED		
Instance on Room 240	Does not exist	
Raceway With Receptacles		
Instance on Room 240	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
GYMNASIUM	Inspected	
Instance on 1st Floor	Inspected	
Lighting	порессе	
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent	персота	
Instance on 1st Floor	Inspected	
Pendant Mounted	1	
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID	Does not exist	
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Instance on 1st Floor	Does not exist	
	Does not exist	
Lighting Fixture - LED  Instance on 1st Floor	Inspected	
Pendant Mounted	шърсесси	
Instance on 1st Floor	Does not exist	
	Does not exist	
Surface Mounted	Inchected	
Instance on 1st Floor	Inspected	

# **Building Condition Assessment Survey 2023-2024**

Question	Response	
GYMNASIUM		
Lighting		
Lighting Fixture - LED		
Surface Mounted		
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Local Sound System	2000 100 01110	
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Installation Year	2015	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 1st Floor	Does not exist	
Scoreboard		
Instance on 1st Floor	Does not exist	
Theater Lighting System		
Instance on 1st Floor	Does not exist	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
Lighting	1	
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent	•	
Instance on 1st Floor	Inspected	
Pendant Mounted	•	
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent	2000 100 01110	
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED	Does not exist	
Instance on 1st Floor	Does not exist	
LIBRARY	Inspected	
Instance on Room 225		
	Inspected	
Lighting	Inconnected	
	Inspected	
Lighting Fixture - Fluorescent	Tananatad	
Instance on Room 225	Inspected	
Pendant Mounted	Incorporte d	
Instance on Room 225	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 225	Does not exist	

Does not exist

Instance on Room 225

### **Building Condition Assessment Survey 2023-2024**

Electrical Inspection	A120

Question	Response	
LIBRARY		
Lighting		
Lighting Fixture - HID		
Instance on Room 225	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 225	Does not exist	
Lighting Fixture - LED		
Instance on Room 225	Does not exist	
Raceway With Receptacles		
Instance on Room 225	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Room 225	Does not exist	
LOCKER ROOM	Inspected	
Instance on 1st Floor	Inspected	
Alternative Use	Yes	
Lighting		
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Does not exist	
MULTIPURPOSE ROOM	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	
	Does not exist	
SCIENCE PREP ROOM		
SWIMMING POOL	Does not exist	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	

### **Building Condition Assessment Survey 2023-2024**

Question	Response
TOILET ROOM - STUDENT	
Lighting	
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	4- Between Fair and Poor
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	21
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	35672658X
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	FIXTURE LAMP NOT OPERATIONAL
Deficiency Location/Instance Deficiency Quantity	Corridor outside Boiler Room
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
EXIT/EMERGENCY LIGHT	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
FIRE ALARM SYSTEM	Inspected
Bell/Horn	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
•	

### **Building Condition Assessment Survey 2023-2024**

estion	Response	
IRE ALARM SYSTEM		
Strobe	Does not exist	
Manual Pull Station	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Does not exist	
Duct Smoke Detector	Does not exist	
Area Smoke Detector	Does not exist	
CO Detector	Does not exist	
Heat Detector	Does not exist	
Elevator Recall	Does not exist	
Magnetic Door Holder/Contactor	Does not exist	
Fused Cutout Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Inspected	
Bell At Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Does not exist	
Fire Alarm Control Panel (Standard)	Inspected	
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	ACME	
EquipmentId	Fire Alarm Control Board	
Installation Year	1971	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Boiler Room	
Deficiency Quantity	96,000	
Quantity Uom	S.F.	
Potential Action	REPLACE	
Urgency of Action Purpose of Action	PRIORITY 1 LEVEL 2	
Violations	No violations recorded	
Sub-Panel	Inspected	
Bell At Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
	Does not exist	
Fire Alarm Control Panel (Electronic)	Inspected	
Fire Alarm Control Panel (Standard)		
Instance Instance Condition	Boiler Room  3- Fair	
-		
Instance Quantity	1 FACH	
Instance Quantity Uom	EACH	
Manufacturer	ACME	
EquipmentId	Sprinkler Annunciator Control Board	
Installation Year	1971	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance Deficiency Quantity	Boiler Room	
Deficiency Qualitity	96,000	

### **Building Condition Assessment Survey 2023-2024**

uestion	Response	
FIRE ALARM SYSTEM		
Sub-Panel		
Fire Alarm Control Panel (Standard)		
Quantity Uom	S.F.	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	ACME	
EquipmentId	Register Control Board	
Installation Year	1971	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Boiler Room	
Deficiency Quantity	96,000	
Quantity Uom	S.F.	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Does not exist	
Printer	Does not exist	
Punch Register	Inspected	
Condition	5- Poor	
Deficiency	REGISTER NOT OPERATIONAL	
Deficiency Location/Instance	Boiler Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Sprinkler Flow/Air Pressure Switch	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Tamper Flow Switch/Chain	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
GROUNDING SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
INTERCOM SYSTEM	Does not exist	
LAN	Inspected	
Local Distribution Frame (I/LDF)	Inspected  2- Between Good and Fair	
Condition		
Deficiency	No deficiencies recorded	
Main Equipment Rack (MDF)	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	

### **Building Condition Assessment Survey 2023-2024**

исан інѕрестон	X12
uestion	Response
LIGHTNING PROTECTION	Does not exist
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Inspected 3- Fair
Condition	7
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B11
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	9
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	General Office - Room 140
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Plena Mixer Amplifier
Installation Year	1971
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Deficiency Location/Instance	General Office - Room 140
Deficiency Location/Instance Deficiency Quantity	
	96,000 S.F.
Quantity Uom Potential Action	S.F.
Potential Action	REPLACE
Lincon over of A -4:	DDIODITY 1
Urgency of Action Purpose of Action	PRIORITY 1 LEVEL 2

### **Building Condition Assessment Survey 2023-2024**

Question	Response	
SECURITY	Inspected	
IPDVS/CCTV System	Inspected	
Condition	1- Good	
Installation Year	2023	
Source of Installation Year	Custodial Staff	
Deficiency	No deficiencies recorded	
Intrusion Alarm System	Inspected	
Central Control Panel	Inspected	
Instance	Room 115	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Vista - 128B	
Installation Year	1999	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Infrared Sensor	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Panic Switch	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
	Inspected	
Remote Annunciator  Condition	-	
	3- Fair	
Deficiency	No deficiencies recorded	
Siren/Strobe	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting - Security	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
SERVICE SWITCH	Inspected	
Instance	Electrical Room B11	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	N/A	
EquipmentId	N/A	
Capacity/Size Quantity	1600	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Inspector Estimate	
Installation Year	1971	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance Deficiency Quantity	Electrical Room B11	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
SWITCHBOARD	Inspected	
Number of Spares	2	
Fused Disconnect Switch Type	Inspected	

### **Building Condition Assessment Survey 2023-2024**

uestion	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Siemens
EquipmentId	Distribution Board
Capacity/Size Quantity	800
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	2018
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Instance	Electrical Room B11
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	General Electric
EquipmentId	N/A
Equipmentid Capacity/Size Quantity	1600
Capacity/Size Quantity  Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Inspector Estimate
Installation Year	1971
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B11
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
	Inspected
PBX/Intercom Condition	2- Between Good and Fair
	No deficiencies recorded
Deficiency	
Standard	Inspected 2- Between Good and Fair
Condition	
Deficiency	No deficiencies recorded