### **Building Condition Assessment Survey 2023-2024**

Electrical Inspection		X138
Asset:	P.S. 138 - BRONX, 2060 LAFAYETTE AVENUE, BRONX, NY, 10473	

Asset:	P.S. 138 - BRON	IX, 2060 LAFAYETTE AVE	NUE, BRONX,	NY, 10473			
Inspectio	n Id Inspection Type				Time	In	Last Edited
	4189 ELECTRICAL				2024-	-03-22 08:11AN	M 2024-06-20 10:43AM
sset Data							
Question				Answer			
Have any Systems/Major Building Components been upgraded		Components been upgraded?		Systems:	Computer Lal Fire Alarm Sy		th Receptacle), Library,
				Years:	2023		
				Systems:	LAN (Partial	MDF)	
				Years:	2021		
				Systems:	Battery Pack	Exit Lighting	
				Years:	2020, 2012		
				Systems:	Auditorium, ( Lighting)	Gymnasium (Su	rface Mounted LED
				Years:	2020		
				Systems:	Partial Molde	d Case Circuit E	Breaker Panel Boards
				Years:	2019, 2012		
				Systems:		ighting ( Battery	Pack)
				Years:	2019	5 5	,
				Systems:	Telephone Sy	stem	
				Years:	2017		
				Systems:		ing Emergency	Light/Exit Light Panel
				Years:	2012	mg, Emergency	Eight Exit Eight I thei
				Systems:		tina	
				Years:	2010, 2000	ting	
				Systems:		System	
				Years:	2009	System	
T				Below Gi			
Type of S	ervice eractive Whiteboard (IWB)	Exist?		Yes	Ound		
	netration In Electrical Room			Yes			
		N FIRE RESCUE AREAS		103			
Question		THE RESCRIPTION			Response		
Are the		nce Areas, Fire Rescue Areas, an	nd/or Holding Roo	ms in	No		
Priority Co	ndition						
Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No	Water Penetration in	Water Penetration	Electrical	Electrical	Galan	Fireman	No Photo Taken
	Electrical Room	Through Foundation Wall	Equipment	Room	Sanders		
nspection	ı						
Question	l			Response	<u>)</u>		
Electrica	1						
ATHL	ETIC FIELD			Does not	exist		
AUDITORIUM			Inspected				
	Instance on 1st Floor			Inspected			
Hous	e Lighting						
	Instance on 1st Floor			Inspected			
_	Does a Chandelier Exi			No			
Lig	hting Fixture - Fluoresce	nt					
	Instance on 1st Floor			Does not	exist		
Lig	hting Fixture - HID						
	Instance on 1st Floor			Does not	exist		
Lig	hting Fixture - Incandesc	ent					
	Instance on 1st Floor			Does not	exist		
Lig	hting Fixture - LED						

# **Building Condition Assessment Survey 2023-2024**

Electrical Inspection	A138

estion	Response	
UDITORIUM		
House Lighting		
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Installation Year	2020	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Is the projector on a cart or installed on the ceiling?	Ceiling	
Deficiency	No deficiencies recorded	
Theater Lighting System		
Instance on 1st Floor	Inspected	
Dimming System		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Theater Lighting		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
AFETERIA	Inspected	
Instance on 1st Floor	Inspected	
Lighting	1	
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent	•	
Instance on 1st Floor	Inspected	
Pendant Mounted	•	
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	140 deficiences recorded	
	Does not exist	
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID  Instance on 1st Floor	Does not exist	

### **Building Condition Assessment Survey 2023-2024**

	A130
Response	
Does not exist	
Does not exist	
Inspected	
4- Between Fair and Poor	
2009	
Documented	
SYSTEM DEFECTIVE	
ino violations recorded	
Door not aviet	
Does not exist	
Door not aviet	
<del>_</del>	
<del>_</del>	
Inspected	
No	
Inspected	
Inspected	
Does not exist	
Inspected	
2- Between Good and Fair	
No deficiencies recorded	
	Does not exist  Inspected  4- Between Fair and Poor 2009 Documented SYSTEM DEFECTIVE 1 EACH REPAIR SYSTEM PRIORITY 2 LEVEL 2 No violations recorded  Does not exist  Inspected Inspected Inspected Inspected 2- Between Good and Fair No deficiencies recorded  Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 1- Setween Good and Fair No deficiencies recorded Inspected 1- Setween Good and Fair No deficiencies recorded Inspected 1- Does not exist Inspected

### **Building Condition Assessment Survey 2023-2024**

icui mspeciion		Aisc
uestion	Response	
COMPUTER LAB		
Lighting		
Lighting Fixture - HID		
Instance on Room 307	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 307	Does not exist	
Lighting Fixture - LED		
Instance on Room 307	Does not exist	
Raceway With Receptacles		
Instance on Room 307	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
GYMNASIUM	Inspected	
Instance on 1st Floor	Inspected	
Lighting	mspecceu	
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent	шересси	
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID	Does not exist	
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED	Does not exist	
Instance on 1st Floor	Inspected	
Pendant Mounted	mspecieu	
Instance on 1st Floor	Does not exist	
Surface Mounted	DOCS HOT CAIST	
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
	ino deficiencies recorded	
Recessed Mounted	<u> </u>	
Instance on 1st Floor	Does not exist	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Installation Year Source of Installation Year	2009 Documented	
Deficiency	No deficiencies recorded	
Projection System	100 deficiencies recorded	
Instance on 1st Floor	Does not exist	
Scoreboard	DOCS HOT CAIST	
Instance on 1st Floor	Does not exist	
	DOCS HOT CAIST	
Theater Lighting System  Instance on 1st Floor	Does not exist	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
Lighting Leather and Let Flore	T 1	
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Inspected	

### **Building Condition Assessment Survey 2023-2024**

Question	Response
KITCHEN	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
LIBRARY	Inspected
Instance on Room 221	_
Lighting	Inspected
Instance on Room 221	Inspected
	nispected
Lighting Fixture - Fluorescent Instance on Room 221	Does not exist
	Does not exist
Lighting Fixture - HID  Instance on Room 221	Does not exist
	Does not exist
Lighting Fixture - Incandescent  Instance on Room 221	December of the control of the contr
	Does not exist
Lighting Fixture - LED	T 1
Instance on Room 221	Inspected
Pendant Mounted	T 1
Instance on Room 221	Inspected 1- Good
Instance Condition	
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 221	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 221	Does not exist
Raceway With Receptacles	
Instance on Room 221	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Projection System	
Instance on Room 221	Does not exist
LOCKER ROOM	Inspected
Instance on Room 132 - Girls	Inspected
Alternative Use	Yes
Instance on Room 134 - Boys	Inspected
Alternative Use	Yes
Lighting	_
Instance on Room 132 - Girls	Inspected
Instance on Room 134 - Boys	Inspected
Lighting Fixture - Fluorescent	<del></del>
<u> </u>	

### **Building Condition Assessment Survey 2023-2024**

Response
Inspected
Inspected
Does not exist
Does not exist
Inspected
2- Between Good and Fair
No deficiencies recorded
Inspected
2- Between Good and Fair
No deficiencies recorded
Does not exist
Does not exist
Does not exist
Does not exist
Does not exist
Does not exist
Does not exist
Does not exist
Does not exist
Inspected
Inspected
Inspected
Does not exist
Inspected
2- Between Good and Fair
No deficiencies recorded
Does not exist
Inspected
Inspected
Inspected
Does not exist
Inspected
2- Between Good and Fair
No deficiencies recorded
Does not exist
Does not exist

### **Building Condition Assessment Survey 2023-2024**

icai inspection		X13
nestion	Response	
TOILET ROOM - STUDENT		
Lighting		
Lighting Fixture - LED	Does not exist	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	
EMERGENCY GENERATOR SET	Does not exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
EMERGENCY LIGHTING	Inspected	
Battery Pack	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Non Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EXIT LIGHT	Inspected	
Battery Pack	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Non Battery Pack	Does not exist	
EXIT/EMERGENCY LIGHT	Does not exist	
FIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
CO Detector	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Heat Detector	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Elevator Recall	Does not exist	
Magnetic Door Holder/Contactor	Does not exist	
Fused Cutout Panel	Inspected 1- Good	

### **Building Condition Assessment Survey 2023-2024**

### **Building Condition Assessment Survey 2023-2024**

iricii Inspection	Also
Question	Response
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Does not exist
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	13
	EACH
Quantity Uom	
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	NO SPARE
Deficiency Location/Instance	Second and Third Floor Corridors, Kitchen, Mechanical
	Equipment Room B12, Boiler Room
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Under construction
SECURITY	Inspected
IPDVS/CCTV System	Under construction
Intrusion Alarm System	Under construction
Lighting - Security	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
SERVICE SWITCH	Inspected
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Cole Electric
	Main Service Switch A
EquipmentId	Main Service Switch A  600
Capacity/Size Quantity	
Capacity/Size UOM Source of Capacity/Size	Amps Nameplate
Installation Year	1958
Installation Year Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE

### **Building Condition Assessment Survey 2023-2024**

Question	Response
SERVICE SWITCH	
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
	EACH
Instance Quantity Uom	
Manufacturer	N/A
EquipmentId Capacity/Size Quantity	Main Service Switch B 600
Capacity/Size Quantity  Capacity/Size UOM	
Source of Capacity/Size	Amps Inspector Estimate
Installation Year	1958
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
SWITCHBOARD	Inspected
Number of Spares	0
Fused Disconnect Switch Type	Does not exist
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Federal Pacific Electric
EquipmentId	Main Switchboard Sec A
Capacity/Size Quantity	400
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	1958
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Federal Pacific Electric
EquipmentId	Main Switchboard Sec B
Capacity/Size Quantity	400

# **Building Condition Assessment Survey 2023-2024**

euestion	Response
SWITCHBOARD	
Molded Case Circuit Breaker Type	
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	1958
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not exist