#### **Building Condition Assessment Survey 2023-2024**

Electrical Inspection X139

Asset:	J.H.S. 222 - BRONX, 345 BROOK AVENUE, BRONX, NY, 10454		
Inspection Io	Inspection Type	Time In	Last Edited
410	5 ELECTRICAL	2024-03-22 09:32AM	2024-06-04 01:32PM

# Asset Data Question

Have any Systems/Major Building Components been upgraded?	Systems:	Partial Molded Case Circuit Breaker Type Panel Board

Years: 2023, 2011, 2007, 1998

Systems: Gymnasium (Scoreboard), Transformer and Main

Disconnect for Solar System

Years: 2023

Answer

Systems: Exit Light (Battery Pack)

Years: 2020

Systems: Student Toilet Rooms (Pendant Fluorescent Lighting),

IPDVS/CCTV System, Gymnasium LED Lighting

Years: 2019

Systems: Telephone System

Years: 2016

Systems: Partial Security Lighting, Interior Lighting (Except

Science Rooms 331, 335, 431, 433, 435), Partial Emergency Lighting (Non Battery Pack), Intrusion Alarm System (Panic Switch, Siren/Strobe)

Years: 2015

Systems: Auditorium (Projection System), Science Rooms

(Except Room 437)

Years: 2012

Systems: Public Address System, Local Sound System

Years: 2010

Systems: Auditorium (Theatre Lighting System)

Years: 2007

Systems: Emergency Light/Exit Light Panel

Years: 2005

Systems: Intrusion Alarm System

Years: 1996 Below Ground

Yes

No

#### DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Does Interactive Whiteboard (IWB) Exist?

Water Penetration In Electrical Room?

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in	No
your building?	

#### **Priority Condition**

Type of Service

Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
No	Exposed Electrical Wires	N/A	Raceway With Receptacles	Computer Lab - Room 417	Emerson Brea Jr.	Fireman	

#### Inspection

pecuon			
Question	Response		
Electrical			
ATHLETIC FIELD	Does not exist		
AUDITORIUM	Inspected		
Instance on 1st Floor	Inspected		
House Lighting			

# **Building Condition Assessment Survey 2023-2024**

ricui inspection		AIJ
euestion	Response	
AUDITORIUM		
House Lighting		
Instance on 1st Floor	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted	•	
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	2010	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Is the projector on a cart or installed on the ceiling?	Ceiling	
Deficiency	No deficiencies recorded	
Theater Lighting System		
Instance on 1st Floor	Inspected	
Dimming System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Theater Lighting		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
CAFETERIA	Inspected	
Instance on 1st Floor	Inspected	
Lighting	пореска	

# **Building Condition Assessment Survey 2023-2024**

icui Inspection		113
uestion	Response	
CAFETERIA		
Lighting		
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		_
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent	2000 100 4.100	_
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED	Does not exist	
Instance on 1st Floor	Does not exist	
Local Sound System	DOG NOT CAST	
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	2010	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System	To deficiences recorded	
Instance on 1st Floor	Inspected	_
Instance Condition	3- Fair	
Is the projector on a cart or installed on the ceiling?	Ceiling	
Deficiency	No deficiencies recorded	_
Theater Lighting System	The deficiencies recorded	_
Instance on 1st Floor	Does not exist	_
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting Does a Chandelier Exist?	Inspected No	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	_
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE	_
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	REPLACE BALLAST	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Surface Mounted	Inspected  2- Between Good and Fair	
Condition		
Deficiency Operatity	LIGHTING FIXTURE BALLAST DEFECTIVE	
Deficiency Quantity	2 EACH	
Quantity Uom	EACH	
Potential Action	REPLACE BALLAST	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	

# **Building Condition Assessment Survey 2023-2024**

Electrical Inspection	X139

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
COMPUTER LAB	Inspected
Instance on Room 330	Inspected
Power Panel?	Yes
Instance on Room 417	Inspected
Power Panel?	No
Lighting	
Instance on Room 330	Inspected
Instance on Room 417	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 330	Inspected
Instance on Room 417	Inspected
Pendant Mounted	
Instance on Room 330	Does not exist
Instance on Room 417	Does not exist
Surface Mounted	
Instance on Room 330	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 417	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 330	Does not exist
Instance on Room 417	Does not exist
Lighting Fixture - HID	
Instance on Room 330	Does not exist
Instance on Room 417	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 330	Does not exist
Instance on Room 417	Does not exist
Lighting Fixture - LED	
Instance on Room 330	Does not exist
Instance on Room 417	Does not exist
Raceway With Receptacles	
Instance on Room 330	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 417	Inspected

# **Building Condition Assessment Survey 2023-2024**

cirical Inspection		A139
Question	Response	
COMPUTER LAB		
Raceway With Receptacles		
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
GYMNASIUM	Inspected	
Instance on 1st Floor	Inspected	
Lighting	1	
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent	•	
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted	1	
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Local Sound System	1.0 0011011010110101	
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	2010	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 1st Floor	Does not exist	
Scoreboard		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Theater Lighting System		
Instance on 1st Floor	Does not exist	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
Lighting	•	
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent	•	
Instance on 1st Floor	Inspected	
Pendant Mounted	1	
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	1.5 deficiences recorded	
Instance on 1st Floor	Inspected	
	Inspected  2- Between Good and Fair	
Instance Condition  Deficiency	No deficiencies recorded	
Deficiency	no deficiencies recorded	

# **Building Condition Assessment Survey 2023-2024**

iricai inspeciion		A139
Question	Response	
KITCHEN		
Lighting		
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Does not exist	
LIBRARY	Does not exist	
LOCKER ROOM	Inspected	
Instance on Basement - Boys, Basement - Girls	Inspected	
Alternative Use	Yes	
Lighting	105	
Instance on Basement - Boys, Basement - Girls	Inspected	
Lighting Fixture - Fluorescent	mspected	
Instance on Basement - Boys, Basement - Girls	Inspected	
Pendant Mounted	nispected	
Instance on Basement - Boys, Basement - Girls	Does not exist	
Surface Mounted	Does not exist	
Instance on Basement - Boys, Basement - Girls Instance Condition	Inspected  2- Between Good and Fair	
Deficiency Deficiency Quantity	LIGHTING FIXTURE BALLAST DEFECTIVE 8	
Quantity Uom	8 EACH	
Potential Action	REPLACE BALLAST	
Urgency of Action	PRIORITY 3	
	LEVEL 2	
Purpose of Action Violations		
	No violations recorded	
Recessed Mounted		
Instance on Basement - Boys, Basement - Girls	Does not exist	
Lighting Fixture - HID	D	
Instance on Basement - Boys, Basement - Girls	Does not exist	
Lighting Fixture - Incandescent		
Instance on Basement - Boys, Basement - Girls	Does not exist	
Lighting Fixture - LED		
Instance on Basement - Boys, Basement - Girls	Does not exist	
MULTIPURPOSE ROOM	Does not exist	
SCIENCE DEMO ROOM	Inspected	
Instance on Rooms 331, 335	Inspected	
Power Panel?	No	
Alternative Use	Yes	
Instance on Room 437	Inspected	
Power Panel?	No	
Alternative Use	No	
Lighting		
Instance on Rooms 331, 335	Inspected	
Instance on Room 437	Inspected	
Lighting Fixture - Fluorescent	1	
Instance on Rooms 331, 335	Inspected	
Instance on Room 437	Inspected	
Pendant Mounted	шърсски	
Instance on Rooms 331, 335	Inspected	

# **Building Condition Assessment Survey 2023-2024**

icui Inspection		AIS
uestion	Response	
SCIENCE DEMO ROOM		
Lighting		
Lighting Fixture - Fluorescent		
Pendant Mounted		
Deficiency	No deficiencies recorded	
Instance on Room 437	Does not exist	
Surface Mounted		
Instance on Rooms 331, 335	Does not exist	
Instance on Room 437	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Rooms 331, 335	Does not exist	
Instance on Room 437	Does not exist	
Lighting Fixture - HID		
Instance on Rooms 331, 335	Does not exist	
Instance on Room 437	Does not exist	
Lighting Fixture - Incandescent		
Instance on Rooms 331, 335	Does not exist	
Instance on Room 437	Does not exist	
Lighting Fixture - LED		
Instance on Rooms 331, 335	Does not exist	
Instance on Room 437	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Rooms 331, 335	Does not exist	
Instance on Room 437	Does not exist	
Emergency Shut-Off Power		
Instance on Rooms 331, 335	Does not exist	
Instance on Room 437	Does not exist	
Power Supply		
Instance on Rooms 331, 335	Does not exist	
Instance on Room 437	Does not exist	
Projection System		
Instance on Rooms 331, 335	Does not exist	
Instance on Room 437	Does not exist	
SCIENCE LAB	Inspected	
Instance on Room 431	Inspected	
Power Panel?	Yes	
Alternative Use	No	
Instance on Room 435	Inspected	
Power Panel?	No	
Alternative Use	No	
Lighting		
Instance on Room 431	Inspected	
Instance on Room 435	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 431	Inspected	
Instance on Room 435	Inspected	
Pendant Mounted	-	
Instance on Room 431	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Room 435	Inspected	
Instance Condition	2- Between Good and Fair	

# **Building Condition Assessment Survey 2023-2024**

Electrical Inspection	X139
-----------------------	------

estion	Response	
CIENCE LAB		
Lighting		
Lighting Fixture - Fluorescent		
Pendant Mounted		
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 431	Does not exist	
Instance on Room 435	Does not exist	
Recessed Mounted		
Instance on Room 431	Does not exist	
Instance on Room 435	Does not exist	
Lighting Fixture - HID		
Instance on Room 431	Inspected	
Instance on Room 435	Inspected	
Pendant Mounted	1	
Instance on Room 431	Does not exist	
Instance on Room 435	Does not exist	
Surface Mounted		
Instance on Room 431	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Room 435	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	140 deficiencies recorded	
Instance on Room 431	Does not exist	
Instance on Room 435	Does not exist  Does not exist	
	Does not exist	
Lighting Fixture - Incandescent Instance on Room 431	Does not exist	
Instance on Room 435	Does not exist	
Lighting Fixture - LED	Does not exist	
Instance on Room 431	Does not exist	
Instance on Room 435	Does not exist	
	Does not exist	
Emergency Gas Shut-Off Valve Instance on Room 431	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 435		
Instance Condition	Inspected 3- Fair	
	No deficiencies recorded	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power Instance on Room 431	Inspected	
Instance Condition	3- Fair	
	No deficiencies recorded	
Deficiency 125		
Instance on Room 435	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Power Supply	¥ •	
Instance on Room 431	Inspected	
Instance on Room 435	Inspected	
Instructor Unit		
Instance on Room 431	Inspected	
Instance Condition	3- Fair	

# **Building Condition Assessment Survey 2023-2024**

Electrical Inspection	X139

orded orded orded orded
orded
orded
orded
orded
nd Fair
orded
orded
orded

# **Building Condition Assessment Survey 2023-2024**

ricui Inspection	AIJ
uestion	Response
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
	Does not exist  Does not exist
Lighting Fixture - HID	Does not exist  Does not exist
Lighting Fixture - Incandescent	Does not exist  Does not exist
Lighting Fixture - LED	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	FIXTURE LAMP NOT OPERATIONAL
Deficiency Location/Instance	Basement - By (Stair C, Room B12)
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded

# **Building Condition Assessment Survey 2023-2024**

estion	Response
EXIT/EMERGENCY LIGHT	Does not exist
FIRE ALARM SYSTEM	Inspected
Bell/Horn	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Strobe	Does not exist
Manual Pull Station	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Does not exist
Duct Smoke Detector	Does not exist
Area Smoke Detector	Does not exist
CO Detector	Does not exist
Heat Detector	Does not exist
Elevator Recall	Does not exist
Magnetic Door Holder/Contactor	Does not exist
Fused Cutout Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Does not exist
Fire Alarm Control Panel (Standard)	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ACME
EquipmentId	Fire Alarm
Installation Year	1957
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	137,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Sub-Panel	Inspected
Bell At Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Does not exist
Fire Alarm Control Panel (Standard)	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ACME
EquipmentId	Sprinkler Alarm
Installation Year	1957

# **Building Condition Assessment Survey 2023-2024**

ricui inspection		AIS
uestion	Response	
FIRE ALARM SYSTEM		
Sub-Panel		
Fire Alarm Control Panel (Standard)		
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Boiler Room	
Deficiency Quantity	137,000	
Quantity Uom	S.F.	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	ACME	
EquipmentId	Register Control Board	
Installation Year	1957	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Boiler Room	
Deficiency Quantity	137,000	
Quantity Uom	S.F.	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Does not exist	
Printer	Does not exist	
Punch Register	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Sprinkler Flow/Air Pressure Switch	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Tamper Flow Switch/Chain	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
GROUNDING SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
NTERCOM SYSTEM	Does not exist	
ZAN	Inspected	
Local Distribution Frame (I/LDF)	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Main Equipment Rack (MDF)	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
LIGHTNING PROTECTION	Does not exist	

# **Building Condition Assessment Survey 2023-2024**

rcal Inspection	X13
uestion	Response
MOTOR CONTROLLER	
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B7, Boiler Room
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	15
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	NO SPARE
Deficiency Location/Instance	Electrical Room B7, by Rooms (106, 234)
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Mechanical Room B20
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Boiler Room

# **Building Condition Assessment Survey 2023-2024**

uestion	Response
PANEL BOARD	
Molded Case Circuit Breaker Type	
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	General Office - Room 101
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Bogen Multicom - 2000
Installation Year	2010
Source of Installation Year	Documented
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Kitchen
Deficiency Quantity	l
Quantity Uom	EACH
Potential Action	REPLACE
	PRIORITY 3
Urgency of Action Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	SPEAKER NOT OPERATIONAL
Deficiency Location/Instance	Play Yard
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Condition	2- Between Good and Fair
Installation Year	2019
Source of Installation Year	Documented
Deficiency	CAMERA NOT OPERATIONAL
Deficiency Location/Instance	E1/C2 (Facing playground), C3/44 (Facing Stairwell Landing 1)
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	General Office - Room 101
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	
	4140 XMPT2
Installation Year	1996
Source of Installation Year	Documented DEVAND VALUE
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	General Office - Room 101

# **Building Condition Assessment Survey 2023-2024**

uestion	Response
SECURITY	
Intrusion Alarm System	
Central Control Panel	
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 3
Violations	No violations recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	2- Between Good and Fair
	No deficiencies recorded
Deficiency	
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	2- Between Good and Fair
Deficiency	TIME CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Violations	No violations recorded
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Location/Instance	Canopy Facing Brook Avenue, Exterior Wall (Facing Piccirilli Pl.
Deficiency Escation instance	Street, by Exit 5)
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 3
Violations	No violations recorded
SERVICE SWITCH	Inspected
	Electrical Room B7
Instance Instance Condition	3- Fair
Instance Condition	
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Standard Switchboard
EquipmentId	Service A
Capacity/Size Quantity	800
Capacity/Size UOM	Amps
Source of Capacity/Size	Inspector Estimate
Installation Year	1957
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B7
Deficiency Quantity	1

# **Building Condition Assessment Survey 2023-2024**

cirical Inspection	Also
Question	Response
SERVICE SWITCH	
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room B7
Instance Condition	3- Fair
Instance Quantity	1
	EACH
Instance Quantity Uom	
Manufacturer	Standard Switchboard
EquipmentId	Service B
Capacity/Size Quantity	800
Capacity/Size UOM	Amps
Source of Capacity/Size  Installation Year	Inspector Estimate 1957
Installation Year Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B7
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room B7
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	EATON
EquipmentId	89L Solar Generator Disconnect Switch
Capacity/Size Quantity	1200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2023
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
SWITCHBOARD	Inspected
Number of Spares	5
Fused Disconnect Switch Type	Does not exist
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Instance	Electrical Room B7
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Standard Switchboard
EquipmentId	Main Dist. SWBD A
Capacity/Size Quantity	800
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Inspector Estimate
Installation Year	1957
Source of Installation Year	Documented

# **Building Condition Assessment Survey 2023-2024**

Question	Response
	Acsponse
SWITCHBOARD	
Molded Case Circuit Breaker Type	
Deficiency Location/Instance Deficiency Quantity	Electrical Room B7
	1 EACH
Quantity Uom	EACH DELLACE
Potential Action	REPLACE PRIORITY I
Urgency of Action	
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room B7
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Standard Switchboard
EquipmentId	Main Dist. SWBD B
Capacity/Size Quantity	800
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Inspector Estimate
Installation Year	1957
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B7
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Inspected
	<u>-</u>
Instance	Electrical Room B7
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	HPS Sentinel
EquipmentId	Transformer
Capacity/Size Quantity	300
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	2023
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded