### **Building Condition Assessment Survey 2023-2024**

Asset:	1.5. 142 - E	BRONX, 3750 BAYCHESTEI	X AV ENUE, BKUNX	L, IN I , 1U400			
Inspectio	n Id Inspection	Гуре			Time l	ĺn	Last Edited
	1215 MECHANIC	CAL			2023-	11-22 07:21AN	M 2023-12-27 11:22AM
sset Data	!						
Question	1			Answer			
Have any	Systems/Major Bu	ilding Components been upgraded	1?	Systems:	Fixtures - Drin	nking Fountains	s (~50%)
				Years:	2019		
				Systems:			Room - Dedicated A/C
						X Split System	)
				Years:	2017	***	
				Systems:			ter in Boiler Room;
					Traps	rip Traps; Term	inal Unit Thermostatic
				Years:	2015		
				Systems:		ets; Water Serv	ice (1 of 3)
				Years:	2014	,	()
Are there	e fuel tanks?			No	201.		
	f water main service	e entries to the asset		3			
	an Rooms Locations				oom Mechanical	Area, Sub-Rase	ement MER, MER
1111110/16	Icomo Locations	•		above Au		, 540 15450	ming min
Are there	e any spaces with M	issing or Defective CO Detectors?	•	Yes			
Location				Kitchen,	Science Prep Roo	om 105A	
Are there	e any Painted/Obstru	acted Sprinkler Heads?		Yes			
Location	(s)			Rooms B	9, B21, B22, B26	6, 201, 205, 223	3, 233, 333, Storage
					_	School Safety F	emale Locker Room
				(painted,			
		op Switches with Missing Hamme	rs?	No comp	onents		
riority Co	ondition						
Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo
	tion recorded	Description	Affecteu	Description	Notifieu	Title	Image
Inspection	1						
Question	1			Respons	e		
Mechani	ical						
AIR C	ONDITIONING			Inspected	l		
Chill	led Water System			Does not	exist		
	· · · · · · · · · · · · · · · · · · ·	ibution: Piping, Pumps and Auxi	iliaries	Does not	exist		
	ing Coil in Ductwo			Does not	exist		
Cooli	ing Tower			Does not	exist		
DX S	Split System			Inspected	l		
Ind	loor Unit			Inspected	l		
$\overline{c}$	Condition			3- Fair			
	Deficiency			UP TO 5	TONS:DEFECT	IVE	
	Deficiency Lo	ocation/Instance		Kitchen			
	Deficiency Q	uantity		3			
	Quantity Uon	n		EACH			
Potential Action			REPAIR				
	Urgency of A	ction		PRIORIT	TY 3		
Purpose of Action			LEVEL 2	2			
_	Violations			No violat	tions recorded		
Ou	tdoor Unit			Inspected	1		
$\overline{c}$	Condition			2- Betwe	en Good and Fair	r	
	Deficiency			No defici	iencies recorded		
Dry	Cooler			Does not	exist		
	aged / Rooftop Uni	it		Does not	exist		
•	aged Terminal A/C			Does not	exist		
~.~-							<u> </u>
CAS Partners	s Version 2.0 (P)		Page 1	of 10			Print Date: 8/8/2024

## **Building Condition Assessment Survey 2023-2024**

X142
Response
Does not exist
Inspected
3- Fair
No deficiencies recorded
Does not exist
Does not exist
Under construction
Does not exist
Inspected
Inspected
5- Poor
No
No deficiencies recorded
Does not exist
Inspected
Inspected
Does not exist
Does not exist
Inspected
Sub-Basement - Crawlspace
1- Good
1
EACH
WATER MAIN:MISSING BACKFLOW PREVENTION DEVICE
Sub-Basement - Crawlspace
1
EACH
INSTALL
PRIORITY 3
LEVEL 2
No violations recorded
Sprinkler/Gas Meter Room B38
3- Fair
2
EACH
WATER MAIN:MISSING BACKFLOW PREVENTION DEVICE
Sprinkler/Gas Meter Room B38
2
EACH
INSTALL
PRIORITY 3
LEVEL 2
No violations recorded
Inspected
Does not exist
Does not exist
Inspected

## **Building Condition Assessment Survey 2023-2024**

Question	Response	
DOMESTIC WATER SYSTEM		
Domestic Hot Water System		
Electric Domestic Water Heater		
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Gas Fired Domestic Water Heater	Does not exist	
Oil Fired Domestic Water Heater	Does not exist	
Heat Pump Domestic Water Heater	Does not exist	
Domestic Water Distribution Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected	
Interior Storm Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Sewage/Waste/Vent Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Sewage Ejector Pump	Does not exist	
Sump Pump	Does not exist	
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist	
FIXTURES	Inspected	
Staff And Other	Inspected	
Janitor Sink	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lavatory/Sink	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Toilet	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Urinal	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Student	Inspected	
Drinking Fountain	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lavatory/Sink	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Locker Room Shower	Inspected	
Instance on Basement - Boys	Inaccessible	
Instance on Basement - Girls	Inaccessible	
Sink And Fountain Combo Unit	Does not exist	
Toilet	Inspected	
Condition	2- Between Good and Fair	
Deficiency	CLOGGED/LEAKING	
Deficiency Location/Instance	Girl's Toilet Room 211	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	

## **Building Condition Assessment Survey 2023-2024**

estion	Response	
IXTURES		
Student		
Toilet		
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Urinal	Inspected	
Condition	3- Fair	
Deficiency	CRACKED/PHYSICAL DAMAGE	
Deficiency Location/Instance	Boy's Toilet Rooms 215, 315	
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
AS FIRED FURNACE	Does not exist	
AS SERVICE	Inspected	
Gas Distribution Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Gas Meter Room Exhaust Fan	Does not exist	
Gas Meter Room Vent	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Gas Pressure Booster	Does not exist	
CO/Gas Leak Detection	Under construction	
EATING	Inspected	
Heating Coil In Ductwork	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hydronic Heating	Does not exist	
Radiator/Convector/Fin Tube	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Steam Heating	Inspected	
F&T/Steam Drip Trap	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
MER Steam and Condensate Piping	Inspected	
Condition	3- Fair	
Deficiency	DAMAGED/MISSING INSULATION	
Deficiency Location/Instance	MER above Auditorium	
Deficiency Quantity	40	
Quantity Uom	L.F.	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Steam Condensate Return Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Steam Condensate Return Pumping System	Under construction	
Steam Piping	Inspected	

## **Building Condition Assessment Survey 2023-2024**

uestion	Response	
	Response	
HEATING  Starry Heating		
Steam Heating Steam Pining		
Steam Piping Deficiency	No deficiencies recorded	
Terminal Unit Thermostatic Trap	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Steam supplied by External Sources	Does not exist	
Unit Heater/Cabinet Heater	Under construction	
HEATING PLANT	Inspected	
Instance on Sub-Basement	Under construction	
Enclosed IDF Room	Inspected	
Instance on Rooms 113, 137, 337	Inspected	
Dedicated A/C Equipment		
Instance on Rooms 113, 137, 337	Inspected	
Instance Condition	4- Between Fair and Poor	
Deficiency	DOES NOT EXIST	
Deficiency Location/Instance	Rooms 113, 137, 337	
Deficiency Quantity	3	
Quantity Uom	EACH	
Potential Action	INSTALL	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
KITCHEN	Inspected	
Instance on Basement	Inspected	
CO Detector		
Instance on Basement	Inspected	
Instance Condition	4- Between Fair and Poor	
Deficiency	DEFECTIVE/MISSING	
Deficiency Location/Instance	Kitchen	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Gas System		
Instance on Basement	Inaccessible	
Grease Trap		
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Hood		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hood Exhaust Ductwork		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hood Exhaust Fan	140 deficiencies recorded	
Instance on Basement	Inencated	
	Inspected 3- Fair	
Instance Condition	3- Fair	

## **Building Condition Assessment Survey 2023-2024**

Mechanical Inspection	X142
-----------------------	------

nunicui Inspection		711-12
Question	Response	
KITCHEN		
Hood Exhaust Fan		
Deficiency	No deficiencies recorded	
Hood Fire Suppression System		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hot Water Temperature Booster		
Instance on Basement	Does not exist	
Kitchen Sink		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	Missing Air Gap	
Deficiency Location/Instance	Kitchen (2 of 4)	
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
MDF Room	Inspected	
Instance on Room 221	Inspected	
Dedicated A/C Equipment	•	
Instance on Room 221	Inspected	
Instance Condition	3- Fair	
Deficiency	DEFECTIVE	
Deficiency Location/Instance	Room 221	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
SCIENCE DEMO ROOM	Inspected	
Instance on Room 218	Inspected	
Alternative Use	No	
Instance on Room 222	Inspected	
Alternative Use	Yes	
Acid Waste Neutralizing Tank	103	
Instance on Room 218	Does not exist	
Instance on Room 222	Does not exist	
CO Detector	Does not exist	
Instance on Room 218	Not required	
Instance on Room 222	Not required	
	Not required	
Emergency Shower Instance on Room 218	Does not exist	
Instance on Room 222	Does not exist	
Eye Wash	Door not aviet	
Instance on Room 218	Does not exist	
Instance on Room 222	Does not exist	
Hood Exhaust Ductwork	D	
Instance on Room 218	Does not exist	
Instance on Room 222	Does not exist	
Hood Exhaust Fan	D	
Instance on Room 218	Does not exist	

## **Building Condition Assessment Survey 2023-2024**

micui Inspection	
estion	Response
CIENCE DEMO ROOM	
Hood Exhaust Fan	
Instance on Room 222	Does not exist
Fixed Laboratory Hood	
Instance on Room 218	Does not exist
Instance on Room 222	Does not exist
Laboratory Sink	
Instance on Room 218	Inspected
Instance Condition	4- Between Fair and Poor
Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF
	VALVE,ETC.)
Deficiency Location/Instance	Room 218
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on Room 222	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Make-up Air Unit	
Instance on Room 218	Does not exist
Instance on Room 222	Does not exist
CIENCE LAB	Inspected
Instance on Room 105	Inspected
Alternative Use	No
	190
Acid Waste Neutralizing Tank	Does not exist
Instance on Room 105	DOES HOL EXIST
CO Detector  Instance on Room 105	
	Inspected 3- Fair
Instance Condition	
Deficiency	No deficiencies recorded
Emergency Shower	
Instance on Room 105	Does not exist
Eye Wash	
Instance on Room 105	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Hood Exhaust Ductwork	
Instance on Room 105	Does not exist
Hood Exhaust Fan	
Instance on Room 105	Does not exist
Fixed Laboratory Hood	
Instance on Room 105	Does not exist
Laboratory Sink	
Instance on Room 105	Inspected
Instance Condition	3- Fair
Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF VALVE,ETC.)
Deficiency Location/Instance	Room 105 ( 3 of 3)
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3

## **Building Condition Assessment Survey 2023-2024**

Mechanical Inspection	X142

unicui Inspection		
uestion	Response	
SCIENCE LAB		
Laboratory Sink		
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Make-up Air Unit		
Instance on Room 105	Does not exist	
SCIENCE PREP ROOM	Inspected	
Instance on Room 105A	Inspected	
Alternative Use	No	
Instance on Rooms 120, 220	Inspected	
Alternative Use	Yes	
Acid Waste Neutralizing Tank		
Instance on Room 105A	Does not exist	
Instance on Rooms 120, 220	Does not exist	
CO Detector		
Instance on Room 105A	Inspected	
Instance Condition	4- Between Fair and Poor	
Deficiency	DEFECTIVE/MISSING	
Deficiency Location/Instance	Room 105A	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Instance on Rooms 120, 220	Not required	
Emergency Shower		
Instance on Room 105A	Does not exist	
Instance on Rooms 120, 220	Does not exist	
Eye Wash		
Instance on Room 105A	Does not exist	
Instance on Rooms 120, 220	Does not exist	
Hood Exhaust Ductwork		
Instance on Room 105A	Does not exist	
Instance on Rooms 120, 220	Does not exist	
Hood Exhaust Fan		
Instance on Room 105A	Does not exist	
Instance on Rooms 120, 220	Does not exist	
Fixed Laboratory Hood		
Instance on Room 105A	Does not exist	
Instance on Rooms 120, 220	Does not exist	
Laboratory Sink		
Instance on Room 105A	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 120, 220	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Make-up Air Unit		
Instance on Room 105A	Does not exist	
Instance on Rooms 120, 220	Does not exist	
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected	
Dry Sprinkler Alarm Valve Assembly	Does not exist	
Wet Sprinkler Alarm Valve Assembly	Inspected	

## **Building Condition Assessment Survey 2023-2024**

<u> </u>			
uestion	Response		
SPRINKLERS, STANDPIPE, FIRE SYSTEM			
Wet Sprinkler Alarm Valve Assembly			
Condition	3- Fair		
Deficiency	NOT IN USE		
Deficiency Location/Instance	Sprinkler/Gas Meter Room B38		
Deficiency Quantity	1		
Quantity Uom	EACH		
Potential Action	NO ACTION		
Urgency of Action	PRIORITY 1		
Purpose of Action	LEVEL 1		
Violations	No violations recorded		
Fire Booster Pump Assembly	Does not exist		
Roof Tank	Does not exist		
Siamese Connection	Inspected		
Condition	3- Fair		
Deficiency	No deficiencies recorded		
Sprinkler Head	Inspected		
Condition	5- Poor		
Deficiency	DEFECTIVE/DETERIORATED		
Deficiency Location/Instance	Rooms B9, B21, B22, B26, 201, 205, 223, 233, 333, Storage		
	Room back of the Stage, School Safety Female Locker Room		
	(painted, 75)		
Deficiency Quantity	75		
Quantity Uom	EACH		
Potential Action	REPLACE		
Urgency of Action	PRIORITY 5		
Purpose of Action	LEVEL 6		
Violations	No violations recorded		
Sprinkler Piping	Inspected		
Condition	3- Fair		
Deficiency	No deficiencies recorded		
Standpipe System	Does not exist		
Water Gong	Does not exist		
SWIMMING POOL	Does not exist		
VENTILATION	Inspected		
Is the building Mechanically ventilated?	Partial		
Exhaust Fan	Inspected		
Condition	3- Fair		
Approximate Total # of Fans	1-25		
Deficiency	No deficiencies recorded		
Heating And Ventilating Unit	Inspected		
Condition	3- Fair		
Deficiency	DEFECTIVE		
Deficiency Location/Instance	MER above Auditorium / Auditorium BL #7 (missing belt)		
Deficiency Quantity	1		
Quantity Uom	EACH		
Potential Action	MAINTENANCE		
Urgency of Action	PRIORITY 3		
Purpose of Action	LEVEL 2		
Violations	No violations recorded		
Metal Ductwork	Inspected		
Condition	3- Fair		
Are there any uninsulated ductwork by design in Mechanical rooms?	Yes		
Are there chain operated dampers?	No		
Deficiency	DAMAGED FLEXIBLE CONNECTION		
Deficiency Location/Instance	MER above Auditorium @ Gymnasium BL #3		

### **Building Condition Assessment Survey 2023-2024**

uestion	Response	
VENTILATION		
Metal Ductwork		
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Supply Fan	Inspected	
Condition	3- Fair	
Approximate Total # of Fans	1-5	
Deficiency	No deficiencies recorded	
Unit Ventilator	Does not exist	