# **Building Condition Assessment Survey 2023-2024**

				Y, 10454		
Inspection Id	Inspection Type				Time In	Last Edited
1386	ELECTRICAL				2023-12-01 07:47AM	2023-12-18 03:58P
sset Data						
Question				Answer		
Have any Syster	ns/Major Building Co	omponents been upgraded		Systems:	Partial Molded Case Circuit Br	eaker Panel Boards
				Years:	2023, 2012, 1999	
				Systems:	System), LAN	om 305 (Projection
				Years:	2020	
				Systems:	Lighting)	311, 313 (Surface LED
				Years:	2019	. 1)
				Systems:		ack)
				Years:	2018	
				Systems:	Partial Exit Lights (Battery Pac Most Emergency Lighting (No Frequency Drive 2016	
				Years: Systems:		Lighting Event
				Systems.	(Gymnasium, Library, 3rd Floo Offices, Computer Lab - Room Rooms: 305, 309; Science Prep Lab Room 205 - Incandescent Rooms: 322, 323; Science Prep	or Classrooms and a 300, Science Lab o Room 307; Science Lighting), Science Lab -
				Years:	2015	
				Systems:	Most Security Lights	
				Years:	2013, 1994	
				Systems:	*	
				Years:	2013	
				Systems:		em, Theater Lighting
				Years:	System, Projection System) 2012	, 5 5
				Systems:	3rd Floor Classrooms and Offic Lab - Room 300, Science Lab - Science Prep Room 307, Scien (Incandescent Lighting)	- Rooms: 305, 309;
				Years:	2007	
				Systems:		Sound System
				Systems.	(Cafeteria), Emergency Light/F	•
				Years:	2001	
				Systems:	Intrusion Alarm System	
				Years:	1999	
Type of Service				Below Gr	round	
Does Interactive	Whiteboard (IWB) I	Exist?		Yes		
Water Penetratio	on In Electrical Room	?		Yes		
DEDICATED	INTERCOMS IN	FIRE RESCUE AREA	S			
Question				]	Response	
Are there any your building?		ce Areas, Fire Rescue Area	, and/or Holding Roo	oms in	No	
iority Conditi	on					
Exist Prior		Condition Description	Component Affected	Location Description		Photo Image

#### **Building Condition Assessment Survey 2023-2024**

#### Electrical Inspection X149

Basement -

Hector

Fireman

Lighting

No

Water Leaks onto

Water penetrates from a

	Electrical Equipment	broken steam pipe.	Fixture	Room C16	Franqui		
Yes	Water Penetration in Electrical Room	Water penetrates through CT cabinet when it rains.	Electrical Equipment	Electrical Room	Hector Frsnqui	Fireman	
Inspection	on						
Questi	ion			Respons	e		
Electr	ical						
ATH	ILETIC FIELD			Does not	exist		
AUD	DITORIUM			Inspected	d		
	Instance on 1st Floor			Inspected	d		
Ho	ouse Lighting						
	Instance on 1st Floor			Inspected	d		
_	Does a Chandelier Exi			No			
I	Lighting Fixture - Fluoresce	nt					
	Instance on 1st Floor			Inspected	d		
	Pendant Mounted			Does not	- arriat		
	Instance on 1st Floor Surface Mounted			Does not	. exist		
	Instance on 1st Floor			Inspected			
	Instance Condition				en Good and Fa	nir	
	Deficiency				iencies recorded		
	Recessed Mounted						
	Instance on 1st Floor			Does not	exist		
Ī	ighting Fixture - HID						
	Instance on 1st Floor			Does not	exist		
Ī	ighting Fixture - Incandesc	cent					
_	Instance on 1st Floor			Does not	exist		
I	Lighting Fixture - LED						
	Instance on 1st Floor			Inspected	d		
	Pendant Mounted						
	Instance on 1st Floor			Does not	exist		
	Surface Mounted			ъ.	• .		
	Instance on 1st Floor			Does not	exist		
	Recessed Mounted Instance on 1st Floor			Imamanta	.1		
	Instance Condition			Inspected	en Good and Fa	nir	_
	Deficiency				NG FIXTURE 1		IONAI
	Deficiency Quantity	,		1	NOTE TORE	(OI OI LIUII)	
	Quantity Uom			EACH			
	Potential Action			REPLAC	CE		
	Urgency of Action			PRIORI			
	Purpose of Action			LEVEL			
	Violations			No viola	tions recorded		
Lo	cal Sound System			T 4	.1		
	Instance on 1st Floor Instance Condition			Inspected 3- Fair	ı		
	Installation Year			2012			

### **Building Condition Assessment Survey 2023-2024**

action	Dognanca
estion	Response
AUDITORIUM	
Local Sound System  Source of Installation Year	Degramented
Source of Installation Year	Documented  No deficiencies recorded
Deficiency	No deficiencies recorded
Projection System  Instance on 1st Floor	Inconnected
Instance Condition	Inspected 4- Between Fair and Poor
Is the projector on a cart or installed on the ceiling?	Ceiling
Deficiency	VIDEO PROJECTOR IS NOT OPERATIONAL
Deficiency Quantity	VIDEO PROJECTOR IS NOT OPERATIONAL  1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Theater Lighting System	No violations recorded
Instance on 1st Floor	Inspected
	nispected
Dimming System  Instance on 1st Floor	Inspected
	4- Between Fair and Poor
Instance Condition	
Deficiency Deficiency Quantity	DIMMING RACK/LIGHT CONSOLE NOT OPERATIONAL
	1
Quantity Uom	EACH
Potential Action	REPAIR PRIORITY 3
Urgency of Action Purpose of Action	LEVEL 2
Violations	No violations recorded
	No violations recorded
Theater Lighting	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
CAFETERIA	Inspected
Instance on Basement	Inspected
Lighting	
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	
Instance on Basement	Does not exist
Surface Mounted	
Instance on Basement	Does not exist
Recessed Mounted	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - HID	110 HOMHOLD FOOTHOU
Instance on Basement	Does not exist
	Does not exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not exist

### **Building Condition Assessment Survey 2023-2024**

icui mopecuon		711
uestion	Response	
CAFETERIA		
Lighting		
Lighting Fixture - LED		
Instance on Basement	Does not exist	
Local Sound System		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Installation Year	2001	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Cafeteria-Basement	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Projection System		
Instance on Basement	Does not exist	
Theater Lighting System		
Instance on Basement	Does not exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
	Does not exist	
Lighting Fixture - HID		
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
COMPUTER LAB	Inspected	
Instance on Room 300	Inspected	
Power Panel?	Yes	
Lighting		
Instance on Room 300	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 300	Inspected	
Pendant Mounted		
Instance on Room 300	Does not exist	
Surface Mounted		
Instance on Room 300	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Room 300	Does not exist	

### **Building Condition Assessment Survey 2023-2024**

tout inspection		111.7
Question	Response	
COMPUTER LAB		
Lighting		
Lighting Fixture - Incandescent		
Instance on Room 300	Does not exist	
Lighting Fixture - LED		
Instance on Room 300	Does not exist	
Raceway With Receptacles		
Instance on Room 300	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
GYMNASIUM	Inspected	
Instance on 1st Floor	Inspected	
Lighting		
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent	•	
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted	1	
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Installation Year	2020	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 1st Floor	Does not exist	
Scoreboard		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Theater Lighting System		
Instance on 1st Floor	Does not exist	
KITCHEN	Inspected	
Instance on Basement	Inspected	
Lighting	^	
Instance on Basement	Inspected	
Lighting Fixture - Fluorescent		
Instance on Basement	Inspected	
Pendant Mounted	^	
Instance on Basement	Does not exist	
Surface Mounted		
Instance on Basement	Inspected	
	1	

Electrical Inspection		X149
Question	Resnonse	

Question	Response	
KITCHEN		
Lighting		
Lighting Fixture - Fluorescent		
Surface Mounted		
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on Basement	Does not exist	
Lighting Fixture - Incandescent		
Instance on Basement	Does not exist	
Lighting Fixture - LED		
Instance on Basement	Does not exist	
LIBRARY	Inspected	
Instance on 2nd Floor	Inspected	
Lighting		
Instance on 2nd Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 2nd Floor	Inspected	
Pendant Mounted		
Instance on 2nd Floor	Does not exist	
Surface Mounted		
Instance on 2nd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE BALLAST	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Recessed Mounted		
Instance on 2nd Floor	Does not exist	
Lighting Fixture - HID		
Instance on 2nd Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 2nd Floor	Does not exist	
Lighting Fixture - LED		
Instance on 2nd Floor	Inspected	
Pendant Mounted		
Instance on 2nd Floor	Does not exist	
Surface Mounted		
Instance on 2nd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 2nd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL	
Deficiency Quantity	1	
Quantity Uom	EACH	

Electrical Inspection	X149
<b>A</b>	

Question	Response	
LIBRARY	•	
Lighting		
Lighting Fixture - LED		
Recessed Mounted		
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Raceway With Receptacles		
Instance on 2nd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 2nd Floor	Does not exist	
LOCKER ROOM	Inspected	
Instance on Basement - Boys, Basement - Girls	Inspected	
Alternative Use	Yes	
Lighting	103	
Instance on Basement - Boys, Basement - Girls	Inspected	
Lighting Fixture - Fluorescent		
Instance on Basement - Boys, Basement - Girls	Inspected	
Pendant Mounted		
Instance on Basement - Boys, Basement - Girls	Does not exist	
Surface Mounted	Does not exist	
Instance on Basement - Boys, Basement - Girls	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE	
Deficiency Quantity	6	
Quantity Uom	EACH	
Potential Action	REPLACE BALLAST	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Recessed Mounted		
Instance on Basement - Boys, Basement - Girls	Does not exist	
Lighting Fixture - HID		
Instance on Basement - Boys, Basement - Girls	Does not exist	
Lighting Fixture - Incandescent		
Instance on Basement - Boys, Basement - Girls	Does not exist	
Lighting Fixture - LED		
Instance on Basement - Boys, Basement - Girls	Does not exist	
MULTIPURPOSE ROOM	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Inspected	
Instance on Room 205	Inspected	
Power Panel?	No	
Alternative Use	No	
Instance on Room 305	Inspected	
Power Panel?	Yes	
Alternative Use	No	
Instance on Room 309	Inspected	
Power Panel?	No	
Alternative Use	No	
Instance on Room 322	Inspected	
	*	

Electrical Inspection	X149
-----------------------	------

-		
estion	Response	
CIENCE LAB		
Power Panel?	No	
Alternative Use	No	
Instance on Room 32	Inspected	
Power Panel?	Yes	
Alternative Use	No	
Lighting		
Instance on Room 20	Inspected	
Instance on Room 30	Inspected	
Instance on Room 30	Inspected	
Instance on Room 32	Inspected	
Instance on Room 32	Inspected	
Lighting Fixture - Fluoresc		
Instance on Room 20	Inspected	
Instance on Room 30	Inspected	
Instance on Room 30	Inspected	
Instance on Room 32	Inspected	
Instance on Room 32	Inspected	
Pendant Mounted	nispecied	
Instance on Room 20	Does not exist	
Instance on Room 30	Inspected 3- Fair	
Instance Condition	-	
Deficiency	No deficiencies recorded	
Instance on Room 30	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 32	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Room 32	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 20	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Room 30	Does not exist	
Instance on Room 30	Does not exist	
Instance on Room 32	Does not exist	
Instance on Room 32	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Room 20	Does not exist	
Instance on Room 30	Does not exist	
Instance on Room 30	Does not exist	
Instance on Room 32	Does not exist	
Instance on Room 32	Does not exist	
Lighting Fixture - HID		
Instance on Room 20	Does not exist	
Instance on Room 30	Does not exist	
Instance on Room 30	Does not exist	
Instance on Room 32	Does not exist	

### **Building Condition Assessment Survey 2023-2024**

uestion	Response	
SCIENCE LAB	·	
Lighting		
Lighting Fixture - HID		
Instance on Room 323	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 205	Inspected	
Instance on Room 305	Does not exist	
Instance on Room 309	Does not exist	
Instance on Room 322	Inspected	
Instance on Room 323	Inspected	
Pendant Mounted	*	
Instance on Room 205	Does not exist	
Instance on Room 322	Does not exist	
Instance on Room 323	Does not exist	
Surface Mounted		
Instance on Room 205	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 322	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Room 323	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	No deficiencies recorded	
Instance on Room 205	Does not exist	
Instance on Room 322	Does not exist  Does not exist	
Instance on Room 323	Does not exist  Does not exist	
	Does not exist	
Lighting Fixture - LED  Instance on Room 205	Does not exist	
Instance on Room 305	Does not exist	
Instance on Room 309	Does not exist	
Instance on Room 322	Does not exist	
Instance on Room 323	Does not exist	
Emergency Gas Shut-Off Valve	Insuranted	
Instance on Room 205	Inspected 3- Fair	
Instance Condition	No deficiencies recorded	
Deficiency		
Instance on Room 305	Inspected 3- Fair	
Instance Condition		
Deficiency	No deficiencies recorded	
Instance on Room 309	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 322	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Room 323	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power		
Instance on Room 205	Inspected	
T t C 1't'	2 Fain	

Instance Condition

3- Fair

Electrical Inspection	X149
-----------------------	------

uestion		Response	
SCIENCE LAB			
Emergency Shut-	Off Power		
Deficien	гу	No deficiencies recorded	
Instance	on Room 305	Does not exist	
Instance	on Room 309	Does not exist	
Instance	on Room 322	Inspected	
Instance	Condition	2- Between Good and Fair	
Deficien	cy	No deficiencies recorded	
Instance	on Room 323	Inspected	
Instance	Condition	2- Between Good and Fair	
Deficien	гу	No deficiencies recorded	
Power Supply			
Instance	on Room 205	Inspected	
Instance	on Room 305	Does not exist	
Instance	on Room 309	Does not exist	
Instance	on Room 322	Does not exist	
Instance	on Room 323	Inspected	
Instructor Unit			
Instance	on Room 205	Inspected	
Instance	Condition	3- Fair	
Deficien	cy .	No deficiencies recorded	
Instance	on Room 323	Inspected	
Instance	Condition	2- Between Good and Fair	
Deficien	гу	No deficiencies recorded	
Meter Demonst	ration Unit		
Instance	on Room 205	Inspected	
Instance	Condition	3- Fair	
Deficien	ey	No deficiencies recorded	
Instance	on Room 323	Inspected	
Instance	Condition	2- Between Good and Fair	
Deficien	су	No deficiencies recorded	
Student Unit			
Instance	on Room 205	Does not exist	
Instance	on Room 323	Does not exist	
Projection System	ı		
Instance	on Room 205	Does not exist	
Instance	on Room 305	Inspected	
Instance	Condition	1- Good	
Deficien	у	No deficiencies recorded	
Instance	on Room 309	Does not exist	
Instance	on Room 322	Does not exist	
Instance	on Room 323	Does not exist	
SCIENCE PREP R	OOM	Inspected	
Instance	on Room 205A	Inspected	
Power Pa	nel?	No	
Alternati	ve Use	No	
Instance	on Room 307	Inspected	
Power Pa	nel?	No	
Alternati		Yes	
	on Room 324	Inspected	
Power Pa		No	
Alternati		No	
Lighting		100	

Electrical Inspection	A149

estion	Response	
CIENCE PREP ROOM		
Lighting		
Instance on Room 205A	Inspected	
Instance on Room 307	Inspected	
Instance on Room 324	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 205A	Inspected	
Instance on Room 307	Inspected	
Instance on Room 324	Inspected	
Pendant Mounted		
Instance on Room 205A	Does not exist	
Instance on Room 307	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 324	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 205A	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Room 307	Does not exist	
Instance on Room 324	Does not exist	
Recessed Mounted		
Instance on Room 205A	Does not exist	
Instance on Room 307	Does not exist	
Instance on Room 324	Does not exist	
Lighting Fixture - HID		
Instance on Room 205A	Does not exist	
Instance on Room 307	Does not exist	
Instance on Room 324	Does not exist	
<b>Lighting Fixture - Incandescent</b>		
Instance on Room 205A	Does not exist	
Instance on Room 307	Does not exist	
Instance on Room 324	Does not exist	
Lighting Fixture - LED		
Instance on Room 205A	Does not exist	
Instance on Room 307	Does not exist	
Instance on Room 324	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Room 205A	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 307	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 324	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power		
Instance on Room 205A	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	

### **Building Condition Assessment Survey 2023-2024**

· · · · · · · · · · · · · · · · · · ·		
Question	Response	
SCIENCE PREP ROOM		
Emergency Shut-Off Power		
Instance on Room 307	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 324	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Power Supply		
Instance on Room 205A	Does not exist	
Instance on Room 307	Does not exist	
Instance on Room 324	Does not exist	
SWIMMING POOL	Does not exist	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	
EMERGENCY GENERATOR SET	Does not exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EMERGENCY LIGHTING	Inspected	
Battery Pack	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Non Battery Pack	Inspected	
LIOI DAILLI J I ALK		

### **Building Condition Assessment Survey 2023-2024**

icui Inspection		ZX17)
uestion	Response	
EMERGENCY LIGHTING		
Non Battery Pack		
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
EXIT LIGHT	Inspected	
Battery Pack	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Non Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	FIXTURE LAMP NOT OPERATIONAL	
Deficiency Location/Instance	Locker Room - Girls	
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 4	
Violations	11688123P	
EXIT/EMERGENCY LIGHT	Does not exist	
FIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Strobe	Does not exist	
Manual Pull Station	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Does not exist	
Duct Smoke Detector	Does not exist	
Area Smoke Detector	Does not exist	
CO Detector	Does not exist	
Heat Detector	Does not exist	
Elevator Recall	Does not exist	
Magnetic Door Holder/Contactor	Does not exist	
Fused Cutout Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Inspected	
Bell At Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Does not exist	
Fire Alarm Control Panel (Standard)	Inspected	
Instance	Boiler Room C9	
Instance Condition	3- Fair	
Instance Condition  Instance Quantity		
	1 EACH	
Instance Quantity Uom		
Manufacturer	Edwards	
EquipmentId	Fire Alarm Box	
Installation Year	1958	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Boiler Room C9	
Deficiency Quantity	133,000	

### **Building Condition Assessment Survey 2023-2024**

nestion	Response	
FIRE ALARM SYSTEM		
Main Panel		
Fire Alarm Control Panel (Standard)		
Quantity Uom	S.F.	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Sub-Panel	Inspected	
Bell At Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Does not exist	
Fire Alarm Control Panel (Standard)	Inspected	
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Edwards	
EquipmentId	Sprinkler Control Panel	
Installation Year	1958	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Boiler Room	
Deficiency Quantity	133,000	
Quantity Uom	S.F.	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	Boiler Room C9	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Edwards	
EquipmentId	Fire Alarm Box	
Installation Year	1958	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Boiler Room C9	
Deficiency Quantity	133,000	
Quantity Uom	S.F.	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Does not exist	
Printer	Does not exist	
Punch Register	Inspected	
Condition	5- Poor	
Deficiency	REGISTER NOT OPERATIONAL	
Deficiency Location/Instance	Custodian's Office	
Deficiency Quantity	1	

### **Building Condition Assessment Survey 2023-2024**

incui inspection	Al
Question	Response
FIRE ALARM SYSTEM	
Remote Annunciator	
Punch Register	
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not exist
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Does not exist
MOTOR CONTROL CENTER  MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Does not exist
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room C12
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	23
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1

### **Building Condition Assessment Survey 2023-2024**

ical Inspection	X14
uestion	Response
PANEL BOARD	
Molded Case Circuit Breaker Type	
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	Main Office
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Dukane 250
Installation Year	2001
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Condition	2- Between Good and Fair
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 50P
Installation Year	1999
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition Condition	3- Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Location/Instance	Main Roof by Exits 3 and 4
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Violations	No violations recorded
SERVICE SWITCH	Inspected
Instance	Electrical Room C12
Instance Condition	3- Fair

### **Building Condition Assessment Survey 2023-2024**

Question	Response	
SERVICE SWITCH		
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Lexington	
EquipmentId	Service A	
Capacity/Size Quantity	1600	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Fuse Size	
Installation Year	1958	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room C12	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	Electrical Room C12	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Lexington	
EquipmentId	Service B	
Capacity/Size Quantity	1600	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Fuse Size	
Installation Year	1958	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room C12	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
SWITCHBOARD	Inspected	
Number of Spares	0	
	Does not exist	
Fused Disconnect Switch Type	Does not exist  Does not exist	
Fused Knife Switch Type		
Molded Case Circuit Breaker Type	Inspected	
Instance	Electrical Room C12	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Lexington Electric	
EquipmentId	N/A	
Capacity/Size Quantity	1600	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	1	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Service Switch Fuse Size	
Installation Year	1958	
Source of Installation Year	Documented	
Deficiency		

#### **Building Condition Assessment Survey 2023-2024**

Question	Response
SWITCHBOARD	
Molded Case Circuit Breaker Type	
Deficiency Location/Instance	Electrical Room C12
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room C12
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Lexington Electric
EquipmentId	N/A
Capacity/Size Quantity	1600
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Fuse Size
Installation Year	1958
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room C12
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not exist