## **Building Condition Assessment Survey 2023-2024**

Inspection	n Id Inspection Typ	pe			Time I	n	Last Edited
	1585 MECHANICA	L			2023-1	12-11 07:08AM	2024-05-08 06:48PM
sset Data							
Question				Answer			
Have any	Systems/Major Build	ing Components been upgraded?		Systems:	Kitchen - Grea	se Trap	
·				Years:	2024		
				Systems:	MDF Room - l	Dedicated A/C E	Equipment (DX Split
				-	System)		
				Years:	2023		
				Systems:	Electric Dome	stic Water Heate	er (1 of 2)
				Years:	2022		
				Systems:	Exhaust Fans		
				Years:	2021		
				Systems:	Packaged Air (	Cooled Chillers;	Electric Domestic Water
					Heater (1 of 2,	temporary)	
				Years:	2019		
				Systems:	Fixtures - Toile	ets, Urinals	
				Years:	2015		
Are there	fuel tanks?			No			
Total # of	f water main service er	ntries to the asset		2			
	n Rooms Locations			MER C12			
		ing or Defective CO Detectors?		No			
	any Painted/Obstructe	ed Sprinkler Heads?		Yes			
Location	* *				, C2, C3, C4, C	5 (painted, 7)	
Are there	any Emergency Stop	Switches with Missing Hammers?		No compo	nents		
riority Co	ndition						
Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
No condi	tion recorded	Description	Affected	Description	Notified	Title	Image
	tion recorded	Description	Affected	Description	Notified	Title	Image
No condi	tion recorded	Description	Affected	Description  Response		Title	Image
No condi	tion recorded	Description	Affected	•		Title	Image
No condition No co	tion recorded	Description	Affected	•		Title	Image
No condition of the No con	tion recorded  t t cal ONDITIONING	Description	Affected	Response		Title	Image
No condition of the No con	tion recorded  (cal	Description	Affected	Response		Title	Image
No condition of the con	tion recorded  t cal ONDITIONING ed Water System	Description	Affected	Response  Inspected Inspected	exist	Title	Image
No condition of the con	tion recorded  t cal ONDITIONING ed Water System sorption Chiller	Description	Affected	Response  Inspected Inspected Does not of	exist exist	Title	Image
No condition of the con	tion recorded  ONDITIONING ed Water System sorption Chiller Cooled Chiller	ion: Piping, Pumps and Auxiliaries	Affected	Inspected Inspected Does not of	exist exist	Title	Image
No condition of the con	tion recorded  ONDITIONING ed Water System sorption Chiller Cooled Chiller	•	Affected	Inspected Inspected Does not of Does not of Does not of	exist exist	Title	Image
No condition of the con	tion recorded  Color of the col	•	Affected	Inspected Inspected Does not of Does not of Inspected Joseph Does not of Joseph Does not	exist exist	Title	Image
No condition of the con	tion recorded  Coal  ONDITIONING  ed Water System  sorption Chiller  Cooled Chiller  Cooled Condenser  illed Water Distributi	•	Affected	Inspected Inspected Does not of Does not of Inspected Joseph Does not of Joseph Does not	exist exist exist	Title	Image
No condition of the con	cal ONDITIONING ed Water System sorption Chiller Cooled Condenser illed Water Distributi ondition Deficiency	•	Affected	Inspected Inspected Does not of Does not of Inspected The second of the	exist exist exist	Title	Image
No condition of the con	cal ONDITIONING ed Water System sorption Chiller Cooled Condenser illed Water Distribution Deficiency ekflow Preventer ondition	•	Affected	Inspected Inspected Does not of Does not of Inspected 3- Fair No deficie Inspected 3- Fair	exist exist exist	Title	Image
No condition of the con	cal ONDITIONING ed Water System sorption Chiller Cooled Condenser illed Water Distributi ondition Deficiency ckflow Preventer ondition Deficiency	ion: Piping, Pumps and Auxiliaries	Affected	Inspected Inspected Does not of Does not of Inspected 3- Fair No deficie Inspected 3- Fair No deficie	exist exist exist exist encies recorded	Title	Image
No condition of the con	cal ONDITIONING ed Water System sorption Chiller Cooled Condenser illed Water Distributi ondition Deficiency ckflow Preventer ondition Deficiency ntral Station Air Hand	ion: Piping, Pumps and Auxiliaries	Affected	Inspected Inspected Does not of Does not of Inspected 3- Fair No deficie Inspected 3- Fair No deficie Inspected	exist exist exist exist encies recorded	Title	Image
No condition of the con	cal ONDITIONING ed Water System sorption Chiller Cooled Chiller Cooled Condenser illed Water Distribution Deficiency skflow Preventer ondition Deficiency ntral Station Air Hand Instance	ion: Piping, Pumps and Auxiliaries	Affected	Inspected Inspected Does not of Does not of Inspected 3- Fair No deficie Inspected 3- Fair No deficie	exist exist exist exist encies recorded	Title	Image
No conditions of the condition	cal ONDITIONING ed Water System sorption Chiller Cooled Chiller Cooled Condenser illed Water Distribution ondition Deficiency ckflow Preventer ondition Deficiency ntral Station Air Hand Instance Instance Condition	ion: Piping, Pumps and Auxiliaries	Affected	Inspected Inspected Does not of Does not of Does not of Inspected 3- Fair No deficie Inspected 3- Fair No deficie Inspected Roof 3- Fair	exist exist exist exist encies recorded	Title	Image
No condition of the con	cal ONDITIONING ed Water System sorption Chiller Cooled Condenser illed Water Distributi ondition Deficiency ekflow Preventer ondition Deficiency intral Station Air Hand Instance Instance Quantity	don: Piping, Pumps and Auxiliaries	Affected	Inspected Inspected Does not of Does not of Does not of Inspected 3- Fair No deficie Inspected 3- Fair No deficie Inspected Roof 3- Fair	exist exist exist exist encies recorded	Title	Image
No conditions of the condition	cal ONDITIONING ed Water System sorption Chiller Cooled Condenser illed Water Distributi ondition Deficiency ekflow Preventer ondition Deficiency intral Station Air Hand Instance Instance Quantity Instance Quantity	don: Piping, Pumps and Auxiliaries	Affected	Inspected Inspected Does not of Does not of Does not of Inspected 3- Fair No deficied Inspected 3- Fair No deficied Inspected 3- Fair A deficied Roof 3- Fair 4 EACH	exist exist exist exist encies recorded	Title	Image
No conditions of the condition	cal ONDITIONING ed Water System sorption Chiller Cooled Condenser illed Water Distribution in Deficiency ckflow Preventer ondition Deficiency intral Station Air Hand Instance Instance Quantity Instance Quantity Manufacturer	don: Piping, Pumps and Auxiliaries	Affected	Inspected Inspected Does not of Does not of Does not of Inspected 3- Fair No deficie Inspected 3- Fair No deficie Inspected Roof 3- Fair 4 EACH Air Fan	exist exist exist encies recorded encies recorded	Title	Image
No condition of the con	cal ONDITIONING ed Water System sorption Chiller Cooled Condenser illed Water Distributiondition Deficiency ekflow Preventer ondition Deficiency intral Station Air Hand Instance Instance Condition Instance Quantity Manufacturer EquipmentId	dler Uom	Affected	Inspected Inspected Does not of Does not of Does not of Inspected 3- Fair No deficie Inspected 3- Fair No deficie Inspected Roof 3- Fair 4 EACH Air Fan AHU-2, A	exist exist exist exist encies recorded	Title	Image
No condition of the con	cal ONDITIONING ed Water System sorption Chiller Cooled Condenser illed Water Distributiondition Deficiency ckflow Preventer ondition Deficiency intral Station Air Hand Instance Instance Condition Instance Quantity Manufacturer EquipmentId Capacity/Size Qua	dler Uom	Affected	Inspected Inspected Does not of Does not of Does not of Inspected 3- Fair No deficied Inspected 3- Fair No deficied Inspected Roof 3- Fair 4 EACH Air Fan AHU-2, A	exist exist exist encies recorded encies recorded	Title	Image
No condition of the con	cal ONDITIONING ed Water System sorption Chiller Cooled Condenser illed Water Distributiondition Deficiency ekflow Preventer ondition Deficiency intral Station Air Hand Instance Instance Condition Instance Quantity Manufacturer EquipmentId	dler  Uom  untity M	Affected	Inspected Inspected Does not of Does not of Does not of Inspected 3- Fair No deficie Inspected 3- Fair No deficie Inspected Roof 3- Fair 4 EACH Air Fan AHU-2, A	exist exist exist encies recorded encies recorded	Title	Image

## **Building Condition Assessment Survey 2023-2024**

uestion	Response	
AIR CONDITIONING		
Chilled Water System		
Central Station Air Handler		
Source of Installation Year	Inspector Estimate	
Deficiency	No deficiencies recorded	
Instance	Roof	
Instance Condition	3- Fair	
Instance Quantity	1 EACH	
Instance Quantity Uom	EACH	
Manufacturer	Air Fan	
EquipmentId	AHU-5	
Capacity/Size Quantity	20	
Capacity/Size UOM	Fan Motor HP	
Source of Capacity/Size	Documented	
Installation Year Source of Installation Year	1993	
-	Inspector Estimate	
Deficiency	No deficiencies recorded	
Instance	MER C12	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	American Air Filter	
EquipmentId	AHU-6	
Capacity/Size Quantity	5	
Capacity/Size UOM	Fan Motor HP	
Source of Capacity/Size	Documented	
Installation Year	1971	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	MER C12	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	Roof	
Instance Condition	4- Between Fair and Poor	
Instance Quantity	1	
	EACH	
Instance Quantity Uom		
Manufacturer	Air Fan	
EquipmentId	AHU-1	
Capacity/Size Quantity	15	
Capacity/Size UOM	Fan Motor HP	
Source of Capacity/Size	Documented	
Installation Year	1993	
Source of Installation Year	Inspector Estimate	
Deficiency	DEFECTIVE MOTOR	
Deficiency Location/Instance	Roof	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	

## **Building Condition Assessment Survey 2023-2024**

iunicui Inspection	
Question	Response
AIR CONDITIONING	
Chilled Water System	
Packaged Air Cooled Chiller	Inspected
Instance	Building Exterior by Loading Dock
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Trane
EquipmentId	CH-1
Capacity/Size Quantity	200
Capacity/Size UOM	Tons
Source of Capacity/Size	Inspector Estimate
Installation Year	2019
Source of Installation Year	Custodial Staff R-134A
Refrigerant Type Deficiency	OVER 100 TONS:DEFECTIVE CONTROLS
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Building Exterior by Loading Dock
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Trane
EquipmentId	CH-2
Capacity/Size Quantity	200
Capacity/Size UOM	Tons
Source of Capacity/Size	Inspector Estimate
Installation Year	2019
Source of Installation Year	Custodial Staff
Refrigerant Type	R-134A
Deficiency	No deficiencies recorded
Water Cooled Chiller	Does not exist
Condenser Water Distribution: Piping, Pumps and Auxiliaries	Does not exist
Cooling Coil in Ductwork	Does not exist
Cooling Tower	Does not exist
DX Split System	Does not exist
Dry Cooler	Does not exist
Packaged / Rooftop Unit	Does not exist
Packaged Terminal A/C	Does not exist  Does not exist
Refrigerant Leak Detection System	Does not exist  Does not exist
Refrigerant Piping Return Fan	Does not exist  Does not exist
CENTRAL ACID WASTE NEUTRALIZING TANK	Does not exist
CLIMATE CONTROL SYSTEM	Inspected  Descriptions:
BMS Propunctio System	Does not exist Inspected
Pneumatic System Instance	1
	Basement, Kitchen, Building Perimeter  4- Between Fair and Poor
Instance Condition	
Instance Quantity	1 EACH
Instance Quantity Uom	
Building Area Covered by Operational System  Deficiency	21-40%  DEFECTIVE TERMINAL UNIT CONTROL VALVE

## **Building Condition Assessment Survey 2023-2024**

нинист търссион	Ais
Question	Response
CLIMATE CONTROL SYSTEM	
Pneumatic System	
Deficiency Location/Instance	Perimeter Classrooms
Deficiency Quantity	25
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE TEMPERATURE CONTROL THERMOSTAT
Deficiency Location/Instance	Perimeter Classrooms
Deficiency Quantity	25
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE DAMPER ACTUATOR
Deficiency Location/Instance	MER C12 @ AHU-6
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Hybrid System	Does not exist
Electric System	Does not exist
COMPACTOR	Does not exist
CONVEYING	Inspected
Dumbwaiter	Does not exist
Elevator	Inspected
Condition	3- Fair
Are all the existing elevators operable?	Yes
Deficiency	No deficiencies recorded
Escalator	Does not exist
Non-auditorium Handicap Lift - Vertical	Does not exist
Non-auditorium Handicap Lift - Stair	Does not exist
Ash Hoist	Does not exist
Sidewalk Elevator	Does not exist
DOMESTIC WATER SYSTEM	Inspected
	Inspected
Domestic Cold Water System	Does not exist
Gravity System	
Pressure Booster System	Does not exist
Water Service	Inspected
Instance	Sprinkler/Water Meter Room C2
Instance Condition	3- Fair
Instance Quantity	2
Instance Quantity Uom	EACH
Deficiency	WATER MAIN:MISSING BACKFLOW PREVENTION DEVICE
Deficiency Location/Instance Deficiency Quantity	Sprinkler/Water Meter Room C2 2
Quantity Uom	EACH
Potential Action	
	INSTALL PRICEDITY 2
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

## **Building Condition Assessment Survey 2023-2024**

nanicai Inspection	Als
Question	Response
DOMESTIC WATER SYSTEM	
Domestic Cold Water System	
Water Service	
Violations	No violations recorded
Domestic Hot Water System	Inspected
Domestic Hot Water Remote Storage Tank	Does not exist
Domestic Water Heat Exchanger	Inspected
Condition	5- Poor
Deficiency	DETERIORATED
Deficiency Location/Instance	MER C12
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Electric Domestic Water Heater	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Gas Fired Domestic Water Heater	Does not exist
Oil Fired Domestic Water Heater	Does not exist
Heat Pump Domestic Water Heater	Does not exist
Domestic Water Distribution Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected
Interior Storm Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sewage/Waste/Vent Piping	Inspected
Condition	3- Fair
Deficiency	INTERIOR FLOOR DRAIN:DEFECTIVE
Deficiency Location/Instance	Toilet Room 279
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Sewage Ejector Pump	Does not exist
Sump Pump	Does not exist
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Inspected
Dual Temperature Distribution: Piping, Pumps and Auxiliaries	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Dual Temperature Terminal Fan Coil Unit	Does not exist
FIXTURES	Inspected
Staff And Other	Inspected
Janitor Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<del></del> ,	

## **Building Condition Assessment Survey 2023-2024**

municui inspecuon	Alss
Question	Response
FIXTURES	
Staff And Other	
Toilet	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Urinal	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Student	Inspected
Drinking Fountain	Inspected
Condition	2- Between Good and Fair
Deficiency	CLOGGED/LEAKING
Deficiency Location/Instance	1st Floor Cafeteria, Corridor near Room 258
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lavatory/Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Locker Room Shower	Does not exist
Sink And Fountain Combo Unit	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Urinal	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
GAS FIRED FURNACE	Does not exist
GAS SERVICE	Inspected
Gas Distribution Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Gas Meter Room Exhaust Fan	Does not exist
Gas Meter Room Vent	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Gas Pressure Booster	Does not exist
CO/Gas Leak Detection	Does not exist
HEATING	Inspected
Heating Coil In Ductwork	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Hydronic Heating	Inspected
Hydronic Hot Water Distribution: Piping, Pumps and Auxiliaries	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Backflow Preventer	Does not exist
Hot Water Heat Exchanger	Inspected
Condition	3- Fair

## **Building Condition Assessment Survey 2023-2024**

Mechanical Inspection	X153
-----------------------	------

estion	Response	
HEATING		
Hydronic Heating		
Hot Water Heat Exchanger		
Deficiency	DEFECTIVE	
Deficiency Location/Instance	MER C12 (1 of 2)	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPAIR	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Radiator/Convector/Fin Tube	Inspected	
Condition	3- Fair	
Deficiency	RADIATOR/CONVECTOR: DEFECTIVE	
Deficiency Location/Instance	Stairs "A", "B", "C", "D".	
Deficiency Quantity	14	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Steam Heating	Does not exist	
Steam supplied by External Sources	Does not exist	
Unit Heater/Cabinet Heater	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
IEATING PLANT	Does not exist	
Enclosed IDF Room	Does not exist	
ATCHEN	Inspected	
Instance on 1st Floor	Inspected	
CO Detector	Y 1	
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Gas System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Grease Trap		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Hood		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
	No deficiencies recorded	
Hood Exhaust Ductwork Instance on 1st Floor	Inspected	
	3- Fair	
Instance Condition		
Deficiency	No deficiencies recorded	
Hood Exhaust Fan		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hood Fire Suppression System		

## **Building Condition Assessment Survey 2023-2024**

municui Inspection		A133
Question	Response	
KITCHEN		
Hood Fire Suppression System		
Instance on 1st Floor	Does not exist	
Hot Water Temperature Booster		
Instance on 1st Floor	Does not exist	
Kitchen Sink		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	Missing Air Gap	
Deficiency Location/Instance	Kitchen	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
MDF Room	Inspected	
Instance on Library - Room 268	Inspected	
Dedicated A/C Equipment	•	
Instance on Library - Room 268	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Inspected	
Instance on Room 254	Inspected	
Alternative Use	No	
Acid Waste Neutralizing Tank		
Instance on Room 254	Does not exist	
CO Detector		
Instance on Room 254	Not required	
Emergency Shower		
Instance on Room 254	Does not exist	
Eye Wash		
Instance on Room 254	Does not exist	
Hood Exhaust Ductwork		
Instance on Room 254	Does not exist	
Hood Exhaust Fan		
Instance on Room 254	Does not exist	
Fixed Laboratory Hood		
Instance on Room 254	Does not exist	
Laboratory Sink		
Instance on Room 254	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Make-up Air Unit		
Instance on Room 254	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected	
Dry Sprinkler Alarm Valve Assembly	Does not exist	
Wet Sprinkler Alarm Valve Assembly	Does not exist	
Fire Booster Pump Assembly	Does not exist	
Roof Tank	Does not exist	
Siamese Connection	Inspected	
Condition	3- Fair	
Deficiency	MISSING CAPS	
Deficiency	MIDDING ON D	

## **Building Condition Assessment Survey 2023-2024**

	11
uestion	Response
SPRINKLERS, STANDPIPE, FIRE SYSTEM	
Siamese Connection	
Deficiency Location/Instance	Building Exterior
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Sprinkler Head	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Rooms C1, C2, C3, C4, C5 (painted, 7)
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Sprinkler Piping	Inspected
Condition	3- Fair
	No deficiencies recorded
Deficiency	
Standpipe System	Inspected
Hose Valve Assembly	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Water Gong	Does not exist
SWIMMING POOL	Does not exist
VENTILATION	Inspected
Is the building Mechanically ventilated?	Yes
Exhaust Fan	Inspected
Condition	1- Good
Approximate Total # of Fans	1-25
Deficiency	No deficiencies recorded
	Does not exist
Heating And Ventilating Unit Metal Ductwork	Inspected
Condition	3- Fair
Are there any uninsulated ductwork by design in Mechanical rooms?	No
Are there chain operated dampers?	No
Deficiency	DEFECTIVE REGISTER/DIFFUSER
•	
Deficiency Location/Instance Deficiency Quantity	Corridor near Main Entrance, Rooms 310, 341, 365A
Quantity Uom	
· · · · · · · · · · · · · · · · · · ·	EACH MAINTENANCE
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Supply Fan	Does not exist
Unit Ventilator	Does not exist