Building Condition Assessment Survey 2023-2024

Electrical Inspection X154

Asset:	P.S. 154 - BRONX, 333 EAST 135 STREET, BRONX, NY, 10454		
Inspection Id	d Inspection Type Time In Last Edited		
1710	ELECTRICAL	2023-12-15 07:57AM	2024-02-09 11:38AM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Partial Molded Case Circuit Breaker Panel Boards
	Years: 2023, 2022, 2008, 2000, 1985
	Systems: Fire Rescue Area Intercom System
	Years: 2023
	Systems: Variable Frequency Drive
	Years: 2022
	Systems: Intrusion Alarm System
	Years: 2016
	Systems: Interior Lighting (Except Library), Telephone System,
	Most Exit Lights (Battery Pack)
	Years: 2015
	Systems: Public Address System, Local Sound System
	Years: 2010
	Systems: Most Security Lights
	Years: 2009, 1995
	Systems: Library
	Years: 2008
	Systems: Emergency Light
	/Exit Light Panel
	Years: 1994
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Water Penetration In Electrical Room?

Question	Response	
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in	Yes	
your building?		
Are dedicated intercoms available in all of these spaces for use during a fire?	Yes	
Are all dedicated intercoms operational?	Yes	

No

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
Yes	Public Address System - Speakers Not Operational	All speakers on the School Play Yard are out of order.	Public Address System	School Play Yard	Julio Mateo	Custodian	No Photo Taken
Yes	Water Leaks onto Electrical Equipment	Water penetrates through foundation wall onto electrical panel.	Panel Board	Boiler Room	Julio Mateo	Custodian	COLD WITER

Inspection

Question	Response
Electrical	
ATHLETIC FIELD	Does not exist
AUDITORIUM	Inspected
Instance on 1st Floor	Inspected
House Lighting	
Instance on 1st Floor	Inspected
Does a Chandelier Exist?	No

Electrical Inspection	X154
O	D

uestion	Response
AUDITORIUM	
House Lighting	
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	<u></u>
Instance on 1st Floor	Does not exist
Surface Mounted	2005 Hot VAIST
Instance on 1st Floor	Does not exist
Recessed Mounted	DOG HOL CAIST
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Local Sound System	ivo deficiencies recorded
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Does not exist
Theater Lighting System	
Instance on 1st Floor	Inspected
Dimming System	1
Instance on 1st Floor	Does not exist
Theater Lighting	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	32
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
CAFETERIA	Inspected
Instance on 1st Floor	Inspected
Lighting Instance on 1st Floor	Inspected

Electrical Inspection	X154
Question	Response

Question	Response
CAFETERIA	•
Lighting	
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	Description of society
Instance on 1st Floor	Does not exist
Theater Lighting System Instance on 1st Floor	Does not exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
COMPUTER LAB	Does not exist
GYMNASIUM	Inspected
Instance on 2nd Floor	Inspected
Lighting	
Instance on 2nd Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 2nd Floor	Does not exist
Lighting Fixture - HID	
Instance on 2nd Floor	Does not exist
Lighting Fixture - Incandescent	

Building Condition Assessment Survey 2023-2024

Electrical Inspection X154

· · · · · · · · · · · · · · · · · · ·		
Question	Response	
GYMNASIUM		
Lighting		
Lighting Fixture - Incandescent		
Instance on 2nd Floor	Does not exist	
Lighting Fixture - LED		
Instance on 2nd Floor	Inspected	
Pendant Mounted		
Instance on 2nd Floor	Does not exist	
Surface Mounted		
Instance on 2nd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 2nd Floor	Does not exist	
Local Sound System		
Instance on 2nd Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	2010	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 2nd Floor	Does not exist	
Scoreboard		
Instance on 2nd Floor	Does not exist	
Theater Lighting System		
Instance on 2nd Floor	Does not exist	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
Lighting		
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Does not exist	
LIBRARY	Inspected	
Instance on 1st Floor	Inspected	
Lighting	<u>-</u>	
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted	пареска	
Instance on 1st Floor	Inspected	
mountee on 15t I 1001	порессе	

Electrical Inspection	X154

icui inspection	AIS
uestion	Response
LIBRARY	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
Raceway With Receptacles	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Does not exist
OCKER ROOM	Inspected
Instance on 2nd Floor	Inaccessible
MULTIPURPOSE ROOM	Does not exist
CIENCE DEMO ROOM	Does not exist
CIENCE LAB	Does not exist
CIENCE PREP ROOM	Does not exist
SWIMMING POOL	Does not exist
TOILET ROOM - STAFF	Inspected Inspected
Lighting	Ingraphed

Building Condition Assessment Survey 2023-2024

Electrical Inspection X154

iricai Inspection	A134
Question	Response
TOILET ROOM - STAFF	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	2- Between Good and Fair
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Boiler Room, 1st Floor by Exit A, 2nd Floor by Exit B
Deficiency Quantity Quantity Hom	
Quantity Uom	EACH

Electrical Inspection		X154
	~	

Question	Response
EXIT LIGHT	
Battery Pack	
Violations	No violations recorded
Non Battery Pack	Does not exist
EXIT/EMERGENCY LIGHT	Does not exist
FIRE ALARM SYSTEM	Under construction
GROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not exist
MOTOR CONTROLLER	Inspected Does not exist
MOTOR CONTROL CENTER MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
·	Inspected
PANEL BOARD Fund Disconnect Switch Type	Inspected
Fused Disconnect Switch Type Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Mechanical Room 301, Boiler Room
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B7
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action Purpose of Action	PRIORITY 1 LEVEL 2
Violations	No violations recorded
	Inspected
Molded Case Circuit Breaker Type Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	26
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Pautuous Vousion 2 () (D)	Page 7 of 10 Print Date: 9/9/2024

Building Condition Assessment Survey 2023-2024

Electrical Inspection X154

*	
uestion	Response
PANEL BOARD	
Molded Case Circuit Breaker Type	
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	Main Office
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Dukane 250
Installation Year	2010
Source of Installation Year	Documented
Deficiency	SPEAKER NOT OPERATIONAL
Deficiency Location/Instance	Play Yard
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5 LEVEL 6
Purpose of Action Violations	No violations recorded
SECURITY	Inspected
IPDVS/CCTV System	Does not exist
Intrusion Alarm System Central Control Panel	Inspected Inspected
Instance	Room 143
Instance Condition	2- Between Good and Fair
Instance Quantity	1
	EACH
Instance Quantity Uom Model	Vista 128BPT
Installation Year	2016
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
-	
Lighting - Security Condition	Inspected 3- Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Location/Instance	By Exit A and B
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3

Electrical Inspection	X154
·	

Question	Response	
SECURITY		
Lighting - Security		
Violations	No violations recorded	
SERVICE SWITCH	Inspected	
Instance	Electrical Room B7	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Metropolitan	
EquipmentId	Main Service Sw.	
Capacity/Size Quantity	1200	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	1962	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room B7	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
SWITCHBOARD	Inspected	
Number of Spares	3	
Fused Disconnect Switch Type	Inspected	
Instance	Electrical Room B7	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Metropolitan Electric	
EquipmentId	Main DIST Center	
Capacity/Size Quantity	1000	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	3	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Nameplate	
Installation Year	1962	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room B7	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Fused Knife Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Does not exist	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	

Building Condition Assessment Survey 2023-2024

Electrical Inspection X154

QuestionResponseTRANSFORMERDoes not exist