Building Condition Assessment Survey 2023-2024

Electrical Inspection

Asset:	I.S. 158 - BRONX, 800 HOME STRE	LL I, DRUMA, INY, 10430			
Inspection Id	Inspection Type			Time In	Last Edited
251	ELECTRICAL			2023-10-17 08:24AM	2023-11-07 08:54AN
set Data					
Question			Answer		
Have any Syste	ms/Major Building Components been upgrad	ded?	Systems:	Most Molded Case Circuit Break	ker Panel Board
			Years:	2022, 2013, 2000, 1985	
			Systems:	Intrusion Alarm System (Remote	e Annunciator)
			Years:	2022	
			Systems:	Partial Motor Starters, Public Ac Clocks)	ldress System (Partial
			Years:	2021	
			Systems:	IPDVS/CCTV System, Most En (Battery Pack)	nergency Lighting
			Years:	2020	
			Systems:	Public Address System (Except	Clocks, Speakers)
			Years:	2017	
			Systems:	Telephone System, LAN	
			Years:	2016	
			Systems:	Interior Lighting Except (HID L Rooms 325, 331)	ighting in Science Lab
			Years:	2015	
			Systems:	Partial Fused Disconnect Switch	Type Panel Board
			Years:	2012, 1998	
			Systems:	Lightning Protection, Science La (Projection System)	ab Room 225
			Years:	2012	
			Systems:	Security Lights	
			Years:	2009	
			Systems:	Fire Alarm System	
			Years:	2007	
			Systems:	Auditorium (Local Sound Syster System), HID Lighting (Science 331)	
			Years:	2005	
			Systems:	Intrusion Alarm System, Emerge Panel	ency Light/Exit Light
			Years:	1998	
			Systems:	Partial Service Switch	
			Years:	1985	
Type of Service			Below Gr	ound	
	e Whiteboard (IWB) Exist?		Yes		
	on In Electrical Room?		No		
	D INTERCOMS IN FIRE RESCUE A	REAS		_	
Question				Response	
your building				Yes	
	ted intercoms available in all of these spaces	for use during a fire?		Yes	
	dicated intercoms operational?			Yes	
ority Condit	ion				
ist Prio	ority Condition	Component Loc	cation	Person(s) Person(s) P	hoto
xist Pric	ority Condition	Component Loc	cation	Person(s) Person(s) P	hoto

Emergency

Building Condition Assessment Survey 2023-2024

Science Lab -

Manuel

Fireman

Electrical Inspection

Emergency Shut-Off

Emergency Shut- Off

Yes

Yes	Emergency Shut-Off Power - Not Operational	Emergency Shut- Off Power was Vandalized	Emergency Shut-Off Power	Science Lab - Room 325	Manuel Amaya	Fireman	
Yes	Emergency Gas Shut-Off Valve - Not Operational	Emergency Gas Shut-Off Valve was vandalized.	Emergency Gas Shut-Off Valve	Science Lab - Room 325	Manuel Amaya	Fireman	
Inspect	ion						
Ques	tion			Response			
Elect	rical						
AT	HLETIC FIELD			Does not o	exist		
AU	DITORIUM			Inspected			
	Instance on 2nd Floor			Inspected			
Н	ouse Lighting						
	Instance on 2nd Floor			Inspected			
	Does a Chandelier Exi	st?		No			
	Lighting Fixture - Fluoresce	nt					
	Instance on 2nd Floor			Inspected			
	Pendant Mounted						
	Instance on 2nd Floor			Does not o	exist		
	Surface Mounted						
	Instance on 2nd Floor			Inspected			
	Instance Condition				en Good and F		
	Deficiency			No deficie	encies recorde	1	
	Recessed Mounted						
	Instance on 2nd Floor			Does not o	exist		
	Lighting Fixture - HID			D (• ,		
	Instance on 2nd Floor			Does not o	exist		
	Lighting Fixture - Incandesc	cent			• ,		
	Instance on 2nd Floor			Does not o	exist		
	Lighting Fixture - LED Instance on 2nd Floor			Inspected			
	Pendant Mounted			Inspected			
	Instance on 2nd Floor			Does not o	evict		
	Surface Mounted			Does not	CAISt		
	Instance on 2nd Floor			Does not o	exist		
	Recessed Mounted						
	Instance on 2nd Floor			Inspected			
	Instance Condition			-	n Good and F	air	
	Deficiency			No deficie	encies recorde	ł	
	ocal Sound System						
	Instance on 2nd Floor			Inspected			
	Instance Condition			3- Fair			
	Installation Year			2005			
	Source of Installation	Year		Document			
_	Deficiency			No deficie	encies recorde	1	
Р	rojection System				• .		
	Instance on 2nd Floor			Does not o	exist		
Т	heater Lighting System			Tagar 4 1			
	Instance on 2nd Floor			Inspected			
3CAS Part	ners Version 2.0 (P)		Page 2	of 19			Print Date: 8/8/2024

Building Condition Assessment Survey 2023-2024

Electrical Inspection

uestion	Response	
AUDITORIUM	. .	
Theater Lighting System		
Dimming System		
Instance on 2nd Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Theater Lighting		
Instance on 2nd Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
CAFETERIA	Inspected	
Instance on 1st Floor - Large	Inspected	
Instance on 1st Floor - Small	Inspected	
Lighting	mspected	
Instance on 1st Floor - Large	Inspected	
Instance on 1st Floor - Small	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor - Large	Inspected	
Instance on 1st Floor - Small	Inspected	
Pendant Mounted		
Instance on 1st Floor - Large	Does not exist	
Instance on 1st Floor - Small	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on 1st Floor - Large	Does not exist	
Instance on 1st Floor - Small	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor - Large	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on 1st Floor - Small	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor - Large	Does not exist	
Instance on 1st Floor - Small	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor - Large	Does not exist	
Instance on 1st Floor - Small	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor - Large	Does not exist	
Instance on 1st Floor - Small	Does not exist	
Local Sound System		
Instance on 1st Floor - Large	Inspected	
Instance Condition	5- Poor	
Installation Year	1974	
Source of Installation Year	Documented	
Deficiency	AMPLIFIER NOT OPERATIONAL	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE SYSTEM	
Urgency of Action	PRIORITY 2	
Purpose of Action	LEVEL 2	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

rical Inspection		A150
Question	Response	
CAFETERIA		
Local Sound System		
Violations	No violations recorded	
Instance on 1st Floor - Small	Does not exist	
Projection System		
Instance on 1st Floor - Large	Does not exist	
Instance on 1st Floor - Small	Does not exist	
Theater Lighting System		
Instance on 1st Floor - Large	Does not exist	
Instance on 1st Floor - Small	Does not exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
COMPUTER LAB	Inspected	
Instance on Room 322C	Inspected	
Power Panel?	Yes	
Lighting		
Instance on Room 322C	Inspected	
Lighting Fixture - Fluorescent	1	
Instance on Room 322C	Inspected	
Pendant Mounted	1	
Instance on Room 322C	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 322C	Does not exist	
Recessed Mounted		
Instance on Room 322C	Does not exist	
Lighting Fixture - HID		
Instance on Room 322C	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 322C	Does not exist	
Lighting Fixture - LED		
Instance on Room 322C	Does not exist	
Raceway With Receptacles		
Instance on Room 322C	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
GYMNASIUM	Inspected	
Instance on Ground Floor	Inspected	
Lighting	nispecieu	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

ricui Inspeciion		A150
uestion	Response	
GYMNASIUM		
Lighting		
Instance on Ground Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on Ground Floor	Does not exist	
Lighting Fixture - HID		
Instance on Ground Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on Ground Floor	Does not exist	
Lighting Fixture - LED		
Instance on Ground Floor	Inspected	
Pendant Mounted	I	
Instance on Ground Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Ground Floor	Does not exist	
Recessed Mounted		
Instance on Ground Floor	Does not exist	
Local Sound System Instance on Ground Floor	Inspected	
Instance Condition	5- Poor	
Installation Year	1974	
Source of Installation Year	Documented	
Deficiency	AMPLIFIER NOT OPERATIONAL	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE SYSTEM	
Urgency of Action	PRIORITY 2	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Projection System		
Instance on Ground Floor	Does not exist	
	Does not exist	
Scoreboard Instance on Ground Floor	Does not exist	
Theater Lighting System		
Instance on Ground Floor	Does not exist	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
Lighting		
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		

Building Condition Assessment Survey 2023-2024

Electrical Inspection

	ΛΙ
uestion	Response
KITCHEN	
Lighting	
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
LIBRARY	Inspected
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
Raceway With Receptacles	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Does not exist
OCKER ROOM	Inspected
Instance on Ground Floor - Boys	Inspected
Alternative Use	
	Yes
Instance on Ground Floor - Girls	Inspected
Alternative Use	No
Lighting	Y
Instance on Ground Floor - Boys	Inspected
Instance on Ground Floor - Girls	Inspected
Lighting Fixture - Fluorescent	
Instance on Ground Floor - Boys	Inspected
Instance on Ground Floor - Girls	Inspected
Pendant Mounted	
Instance on Ground Floor - Boys	Does not exist
Instance on Ground Floor - Girls	Does not exist
Surface Mounted	
Instance on Ground Floor - Boys	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Ground Floor - Girls	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded

Building Condition Assessment Survey 2023-2024

Electrical Inspection

ical Inspection		
uestion	Response	
LOCKER ROOM		
Lighting		
Lighting Fixture - Fluorescent		
Recessed Mounted		
Instance on Ground Floor - Boys	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Ground Floor - Girls	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on Ground Floor - Boys	Does not exist	
Instance on Ground Floor - Girls	Does not exist	
Lighting Fixture - Incandescent		
Instance on Ground Floor - Boys	Does not exist	
Instance on Ground Floor - Girls	Does not exist	
Lighting Fixture - LED		
Instance on Ground Floor - Boys	Does not exist	
Instance on Ground Floor - Girls	Does not exist	
MULTIPURPOSE ROOM	Does not exist	
SCIENCE DEMO ROOM	Inspected	
Instance on Room G118	Inspected	
Power Panel?		
	Yes	
Alternative Use	Yes	
Lighting Instance on Room G118	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Instance on Room G118	Inspected	
Pendant Mounted	inspected	
Instance on Room G118	Does not exist	
Surface Mounted	Does not exist	
Instance on Room G118	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	No deficicités récorded	
Instance on Room G118	Does not exist	
Lighting Fixture - HID	Does not exist	
Instance on Room G118	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Instance on Room G118	Does not exist	
Lighting Fixture - LED	DOES NOT CAISE	
Instance on Room G118	Does not exist	
Emergency Gas Shut-Off Valve	DOES NOT CAISE	
Instance on Room G118	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power		
Instance on Room G118	Does not exist	
Power Supply		
Instance on Room G118	Does not exist	
Projection System		
Instance on Room G118	Does not exist	

NYC Department of Education Building Condition Assessment Survey 2023-2024

Electrical Inspection

•	cuon	
estion		Response
CIENCE LA	B	
Inst	tance on Rooms 425, 427	Inspected
Pov	ver Panel?	Yes
Alt	ernative Use	No
Inst	tance on Room 325	Inspected
Pov	ver Panel?	Yes
Alt	ernative Use	No
Inst	tance on Room 331	Inspected
Pov	ver Panel?	Yes
	ernative Use	No
	tance on Room 227	Inspected
	ver Panel?	Yes
	ernative Use	No
	tance on Room 225	Inspected
	ver Panel?	*
	ernative Use	No
	ernative Use	No
Lighting	D 405 407	T (1
	tance on Rooms 425, 427	Inspected
	tance on Room 325	Inspected
	tance on Room 331	Inspected
	tance on Room 227	Inspected
	tance on Room 225	Inspected
	ïxture - Fluorescent	
	tance on Rooms 425, 427	Inspected
	tance on Room 325	Inspected
	tance on Room 331	Inspected
Inst	tance on Room 227	Inspected
Inst	tance on Room 225	Inspected
	Mounted	
	tance on Rooms 425, 427	Inspected
	tance Condition	2- Between Good and Fair
	ficiency	No deficiencies recorded
Inst	tance on Room 325	Inspected
Inst	tance Condition	2- Between Good and Fair
Det	ficiency	No deficiencies recorded
Inst	tance on Room 331	Inspected
Inst	tance Condition	2- Between Good and Fair
Def	ficiency	No deficiencies recorded
Inst	tance on Room 227	Does not exist
Inst	tance on Room 225	Inspected
Inst	tance Condition	2- Between Good and Fair
Def	ficiency	No deficiencies recorded
Surface	Mounted	
Inst	tance on Rooms 425, 427	Does not exist
Inst	tance on Room 325	Does not exist
Inst	tance on Room 331	Does not exist
Inst	tance on Room 227	Does not exist
Inst	tance on Room 225	Does not exist
	I Mounted	
	tance on Rooms 425, 427	Inspected
	tance Condition	2- Between Good and Fair
	ficiency	No deficiencies recorded
	tance on Room 325	Does not exist

Building Condition Assessment Survey 2023-2024

Electrical Inspection

		ΛΙ
estion	Response	
CIENCE LAB		
Lighting		
Lighting Fixture - Fluorescent		
Recessed Mounted		
Instance on Room 331	Does not exist	
Instance on Room 227	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Room 225	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on Rooms 425, 427	Does not exist	
Instance on Room 325	Inspected	
Instance on Room 331	Inspected	
Instance on Room 227	Does not exist	
Instance on Room 225	Does not exist	
Pendant Mounted		
Instance on Room 325	Does not exist	
Instance on Room 331	Does not exist	
Surface Mounted		
Instance on Room 325	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 331	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Room 325	Does not exist	
Instance on Room 331	Does not exist	
Lighting Fixture - Incandescent		
Instance on Rooms 425, 427	Does not exist	
Instance on Room 325	Does not exist	
Instance on Room 331	Does not exist	
Instance on Room 227	Does not exist	
Instance on Room 225	Does not exist	
Lighting Fixture - LED		
Instance on Rooms 425, 427	Does not exist	
Instance on Room 325	Does not exist	
Instance on Room 331	Does not exist	
Instance on Room 227	Does not exist	
Instance on Room 225	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Rooms 425, 427	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 325	Inspected	
Instance Condition	4- Between Fair and Poor	
Deficiency	NOT OPERATIONAL	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

icai Inspection		АЦ
uestion	Response	
SCIENCE LAB		
Emergency Gas Shut-Off Valve		
Violations	No violations recorded	
Instance on Room 331	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 227	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 225	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power		
Instance on Rooms 425, 427	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 325	Inspected	
Instance Condition	4- Between Fair and Poor	
Deficiency	NOT OPERATIONAL	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Instance on Room 331	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 227	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 225	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Power Supply		
Instance on Rooms 425, 427	Does not exist	
Instance on Room 325	Inspected	
Instance on Room 331	Inspected	
Instance on Room 227	Does not exist	
Instance on Room 225	Does not exist	
Instructor Unit		
Instance on Room 325	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 331	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Meter Demonstration Unit		
Instance on Room 325	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 331	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

		ЛІЗ
Question	Response	
SCIENCE LAB		
Power Supply		
Student Unit		
Instance on Room 325	Does not exist	
Instance on Room 331	Does not exist	
Projection System		
Instance on Rooms 425, 427	Does not exist	
Instance on Room 325	Does not exist	
Instance on Room 331	Does not exist	
Instance on Room 227	Does not exist	
Instance on Room 225	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
SCIENCE PREP ROOM	Inspected	
Instance on Room 327	Inspected	
Power Panel?	Yes	
Alternative Use	Yes	
Instance on Room G118A	Inspected	
Power Panel?	No	
Alternative Use	Yes	
Lighting	105	
Instance on Room 327	Inspected	
Instance on Room G118A	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 327	Increated	
Instance on Room G118A	Inspected	
	Inspected	
Pendant Mounted Instance on Room 327	Inspected	
Instance Condition	2- Between Good and Fair	
	No deficiencies recorded	
Deficiency	Does not exist	
Instance on Room G118A	Does not exist	
Surface Mounted		
Instance on Room 327	Does not exist	
Instance on Room G118A	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Room 327	Does not exist	
Instance on Room G118A	Does not exist	
Lighting Fixture - HID		
Instance on Room 327	Does not exist	
Instance on Room G118A	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 327	Does not exist	
Instance on Room G118A	Does not exist	
Lighting Fixture - LED		
Instance on Room 327	Does not exist	
Instance on Room G118A	Does not exist	
Emergen <u>cy</u> Gas Shut-Off Valve		
Instance on Room 327	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room G118A	Inspected	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

ncui Inspection		AIJO
uestion	Response	
SCIENCE PREP ROOM		
Emergency Gas Shut-Off Valve		
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power		
Instance on Room 327	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room G118A	Does not exist	
Power Supply		
Instance on Room 327	Does not exist	
Instance on Room G118A	Does not exist	
SWIMMING POOL	Does not exist	
TOILET ROOM - STAFF	Inspected	
	Inspected	
Lighting Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
	Does not exist	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent		
Lighting Fixture - LED	Does not exist	
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	
EMERGENCY GENERATOR SET	Does not exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EMERGENCY LIGHTING	Inspected	
Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	BATTERY NOT OPERATIONAL	
Deficiency Location/Instance	Throughout the Building	
Deficiency Quantity	18	
Quantity Uom	EACH	
Potential Action Urgency of Action	REPLACE BATTERY PRIORITY 5	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

estion	Response
MERGENCY LIGHTING	
Battery Pack	
Violations	No violations recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Auditorium, Library
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
XIT LIGHT	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	3- Fair
	FIXTURE NOT OPERATIONAL
Deficiency	
Deficiency Location/Instance Deficiency Quantity	Girls Locker Room, Penthouse B, Corridor by Room 403 3
Quantity Uom Potential Action	EACH
	REPLACE
Urgency of Action	PRIORITY 5 LEVEL 2
Purpose of Action	
Violations	No violations recorded
EXIT/EMERGENCY LIGHT	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
TRE ALARM SYSTEM	Inspected
Bell/Horn	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected 2- Between Good and Fair
Condition	
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
CO Detector	Does not exist
Heat Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Elevator Recall	Inspected

Building Condition Assessment Survey 2023-2024

Electrical Inspection

	711
Response	
No deficiencies recorded	
Does not exist	
Inspected	
2- Between Good and Fair	
No deficiencies recorded	
Does not exist	
Inspected	
Inspected	
2- Between Good and Fair	
No deficiencies recorded	
Inspected	
Main Entrance Lobby	
2- Between Good and Fair	
1	
EACH	
Edwards System Technology	
EST 2	
Fire Alarm Control	
2007	
Documented	
No deficiencies recorded	
Does not exist	
Does not exist	
Inspected	
Does not exist	
Inspected	
2- Between Good and Fair	
No deficiencies recorded	
Inspected	
2- Between Good and Fair	
No deficiencies recorded	
Does not exist	
Does not exist Inspected	
Inspected	
Inspected 2- Between Good and Fair No deficiencies recorded	
Inspected 2- Between Good and Fair	
Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair	
Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded	
Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected	
Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 3- Fair	
Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 3- Fair No deficiencies recorded	
Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 3- Fair No deficiencies recorded Inspected 3- Fair No deficiencies recorded Inspected	
Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 3- Fair No deficiencies recorded Inspected 3- Fair No deficiencies recorded Inspected Inspected Inspected Inspected Inspected	
Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 3- Fair No deficiencies recorded Inspected 3- Fair No deficiencies recorded Inspected 3- Fair Spected Inspected 3- Fair	
Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 3- Fair No deficiencies recorded No deficiencies recorded	
Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 3- Fair No deficiencies recorded Inspected	
Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 3- Fair	
Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 3- Fair No deficiencies recorded	
Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 3- Fair	
Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 3- Fair No deficiencies recorded	
	No deficiencies recorded Does not exist Inspected 2- Between Good and Fair No deficiencies recorded Does not exist Inspected 1 No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected Main Entrance Lobby 2- Between Good and Fair 1 Edwards System Technology EST 2 Fire Alarm Control 2007 Documented No deficiencies recorded Does not exist Does not exist Inspected Does not exist Inspected Does not exist Inspected Does not exist Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected <td< td=""></td<>

Building Condition Assessment Survey 2023-2024

Electrical Inspection

icai Inspeciion	A13
uestion	Response
LAN	
Main Equipment Rack (MDF)	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
AOTOR CONTROLLER	Inspected
MOTOR CONTROLLER MOTOR CONTROL CENTER	Inspected
Instance	4th Floor Roof -Penthouse A
Instance Condition	3- Fair
Instance Quantity	1
	EACH
Instance Quantity Uom	
Manufacturer	Lexington Standard
EquipmentId	Motor Control Center #1
Capacity/Size Quantity	500
Capacity/Size UOM Capacity/Size 2 Quantity	Amps 1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	1974
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	4th Floor Roof -Penthouse A
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	3rd Floor Roof - Penthouse B
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
	Lexington Standard
Manufacturer	Motor Control Center #2
EquipmentId Capacity/Size Quantity	500
Capacity/Size UOM	Amps
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	1974
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	3rd Floor Roof - Penthouse B
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not exist
PANEL BOARD	Inspected

Building Condition Assessment Survey 2023-2024

Electrical Inspection

lestion	Response
PANEL BOARD	
Fused Disconnect Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Penthouse A and B
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Meter Room C12
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	12
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	Main Office - Room 135
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	TOA 900 SERIES II
Installation Year	2017
Source of Installation Year	Documented
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	14
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Condition	1- Good
Installation Year	2020
Source of Installation Year	Documented
	No deficiencies recorded
Deficiency	
Deficiency Intrusion Alarm System	Inspected

Building Condition Assessment Survey 2023-2024

Electrical Inspection

iestion	Response
SECURITY	
Intrusion Alarm System	
Central Control Panel	
Instance	Custodian's Office
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 50P
Installation Year	1998
Source of Installation Year	Documented
Deficiency	PANEL NOT CONNECTED TO DOE CENTRAL STATION
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL CONNECTION
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	
	1- Good
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Main Roof above Exit 9
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Violations	No violations recorded
ERVICE SWITCH	Inspected
Instance	Electrical Meter Room C12
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Lexington
EquipmentId	Main Switch #1
Capacity/Size Quantity	1800
Capacity/Size UOM	Amps
Source of Capacity/Size	Inspector Estimate
Installation Year	1974
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Meter Room C12
Deficiency Quantity	1
Quantity Uom	EACH

NYC Department of Education Building Condition Assessment Survey 2023-2024

Electrical Inspection

neui Inspeciion		AIS
Question	Response	
SERVICE SWITCH		
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	Electrical Meter Room C12	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Lexington Main Switch #2	
EquipmentId Capacity/Size Quantity	2500	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Inspector Estimate	
Installation Year	1974	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Meter Room C12	
Deficiency Quantity		
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	Electrical Meter Room C12	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Lexington	
EquipmentId	Air Conditioning Switch	
Capacity/Size Quantity	1000	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Inspector Estimate	
Installation Year	1974	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Meter Room C12	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
SWITCHBOARD	Inspected	
Number of Spares	3	
Fused Disconnect Switch Type	Inspected	
Instance	Electrical Meter Room C12	
Instance Condition	3- Fair	
Instance Quantity	1	
	EACH	
Instance Quantity Uom		
Manufacturer	Lexington	
EquipmentId	N/A	
Capacity/Size Quantity	1800	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	3	
Capacity/Size 2 UOM	Section(s)	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

1		
uestion	Response	
SWITCHBOARD		
Fused Disconnect Switch Type		
Source of Capacity/Size	Inspector Estimate	
Installation Year	1974	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Meter Room C12	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	Electrical Room C1	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Lexington	
EquipmentId	N/A	
Capacity/Size Quantity	2500	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	5	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Switchboard Mains Size	
Installation Year	1974	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room C1	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Fused Knife Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Does not exist	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	_
Standard	Inspected	
Condition	2- Between Good and Fair	-
Deficiency	No deficiencies recorded	
FRANSFORMER	Does not exist	

TRANSFORMER

Does not exist