Building Condition Assessment Survey 2023-2024

Mechanical Inspection

Inspection Id	I.S. 162 - BRONX, 600 ST ANNS AVENUE, BRONX, I	·	Time In	Last Edited
Inspection Id	Inspection Type		-	
	MECHANICAL		2024-03-14 09:16AM	2024-06-10 11:00AN
et Data				
Question		Answer		
Have any Syste	ems/Major Building Components been upgraded?	Systems:	DX Split Systems for Class Room 7)	ns 234 and 308 (2 of
		Years:	2024	
		Systems:	Heat Pump Domestic Water Heat Drinking Fountains (~60%)	ers; Water Services;
	Years:	2022		
		Systems:	F&T/Steam Drip Traps (~80%), Thermostatic Traps (~80%)	Terminal Unit
		Years:	2020	
		Systems:	Kitchen - Grease Trap	
		Years:	2018	
		Systems:	Electric Domestic Water Heater H 2, in Health Clinic 110 - Water H	· · · · · · · · · · · · · · · · · · ·
		Years:	2017	,
		Systems:	Fixtures - Toilets, Urinals	
		Years:	2015	
		Systems:	Science Labs 329, 333; Science I Room Dedicated A/C Equipment System); Enclosed IDF Rooms - Equipment (DX Split Systems); I Water Heater for Science Labs (1 324)	(1 of 2, DX Split Dedicated A/C Electric Domestic
		Years:	2014	
		Systems:	MDF Room - Dedicated A/C Equ	ipment (1 of 2,
		**	Window A/C)	
A 41 6	se	Years: Yes	2013	
Are there fuel t	anks? bove ground tanks	2 Yes		
	bove ground tanks ity of all above ground tanks in gal.	2 20,000		
	below ground tanks	0		
	tity of all below ground tanks in gal.	0		
	r main service entries to the asset	3		
MERs/Fan Roo	oms Locations	Basement	MER, 3rd Floor MER	
Are there any s	spaces with Missing or Defective CO Detectors?	No		
Are there any I	Painted/Obstructed Sprinkler Heads?	Yes		
Location(s)		Basement 356 (paint	Corridor, Gymnasium, Rooms 102 ted, 40)	, 101A, 103, 105,
Are there any E	Emergency Stop Switches with Missing Hammers?	No compo	onents	

Priority Condition

Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
Yes	Defective Boiler Safety Auxiliary	Water Column's Try Cocks missing knobs	Steam Boiler	Boiler Room / Boilers #1, #2, #3	JULIO MATEO	Custodian	

Question	Response	
Mechanical		
AIR CONDITIONING	Inspected	
Chilled Water System	Does not exist	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

	2	A10.
Question	Response	
AIR CONDITIONING		
Condenser Water Distribution: Piping, Pumps and Auxiliaries	Does not exist	
Cooling Coil in Ductwork	Does not exist	
Cooling Tower	Does not exist	
DX Split System	Inspected	-
Indoor Unit	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Outdoor Unit	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Dry Cooler	Does not exist	
Packaged / Rooftop Unit	Does not exist	
Packaged Terminal A/C	Does not exist	
Refrigerant Leak Detection System	Does not exist	
Refrigerant Piping	Inspected	
Condition	1- Good	
Deficiency	DAMAGED/MISSING INSULATION	
•		
Deficiency Location/Instance Deficiency Quantity	Roof	
	20	
Quantity Uom	L.F.	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Return Fan	Does not exist	
CENTRAL ACID WASTE NEUTRALIZING TANK	Does not exist	
CLIMATE CONTROL SYSTEM	Inspected	
BMS	Does not exist	
Pneumatic System	Inspected	
Instance	Throughout	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
•		
Building Area Covered by Operational System	81-100% No deficiencies recorded	
Deficiency		
Hybrid System	Does not exist	
Electric System	Does not exist	
COMPACTOR	Inspected	
Condition	3- Fair	
Deficiency	NOT IN USE	
Deficiency Location/Instance	Basement - Storage Room by Room 153	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	NO ACTION	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 1	
Violations	No violations recorded	
CONVEYING	Inspected	
Dumbwaiter	Does not exist	
Elevator	Inspected	
Condition	3- Fair	
	Yes	
Are all the existing elevators operable?		
Are all the existing elevators operable? Deficiency	No deficiencies recorded	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

Question	Response
CONVEYING	
Non-auditorium Handicap Lift - Vertical	Does not exist
Non-auditorium Handicap Lift - Stair	Does not exist
Ash Hoist	Does not exist
Sidewalk Elevator	Does not exist
DOMESTIC WATER SYSTEM	Inspected
Domestic Cold Water System	Inspected
Gravity System	Does not exist
Pressure Booster System	Inspected
Electric Pressure Booster System	Does not exist
Hydraulic/Pneumatic Booster System	Inspected
Water Pressure Booster - Compressor	Inspected
Condition	3- Fair
Deficiency	NOT IN USE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	l
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
Pressure Booster Pump	Inspected
Condition	3- Fair
Deficiency	NOT IN USE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
Domestic Cold Water Tank	Inspected
Condition	3- Fair
Deficiency	NOT IN USE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
Water Service	Inspected
Instance	Basement - Water/Sprinkler/Gas Meter Room, Sprinkler Room by
	Gymnasium
Instance Condition	1- Good
Instance Quantity	3
Instance Quantity Uom	EACH
Deficiency	No deficiencies recorded
Domestic Hot Water System	Inspected
Domestic Hot Water System Domestic Hot Water Remote Storage Tank	Does not exist
Domestic Water Heat Exchanger	Inspected
Condition	3- Fair
Deficiency	NOT IN USE
Deficiency Location/Instance Deficiency Quantity	Boiler Room (2 of 2)
	2
Quantity Uom	EACH

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

1		
stion	Response	
OMESTIC WATER SYSTEM		
Domestic Hot Water System		
Domestic Water Heat Exchanger		
Potential Action	NO ACTION	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 1	
Violations	No violations recorded	
Electric Domestic Water Heater	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Gas Fired Domestic Water Heater	Does not exist	
Oil Fired Domestic Water Heater	Does not exist	
Heat Pump Domestic Water Heater	Inspected	
Instance	Boiler Room	
Instance Condition	1- Good	
Instance Quantity	2	
Instance Quantity Uom	EACH	
Manufacturer	Lochinvar	
EquipmentId	N/A	
Capacity/Size Quantity	5	
Capacity/Size UOM	KW Input	
Capacity/Size 2 Quantity	119	
Capacity/Size 2 UOM	Gallons	
Source of Capacity/Size	Documented	
Installation Year	2022	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Kitchen	
Instance Condition	1- Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	A.O. Smith	
EquipmentId	N/A	
Capacity/Size Quantity	3	
Capacity/Size UOM	KW Input	
Capacity/Size 2 Quantity	50	
Capacity/Size 2 UOM	Gallons	
Source of Capacity/Size	Documented	
Installation Year	2022	
Source of Installation Year	Custodial Staff	
Deficiency	No deficiencies recorded	
Oomestic Water Distribution Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
RAIN/WASTE/VENT AND STORM SYSTEM	Inspected	
nterior Storm Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Sewage/Waste/Vent Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Sewage Ejector Pump	Does not exist	
wage Elector I ump		
	Inspected	
Sump Pump Condition	Inspected 3- Fair	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

	A10
estion	Response
UAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist
IXTURES	Inspected
Staff And Other	Inspected
Janitor Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Urinal	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Student	Inspected
Drinking Fountain	Inspected
Condition	2- Between Good and Fair
Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF VALVE,ETC.)
Deficiency Location/Instance	Gymnasium, Corridor near Rooms 307, 357, 407
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lavatory/Sink	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF VALVE,ETC.)
Deficiency Location/Instance	Girl's Toilet Room 239, Boy's Toilet Room 320
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Locker Room Shower	Inspected
Instance on Basement - Boys	Inspected
Instance Condition	3- Fair
Alternative Use	Yes
Deficiency	No deficiencies recorded
Instance on Basement - Girls	Inaccessible
Sink And Fountain Combo Unit	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	2- Between Good and Fair
Deficiency	CLOGGED/LEAKING
Deficiency Location/Instance	Girl's Toilet Room 337
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

iunicui Inspeciion	
Question	Response
FIXTURES	
Student	
Toilet	
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Urinal	Inspected
Condition	2- Between Good and Fair
Deficiency	CLOGGED/LEAKING
Deficiency Location/Instance	Boy's Toilet Room 220
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
GAS FIRED FURNACE	Does not exist
GAS SERVICE	Inspected
Gas Distribution Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Gas Meter Room Exhaust Fan	Does not exist
Gas Meter Room Vent	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Gas Pressure Booster	Does not exist
CO/Gas Leak Detection	Inspected
Instance	Basement - Gas Meter Room, Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Installation Year	2007
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
HEATING	Inspected
Heating Coil In Ductwork	Does not exist
Hydronic Heating	Does not exist
Radiator/Convector/Fin Tube	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Steam Heating	Inspected
F&T/Steam Drip Trap	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
MER Steam and Condensate Piping	Inspected
Condition	3- Fair
Deficiency	DAMAGED/MISSING INSULATION
Deficiency Location/Instance	Basement MER, 3rd Floor MER
Deficiency Quantity	50
Quantity Uom	L.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Condensate Return Piping	Inspected

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

		ΛΙ
estion	Response	
IEATING		
Steam Heating		
Steam Condensate Return Piping		
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Steam Condensate Return Pumping System	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Steam Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Terminal Unit Thermostatic Trap	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Steam supplied by External Sources	Does not exist	
Unit Heater/Cabinet Heater	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
IEATING PLANT	Inspected	
Instance on Basement	Inspected	
Is there a water meter on the boiler make-up water piping?	No	
Burner Manufacturer	Preferred Utilities	
Burner Model	BHE7-346	
Burner Type	Oil	
Heating Plant Oil Number	4	
Boiler Auxiliaries		
Instance on Basement	Inspected	
Boiler Auxiliary Piping		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler Emergency Stop Switch		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler Feedwater System		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler Feedwater Treatment(Automatic)		
Instance on Basement	Does not exist	
Boiler Flue Exhaust		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler Make-up Water Backflow Preventer		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler Room Steam And Condensate Piping		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler Safety Valve		

Building Condition Assessment Survey 2023-2024

estion	Response
EATING PLANT	.
Boiler Auxiliaries	
Boiler Safety Valve	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler System	
Instance on Basement	Inspected
Coal-fired Boiler	
Instance on Basement	Does not exist
Hot Water Boiler	
Instance on Basement	Does not exist
Modular Boiler	
Instance on Basement	Does not exist
	Does not exist
Steam Boiler	
Instance on Basement	Inspected
Instance on Basement	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	4,194
Instance Quantity Uom	MBH NET
Cast Iron Boiler?	No
Manufacturer	Kewanee Boiler Corporation
EquipmentId	55963-1
Capacity/Size Quantity	5402
Capacity/Size UOM	MBH Gross
Source of Capacity/Size	Documented
Installation Year	1971
Source of Installation Year	Custodial Staff
Deficiency	DEFECTIVE SAFETY AUXILIARY: LOW-WATER CUT-OFF,
	WATER COLUMN ASSEMBLY
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	4,194
Instance Quantity Uom	MBH NET
Cast Iron Boiler?	No
Manufacturer	Kewanee Boiler Corporation
EquipmentId	55963-2
Capacity/Size Quantity	5402
Capacity/Size UOM	MBH Gross
Source of Capacity/Size	Documented
Installation Year	1971
Source of Installation Year	Documented
Deficiency	DEFECTIVE SAFETY AUXILIARY: LOW-WATER CUT-OFF, WATER COLUMN ASSEMBLY
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

iestion	Response
HEATING PLANT	
Boiler System	
Steam Boiler	
Violations	No violations recorded
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	4,194
Instance Quantity Uom	MBH NET
Cast Iron Boiler?	No
Manufacturer	Kewanee Boiler Corporation
EquipmentId	55963-3
Capacity/Size Quantity	5402
Capacity/Size UOM	MBH Gross
Source of Capacity/Size	Documented
Installation Year	1971
Source of Installation Year	Documented
Deficiency	DEFECTIVE SAFETY AUXILIARY: LOW-WATER CUT-OFF, WATER COLUMN ASSEMBLY
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Fuel System	
Instance on Basement	Inspected
Boiler Fresh Air Louver/Damper	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Туре	Automatic
Deficiency	No deficiencies recorded
Burner/Burner Control Panel	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Fuel Oil Storage/Supply System	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Gas Trains And Vent At The Boiler	
Instance on Basement	Does not exist
nclosed IDF Room	Inspected
Instance on Rooms 116, 316, 403A	Inspected
Dedicated A/C Equipment	
Instance on Rooms 116, 316, 403A	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
AITCHEN	Inspected
Instance on 1st Floor	Inspected
CO Detector	
Instance on 1st Floor	Not required
Gas System	
Instance on 1st Floor	Does not exist
Instance on 1st Ploor	Does not exist
Grease Trap	

Building Condition Assessment Survey 2023-2024

stion		Response	
ITCHEN	Ň		
Grease T			
	Instance Condition	1- Good	
	Deficiency	No deficiencies recorded	
Hood	· · ·		
	Instance on 1st Floor	Inspected	
	Instance Condition	3- Fair	
	Deficiency	No deficiencies recorded	
Hood Ex	haust Ductwork		
	Instance on 1st Floor	Inspected	
	Instance Condition	3- Fair	
	Deficiency	No deficiencies recorded	
Hood Ex	khaust Fan		
	Instance on 1st Floor	Inspected	
	Instance Condition	3- Fair	
	Deficiency	No deficiencies recorded	
Hood Fi	re Suppression System		
	Instance on 1st Floor	Inspected	
	Instance Condition	3- Fair	
	Deficiency	No deficiencies recorded	
	er Temperature Booster		
	Instance on 1st Floor	Does not exist	
Kitchen			
	Instance on 1st Floor	Inspected	
	Instance Condition	3- Fair	
	Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF VALVE,ETC.)	
	Deficiency Location/Instance Deficiency Quantity	Kitchen 1	
	Quantity Uom	EACH	
	Potential Action	MAINTENANCE	
	Urgency of Action	PRIORITY 3	
	Purpose of Action	LEVEL 2	
	Violations	No violations recorded	
DF Rooi		Inspected	
	Instance on Room 345B	Inspected	
	ed A/C Equipment		
	Instance on Room 345B	Inspected	
	Instance Condition	2- Between Good and Fair	
	Deficiency	No deficiencies recorded	
CIENCE	DEMO ROOM	Inspected	
	Instance on Room 223	Inspected	
	Alternative Use	No	
	ste Neutralizing Tank		
	Instance on Room 223	Does not exist	
CO Dete			
	Instance on Room 223	Not required	
-	ncy Shower	D	
	Instance on Room 223	Does not exist	
Eye Was			
	Instance on Room 223	Does not exist	
	khaust Ductwork	Doos not aviat	
	Instance on Room 223	Does not exist	
	thaust Fan		

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

ΑΙΟ
Response
Does not exist
Inspected
3- Fair
No deficiencies recorded
Does not exist
Inspected
Inspected
No
110
Does not exist
Inspected
3- Fair
No deficiencies recorded
Inspected
2- Between Good and Fair
No deficiencies recorded
Does not exist
Does not exist
Not required
Does not exist
Inspected
2- Between Good and Fair
No deficiencies recorded
Inspected
2- Between Good and Fair
No deficiencies recorded
Does not exist
Dans not spirt
Does not exist
Inspected
2- Between Good and Fair
No deficiencies recorded Does not exist

NYC Department of Education Building Condition Assessment Survey 2023-2024

Mechanical Inspection

•	non	
uestion		Response
SCIENCE LAB		
Hood Ex <u>haust F</u>		
	e on Room 233	Does not exist
	e on Room 329	Inspected
	e Condition	2- Between Good and Fair
Deficie		No deficiencies recorded
	e on Room 333	Does not exist
	e on Room 429	Does not exist
Fixed Laborato		
	e on Room 233	Does not exist
Instanc	e on Room 329	Inspected
Instanc	e Condition	2- Between Good and Fair
Deficie	ncy	No deficiencies recorded
Instanc	e on Room 333	Does not exist
Instanc	e on Room 429	Does not exist
Laboratory Sin	ζ	
Instanc	e on Room 233	Inspected
Instanc	e Condition	3- Fair
Deficie	ncy	No deficiencies recorded
Instanc	e on Room 329	Inspected
Instanc	e Condition	2- Between Good and Fair
Deficie	ncy	No deficiencies recorded
Instanc	e on Room 333	Inspected
Instanc	e Condition	2- Between Good and Fair
Deficie	ncy	No deficiencies recorded
Instanc	e on Room 429	Inspected
Instanc	e Condition	4- Between Fair and Poor
Deficie	ncy	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF VALVE,ETC.)
Defic	iency Location/Instance	Room 429
	iency Quantity	4
Quan	tity Uom	EACH
Poter	tial Action	MAINTENANCE
Urge	ncy of Action	PRIORITY 3
Purpo	ose of Action	LEVEL 2
Viola	tions	No violations recorded
Make-up Air U	it	
Instanc	e on Room 233	Does not exist
Instanc	e on Room 329	Does not exist
Instanc	e on Room 333	Does not exist
Instanc	e on Room 429	Does not exist
CIENCE PREP	ROOM	Inspected
Instanc	e on Room 331	Inspected
Alterna	tive Use	Yes
Instanc	e on Rooms 231, 349	Inspected
	tive Use	Yes
Acid Waste Neu		
	e on Room 331	Inspected
	e Condition	2- Between Good and Fair
Deficie		No deficiencies recorded
	e on Rooms 231, 349	Does not exist
CO Detector	5 011 KUO1115 251, 547	Does not exist
	e on Room 331	Not required
mstalle	e on Rooms 231, 349	Not required

NYC Department of Education **Building Condition Assessment Survey 2023-2024**

estion	Response	
estion	Response	
CIENCE PREP ROOM		
Emergency Shower Instance on Room 331	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
	Does not exist	
Instance on Rooms 231, 349	Does not exist	
Eye Wash Instance on Room 331	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
	Does not exist	
Instance on Rooms 231, 349	Does not exist	
Hood Exhaust Ductwork Instance on Room 331	Inspected	
Instance Condition	2- Between Good and Fair	
	No deficiencies recorded	
Deficiency		
Instance on Rooms 231, 349	Does not exist	
Hood Exhaust Fan Instance on Room 331	Inspected	
Instance Condition	2- Between Good and Fair	
	No deficiencies recorded	
Deficiency		
Instance on Rooms 231, 349	Does not exist	
Fixed Laboratory Hood Instance on Room 331	Instructord	
	Inspected 2- Between Good and Fair	
Instance Condition		
Deficiency	No deficiencies recorded	
Instance on Rooms 231, 349	Does not exist	
Laboratory Sink Instance on Room 331	Instructord	
	Inspected 2- Between Good and Fair	
Instance Condition	No deficiencies recorded	
Deficiency		
Instance on Rooms 231, 349	Inspected 3- Fair	
Instance Condition		
Deficiency	No deficiencies recorded	
Make-up <u>Air Unit</u>	De la la	
Instance on Room 331	Does not exist	
Instance on Rooms 231, 349	Does not exist	
PRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected	
Dry Sprinkler Alarm Valve Assembly	Does not exist	
Wet Sprinkler Alarm Valve Assembly	Does not exist	
Fire Booster Pump Assembly	Does not exist Does not exist	
Roof Tank Siamese Connection	Inspected	
Condition	3- Fair	
Deficiency	MISSING CAPS	
Deficiency Location/Instance	Building Exterior by Street E149	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Sprinkler Head	Inspected	
Condition	3- Fair	
Deficiency	DEFECTIVE/DETERIORATED	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

Question	Response
SPRINKLERS, STANDPIPE, FIRE SYSTEM	
Sprinkler Head	
Deficiency Location/Instance	Basement Corridor, Gymnasium, Rooms 101, 101A, 103, 105, 356 (painted, 40)
Deficiency Quantity	40
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Sprinkler Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Standpipe System	Does not exist
Water Gong	Does not exist
SWIMMING POOL	Does not exist
	Inspected
VENTILATION Is the building Mechanically ventilated?	Yes
Exhaust Fan	Inspected
Condition	3- Fair
Approximate Total # of Fans	26-50
	DEFECTIVE MOTOR
Deficiency Deficiency Location/Instance	
Deficiency Quantity	Roof/ Exh. Fans #11, #16 2
Quantity Uom	EACH
Potential Action	REPLACE PRIORITY 3
Urgency of Action	LEVEL 2
Purpose of Action Violations	
	No violations recorded
Heating And Ventilating Unit	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE
Deficiency Location/Instance	3rd Floor MER / HV-5
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Metal Ductwork	Inspected
Condition	3- Fair
Are there any uninsulated ductwork by design in Mechanical rooms?	Yes
Are there chain operated dampers?	No
Deficiency	DAMAGED/MISSING INSULATION
Deficiency Location/Instance	3rd Floor MER
Deficiency Quantity	30
Quantity Uom	L.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE REGISTER/DIFFUSER
Deficiency Location/Instance	Gymnasium
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3

Building Condition Assessment Survey 2023-2024

nanical Inspection		X162
Question	Response	
VENTILATION		
Metal Ductwork		
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Supply Fan	Does not exist	
Unit Ventilator	Does not exist	