Building Condition Assessment Survey 2023-2024

Electrical Inspe		7. 4050 WEGE EADS	N DO A D. DDONW A	IN 10460			X1
Asset: Inspection Id	Inspection Type	K, 1970 WEST FARMS	S ROAD, BRONX, N	NY, 10460	Time In		Last Edited
	ELECTRICAL				2024-03-27	08·46AM	2024-04-25 10:34AM
sset Data	<u> </u>				2021 03 27	001101211	2021 01 20 1010 11111
Question				Answer			
	ms/Maior Building Co	omponents been upgraded	?	Systems:	IPDVS/CCTV Syste	m	
Tiure uity System	menning et	impenente even apgradea		Years:	2023		
				Systems:	Security Lighting, Ex	xit Light (B	attery Pack)
				Years:	2022		
				Systems:	LAN		
				Years:	2020		
				Systems:	Partial Fused Discon	nect Switch	n Type Panel Boards
				Years:	2015, 1996		
				Systems:	LED Lighting (Gym	nasium, Au	ditorium)
				Years:	2015		
				Systems:	Molded Case Circuit	Breaker Ty	pe Panel Board
				Years:	2014, 2001, 1990		
				Systems:	Lightning Protection		
				Years:	2014	Duine	
				Systems: Years:	Variable Frequency l 2012	Drive	
				Systems:		Evcent Spri	nkler Flow/Air Pressure
				Years:	Switch, Tamper Flow 2011		
				Systems:	Telephone System		
				Years:	2010		
				Systems:	Pendant and Surface Fluorescent Lighting		
				Years:	1998	(Kenoniie	u)
				Systems:	Emergency Light/Ex	it Panel	
				Years:	1996		
Type of Service	;			Below Gr	ound		
Does Interactive	e Whiteboard (IWB) E	Exist?		Yes			
	on In Electrical Room			No			
	INTERCOMS IN	FIRE RESCUE ARE	AS		_		
Question	I :C- D Ai-t	A Ei D A	4/ II-14: D		Response		
your building	?	ce Areas, Fire Rescue Area	as, and/or Holding Roof	ms in i	No		
riority Conditi							
Exist Prio Last Year? Cate		Condition	Component Affected	Location	* *	` '	Photo
	egory	Description	Affected	Description	Notified Title	; ı	mage
No condition re	corded						
rspection							
Question				Response			
Electrical							
ATHLETIC	FIELD			Does not o	exist		
AUDITORIUM			Inspected				
Ins	stance on 2nd Floor			Inspected			
House Ligh	nting						
	stance on 2nd Floor			Inspected			
	oes a Chandelier Exist			No			
	Fixture - Fluorescent	<u> </u>					
	stance on 2nd Floor			Inspected			
	t Mounted						
Ins	stance on 2nd Floor			Does not o	exist		

Question	Response
AUDITORIUM	<u> </u>
House Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Instance on 2nd Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 2nd Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 2nd Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 2nd Floor	Inspected
Pendant Mounted	
Instance on 2nd Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	
Instance on 2nd Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	
Instance on 2nd Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action Purpose of Action	PRIORITY 1 LEVEL 2
Violations	No violations recorded
	110 violations recorded
Lighting Fixture - LED	Ingnosted
Instance on 2nd Floor	Inspected
Pendant Mounted	Inconnected
Instance on 2nd Floor	Inspected 2- Between Good and Fair
Instance Condition	
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 2nd Floor	Does not exist
Recessed Mounted	

Electrical Inspection	A10/

1	
estion	Response
UDITORIUM	
Local Sound System	
Instance on 2nd Floor	Inspected
Instance Condition	3- Fair
Installation Year	2005
Source of Installation Year	Inspector Estimate
Deficiency	No deficiencies recorded
Projection System	
Instance on 2nd Floor	Inspected
Instance Condition	3- Fair
Is the projector on a cart or installed on the ceiling?	Cart
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 2nd Floor	Inspected
Dimming System	
Instance on 2nd Floor	Inspected
Instance Condition	5- Poor
Deficiency	DIMMING RACK/LIGHT CONSOLE NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Theater Lighting	
Instance on 2nd Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	204
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action Violations	LEVEL 2
	No violations recorded
AFETERIA	Inspected
Instance on 1st Floor - Staff	Inspected
Instance on 1st Floor - Students	Inspected
Lighting	
Instance on 1st Floor - Staff	Inspected
Instance on 1st Floor - Students	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor - Staff	Inspected
Instance on 1st Floor - Students	Inspected
Pendant Mounted	
Instance on 1st Floor - Staff	Does not exist
Instance on 1st Floor - Students	Does not exist
Surface Mounted	
Instance on 1st Floor - Staff	Does not exist
Instance on 1st Floor - Students	Does not exist
Recessed Mounted	
Instance on 1st Floor - Staff	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on 1st Floor - Students	Inspected
instance on 1st 1 tool - Students	3- Fair

Building Condition Assessment Survey 2023-2024

cui inspection	Al
estion	Response
CAFETERIA	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor - Staff	Does not exist
Instance on 1st Floor - Students	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor - Staff	Does not exist
Instance on 1st Floor - Students	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor - Staff	Does not exist
Instance on 1st Floor - Students	Does not exist
Local Sound System	
Instance on 1st Floor - Staff	Does not exist
Instance on 1st Floor - Students	Inspected
Instance Condition	5- Poor
Installation Year	1973
Source of Installation Year	Inspector Estimate
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Projection System	
Instance on 1st Floor - Staff	Does not exist
Instance on 1st Floor - Students	Does not exist
Theater Lighting System	
Instance on 1st Floor - Staff	Does not exist
Instance on 1st Floor - Students	Does not exist
LASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Inspected
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	26
Quantity Uom Potential Action	EACH REPLACE-UPGRADE

Building Condition Assessment Survey 2023-2024

Response
LEVEL 2
No violations recorded
Inspected
3- Fair
LIGHTING FIXTURE BEYOND USEFUL LIFE
25
EACH
REPLACE-UPGRADE
PRIORITY 1
LEVEL 2
No violations recorded
Does not exist
Does not exist
Does not exist
Inspected
Inspected
nispecteu
Inspected
mspected
Does not exist
DOES HOT EXIST
December with
Does not exist
Does not exist
Inspected
Does not exist
Does not exist
Inspected
2- Between Good and Fair
No deficiencies recorded
Inspected
5- Poor
1973
Inspector Estimate
AMPLIFIER NOT OPERATIONAL
1
EACH
REPLACE SYSTEM
PRIORITY 2
LEVEL 2
No violations recorded
Does not exist

Inspected 3- Fair

Instance on Basement

Instance Condition

Electrical Inspection	X167
Question	Response

Question	Response
GYMNASIUM	
Scoreboard	
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on Basement	Does not exist
KITCHEN	Inspected
Instance on 1st Floor	Inspected
Lighting	•
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
LIBRARY	Inspected
Instance on Room 231	Inspected
Lighting	Inspected
Instance on Room 231	Inspected
Lighting Fixture - Fluorescent	mspected
Instance on Room 231	Inspected
Pendant Mounted	mspected
Instance on Room 231	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	1 to deficiences recorded
Instance on Room 231	Does not exist
Recessed Mounted	DOES NOT CALST
Instance on Room 231	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	1 to deficiences recorded
Instance on Room 231	Does not exist
Lighting Fixture - Incandescent	DOES HOT CAIST
Instance on Room 231	Does not exist
	DOGG HOL CALIST
Lighting Fixture - LED Instance on Room 231	Does not exist
	DOGG HOT CALIST
Raceway With Receptacles Instance on Room 231	Inspected
Instance Condition	3- Fair
	No deficiencies recorded
Deficiency Projection System	140 deficielles recolucu
Projection System Instance on Room 231	Does not exist
motance on Room 231	Does not exist

Electrical Inspection	X167
Question	Response

Question LOCKER ROOM	Response
LOCKER ROOM	Y . 1
EOCHER ROOM	Inspected
Instance on Basement - Boys	Inspected
Alternative Use	No
Instance on Basement - Girls	Inspected
Alternative Use	No
Lighting	
Instance on Basement - Boys	Inspected
Instance on Basement - Girls	Inspected
Lighting Fixture - Fluorescent	•
Instance on Basement - Boys	Inspected
Instance on Basement - Girls	Inspected
Pendant Mounted	•
Instance on Basement - Boys	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Basement - Girls	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Basement - Boys	Does not exist
Instance on Basement - Girls	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Basement - Boys	Does not exist
Instance on Basement - Girls	Does not exist
Lighting Fixture - HID	
Instance on Basement - Boys	Does not exist
Instance on Basement - Girls	Does not exist
Lighting Fixture - Incandescent	
Instance on Basement - Boys	Does not exist
Instance on Basement - Girls	Does not exist
Lighting Fixture - LED	
Instance on Basement - Boys	Does not exist
Instance on Basement - Girls	Does not exist
MULTIPURPOSE ROOM	Does not exist
SCIENCE DEMO ROOM	Inspected
Instance on Room 254	Inspected
Power Panel?	Yes
Alternative Use	
	No
Lighting	Inspected
Lighting Fixture - Fluorescent	nispected
Instance on Room 254	Inspected
Pendant Mounted	nispected
Instance on Room 254	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	110 deficiencies recorded
Instance on Room 254	Does not exist
Recessed Mounted	Does not caust
Instance on Room 254	Does not exist
Lighting Fixture - HID	2000 Hot Calot
righting Livinit - Hin	

Electrical Inspection	A10/

Question	Response	
SCIENCE DEMO ROOM		
Lighting		
Lighting Fixture - HID		
Instance on Room 254	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 254	Does not exist	
Lighting Fixture - LED		
Instance on Room 254	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Room 254	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power		
Instance on Room 254	Does not exist	
Power Supply		
Instance on Room 254	Does not exist	
Projection System		
Instance on Room 254	Does not exist	
SCIENCE LAB	Inspected	
Instance on Rooms 103, 105, 303, 305	Inspected	
Power Panel?	Yes	
Alternative Use	Yes	
Instance on Rooms 203, 205	Inspected	
Power Panel?	Yes	
Alternative Use	No	
Lighting		
Instance on Rooms 103, 105, 303, 305	Inspected	
Instance on Rooms 203, 205	Inspected	
Lighting Fixture - Fluorescent		
Instance on Rooms 103, 105, 303, 305	Inspected	
Instance on Rooms 203, 205	Inspected	
Pendant Mounted		
Instance on Rooms 103, 105, 303, 305	Does not exist	
Instance on Rooms 203, 205	Does not exist	
Surface Mounted		
Instance on Rooms 103, 105, 303, 305	Does not exist	
Instance on Rooms 203, 205	Does not exist	
Recessed Mounted		
Instance on Rooms 103, 105, 303, 305	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 203, 205	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	·	
Instance on Rooms 103, 105, 303, 305	Does not exist	
Instance on Rooms 203, 205	Does not exist	
Lighting Fixture - Incandescent		
Instance on Rooms 103, 105, 303, 305	Does not exist	
Instance on Rooms 203, 205	Does not exist	
Lighting Fixture - LED	Does not exist	
Instance on Rooms 103, 105, 303, 305	Does not exist	
	Does not exist Does not exist	
Instance on Rooms 203, 205	Does not exist	
Emergency Gas Shut-Off Valve		

Building Condition Assessment Survey 2023-2024

ciricai Inspection		A107
Question	Response	
SCIENCE LAB		
Emergency Gas Shut-Off Valve		
Instance on Rooms 103, 105, 303, 305	Does not exist	
Instance on Rooms 203, 205	Does not exist	
Emergency Shut-Off Power		
Instance on Rooms 103, 105, 303, 305	Does not exist	
Instance on Rooms 203, 205	Does not exist	
Power Supply		
Instance on Rooms 103, 105, 303, 305	Does not exist	
Instance on Rooms 203, 205	Does not exist	
Projection System	2 040 100 0.1100	
Instance on Rooms 103, 105, 303, 305	Does not exist	
Instance on Rooms 203, 205	Does not exist	
	Inspected	
SCIENCE PREP ROOM	-	
Instance on Room 254A	Inspected	
Power Panel?	No	
Alternative Use	No	
Lighting		
Instance on Room 254A	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 254A	Inspected	
Pendant Mounted		
Instance on Room 254A	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 254A	Does not exist	
Recessed Mounted		
Instance on Room 254A	Does not exist	
Lighting Fixture - HID		
Instance on Room 254A	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 254A	Does not exist	
Lighting Fixture - LED	Does not exist	
Instance on Room 254A	Does not exist	
-	Does not exist	
Emergency Gas Shut-Off Valve Instance on Room 254A	Does not exist	
	Does not exist	
Emergency Shut-Off Power Instance on Room 254A	Does not exist	
<u> </u>	Does not exist	
Power Supply Instance on Room 254A	Does not exist	
SWIMMING POOL	Does not exist	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Does not exist	
Recessed Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
TOILET ROOM - STUDENT	Inspected	
	ı	

Building Condition Assessment Survey 2023-2024

cirical inspection	A107
Question	Response
TOILET ROOM - STUDENT	
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
	Does not exist
EMERGENCY GENERATOR SET	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	1- Good
Deficiency	FIXTURE LAMP NOT OPERATIONAL
Deficiency Location/Instance	Auditorium, by Room 246C
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Non Battery Pack	Does not exist
EXIT/EMERGENCY LIGHT	Does not exist
FIRE ALARM SYSTEM	Inspected
Bell/Horn	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	2- Between Good and Fair
Deficiency	PULL STATION COVER IS MISSING
Deficiency Location/Instance	By Room 133, Gymnasium
Deficiency Quantity	3
Quantity Uom	EACH
Deficiency Quantity	3

Building Condition Assessment Survey 2023-2024

	111
Response	
INSTALL COVER	
PRIORITY 5	
LEVEL 2	
No violations recorded	
Inspected	
2- Between Good and Fair	
No deficiencies recorded	
Inspected	
2- Between Good and Fair	
No deficiencies recorded	
Inspected	
2- Between Good and Fair	
No deficiencies recorded	
Does not exist	
Inspected	
2- Between Good and Fair	
No deficiencies recorded	
Inspected	
<u>.</u>	
-	
•	
2 Patryaan Good and Fair	
No deficiencies recorded	
	INSTALL COVER PRIORITY 5 LEVEL 2 No violations recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Does not exist Inspected 2- Between Good and Fair

Building Condition Assessment Survey 2023-2024

icui inspection		Alu
uestion	Response	
FIRE ALARM SYSTEM		
Sprinkler Flow/Air Pressure Switch		
Deficiency	No deficiencies recorded	
Tamper Flow Switch/Chain	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
GROUNDING SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
INTERCOM SYSTEM	Inspected	
	Inspected	
Elevator Condition	3- Fair	
Deficiency	No deficiencies recorded	
	Does not exist	
Holding Area		
LAN	Inspected	
Local Distribution Frame (I/LDF) Condition	Inspected 1- Good	
	No deficiencies recorded	
Deficiency		
Main Equipment Rack (MDF)	Inspected 1- Good	
Condition	No deficiencies recorded	
Deficiency		
LIGHTNING PROTECTION	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
MOTOR CONTROLLER	Inspected	
MOTOR CONTROL CENTER	Inspected	
Instance	Mechanical Room C7	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Lexington Electric	
EquipmentId	Roof Exhaust Control Center	
Capacity/Size Quantity	200	
Capacity/Size UOM	Amps	
Capacity/Size 2 Quantity	1	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Inspector Estimate	
Installation Year	1973	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Mechanical Room C7	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
MOTOR STARTER/CONTACTOR	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Variable Frequency Drive	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	

Building Condition Assessment Survey 2023-2024

-	Alu
uestion	Response
PANEL BOARD	
Fused Disconnect Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Chiller Room C3
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room C8
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	
Deficiency Quantity	Throughout the Building 32
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
	PRIORITY 1
Urgency of Action	LEVEL 2
Purpose of Action Violations	
	No violations recorded
Deficiency	NO SPARE
Deficiency Location/Instance	By Custodian's Office - Room 144
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Penthouse Mechanical Room East, Electrical Room C8
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
	Inspected
PUBLIC ADDRESS SYSTEM Instance	Closet inside Room 354A
Instance Instance Condition	Closet inside Room 354A 3- Fair
Instance Condition	
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Rauland FAX 250
Installation Year	1973
Source of Installation Year	Documented

Building Condition Assessment Survey 2023-2024

uestion	Response
PUBLIC ADDRESS SYSTEM	
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Students Cafeteria, by Room C20
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Closet inside Room 354A
Deficiency Quantity	173,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Condition	1- Good
Installation Year	2023
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Room 161
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	N/A
Installation Year	1993
Source of Installation Year	Inspector Estimate
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Room 161
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 3
Violations	No violations recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3- Fair
	No deficiencies recorded
Deficiency	
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	1- Good

Building Condition Assessment Survey 2023-2024

Ouestion	Dosnonso
Question	Response
SERVICE SWITCH	Inspected
Instance	Electrical Room C8
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Lexington
EquipmentId	Main LT. & PWR SERV.
Capacity/Size Quantity	2000
Capacity/Size UOM	Amps
Source of Capacity/Size	Fuse Size
Installation Year	1973
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room C8
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room C8
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Lexington
EquipmentId	Air Cond. Equip. & PWR. SERV.
Equipmentid Capacity/Size Quantity	2000
Capacity/Size UOM	
	Amps Fuse Size
Source of Capacity/Size	1973
Installation Year	
Source of Installation Year	Documented DOCKOON AND AND AND AND AND AND AND AND AND AN
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room C8
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
SWITCHBOARD	Inspected
Number of Spares	0
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room C8
Instance Condition	3- Fair
Instance Quantity	1
	EACH
Instance Quantity Uom	
Manufacturer	Lexington
EquipmentId	N/A
Capacity/Size Quantity	3000
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	5
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Inspector Estimate
Installation Year	1973
Source of Installation Year	Documented
Deficiency	FUSED DISCONNECT NOT OPERATIONAL

Building Condition Assessment Survey 2023-2024

Question	Response	
SWITCHBOARD		
Fused Disconnect Switch Type		
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPAIR	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room C8	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Fused Knife Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Does not exist	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
TRANSFORMER	Does not exist	