### **Building Condition Assessment Survey 2023-2024**

Electrical Inspection X170

Asset:	P.S. 170 (ECC) - BRONX, 1598 TOWNSEND AVENU	UE, BRONX, NY, 1045	2	
Inspection Id	Inspection Type		Time In	Last Edited
2121	ELECTRICAL		2024-01-04 10:08AM	2024-01-23 02:16PM
Asset Data				
Question		Answer		
Have any Syste	ms/Major Building Components been upgraded?	Systems:	Library	
		Years:	2023	
		Systems:	Emergency Lighting (Battery Pac	ck), Exit Light (Non
			Battery Pack)	
		Years:	2018	
		Systems:	Intrusion Alarm System (Partial )	Remote Annunciator,
			Most Infrared Sensors, Central C	Control Panel)
		Years:	2017	
		Systems:	LAN	
		Years:	2013	
		Systems:	Molded Case Circuit Breaker Par	nel Board
		Years:	2000, 1993	
		Systems:	All Other Electrical Systems and	Components
		Years:	1993	
Type of Service	÷	Below Gr	ound	

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Does Interactive Whiteboard (IWB) Exist?

Water Penetration In Electrical Room?

Question	Response	
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in	Yes	
your building?		
Are dedicated intercoms available in all of these spaces for use during a fire?	Yes	
Are all dedicated intercoms operational?	Yes	

Yes

No

#### **Priority Condition**

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
Yes	Water Leaks onto Electrical Equipment	Roof Leak	Lighting Fixture	Room 309	Donald Melhado	Fireman	No Photo Taken
No	Fire Alarm System - Defective	N/A	Fire Alarm System - Main Panel	Custodian's Office - Room 104 - Closet	Donald Melhado	Fireman	
No	Fire Alarm System - Components Not Operational	N/A	Fire Alarm System - Area Smoke Detector	Room C01 Water Meter Room	Donald Melhado	Fireman	

#### Inspection

Question	Response	
lectrical		
ATHLETIC FIELD	Does not exist	
AUDITORIUM	Does not exist	
CAFETERIA	Inspected	
Instance on Room 106	Inspected	
Lighting		
Instance on Room 106	Inspected	

## **Building Condition Assessment Survey 2023-2024**

ical Inspection	D	X1'
estion	Response	
CAFETERIA		
Lighting		
Lighting Fixture - Fluorescent	<b>v</b>	
Instance on Room 106	Inspected	
Pendant Mounted		
Instance on Room 106	Does not exist	
Surface Mounted		
Instance on Room 106	Does not exist	
Recessed Mounted		
Instance on Room 106	Inspected	
Instance Condition	3- Fair	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Deficiency Quantity	22	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Lighting Fixture - HID		
Instance on Room 106	Does not exist	
Lighting Fixture - Incandescent	2000 100 0.1100	
Instance on Room 106	Does not exist	
	Does not exist	
Lighting Fixture - LED	D	
Instance on Room 106	Does not exist	
Local Sound System		
Instance on Room 106	Inspected	
Instance Condition	5- Poor	
Installation Year	1993	
Source of Installation Year	Documented	
Deficiency	AMPLIFIER NOT OPERATIONAL	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE SYSTEM	
Urgency of Action	PRIORITY 2	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Projection System		
Instance on Room 106	Does not exist	
Theater Lighting System		
Instance on Room 106	Does not exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	3- Fair	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Deficiency Quantity		
	40 FACH	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Violations	Inspected	

## **Building Condition Assessment Survey 2023-2024**

Electrical InspectionX170QuestionResponse

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	130
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	390
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency Deficiency Quantity	LIGHTING FIXTURE BALLAST DEFECTIVE
Quantity Uom	15 EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
COMPUTER LAB	Does not exist
GYMNASIUM	Does not exist
KITCHEN 10(A 12)	Inspected
Instance on Rooms 106A, 126	Inspected
Lighting	Inquested
Instance on Rooms 106A, 126	Inspected
Lighting Fixture - Fluorescent	Turning d
Instance on Rooms 106A, 126	Inspected
Pendant Mounted	Does not exist
Instance on Rooms 106A, 126	Does not exist
Surface Mounted Instance on Rooms 106A, 126	Door not oviet
	Does not exist
Recessed Mounted	Inquested
Instance on Rooms 106A, 126  Instance Condition	Inspected  3- Fair
Deficiency Deficiency Quantity	LIGHTING FIXTURE BEYOND USEFUL LIFE 15
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - HID	
Instance on Rooms 106A, 126	Does not exist
Lighting Fixture - Incandescent	Does not their

## **Building Condition Assessment Survey 2023-2024**

Question	Response
KITCHEN	•
Lighting	
Lighting Fixture - Incandescent	
Instance on Rooms 106A, 126	Does not exist
Lighting Fixture - LED	
Instance on Rooms 106A, 126	Does not exist
LIBRARY	Inspected
Instance on Room 304A	Inspected
Lighting	*
Instance on Room 304A	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 304A	Does not exist
Lighting Fixture - HID	
Instance on Room 304A	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 304A	Does not exist
Lighting Fixture - LED	
Instance on Room 304A	Inspected
Pendant Mounted	*
Instance on Room 304A	Does not exist
Surface Mounted	
Instance on Room 304A	Does not exist
Recessed Mounted	
Instance on Room 304A	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Raceway With Receptacles	
Instance on Room 304A	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Projection System	
Instance on Room 304A	Does not exist
LOCKER ROOM	Does not exist
MULTIPURPOSE ROOM	Does not exist
SCIENCE DEMO ROOM	Does not exist
	Does not exist
SCIENCE LAB	
SCIENCE PREP ROOM	Does not exist
SWIMMING POOL	Does not exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	Does not exist

## **Building Condition Assessment Survey 2023-2024**

Question	Response
TOILET ROOM - STAFF	· · ·
Lighting	
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	16
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Inspected
Automatic Transfer Switch (ATS)	Inspected
Instance	Electrical Meter Room C28
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Kohler Power Systems
EquipmentId	ATS-1
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate 1993
Installation Year Source of Installation Year	Documented
	No deficiencies recorded
Deficiency	
Instance	Electrical Meter Room C28
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Kohler Power Systems
EquipmentId	ATS-2
Capacity/Size Quantity	400
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1993
Source of Installation Year	Documented  PH OT LIGHT NOT OPERATIONAL
Deficiency Deficiency Quantity	PILOT LIGHT NOT OPERATIONAL
	1 EACH
Quantity Uom	EACH MAINTENANCE
Potential Action	MAINTENANCE  DRIGHTY 5
Urgency of Action	PRIORITY 5

#### **Building Condition Assessment Survey 2023-2024**

	spection		X
uestion		Response	
EMERG	ENCY GENERATOR SET		
Autom	atic Transfer Switch (ATS)		
	Purpose of Action	LEVEL 2	
	Violations	No violations recorded	
Battery	Charger	Inspected	
	Instance	Roof - Emergency Generator	
	Instance Condition	3- Fair	
	Instance Quantity	1	
	Instance Quantity Uom	EACH	
	Manufacturer	Kohler Power Systems	
	EquipmentId	Automatic Battery Charger	
	Capacity/Size Quantity	10	
	Capacity/Size UOM	AmpsDC	
	Capacity/Size 2 Quantity	13	
	Capacity/Size 2 Quantity Capacity/Size 2 UOM	VDC	
	Source of Capacity/Size	Nameplate	
	Installation Year	1993	
	Source of Installation Year	Documented	
	Deficiency	No deficiencies recorded	
Fmerg	ency Distribution Board	Inspected	
	per of Spares	0	
	I Disconnect Switch Type	Does not exist	
	ed Case Circuit Breaker Type	Inspected	
Molu		Electrical Meter Room C28	
	Instance	3- Fair	
	Instance Condition		
	Instance Quantity	1	
	Instance Quantity Uom	ЕАСН	
	Manufacturer	Electrotech	
	EquipmentId	Gen. Panel	
	Capacity/Size Quantity	400	
	Capacity/Size UOM	Amps Total	
	Capacity/Size 2 Quantity	1	
	Capacity/Size 2 UOM	Section(s)	
	Source of Capacity/Size	Nameplate	
	Installation Year	1993	
	Source of Installation Year	Documented	
	Deficiency	No deficiencies recorded	
Diesel		Inspected	
	Instance	Roof - Generator Enclosure	
	Instance Condition	3- Fair	
	Instance Quantity	1	
	Instance Quantity Uom	EACH	
	Manufacturer	Kohler Power Systems	
	EquipmentId	Emergency Generator	
	Capacity/Size Quantity	125	
	Capacity/Size UOM	kVA	
	Capacity/Size 2 Quantity	100	
	Capacity/Size 2 UOM	kW	
	Capacity/Size 3 Quantity	347	
	Capacity/Size 3 UOM	Amps	
	Source of Capacity/Size	Namenlate	

Nameplate 1993

Documented

Does not exist

Does not exist

No deficiencies recorded

Source of Capacity/Size

EMERGENCY LIGHT/EXIT LIGHT PANEL

Installation Year Source of Installation Year

Deficiency

Natural Gas

## **Building Condition Assessment Survey 2023-2024**

neui inspection	Allo
Question	Response
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Does not exist
Non Battery Pack	Inspected
Condition	1- Good
Deficiency	FIXTURE LAMP NOT OPERATIONAL
Deficiency Location/Instance	Staircases A/2, B/2
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
EXIT/EMERGENCY LIGHT	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
FIRE ALARM SYSTEM	Inspected
Bell/Horn	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	3- Fair
Deficiency	
	No deficiencies recorded
Duct Smoke Detector Condition	Inspected 3- Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected 3- Fair
Condition	
Deficiency	DETECTOR NOT OPERATIONAL
Deficiency Location/Instance Deficiency Quantity	Room C01 Water Meter Room
Quantity Uom	I EACH
Potential Action	REPLACE
	PRIORITY 5
Urgency of Action Purpose of Action	LEVEL 6
Violations	No violations recorded
	Does not exist
CO Detector Heat Detector	Inspected
Condition	3- Fair
	No deficiencies recorded
Deficiency	
Elevator Recall	Inspected 3- Fair
Condition	
Deficiency	No deficiencies recorded

## **Building Condition Assessment Survey 2023-2024**

icui inspection	
uestion	Response
FIRE ALARM SYSTEM	
Magnetic Door Holder/Contactor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fused Cutout Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Custodian's Office - Room 104 - Closet
Instance Condition	4- Between Fair and Poor
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Notifier
Model	N/A
EquipmentId	Interior Fire Alarm Control Panel
Installation Year	1993
Source of Installation Year	Documented
Deficiency	PANEL DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Fire Alarm Control Panel (Standard)	Does not exist
Sub-Panel	Does not exist
Remote Annunciator	Does not exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
NTERCOM SYSTEM	Inspected
Elevator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Holding Area	Does not exist
AN	Inspected
	Inspected
Local Distribution Frame (I/LDF)	2- Between Good and Fair
Condition	
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded

# **Building Condition Assessment Survey 2023-2024**

Electrical Inspection	<b>A1</b> /0

<b>.</b>	
uestion	Response
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	General Office - Room 209
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Dukane 125
Installation Year	1993
Source of Installation Year	Documented
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	20
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
SECURITY	Inspected
IPDVS/CCTV System	Does not exist
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office - Room 104 - Closet
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista 128BPT
Installation Year	2017
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
	2- Between Good and Fair
Condition	
Condition  Deficiency  Siren/Strobe	No deficiencies recorded  Inspected

## **Building Condition Assessment Survey 2023-2024**

incui inspection	711
Question	Response
SECURITY	
Intrusion Alarm System	
Siren/Strobe	
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	4- Between Fair and Poor
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Location/Instance	Building Perimeters, Roof
Deficiency Quantity	12
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Violations	No violations recorded
SERVICE SWITCH	Inspected
Instance	Electrical Meter Room C28
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Siemens
EquipmentId	Service Disconnect
Capacity/Size Quantity	2500
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1993
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	Inspected
Number of Spares	0
Fused Disconnect Switch Type	Inspected
Instance	Electrical Meter Room C28
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Siemens
EquipmentId	Main Dist SWBD
Capacity/Size Quantity	2500
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	1993
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
TRANSFORMER	No deficiencies recorded  Does not exist