## **Building Condition Assessment Survey 2023-2024**

## Electrical Inspection

				UE, BRONX, N			
Inspection	n Id Inspection Type				Time	In	Last Edited
	1841 ELECTRICAL				2023-	-12-21 08:57AN	1 2024-03-18 02:03PM
lsset Data							
Question				Answer			
Have any	Systems/Major Building C	Components been upgraded?		Systems:			
				Years:	2022		
				Systems:		ts	
				Years:	2019		
				Systems:	Telephone Sy	stem	
				Years:	2018		
				Systems:		ctrical Systems a	and Components
				Years:	1996		
Type of S				Below G	round		
	ractive Whiteboard (IWB)			Yes			
	netration In Electrical Room	n? N FIRE RESCUE AREAS	2	No			
Question		I FIRE RESCUE AREAS			Response		
		nce Areas, Fire Rescue Areas,	and/or Holding Roon		Yes		
your bu			and of froming from				
Are d	ledicated intercoms availab	le in all of these spaces for us	e during a fire?		Yes		
Are	all dedicated intercoms op	erational?		•	Yes		
riority Co	ndition						
Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
No	Emergency Generator	N/A	Emergency	Penthouse -	Victor	Handyman	
	Components - Not		Generator	Generator	Olmo	-	
	Operational			Room			
							In the second seco
Yes	Intercom - Not Connected to Remote	N/A	Intercom System -	Elevator Device ID:	Victor Olmo	Handyman	No Photo Taken
	Connected to Remote Monitoring Station	N/A				Handyman	No Photo Taken
Inspection	Connected to Remote Monitoring Station	N/A	System -	Device ID: 2P5763	Olmo	Handyman	No Photo Taken
<i>nspection</i> Question	Connected to Remote Monitoring Station	N/A	System -	Device ID:	Olmo	Handyman	No Photo Taken
Inspection Question Electrica	Connected to Remote Monitoring Station	N/A	System -	Device ID: 2P5763 Response	Olmo e	Handyman	No Photo Taken
Inspection Question Electrica ATHLI	Connected to Remote Monitoring Station	N/A	System -	Device ID: 2P5763 Response Does not	Olmo e exist	Handyman	No Photo Taken
Unspection Question Electrica ATHLI AUDIT	Connected to Remote Monitoring Station	N/A	System -	Device ID: 2P5763 Response Does not Does not	Olmo e exist exist	Handyman	No Photo Taken
Electrica ATHLI	Connected to Remote Monitoring Station	N/A	System -	Device ID: 2P5763 Response Does not Inspected	Olmo e exist exist	Handyman	No Photo Taken
Unspection Question Electrica ATHLI AUDIT	Connected to Remote Monitoring Station	N/A	System -	Device ID: 2P5763 Response Does not Does not	Olmo e exist exist	Handyman	No Photo Taken
Unspection Question Electrica ATHLI AUDIT CAFET	Connected to Remote Monitoring Station	N/A	System -	Device ID: 2P5763 Response Does not Inspected	Olmo e exist exist l	Handyman	No Photo Taken
Unspection Question Electrica ATHLL AUDIT CAFET Light	Connected to Remote Monitoring Station		System -	Device ID: 2P5763 Response Does not Does not Inspected Inspected	Olmo e exist exist l	Handyman	No Photo Taken
Unspection Question Electrica ATHLL AUDIT CAFET Light	Connected to Remote Monitoring Station		System -	Device ID: 2P5763 Response Does not Does not Inspected Inspected	Olmo e exist exist l	Handyman	No Photo Taken
Inspection Question Electrica ATHLI AUDIT CAFET Light	Connected to Remote Monitoring Station		System -	Device ID: 2P5763 Response Does not Does not Inspected Inspected	Olmo e exist exist l	Handyman	No Photo Taken
Inspection Question Electrica ATHLI AUDIT CAFET Light	Connected to Remote Monitoring Station Monitoring Station ETIC FIELD FORIUM FERIA Instance on 1st Floor ting Instance on 1st Floor hting Fixture - Fluorescer Instance on 1st Floor		System -	Device ID: 2P5763 Response Does not Does not Inspected Inspected	Olmo e exist exist l l	Handyman	No Photo Taken
<b>Inspection</b> Question         Electrica         ATHLI         AUDIT         CAFET         Light         Lig         Press	Connected to Remote Monitoring Station		System -	Device ID: 2P5763 Response Does not Does not Inspected Inspected Inspected	Olmo e exist exist l l	Handyman	No Photo Taken
Inspection         Question         Electrica         ATHLI         AUDIT         CAFET         Light         Lig         Press	Connected to Remote Monitoring Station		System -	Device ID: 2P5763 Response Does not Does not Inspected Inspected Inspected	Olmo e exist exist l l l exist	Handyman	No Photo Taken
Inspection Question Electrica ATHLI AUDIT CAFET Light Light St	Connected to Remote Monitoring Station		System -	Device ID: 2P5763 Response Does not Does not Inspected Inspected Inspected Does not	Olmo e exist exist l l l exist	Handyman	No Photo Taken
Inspection Question Electrica ATHLI AUDIT CAFET Light Light St	Connected to Remote Monitoring Station Monitoring Station ETIC FIELD FORIUM FERIA Instance on 1st Floor ting Instance on 1st Floor hting Fixture - Fluorescer Instance on 1st Floor endant Mounted Instance on 1st Floor urface Mounted Instance on 1st Floor		System -	Device ID: 2P5763 Response Does not Does not Inspected Inspected Inspected Does not	Olmo e exist exist l exist l exist exist exist	Handyman	No Photo Taken
Inspection Question Electrica ATHLI AUDIT CAFET Light Light St	Connected to Remote Monitoring Station Monitoring Station ETIC FIELD FORIUM FERIA Instance on 1st Floor hting Fixture - Fluorescer Instance on 1st Floor endant Mounted Instance on 1st Floor urface Mounted Instance on 1st Floor eceesed Mounted		System -	Device ID: 2P5763 Response Does not Does not Inspected Inspected Inspected Does not Does not	Olmo e exist exist l exist l exist exist exist	Handyman	No Photo Taken
Inspection Question Electrica ATHLI AUDIT CAFET Light Light St	Connected to Remote Monitoring Station		System -	Device ID: 2P5763 Response Does not Does not Inspected Inspected Inspected Does not Does not Inspected Inspected Inspected Inspected	Olmo e exist	Handyman Handyman	
Inspection Question Electrica ATHLI AUDIT CAFET Light Light	Connected to Remote Monitoring Station Monitoring Station Monitoring Station Monitoring Station Monitoring Station Monitoring Field Monitoring Field Monitoring Monit		System -	Device ID: 2P5763 Response Does not Does not Inspected Inspected Inspected Does not Does not Inspected Inspected Inspected Inspected	Olmo e exist		

## **Building Condition Assessment Survey 2023-2024**

#### Electrical Inspection

icai Inspeciion	ΔΙ
uestion	Response
CAFETERIA	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	5- Poor
Installation Year	1996
Source of Installation Year	Documented
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Projection System	
Instance on 1st Floor	Does not exist
Theater Lighting System	
Instance on 1st Floor	Does not exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	36
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	58 FACU
Quantity Uom	EACH BERLACE LIDCRADE
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1 LEVEL 2
Purpose of Action Violations	
	No violations recorded
Recessed Mounted	Inspected
Condition Deficiency	3- Fair
Lieficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE

## **Building Condition Assessment Survey 2023-2024**

#### **Electrical Inspection**

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
COMPUTER LAB	Does not exist
GYMNASIUM	Does not exist
KITCHEN	Inspected
Instance on Rooms 106, 120	Inspected
Lighting	
Instance on Rooms 106, 120	Inspected
Lighting Fixture - Fluorescent	
Instance on Rooms 106, 120	Inspected
Pendant Mounted	Inspected
Instance on Rooms 106, 120	Does not exist
Surface Mounted	
Instance on Rooms 106, 120	Does not exist
Recessed Mounted	
Instance on Rooms 106, 120	Inspected
Instance Condition	3- Fair
	-
Deficiency Deficiency Quantity	LIGHTING FIXTURE BEYOND USEFUL LIFE 21
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - HID	
Instance on Rooms 106, 120	Does not exist
Lighting Fixture - Incandescent	
Instance on Rooms 106, 120	Does not exist
Lighting Fixture - LED	
Instance on Rooms 106, 120	Does not exist
LIBRARY	Inspected
	•
Instance on Room 302	Inspected
Lighting Instance on Room 302	Turanostad
	Inspected
Lighting Fixture - Fluorescent	Inconcerted
Instance on Room 302	Inspected
Pendant Mounted	
Instance on Room 302	Does not exist
Surface Mounted	
Instance on Room 302	Does not exist
Recessed Mounted	
Instance on Room 302	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE

## **Building Condition Assessment Survey 2023-2024**

#### **Electrical Inspection**

-	
Question	Response
LIBRARY	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	
Deficiency Quantity	11
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - HID	
Instance on Room 302	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 302	Does not exist
Lighting Fixture - LED	
Instance on Room 302	Does not exist
Raceway With Receptacles	
Instance on Room 302	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Projection System	
Instance on Room 302	Does not exist
LOCKER ROOM	Does not exist
MULTIPURPOSE ROOM	Does not exist
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Does not exist
SCIENCE PREP ROOM	Does not exist
SWIMMING POOL	Does not exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Does not exist
Recessed Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Does not exist
Recessed Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	20

## **Building Condition Assessment Survey 2023-2024**

#### **Electrical Inspection**

2		
Question	Response	
TOILET ROOM - STUDENT		
Lighting		
Lighting Fixture - Fluorescent		
Recessed Mounted		
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
	Does not exist	
EMERGENCY DC STANDBY BATTERY POWER		
EMERGENCY GENERATOR SET	Inspected	
Automatic Transfer Switch (ATS)	Inspected	
Instance	Boiler Room C10	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Master Control Systems	
EquipmentId	Automatic Transfer Switch	
Capacity/Size Quantity	15	
Capacity/Size UOM	HP	
Source of Capacity/Size	Nameplate	
Installation Year	1996	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
	Electrical Room C07A	
Instance Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	ASCO	
EquipmentId	EDP	
Capacity/Size Quantity	600	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	1996	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Electrical Room C07A	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	ASCO	
EquipmentId	Fire Alarm Automatic Transfer Switch	
Capacity/Size Quantity	30	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	1996	
Source of Installation Year	Documented	
	Doganontu	
Deficiency	No deficiencies recorded	

## **Building Condition Assessment Survey 2023-2024**

#### **Electrical Inspection**

ieur inspection			111
estion		Response	
MERGENCY GENERA	TOR SET		-
Automatic Transfer Swi	tch (ATS)		
Instance Condit	on	3- Fair	
Instance Quanti	у	1	
Instance Quanti	y Uom	EACH	-
Manufacturer	<i>.</i>	ASCO	
EquipmentId		Fire Smoke Dampers Automatic Transfer Switch	
Capacity/Size Q	uantity	30	
Capacity/Size U		Amps	
Source of Capac		Nameplate	
Installation Year		1996	
Source of Instal	lation Year	Documented	
Deficiency		No deficiencies recorded	
Battery Charger		Inspected	
Instance		Penthouse - Generator Room	
Instance Condit	on	3- Fair	
Instance Quanti	y	1	
Instance Quanti		EACH	
Manufacturer	,	Saftpak	
EquipmentId		Battery Charger	
Capacity/Size Q	uantity	10	
Capacity/Size U		AmpsDC	
Capacity/Size 2		32	
Capacity/Size 2		VDC	
Source of Capac	tity/Size	Nameplate	
Installation Year		1996	
Source of Instal	ation Year	Documented	
Deficiency		No deficiencies recorded	
<b>Emergency Distribution</b>	Board	Inspected	
Number of Spares		4	
Fused Disconnect Swi	ch Type	Inspected	
Instance		Electrical Room C07A	
Instance Condit	on	3- Fair	
Instance Quanti	у	1	
Instance Quanti	y Uom	EACH	
Manufacturer		Siemens	
EquipmentId		EDP	
Capacity/Size Q	uantity	800	
Capacity/Size U	OM	Amps Total	
Capacity/Size 2	Quantity	1	
Capacity/Size 2		Section(s)	
Source of Capac		Nameplate	
Installation Year		1996	
Source of Instal	ation Year	Documented	
Deficiency		No deficiencies recorded	
Molded Case Circuit I	Breaker Type	Does not exist	
Diesel		Inspected	
Instance		Penthouse - Generator Room	
Instance Condit	on	4- Between Fair and Poor	
Instance Quanti	y	1	
Instance Quanti	y Uom	EACH	
Manufacturer	-	Caterpillar	
EquipmentId		Emergency Generator	
1 1	uantity	219	
Capacity/Size C	-		
Capacity/Size Q Capacity/Size U	OM	kVA	

## **Building Condition Assessment Survey 2023-2024**

#### **Electrical Inspection**

ieur inspection	
uestion	Response
EMERGENCY GENERATOR SET	
Diesel	
Capacity/Size 2 UOM	kW
Capacity/Size 3 Quantity	607
Capacity/Size 3 UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1996
Source of Installation Year	Documented
Deficiency	GENERATOR NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Natural Gas	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not exist
EMERGENCY LIGHTING	Inspected
Battery Pack	Does not exist
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Does not exist
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Penthouse
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 4
Violations	35672669L
EXIT/EMERGENCY LIGHT	Does not exist
FIRE ALARM SYSTEM	Inspected
Bell/Horn	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
	Inspected
Manual Pull Station	3- Fair
Condition	
Deficiency	No deficiencies recorded
Fan Shutdown Control Condition	Inspected 3- Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
CO Detector	Does not exist

# **Building Condition Assessment Survey 2023-2024**

### Electrical Inspection

icui Inspeciion		Λ17
estion	Response	
TIRE ALARM SYSTEM		-
Heat Detector	Does not exist	
Elevator Recall	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Magnetic Door Holder/Contactor	Does not exist	
Fused Cutout Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Inspected	
Bell At Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Simplex	
Model	4100	
EquipmentId	Fire Alarm Control Panel	
Installation Year	1996	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel	Does not exist	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	5- Poor	
Deficiency	PRINTER NOT OPERATIONAL	
Deficiency Location/Instance	Custodian's Office	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Punch Register	Does not exist	
Sprinkler Flow/Air Pressure Switch	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Tamper Flow Switch/Chain	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
ROUNDING SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
NTERCOM SYSTEM	Inspected	
Elevator	Inspected	
Condition	3- Fair	

## **Building Condition Assessment Survey 2023-2024**

### **Electrical Inspection**

Duestion	Response
INTERCOM SYSTEM	
Elevator	
Deficiency	NOT CONNECTED TO REMOTE MONITORING STATION
Deficiency Location/Instance	Elevator Device ID: 2P5763
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL CONNECTION
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Holding Area	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not exist
MOTOR CONTROLLER	Inspected
	Does not exist
MOTOR CONTROL CENTER	
MOTOR STARTER/CONTACTOR	Inspected 3- Fair
Condition	
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Does not exist
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	Room C07B
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Dukane 250
Installation Year	1996
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SECURITY	Inspected
	Does not exist
IPDVS/CCTV System	Inspected
Intrusion Alarm System Central Control Panel	Inspected
Instance	Custodian's Office 3- Fair
Instance Condition	
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128B
Installation Year	1996
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Custodian's Office

## **Building Condition Assessment Survey 2023-2024**

#### **Electrical Inspection**

	ΔΙ
uestion	Response
SECURITY	
Intrusion Alarm System	
Central Control Panel	
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 3
Violations	No violations recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
	Inspected
Lighting - Security Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Location/Instance	Main Entrance
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Violations	No violations recorded
SERVICE SWITCH	Inspected
Instance	Electrical Room C07A
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
	Siemens
Manufacturer	S.S. #1
EquipmentId Capacity/Size Quantity	1200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1996
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room C07A
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Siemens
	Siemens S.S. #2
EquipmentId Capacity/Size Quantity	5.5. #2 1200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
	1996
Installation Year	1990

# **Building Condition Assessment Survey 2023-2024**

### **Electrical Inspection**

icui Inspection		AI / 4
uestion	Response	
SERVICE SWITCH		
Deficiency	No deficiencies recorded	
Instance	Electrical Room C07A	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Siemens	
EquipmentId	S.S. #3	
Capacity/Size Quantity	600	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	1996	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Electrical Room C07A	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Siemens	
EquipmentId	S.S. #4 Fire Pump	
Capacity/Size Quantity	200	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	1996	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
SWITCHBOARD	Inspected	
Number of Spares	4	
Fused Disconnect Switch Type	Inspected	
Instance	Electrical Room C07A	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Siemens	
EquipmentId	N/A	
Capacity/Size Quantity	1200	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	2	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Nameplate	
Installation Year	1996	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fused Knife Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Does not exist	
<b>FELEPHONE SYSTEM</b>	Inspected	
PBX/Intercom	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	1- Good	
Condition		
Deficiency	No deficiencies recorded	