# **Building Condition Assessment Survey 2023-2024**

#### Mechanical Inspection

Asset:	P.S. 236 - BRONX, 1871 WALTON AVENUE, BRONX, NY, 10453		
Inspection Id	Inspection Type	Time In	Last Edited
4531	MECHANICAL	2024-04-05 08:58AM	2024-05-15 10:01AM
set Data			

Question	Answer	
Have any Systems/Major Building Components been upgraded?	Systems:	Drinking Fountain (~50%); Water Service: Backflow
		Preventer (2 of 3)
	Years:	2024
	Systems:	Kitchen - Grease Traps
	Years:	2022
	Systems:	Boiler #2 re-tubed; Climate Control System - Termina
		Unit Controllers
	Years:	2021
	Systems:	CO/Gas Leak Detection; Climate Control System -
		Temperature Control Thermostats
	Years:	2019
	Systems:	MDF Room - Dedicated A/C Equipment (DX Split
	X.	System)
	Years:	2014
	Systems:	F&T/Steam Drip Traps
	Years:	2013
Are there fuel tanks?	Yes	
Total # of above ground tanks	2	
Total capacity of all above ground tanks in gal.	2,275	
Total # of below ground tanks	0	
Total capacity of all below ground tanks in gal.	0	
Total # of water main service entries to the asset	3	
MERs/Fan Rooms Locations	MER C03	A, Fire Pump Room C11, Penthouse MER
Are there any spaces with Missing or Defective CO Detectors?	No	
Are there any Painted/Obstructed Sprinkler Heads?	No	
Are there any Emergency Stop Switches with Missing Hammers?	No compo	onents

#### **Priority Condition**

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No condi	tion recorded						
Inspection	ı						
Question	l			Response	2		
Mechani	cal						
AIR C	ONDITIONING			Inspected			
Chill	ed Water System			Inspected			
	sorption Chiller			Does not	exist		
Air	Cooled Chiller			Inspected			
	Instance			Penthous	e MER		
	Instance Condition	n		2-Betwee	en Good and Fa	ir	
	Instance Quantity	7		1			
	Instance Quantity	v Uom		EACH			
	Manufacturer			Carrier			
	EquipmentId			N/A			
	Capacity/Size Qu	antity		96			
	Capacity/Size UC			Tons			
	Source of Capaci	ty/Size		Inspector	Estimate		
	Installation Year			2007			
	Source of Installa	tion Year		Inspector	Estimate		
	Refrigerant Type			R-134A			
	Deficiency			No defici	encies recorded		
	Instance			Penthous	e MER		

# **Building Condition Assessment Survey 2023-2024**

#### **Mechanical Inspection**

3- Fair	
1	
EACH	
McOuay	
-	
96	
Tons	
Inspector Estimate	
1997	
Documented	
R-22	
No deficiencies recorded	
Inspected	
Roof	
3- Fair	
1	
EACH	
McQuay	
ACC-1	
96	
Tons	
Inspector Estimate	
1997	
Documented	
No deficiencies recorded	
Roof	
3- Fair	
1	
EACH	
McOuav	
-	
Documented	
-	
1	
MAINTENANCE	
PRIORITY 3	
LEVEL 2	
No violations recorded	
	1EACHMcQuayRM-296TonsInspector Estimate1997DocumentedR-22No deficiencies recordedInspectedRoof3 - Fair1EACHMcQuayACC-196TonsInspector Estimate1997DocumentedNo deficiencies recordedMcQuayACC-196TonsInspector Estimate1997DocumentedNo deficiencies recordedRoof3 - Fair1EACHMcQuayACC-296TonsInspector Estimate1997DocumentedNo deficiencies recordedInspector Estimate1997DocumentedNo deficiencies recordedInspector Estimate1997DocumentedNo deficiencies recordedInspected3 - FairNo deficiencies recordedInspected4 - Between Fair and PoorDEFECTIVEPenthouse MER1EACHMAINTENANCEPRIORITY 3LEVEL 2

# **Building Condition Assessment Survey 2023-2024**

#### **Mechanical Inspection**

estion	Response	
AIR CONDITIONING	1	
Chilled Water System		
Packaged Air Cooled Chiller	Does not exist	
Water Cooled Chiller	Does not exist	
Condenser Water Distribution: Piping, Pumps and Auxiliaries	Does not exist	
Cooling Coil in Ductwork	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Cooling Tower	Does not exist	
DX Split System	Inspected	
Indoor Unit	Inspected	
Condition	3- Fair	
Deficiency	UP TO 5 TONS:NOT IN USE	
Deficiency Location/Instance	1st Floor Kitchen (1 of 1)	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	NO ACTION	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 1	
Violations	No violations recorded	
Outdoor Unit	Inspected	
Condition	3- Fair	
Deficiency	UP TO 5 TONS:NOT IN USE	
Deficiency Location/Instance	Roof (1 of 1)	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	NO ACTION	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 1	
Violations	No violations recorded	
Dry Cooler	Does not exist	
Packaged / Rooftop Unit	Does not exist	
Packaged Terminal A/C	Does not exist	
Refrigerant Leak Detection System	Does not exist	
Refrigerant Piping Condition	Inspected 3- Fair	
Deficiency	No deficiencies recorded	
Return Fan	Inspected	
Condition	3- Fair	
Deficiency	DEFECTIVE	
Deficiency Location/Instance	Penthouse MER / Return Fan #1 (defective belt)	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
ENTRAL ACID WASTE NEUTRALIZING TANK	Does not exist	
CLIMATE CONTROL SYSTEM	Inspected	
BMS	Does not exist	
Pneumatic System	Inspected	
Instance	Throughout	
Instance Condition	3- Fair	
Instance Quantity	1	

# **Building Condition Assessment Survey 2023-2024**

#### **Mechanical Inspection**

-	
Question	Response
CLIMATE CONTROL SYSTEM	
Pneumatic System	
Building Area Covered by Operational System	81-100%
Deficiency	No deficiencies recorded
Hybrid System	Does not exist
Electric System	Does not exist
COMPACTOR	Does not exist
CONVEYING	Inspected
Dumbwaiter	Does not exist
Elevator	Inspected
Condition	3- Fair
Are all the existing elevators operable?	Yes
Deficiency	No deficiencies recorded
Escalator	Does not exist
Non-auditorium Handicap Lift - Vertical	Does not exist
Non-auditorium Handicap Lift - Stair	Does not exist
Ash Hoist	Does not exist
Sidewalk Elevator	Does not exist
DOMESTIC WATER SYSTEM	Inspected
Domestic Cold Water System	Inspected
Gravity System	Does not exist
Pressure Booster System	Inspected
Electric Pressure Booster System	Inspected
Instance	Fire Pump Room C11
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	B&G
EquipmentId	N/A
Capacity/Size Quantity	2
Capacity/Size UOM	Total # Pumps
Capacity/Size 2 Quantity	10
Capacity/Size 2 UOM	Total Pumps HP
Source of Capacity/Size	Documented
Installation Year	1997
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Hydraulic/Pneumatic Booster System	Does not exist
Water Service	Inspected
Instance	Cellar - Kitchen, Fire Pump Room C11
Instance Condition	3- Fair
Instance Quantity	3
Instance Quantity Uom	EACH
Deficiency	No deficiencies recorded
Domestic Hot Water System	Inspected
Domestic Hot Water Remote Storage Tank	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Domestic Water Heat Exchanger	Does not exist
Electric Domestic Water Heater	Does not exist
Gas Fired Domestic Water Heater	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH

# **Building Condition Assessment Survey 2023-2024**

#### **Mechanical Inspection**

*	
uestion	Response
DOMESTIC WATER SYSTEM	
Domestic Hot Water System	
Gas Fired Domestic Water Heater	
Manufacturer	Lochinvar
EquipmentId	N/A
Capacity/Size Quantity	750
Capacity/Size UOM	MBH Input
Capacity/Size 2 Quantity	0
Capacity/Size 2 UOM	Gallons
Source of Capacity/Size Installation Year	Documented 1997
Installation Year Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Oil Fired Domestic Water Heater	Does not exist
	Does not exist
Heat Pump Domestic Water Heater Domestic Water Distribution Piping	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected
Interior Storm Piping	Inspected 2- Between Good and Fair
Condition	
Deficiency	No deficiencies recorded
Sewage/Waste/Vent Piping	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Sewage Ejector Pump	Does not exist
Sump Pump	Does not exist
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Inspected
Dual Temperature Distribution: Piping, Pumps and Auxiliaries	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Dual Temperature Terminal Fan Coil Unit	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
FIXTURES	Inspected
Staff And Other	Inspected
Janitor Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE FLUSHOMETER VALVE
Deficiency Location/Instance	Staff Locker Room C09A, Staff Toilet Room 107
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Violations Urinal	No violations recorded Does not exist

# **Building Condition Assessment Survey 2023-2024**

### **Mechanical Inspection**

	ΛΙ
iestion	Response
TIXTURES	
Student	
Drinking Fountain	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Locker Room Shower	Does not exist
Sink And Fountain Combo Unit	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Urinal	Does not exist
GAS FIRED FURNACE	Does not exist
GAS SERVICE	Inspected
Gas Distribution Piping	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Gas Meter Room Exhaust Fan	Does not exist
Gas Meter Room Vent	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Gas Pressure Booster	Does not exist
CO/Gas Leak Detection	Inspected
Instance	Boiler Room, Gas Meter Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Installation Year	2019
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
HEATING	Inspected
Heating Coil In Ductwork	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Hydronic Heating	Inspected
Hydronic Hot Water Distribution: Piping, Pumps and Auxiliaries	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Backflow Preventer	Does not exist
Hot Water Heat Exchanger	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Radiator/Convector/Fin Tube	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Steam Heating	Inspected
F&T/Steam Drip Trap	Inspected
Condition	2- Between Good and Fair

# **Building Condition Assessment Survey 2023-2024**

#### **Mechanical Inspection**

		ΛΙ
estion	Response	
IEATING		
Steam Heating		
MER Steam and Condensate Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Steam Condensate Return Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Steam Condensate Return Pumping System	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Steam Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Terminal Unit Thermostatic Trap	Does not exist	
Steam supplied by External Sources	Does not exist	
Unit Heater/Cabinet Heater	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EATING PLANT	Inspected	
Instance on Cellar Is there a water meter on the boiler make-up water piping?	Inspected No	
Burner Manufacturer	Kewanee	
Burner Model	KFC-75	
Burner Type	Dual Fuel (Gas/Oil)	
Heating Plant Oil Number	2	
Boiler Auxiliaries		
Instance on Cellar	Inspected	
Boiler Auxiliary Piping	*	
Instance on Cellar	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler Emergency Stop Switch		
Instance on Cellar	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler Feedwater System	No deficicies recorded	
Instance on Cellar	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
	No deficiencies recorded	
Boiler Feedwater Treatment(Automatic)		
Instance on Cellar	Does not exist	
Boiler Flue Exhaust	· · · ·	
Instance on Cellar	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler Make-up Water Backflow Preventer		
Instance on Cellar	Inspected	
Instance Condition	4- Between Fair and Poor	
Deficiency	DEFECTIVE RPZ	
Deficiency Location/Instance	Boiler Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	

# **Building Condition Assessment Survey 2023-2024**

#### **Mechanical Inspection**

estion	Response	
EATING PLANT		
Boiler Auxiliaries		
Boiler Make-up Water Backflow Preventer		
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Boiler Room Steam And Condensate Piping		
Instance on Cellar	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler Safety Valve		
Instance on Cellar	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler System		
Instance on Cellar	Inspected	
Coal-fired Boiler		
Instance on Cellar	Does not exist	
Hot Water Boiler		
Instance on Cellar	Does not exist	
Modular Boiler		
Instance on Cellar	Does not exist	
Steam Boiler		
Instance on Cellar	Inspected	
Instance on Cellar	Inspected	
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity	1,359	
Instance Quantity Uom	MBH NET	
Cast Iron Boiler?	No	
Manufacturer	Kewanee Boiler Corporation	
EquipmentId	101845-1	
Capacity/Size Quantity	1750	
Capacity/Size UOM	MBH Gross	
Source of Capacity/Size	Documented	
Installation Year	1997	
Source of Installation Year	Documented	
Deficiency Deficiency Quantity	LEAKY/PLUGGED TUBES	
• • •		
Quantity Uom Potential Action	EACH REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity	1,359	
	MBH NET	
Instance Quantity Uom	No	
Cast Iron Boiler? Manufacturer	No Kewanee Boiler Corporation	
EquipmentId	101845-2	
Capacity/Size Quantity	1750	
Capacity/Size UOM	MBH Gross	
Source of Capacity/Size	Documented	
Installation Year	1997	

## **Building Condition Assessment Survey 2023-2024**

#### **Mechanical Inspection**

*	on	Δ
uestion		Response
HEATING PLANT		
Boiler System		
Steam Boiler		
	f Installation Year	Documented
Deficien	cy	No deficiencies recorded
Fuel System		
Instance	on Cellar	Inspected
	r Louver/Damper	
Instance	on Cellar	Inspected
	Condition	3- Fair
Туре		Automatic
Deficien		No deficiencies recorded
Burner/Burner		
	on Cellar	Inspected
	Condition	3- Fair
Deficien		No deficiencies recorded
	e/Supply System	
Instance	on Cellar	Inspected
Instance	Condition	3- Fair
Deficien	су	No deficiencies recorded
Gas Trains And	Vent At The Boiler	
Instance	on Cellar	Inspected
Instance	Condition	3- Fair
Deficien	су	No deficiencies recorded
Enclosed IDF Roor	n	Does not exist
AITCHEN		Inspected
Instance	on Cellar	Inspected
CO Detector		
Instance	on Cellar	Inspected
Instance	Condition	3- Fair
Deficien	су	No deficiencies recorded
Gas System	-	
	on Cellar	Inspected
Instance	Condition	3- Fair
Deficien	cy	No deficiencies recorded
Grease Trap	•	
	on Cellar	Inspected
Instance	Condition	1- Good
Deficien	су	No deficiencies recorded
Hood		
Instance	on Cellar	Inspected
Instance	Condition	3- Fair
Deficien	су	No deficiencies recorded
Hood Exhaust Du		
Instance	on Cellar	Inspected
Instance	Condition	3- Fair
Deficien	cy	No deficiencies recorded
Hood Exhaust Fa		
	on Cellar	Inspected
Instance	Condition	3- Fair
Deficien		No deficiencies recorded
Hood Fire Suppr		
	on Cellar	Inspected
Instance	Condition	3- Fair

## **Building Condition Assessment Survey 2023-2024**

#### Mechanical Inspection

		AI/3
Question	Response	
KITCHEN		
Hood Fire Suppression System		
Deficiency	No deficiencies recorded	
Hot Water Temperature Booster		
Instance on Cellar	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Kitchen Sink		
Instance on Cellar	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
MDF Room	Inspected	
Instance on Room C02D	Inspected	
Dedicated A/C Equipment	1	
Instance on Room C02D	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected	
Dry Sprinkler Alarm Valve Assembly	Does not exist	
Wet Sprinkler Alarm Valve Assembly	Does not exist	
Fire Booster Pump Assembly	Inspected 3- Fair	
Condition		
Deficiency	No deficiencies recorded	
Roof Tank	Does not exist	
Siamese Connection Condition	Inspected 3- Fair	
Deficiency	No deficiencies recorded	
	Inspected	
Sprinkler Head Condition	3- Fair	
Deficiency	No deficiencies recorded	
	Inspected	
Sprinkler Piping Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Standpipe System	Inspected	
Hose Valve Assembly	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
	Inspected	
Piping		
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Water Gong	Does not exist	
SWIMMING POOL	Does not exist	
VENTILATION	Inspected	
Is the building Mechanically ventilated?	Yes	
Exhaust Fan	Inspected	
Condition	3- Fair	
Approximate Total # of Fans	1-25	
Deficiency	No deficiencies recorded	
Heating And Ventilating Unit	Does not exist	
Metal Ductwork	Inspected	

# **Building Condition Assessment Survey 2023-2024**

### **Mechanical Inspection**

uestion	Response
VENTILATION	
Metal Ductwork	
Are there any uninsulated ductwork by design in Mechanical rooms?	No
Are there chain operated dampers?	No
Deficiency	No deficiencies recorded
Supply Fan	Inspected
Condition	3- Fair
Approximate Total # of Fans	1-5
Deficiency	DEFECTIVE
Deficiency Location/Instance	MER C03A / HV-1, Penthouse MER / HV-2 (2 of 5)
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Unit Ventilator	Does not exist