#### **Building Condition Assessment Survey 2023-2024**

**Electrical Inspection** X184

Asset:	I.S. 184 - BRONX, 778 FOREST AVENUE, BRONX, NY, 10456		
Inspection Id	Inspection Type	Time In	Last Edited
4875	ELECTRICAL	2024-04-18 09:22AM	2024-05-22 09:12AM

A	SS	et	$\boldsymbol{\nu}$	ata	

4875 ELECTRICAL	2024-04-18 09:22AM 2024-05-22 09:	12A
set Data		
Question	Answer	
Have any Systems/Major Building Components been upgraded?	Systems: Exit Light (Battery Pack), Emergency Light (Battery Pack)	y
	Years: 2022	
	Systems: Auditorium (Projection System), LED Lighting (Computer Lab - Room 419A, 4th Floor Classrooms	s)
	Years: 2021	
	Systems: Partial Molded Case Circuit Breaker Type Panel Box	ard
	Years: 2020, 2018, 2013, 2000, 1990	
	Systems: Security Lighting	
	Years: 2020	
	Systems: Fire Alarm System	
	Years: 2019	
	Systems: Library	
	Years: 2018	
	Systems: Locker Rooms, LED Recessed Lighting (Weight Room)	
	Years: 2016	
	Systems: Interior Lighting, Partial Emergency Lighting (Non Battery Pack)	
	Years: 2015	
	Systems: Partial Motor Starter	
	Years: 2014	
	Systems: Variable Frequency Drive	
	Years: 2013	
	Systems: Intrusion Alarm System (Siren, Panic Switch)	
	Years: 2011, 2009	
	Systems: LAN	
	Years: 2011	
	Systems: Public Address System, Local Sound System, IPDVS/CCTV System	
	Years: 2010	
	Systems: Emergency Light/Exit Panel	
	Years: 2000	
	Systems: Intrusion Alarm System (Except Siren, Panic Switch	1)
	Years: 1990	
Type of Service	Below Ground	
Does Interactive Whiteboard (IWB) Exist?	Yes	
Water Penetration In Electrical Room?	No	

#### DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in	No
your building?	

#### **Priority Condition**

Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
Yes	Fire Alarm System - Components Not Operational	N/A	Fire Alarm System - Magnetic Door Holder/Contac tor	4th Floor Corridor by Room 409	Luis Vargas	Fireman	

### **Building Condition Assessment Survey 2023-2024**

No	Intercom - Not	N/A	Intercom	Room 415C	Luis	Fireman	No Photo Taken
	Operational		System -		Vargas		
			Holding/Fire				

olding/Fire	
accus Aran	

Rescue A	ica .	
pection		
Question	Response	
Electrical		
ATHLETIC FIELD	Does not exist	
AUDITORIUM	Inspected	
Instance on 1st Floor	Inspected	
House Lighting		
Instance on 1st Floor	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	2010	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Is the projector on a cart or installed on the ceiling?	Ceiling	
Deficiency	No deficiencies recorded	
Theater Lighting System	Inspected	
Instance on 1st Floor  Dimming System	Inspected	

### **Building Condition Assessment Survey 2023-2024**

Inspected 5- Poor  DIMMING RACK/LIGHT CONSOLE NOT OPERATIONAL 1 EACH REPLACE PRIORITY 3 LEVEL 2 No violations recorded  Inspected 3- Fair LIGHTING FIXTURE BEYOND USEFUL LIFE 130 EACH REPLACE-UPGRADE
5- Poor  DIMMING RACK/LIGHT CONSOLE NOT OPERATIONAL  1 EACH REPLACE PRIORITY 3 LEVEL 2 No violations recorded  Inspected 3- Fair LIGHTING FIXTURE BEYOND USEFUL LIFE 130 EACH
5- Poor  DIMMING RACK/LIGHT CONSOLE NOT OPERATIONAL  1 EACH REPLACE PRIORITY 3 LEVEL 2 No violations recorded  Inspected 3- Fair LIGHTING FIXTURE BEYOND USEFUL LIFE 130 EACH
5- Poor  DIMMING RACK/LIGHT CONSOLE NOT OPERATIONAL  1 EACH REPLACE PRIORITY 3 LEVEL 2 No violations recorded  Inspected 3- Fair LIGHTING FIXTURE BEYOND USEFUL LIFE 130 EACH
DIMMING RACK/LIGHT CONSOLE NOT OPERATIONAL  1 EACH REPLACE PRIORITY 3 LEVEL 2 No violations recorded  Inspected 3- Fair LIGHTING FIXTURE BEYOND USEFUL LIFE 130 EACH
1 EACH REPLACE PRIORITY 3 LEVEL 2 No violations recorded  Inspected 3- Fair LIGHTING FIXTURE BEYOND USEFUL LIFE 130 EACH
EACH REPLACE PRIORITY 3 LEVEL 2 No violations recorded  Inspected 3- Fair LIGHTING FIXTURE BEYOND USEFUL LIFE 130 EACH
REPLACE PRIORITY 3 LEVEL 2 No violations recorded  Inspected 3- Fair LIGHTING FIXTURE BEYOND USEFUL LIFE 130 EACH
PRIORITY 3 LEVEL 2 No violations recorded  Inspected 3- Fair LIGHTING FIXTURE BEYOND USEFUL LIFE 130 EACH
LEVEL 2 No violations recorded  Inspected 3- Fair LIGHTING FIXTURE BEYOND USEFUL LIFE 130 EACH
No violations recorded  Inspected 3- Fair LIGHTING FIXTURE BEYOND USEFUL LIFE 130 EACH
Inspected 3- Fair LIGHTING FIXTURE BEYOND USEFUL LIFE 130 EACH
3- Fair LIGHTING FIXTURE BEYOND USEFUL LIFE 130 EACH
3- Fair LIGHTING FIXTURE BEYOND USEFUL LIFE 130 EACH
LIGHTING FIXTURE BEYOND USEFUL LIFE 130 EACH
130 EACH
EACH
REPLACE-UPGRADE
DDIODITY 1
PRIORITY 1 LEVEL 2
No violations recorded
Inspected
Inspected
Inspected
Inspected
Inspected
Inspected
Inspected
Inspected
2- Between Good and Fair
No deficiencies recorded
Inspected
2- Between Good and Fair
No deficiencies recorded
Does not exist
Does not exist
Inspected
2- Between Good and Fair
No deficiencies recorded
Does not exist
Does not exist
Does not exist
Does not exist
Does not exist
Does not exist

Electrical Inspection	λ184

Question	Response
CAFETERIA	
Lighting	
Lighting Fixture - LED	
Instance on 1st Floor Small	Does not exist
Local Sound System	
Instance on 1st Floor Large	Inspected
Instance Condition	3- Fair
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance on 1st Floor Small	Does not exist
Projection System	
Instance on 1st Floor Large	Does not exist
Instance on 1st Floor Small	Does not exist
Theater Lighting System	
Instance on 1st Floor Large	Does not exist
Instance on 1st Floor Small	Does not exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Surface Mounted	Does not exist
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
COMPUTER LAB	Inspected
Instance on Room 125	Inspected
Power Panel?	Yes
Instance on Room 214	Inspected
Power Panel?	No
Instance on Room 419A	Inspected
Power Panel?	Yes
Instance on Rooms 307, 321	Inspected
Power Panel?	Yes
Lighting	Towns stort
Instance on Room 125	Inspected
Instance on Room 214	Inspected
Instance on Room 419A	Inspected
Instance on Rooms 307, 321	Inspected

Electrical Inspection		X184
Ouestion	Response	_

Question	Response
COMPUTER LAB	
Lighting	
Lighting Fixture - Fluorescent	
Instance on Room 125	Inspected
Instance on Room 214	Inspected
Instance on Room 419A	Does not exist
Instance on Rooms 307, 321	Inspected
Pendant Mounted	
Instance on Room 125	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 214	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Rooms 307, 321	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 125	Does not exist
Instance on Room 214	Does not exist
Instance on Rooms 307, 321	Does not exist
Recessed Mounted	
Instance on Room 125	Does not exist
Instance on Room 214	Does not exist
Instance on Rooms 307, 321	Does not exist
Lighting Fixture - HID	
Instance on Room 125	Does not exist
Instance on Room 214	Does not exist
Instance on Room 419A	Does not exist
Instance on Rooms 307, 321	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 125	Does not exist
Instance on Room 214	Does not exist
Instance on Room 419A	Does not exist
Instance on Rooms 307, 321	Does not exist
Lighting Fixture - LED	
Instance on Room 125	Does not exist
Instance on Room 214	Does not exist
Instance on Room 419A	Inspected
Instance on Rooms 307, 321	Does not exist
Pendant Mounted	
Instance on Room 419A	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 419A	Does not exist
Recessed Mounted	
Instance on Room 419A	Does not exist
Raceway With Receptacles	
Instance on Room 125	Does not exist
Instance on Room 214	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded

#### **Building Condition Assessment Survey 2023-2024**

Question	Response
COMPUTER LAB	
Raceway With Receptacles	
Instance on Room 419A	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Rooms 307, 321	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
GYMNASIUM	Inspected
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Does not exist
Scoreboard	
Instance on 1st Floor	Does not exist
Theater Lighting System	
Instance on 1st Floor	Does not exist
KITCHEN	Inspected
Instance on 1st Floor	Inspected
Lighting	·
Instance on 1st Floor	Inspected

Inspected

Does not exist

Instance on 1st Floor

Instance on 1st Floor

**Pendant Mounted** 

Electrical Inspection	X184

Question	Response
KITCHEN	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
LIBRARY	Inspected
Instance on Room 236	Inspected
Lighting	
Instance on Room 236	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 236	Inspected
Pendant Mounted	
Instance on Room 236	Does not exist
Surface Mounted	
Instance on Room 236	Does not exist
Recessed Mounted	
Instance on Room 236	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Room 236	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 236	Does not exist
Lighting Fixture - LED	
Instance on Room 236	Does not exist
Raceway With Receptacles	
Instance on Room 236	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Projection System	D
Instance on Room 236	Does not exist
LOCKER ROOM	Inspected
Instance on Room 139 - Boys	Inspected
Alternative Use	Yes
Instance on Room 141 - Girls	Inaccessible
Lighting	Tu
Instance on Room 139 - Boys	Inspected
Lighting Fixture - Fluorescent	Inquantad
Instance on Room 139 - Boys Pendant Mounted	Inspected
	Inspected
Instance on Room 139 - Boys Instance Condition	Inspected  2- Between Good and Fair
Deficiency	No deficiencies recorded
	140 deficiencies recorded
Surface Mounted	

Electrical Inspection	X184

	A104
Response	
Does not exist	
Inspected	
2- Between Good and Fair	
No deficiencies recorded	
Does not exist	
Does not exist	
Does not exist	
Does not exist	
Inspected	
Yes	
No	
Inspected	
Inspected	
Inspected	
Inspected	
Inspected	
2- Between Good and Fair	
No deficiencies recorded	
Inspected	
2- Between Good and Fair	
No deficiencies recorded	
Does not exist	
Does not exist	
Does not exist	
Does not exist	
Does not exist	
Does not exist	
Does not exist	
2000 100 01100	
Does not exist	
	Does not exist  Inspected 2- Between Good and Fair No deficiencies recorded  Does not exist  Does not exist  Does not exist  Does not exist  Inspected Inspected Yes Yes Inspected Inspected Inspected Inspected Yes No  Inspected Does not exist

### **Building Condition Assessment Survey 2023-2024**

incui inspection		A104
Question	Response	
SCIENCE LAB		
Emergency Gas Shut-Off Valve		
Instance on Room 320	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 216, 218, 318	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power		
Instance on Room 320	Does not exist	
Instance on Rooms 216, 218, 318	Does not exist	
Power Supply		
Instance on Room 320	Does not exist	
Instance on Rooms 216, 218, 318	Does not exist	
Projection System		
Instance on Room 320	Does not exist	
Instance on Rooms 216, 218, 318	Does not exist	
SCIENCE PREP ROOM	Inspected	
Instance on Room 227	Inaccessible	
SWIMMING POOL	Does not exist	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
TOILET ROOM - STUDENT	Inspected	
	Inspected	
Lighting Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED		
AUXILIARY SIGNAL/BELL SYSTEM	Inspected 3- Fair	
Condition		
Deficiency	No deficiencies recorded	
EMERGENCY DC STANDBY BATTERY POWER	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EMERGENCY GENERATOR SET	Does not exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EMERGENCY LIGHTING	Inspected	
	1	

### **Building Condition Assessment Survey 2023-2024**

Response
Inspected
1- Good
BATTERY NOT OPERATIONAL
Boiler Room, Room 153 - School Safety Office
2
EACH
REPLACE BATTERY
PRIORITY 5
LEVEL 2
No violations recorded
Inspected
2- Between Good and Fair
No deficiencies recorded
Inspected
Inspected
1- Good
FIXTURE LAMP NOT OPERATIONAL
Cafeteria
2
EACH
MAINTENANCE
PRIORITY 5
LEVEL 2
No violations recorded
Does not exist
Does not exist
Inspected
Inspected
1- Good
No deficiencies recorded
Inspected
1- Good
No deficiencies recorded
Inspected
1- Good
No deficiencies recorded
Inspected
1- Good
No deficiencies recorded
Inspected
1- Good
No deficiencies recorded
Inspected
1- Good
No deficiencies recorded
Inspected
1- Good
No deficiencies recorded
Inspected
Inspected
1- Good
1- Good No deficiencies recorded
1- Good

### **Building Condition Assessment Survey 2023-2024**

	Ald
Response	
Inspected	
1- Good	
CONTACTOR NOT OPERATIONAL	
4th Floor Corridor by Room 409	
1	
EACH	
REPLACE	
PRIORITY 5	
LEVEL 6	
No violations recorded	
Inspected	
1- Good	
No deficiencies recorded	
*	
•	
1- Good	
1	
EACH	
Notifier	
NFS2-640	
Temporal 3 Fire Alarm System	
2019	
Documented	
No deficiencies recorded	
Does not exist	
Does not exist	
No deficiencies recorded	
Does not exist	
Inspected	
1- Good	
No deficiencies recorded	
Inspected	
No deficiencies recorded	
Inspected	
Inspected	
	Inspected  1- Good  CONTACTOR NOT OPERATIONAL  4th Floor Corridor by Room 409  1  EACH  REPLACE  PRIORITY 5  LEVEL 6  No violations recorded  Inspected  1- Good  No deficiencies recorded  Inspected  Main Entrance Lobby  1- Good  I  EACH  Notifier  NFS2-640  Temporal 3 Fire Alarm System  2019  Documented  No deficiencies recorded  Does not exist  Inspected  Does not exist  Inspected  Inspected  No deficiencies recorded  Does not exist  Does not exist  Inspected  1- Good  No deficiencies recorded  Does not exist  Inspected  1- Good  No deficiencies recorded  Does not exist  Inspected  1- Good  No deficiencies recorded  Does not exist  Inspected  1- Good  No deficiencies recorded  Does not exist  Inspected  1- Good  No deficiencies recorded  Inspected  1- Good  No deficiencies recorded

### **Building Condition Assessment Survey 2023-2024**

uestion	Response
INTERCOM SYSTEM	
Holding Area	Inspected
Condition	4- Between Fair and Poor
Deficiency	INTERCOM CABINET NOT OPERATIONAL
Deficiency Location/Instance	Room 415C
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	3- Fair
	No deficiencies recorded
Deficiency	
Main Equipment Rack (MDF)	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not exist
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Inspected
Instance	Mechanical Room 329
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Lexington Standard
EquipmentId	N/A
Capacity/Size Quantity	760
Capacity/Size UOM	Amps
Capacity/Size 2 Quantity	2
Capacity/Size 2 Quantity	Section(s)
Source of Capacity/Size	Inspector Estimate
Installation Year	1974
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Mechanical Room 329
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
·	
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room, Mechanical Room 329
Deficiency Quantity	4
Quantity Uom	EACH

### **Building Condition Assessment Survey 2023-2024**

Question	Response
PANEL BOARD	
Fused Disconnect Switch Type	
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Mechanical Room 329
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B17
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	31
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	NO SPARE
Deficiency Location/Instance	Kitchen, by Rooms (146, 410, 430)
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	General Office - Room 201
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Telecor II
Installation Year	2010
Installation Year Source of Installation Year	Documented
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity  Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	REPLACE
i otolitidi Action	NEI EINCE

### **Building Condition Assessment Survey 2023-2024**

estion	Response	
PUBLIC ADDRESS SYSTEM		
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
ECURITY	Inspected	
IPDVS/CCTV System	Inspected	
Condition	3- Fair	
Installation Year	2010	
Source of Installation Year	Documented	
Deficiency	CAMERA NOT OPERATIONAL	
Deficiency Location/Instance	1st Floor by Exit 6	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 4	
Purpose of Action	LEVEL 3	
Violations	No violations recorded	
Intrusion Alarm System	Inspected	
Central Control Panel	Inspected	
Instance	Custodian's Office - Room 101	
Instance Condition	3- Fair	
Instance Quantity	1	
	EACH	
Instance Quantity Uom Model	Vista - 50P	
	1990	
Installation Year		
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Custodian's Office - Room 101	
Deficiency Quantity	1	
Quantity Uom	EACH DENIA CE	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 3	
Violations	No violations recorded	
Infrared Sensor	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Panic Switch	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Remote Annunciator	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Siren/Strobe	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting - Security	Inspected	
Condition	1- Good	
Deficiency	TIME CLOCK NOT OPERATIONAL	
Deficiency Location/Instance	Electrical Room B17	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 3	

### **Building Condition Assessment Survey 2023-2024**

icui Inspection		Alo
uestion	Response	
SECURITY		
Lighting - Security		
Violations	No violations recorded	
SERVICE SWITCH	Inspected	
Instance	Electrical Room B17	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Lexington	
EquipmentId	Main Service SW	
Capacity/Size Quantity	4000	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Inspector Estimate	
Installation Year	1974	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room B17	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
SWITCHBOARD	Inspected	
Number of Spares	0	
Fused Disconnect Switch Type	Inspected	
Instance	Electrical Room B17	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Lexington	
EquipmentId	N/A	
Capacity/Size Quantity	4000	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	5	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Inspector Estimate	
Installation Year	1974	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room B17	
Deficiency Quantity	1	
Quantity Uom	EACH PERLACE	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Fused Knife Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Does not exist	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	

#### **Building Condition Assessment Survey 2023-2024**

Electrical Inspection X184

QuestionResponseTRANSFORMERDoes not exist