

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Mechanical Inspection**

**X198**


**Asset:** P.S. 198 - BRONX, 1180 TINTON AVENUE, BRONX, NY, 10456

Inspection Id	Inspection Type	Time In	Last Edited
905	MECHANICAL	2023-11-09 10:05PM	2024-05-04 05:30PM

**Asset Data**

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: DX Split Systems (4 of 6) for 4th floor Years: 2023 Systems: DX Split System (1 of 6) for Elevator Machine Room Years: 2022 Systems: Exhaust Fans (~50%) Years: 2020 Systems: Boiler Safety Valves; Climate Control System: Temperature Control Zone Valves Years: 2019 Systems: DX Split System (1 of 6) and Electric Domestic Water Heater for Medical Clinic; Enclosed IDF Room - Dedicated A/C Equipment (DX Split System); Kitchen - Grease Trap Years: 2018 Systems: MDF Room - Dedicated A/C Equipment (DX Split System) Years: 2014
Are there fuel tanks?	Yes
Total # of above ground tanks	2
Total capacity of all above ground tanks in gal.	15,000
Total # of below ground tanks	0
Total capacity of all below ground tanks in gal.	0
Total # of water main service entries to the asset	3
MERs/Fan Rooms Locations	Boiler Room Mechanical Area; MERs 209, 309E; Penthouse MER
Are there any spaces with Missing or Defective CO Detectors?	No
Are there any Painted/Obstructed Sprinkler Heads?	No
Are there any Emergency Stop Switches with Missing Hammers?	No components

**Priority Condition**

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
Yes	Defective Boiler Safety Auxiliary	(1)	Boiler Safety Valve	Boiler Room @ Boiler #1	MAURIBE ASCENCI O	Custodian	

**Inspection**

Question	Response
<b>Mechanical</b>	
<b>AIR CONDITIONING</b>	Inspected
<b>Chilled Water System</b>	Inspected
<b>Absorption Chiller</b>	Does not exist
<b>Air Cooled Chiller</b>	Inspected
Instance	Penthouse MER
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Trane
EquipmentId	N/A
Capacity/Size Quantity	35

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

***Mechanical Inspection***

**X198**

<b>Question</b>	<b>Response</b>
<b>AIR CONDITIONING</b>	
<b>Chilled Water System</b>	
<b>Air Cooled Chiller</b>	
Capacity/Size UOM	Tons
Source of Capacity/Size	Inspector Estimate
Installation Year	1974
Source of Installation Year	Documented
Refrigerant Type	R-22
Deficiency	No deficiencies recorded
Instance	MER 209
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Trane
EquipmentId	N/A
Capacity/Size Quantity	100
Capacity/Size UOM	Tons
Source of Capacity/Size	Inspector Estimate
Installation Year	1974
Source of Installation Year	Documented
Refrigerant Type	R-22
Deficiency	No deficiencies recorded
Instance	MER 209
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Trane
EquipmentId	N/A
Capacity/Size Quantity	100
Capacity/Size UOM	Tons
Source of Capacity/Size	Inspector Estimate
Installation Year	1974
Source of Installation Year	Documented
Refrigerant Type	R-22
Deficiency	No deficiencies recorded
<b>Air Cooled Condenser</b>	Inspected
Instance	Main Roof
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Trane
EquipmentId	N/A
Capacity/Size Quantity	35
Capacity/Size UOM	Tons
Source of Capacity/Size	Inspector Estimate
Installation Year	1974
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Auditorium Roof
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Trane
EquipmentId	N/A
Capacity/Size Quantity	100
Capacity/Size UOM	Tons

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Mechanical Inspection**

**X198**

Question	Response
<b>AIR CONDITIONING</b>	
<b>Chilled Water System</b>	
<b>Air Cooled Condenser</b>	
Source of Capacity/Size	Inspector Estimate
Installation Year	1974
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Auditorium Roof
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Trane
EquipmentId	N/A
Capacity/Size Quantity	100
Capacity/Size UOM	Tons
Source of Capacity/Size	Inspector Estimate
Installation Year	1974
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Chilled Water Distribution: Piping, Pumps and Auxiliaries</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Backflow Preventer</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Central Station Air Handler</b>	Inspected
Instance	Penthouse MER
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Trane
EquipmentId	Unit #22
Capacity/Size Quantity	3
Capacity/Size UOM	Fan Motor HP
Source of Capacity/Size	Inspector Estimate
Installation Year	1974
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	MER 209
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Trane
EquipmentId	N/A
Capacity/Size Quantity	8
Capacity/Size UOM	Fan Motor HP
Source of Capacity/Size	Inspector Estimate
Installation Year	1974
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	MER 209
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Trane

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Mechanical Inspection**

**X198**

Question	Response
<b>AIR CONDITIONING</b>	
<b>Chilled Water System</b>	
<b>Central Station Air Handler</b>	
EquipmentId	N/A
Capacity/Size Quantity	2
Capacity/Size UOM	Fan Motor HP
Source of Capacity/Size	Inspector Estimate
Installation Year	1974
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Fan Coil Unit</b>	Does not exist
<b>Packaged Air Cooled Chiller</b>	Does not exist
<b>Water Cooled Chiller</b>	Does not exist
<b>Condenser Water Distribution: Piping, Pumps and Auxiliaries</b>	Does not exist
<b>Cooling Coil in Ductwork</b>	Does not exist
<b>Cooling Tower</b>	Does not exist
<b>DX Split System</b>	Inspected
<b>Indoor Unit</b>	
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Outdoor Unit</b>	
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Dry Cooler</b>	Does not exist
<b>Packaged / Rooftop Unit</b>	Does not exist
<b>Packaged Terminal A/C</b>	Does not exist
<b>Refrigerant Leak Detection System</b>	Does not exist
<b>Refrigerant Piping</b>	Inspected
Condition	1- Good
Deficiency	DAMAGED/MISSING INSULATION
Deficiency Location/Instance	MER 209, Auditorium Roof, Penthouse MER, Main Roof
Deficiency Quantity	200
Quantity Uom	L.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Return Fan</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>CENTRAL ACID WASTE NEUTRALIZING TANK</b>	Does not exist
<b>CLIMATE CONTROL SYSTEM</b>	Inspected
<b>BMS</b>	Does not exist
<b>Pneumatic System</b>	
Instance	Throughout
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Building Area Covered by Operational System	81-100%
Deficiency	No deficiencies recorded
<b>Hybrid System</b>	Does not exist
<b>Electric System</b>	Does not exist
<b>COMPACTOR</b>	
Condition	3- Fair
Deficiency	NOT IN USE

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Mechanical Inspection**

**X198**

Question	Response
<b>COMPACTOR</b>	
Deficiency Location/Instance	Room G9
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
<b>CONVEYING</b>	
	Inspected
<b>Dumbwaiter</b>	Does not exist
<b>Elevator</b>	Inspected
Condition	2- Between Good and Fair
Are all the existing elevators operable?	Yes
Deficiency	No deficiencies recorded
<b>Escalator</b>	Does not exist
<b>Non-auditorium Handicap Lift - Vertical</b>	Does not exist
<b>Non-auditorium Handicap Lift - Stair</b>	Does not exist
<b>Ash Hoist</b>	Does not exist
<b>Sidewalk Elevator</b>	Does not exist
<b>DOMESTIC WATER SYSTEM</b>	
	Inspected
<b>Domestic Cold Water System</b>	Inspected
<b>Gravity System</b>	Does not exist
<b>Pressure Booster System</b>	Does not exist
<b>Water Service</b>	Inspected
Instance	Basement - Sprinkler/Water/Gas Meter Room G3; Crawlspace - Union Avenue Side
Instance Condition	3- Fair
Instance Quantity	3
Instance Quantity Uom	EACH
Deficiency	WATER MAIN:MISSING BACKFLOW PREVENTION DEVICE
Deficiency Location/Instance	Basement - Sprinkler/Water/Gas Meter Room G3; Crawlspace - Union Avenue Side
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	INSTALL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Domestic Hot Water System</b>	Inspected
<b>Domestic Hot Water Remote Storage Tank</b>	Does not exist
<b>Domestic Water Heat Exchanger</b>	Does not exist
<b>Electric Domestic Water Heater</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Gas Fired Domestic Water Heater</b>	Does not exist
<b>Oil Fired Domestic Water Heater</b>	Inspected
Instance	Boiler Room Mechanical Area
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	A.O. Smith
EquipmentId	N/A
Capacity/Size Quantity	199
Capacity/Size UOM	MBH Input
Capacity/Size 2 Quantity	150

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Mechanical Inspection**

**X198**

Question	Response
<b>DOMESTIC WATER SYSTEM</b>	
<b>Domestic Hot Water System</b>	
<b>Oil Fired Domestic Water Heater</b>	
Capacity/Size 2 UOM	Gallons
Source of Capacity/Size	Documented
Installation Year	2011
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
<b>Heat Pump Domestic Water Heater</b>	
	Does not exist
<b>Domestic Water Distribution Piping</b>	
Condition	Inspected
Deficiency	3- Fair
	No deficiencies recorded
<b>DRAIN/WASTE/VENT AND STORM SYSTEM</b>	
	Inspected
<b>Interior Storm Piping</b>	
Condition	Inspected
Deficiency	3- Fair
	No deficiencies recorded
<b>Sewage/Waste/Vent Piping</b>	
Condition	Inspected
Deficiency	3- Fair
	No deficiencies recorded
<b>Sewage Ejector Pump</b>	
	Does not exist
<b>Sump Pump</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair
	No deficiencies recorded
<b>DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)</b>	
	Inspected
<b>Dual Temperature Distribution: Piping, Pumps and Auxiliaries</b>	
Condition	Inspected
Deficiency	3- Fair
	PUMP:DEFECTIVE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Dual Temperature Terminal Fan Coil Unit</b>	
Condition	Inspected
Deficiency	3- Fair
	No deficiencies recorded
<b>FIXTURES</b>	
	Inspected
<b>Staff And Other</b>	
	Inspected
<b>Janitor Sink</b>	
Condition	Inspected
Deficiency	3- Fair
	No deficiencies recorded
<b>Lavatory/Sink</b>	
Condition	Inspected
Deficiency	3- Fair
	No deficiencies recorded
<b>Toilet</b>	
Condition	Inspected
Deficiency	3- Fair
	No deficiencies recorded
<b>Urinal</b>	
Condition	Inspected
Deficiency	3- Fair
	No deficiencies recorded
<b>Student</b>	
	Inspected
<b>Drinking Fountain</b>	
Condition	Inspected
	2- Between Good and Fair

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Mechanical Inspection**

**X198**

Question	Response
<b>FIXTURES</b>	
<b>Student</b>	
<b>Drinking Fountain</b>	
Deficiency	No deficiencies recorded
<b>Lavatory/Sink</b>	
Condition	Inspected
Deficiency	3- Fair
<b>Locker Room Shower</b>	
Condition	No deficiencies recorded
<b>Sink And Fountain Combo Unit</b>	
Condition	Does not exist
Deficiency	Inspected
<b>Toilet</b>	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Urinal</b>	
Condition	Inspected
Deficiency	3- Fair
<b>GAS FIRED FURNACE</b>	
Condition	Does not exist
<b>GAS SERVICE</b>	
<b>Gas Distribution Piping</b>	
Condition	Inspected
Deficiency	3- Fair
<b>Gas Meter Room Exhaust Fan</b>	
Condition	No deficiencies recorded
Deficiency	Inspected
<b>Gas Meter Room Vent</b>	
Condition	Does not exist
<b>Gas Pressure Booster</b>	
Condition	Does not exist
<b>CO/Gas Leak Detection</b>	
Condition	Does not exist
<b>HEATING</b>	
<b>Heating Coil In Ductwork</b>	
Condition	Inspected
Deficiency	3- Fair
<b>Hydronic Heating</b>	
<b>Hydronic Hot Water Distribution: Piping, Pumps and Auxiliaries</b>	
Condition	Inspected
Deficiency	3- Fair
<b>Backflow Preventer</b>	
Condition	No deficiencies recorded
<b>Hot Water Heat Exchanger</b>	
Condition	Does not exist
Deficiency	Inspected
<b>Radiator/Convactor/Fin Tube</b>	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Steam Heating</b>	
<b>F&amp;T/Steam Drip Trap</b>	
Condition	Inspected
Deficiency	3- Fair
<b>MER Steam and Condensate Piping</b>	
Condition	Inspected
Deficiency	3- Fair
Deficiency Location/Instance	DAMAGED/MISSING INSULATION
Deficiency Quantity	MER 209
Quantity Uom	40
Potential Action	L.F.
	MAINTENANCE

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

***Mechanical Inspection***

**X198**

Question	Response
<b>HEATING</b>	
<b>Steam Heating</b>	
<b>MER Steam and Condensate Piping</b>	
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Steam Condensate Return Piping</b>	
Inspected	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE/LEAKS
Deficiency Location/Instance	Basement - Crawlspace
Deficiency Quantity	10
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Steam Condensate Return Pumping System</b>	
Inspected	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE CONTROLS
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Steam Piping</b>	
Inspected	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Terminal Unit Thermostatic Trap</b>	
Inspected	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Steam supplied by External Sources</b>	
Does not exist	Does not exist
<b>Unit Heater/Cabinet Heater</b>	
Inspected	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>HEATING PLANT</b>	
Inspected	Inspected
Instance on Basement	Inspected
Is there a water meter on the boiler make-up water piping?	Yes
Observed Operational?	Yes
Burner Manufacturer	Webster
Burner Model	JB30-75-RM7840L-F-MA-UL/IRI/BAR
Burner Type	Oil
Heating Plant Oil Number	2(B10)
<b>Boiler Auxiliaries</b>	
Inspected	Inspected
Instance on Basement	Inspected
<b>Boiler Auxiliary Piping</b>	
Inspected	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	DEFECTIVE BLOWDOWN PIPING
Deficiency Location/Instance	Boiler Room @ Boiler #1
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3



**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Mechanical Inspection**

**X198**

Question	Response
<b>HEATING PLANT</b>	
<b>Boiler Auxiliaries</b>	
<b>Boiler Auxiliary Piping</b>	
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Boiler Emergency Stop Switch</b>	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Boiler Feedwater System</b>	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Boiler Feedwater Treatment(Automatic)</b>	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Boiler Flue Exhaust</b>	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Boiler Make-up Water Backflow Preventer</b>	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Boiler Room Steam And Condensate Piping</b>	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Boiler Safety Valve</b>	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	DEFECTIVE
Deficiency Location/Instance	Boiler Room @ Boiler #1
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
<b>Boiler System</b>	
Instance on Basement	Inspected
<b>Coal-fired Boiler</b>	
Instance on Basement	Does not exist
<b>Hot Water Boiler</b>	
Instance on Basement	Does not exist
<b>Modular Boiler</b>	
Instance on Basement	Inspected
Instance on Basement	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	0
Instance Quantity Uom	MBH NET
Manufacturer	Industrial Engineering @ Equipment Co.

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Mechanical Inspection**

**X198**

Question	Response
<b>HEATING PLANT</b>	
<b>Boiler System</b>	
<b>Modular Boiler</b>	
EquipmentId	N/A
Capacity/Size Quantity	0
Capacity/Size UOM	MBH Net
Source of Capacity/Size	Inspector Estimate
Installation Year	1960
Source of Installation Year	Inspector Estimate
Deficiency	NOT IN USE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
<b>Steam Boiler</b>	
Instance on Basement	Inspected
Instance on Basement	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	6,014
Instance Quantity Uom	MBH NET
Cast Iron Boiler?	No
Manufacturer	Federal Boiler Company
EquipmentId	58889-01
Capacity/Size Quantity	6014
Capacity/Size UOM	MBH Net
Source of Capacity/Size	Documented
Installation Year	1974
Source of Installation Year	Documented
Deficiency	LEAKY/PLUGGED TUBES
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	RUSTED CASING
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	6,014
Instance Quantity Uom	MBH NET
Cast Iron Boiler?	No
Manufacturer	Federal Boiler Company
EquipmentId	58889-02
Capacity/Size Quantity	6014
Capacity/Size UOM	MBH Net
Source of Capacity/Size	Documented

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Mechanical Inspection**

**X198**

Question	Response
<b>HEATING PLANT</b>	
<b>Boiler System</b>	
<b>Steam Boiler</b>	
Installation Year	1974
Source of Installation Year	Documented
Deficiency	RUSTED CASING
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE AUXILIARY (GAUGES, GASKETS ETC.)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Fuel System</b>	
Instance on Basement	Inspected
<b>Boiler Fresh Air Louver/Damper</b>	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Type	Automatic
Deficiency	No deficiencies recorded
<b>Burner/Burner Control Panel</b>	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fuel Oil Storage/Supply System</b>	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	FUEL OIL TRANSFER PUMP:DEFECTIVE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Gas Trains And Vent At The Boiler</b>	
Instance on Basement	Does not exist
<b>Enclosed IDF Room</b>	
Instance on Dedicated A/C Equipment	Inspected
<b>Dedicated A/C Equipment</b>	
Instance on Dedicated A/C Equipment	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>KITCHEN</b>	
Instance on 1st Floor	Inspected
<b>CO Detector</b>	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded

**NYC Department of Education**  
**Building Condition Assessment Survey 2023-2024**

**Mechanical Inspection**

**X198**

Question	Response
<b>KITCHEN</b>	
<b>Gas System</b>	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Grease Trap</b>	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Hood</b>	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Hood Exhaust Ductwork</b>	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Hood Exhaust Fan</b>	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Hood Fire Suppression System</b>	
Instance on 1st Floor	Does not exist
<b>Hot Water Temperature Booster</b>	
Instance on 1st Floor	Does not exist
<b>Kitchen Sink</b>	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	Missing Air Gap
Deficiency Location/Instance	Kitchen
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>MDF Room</b>	
Instance on Room 203A	Inspected
<b>Dedicated A/C Equipment</b>	
Instance on Room 203A	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>SCIENCE DEMO ROOM</b>	
	Does not exist
<b>SCIENCE LAB</b>	
	Does not exist
<b>SCIENCE PREP ROOM</b>	
	Does not exist
<b>SPRINKLERS, STANDPIPE, FIRE SYSTEM</b>	
	Inspected
<b>Dry Sprinkler Alarm Valve Assembly</b>	
	Does not exist
<b>Wet Sprinkler Alarm Valve Assembly</b>	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fire Booster Pump Assembly</b>	
	Does not exist
<b>Roof Tank</b>	
	Does not exist
<b>Siamese Connection</b>	
Condition	Inspected
	3- Fair

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Mechanical Inspection**

**X198**

<b>Question</b>	<b>Response</b>
<b>SPRINKLERS, STANDPIPE, FIRE SYSTEM</b>	
<b>Siamese Connection</b>	
Deficiency	No deficiencies recorded
<b>Sprinkler Head</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Sprinkler Piping</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Standpipe System</b>	Inspected
<b>Hose Valve Assembly</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Piping</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Water Gong</b>	Does not exist
<b>SWIMMING POOL</b>	Does not exist
<b>VENTILATION</b>	Inspected
Is the building Mechanically ventilated?	Yes
<b>Exhaust Fan</b>	Inspected
Condition	2- Between Good and Fair
Approximate Total # of Fans	1-25
Deficiency	DEFECTIVE
Deficiency Location/Instance	Roof / #11 (bearing)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Heating And Ventilating Unit</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Metal Ductwork</b>	Inspected
Condition	3- Fair
Are there any uninsulated ductwork by design in Mechanical rooms?	No
Are there chain operated dampers?	No
Deficiency	DEFECTIVE REGISTER/DIFFUSER
Deficiency Location/Instance	Gymnasium
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DAMAGED/MISSING INSULATION
Deficiency Location/Instance	MER 209
Deficiency Quantity	10
Quantity Uom	L.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Supply Fan</b>	Inspected

NYC Department of Education  
Building Condition Assessment Survey 2023-2024

*Mechanical Inspection*

X198

Question	Response
<b>VENTILATION</b>	
<b>Supply Fan</b>	
Condition	3- Fair
Approximate Total # of Fans	1-5
Deficiency	No deficiencies recorded
<b>Unit Ventilator</b>	Does not exist