Building Condition Assessment Survey 2023-2024

Electrical Inspection X205

Asset:	P.S. 205A (ECF)	- BRONX, 2475 SOUTHE	RN BOULEVARI	D, BRONX, NY	, 10458		
Inspection	n Id Inspection Type				Time	In	Last Edited
	2509 ELECTRICAL				2024-	01-19 08:44AN	M 2024-02-13 08:32AN
set Data							
Question				Answer			
Have any	Systems/Major Building C	Components been upgraded?		Systems:	Lighting Syst		ojection System, Theater
				Years:	2023		
				Systems:		d Case Circuit E	Breaker Panel Board
				Years:	2021, 2009		
				Systems:	Partial Switch	board, Battery I	Pack Emergency Lighting
				Years:	2021		
				Systems:	Public Addres	ss System (Clock	ks), LAN
				Years:	2019		
				Systems:	Telephone Sy	stem	
				Years:	2018		
				Systems:	Cafeteria (Loc	cal Sound System	m)
				Years:	2011		
				Systems:	Fire Alarm Sy	stem, Intrusion	Alarm System
				Years:	2009		
				Systems:	Lighting, Surf Fluorescent L	face Fluorescent	(Pendant Fluorescent Lighting), Retrofitted ed Mounted Type,
				37	Cafeteria)		
				Years:	2008	C (T	`
				Systems:		ss System (Tune	r)
				Years:	2004		
				Systems:		ight/Exit Light I	Panel
				Years:	2001		
Type of S				Below G	round		
	eractive Whiteboard (IWB)			Yes			
	netration In Electrical Room			No			
		N FIRE RESCUE AREAS			n		
Question		nce Areas, Fire Rescue Areas, a	and/or Holding Doom		Response No		
your bu	ilding?	ice Areas, i ne rescue Areas, a	ma/of Holding Roof	13 111	110		
xist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
ast Year?	Category	Description	Affected	Description	Notified	Title	Image
es	Lightning Protection - Defective	N/A	Lightning Protection	Chimney	Johnny Ortiz	Fireman	
es	Public Address System	All Speakers In Student Cafeteria Are Not	Public Address	Student	Johnny	Fireman	No Photo Taken
	- Speakers Not Operational	Operational.	System	Cafeteria	Ortiz		
	Орстанонат	operational.					

Inspection

pection		
Question	Response	
Electrical		
ATHLETIC FIELD	Does not exist	
AUDITORIUM	Does not exist	
CAFETERIA	Inspected	
Instance on 1st Floor - Students	Inspected	

Building Condition Assessment Survey 2023-2024

cui inspection	Λ2
estion	Response
AFETERIA	
Instance on 1st Floor - Staff	Inspected
Lighting	
Instance on 1st Floor - Students	Inspected
Instance on 1st Floor - Staff	Inspected
Lighting Fixture - Fluorescent	-
Instance on 1st Floor - Students	Inspected
Instance on 1st Floor - Staff	Inspected
Pendant Mounted	*
Instance on 1st Floor - Students	Does not exist
Instance on 1st Floor - Staff	Does not exist
Surface Mounted	
Instance on 1st Floor - Students	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on 1st Floor - Staff	Does not exist
Recessed Mounted	DOCS HOT CAIST
Instance on 1st Floor - Students	Does not exist
Instance on 1st Floor - Students	Inspected
	3- Fair
Instance Condition Deficiency	No deficiencies recorded
	No deficiencies recorded
Lighting Fixture - HID	D
Instance on 1st Floor - Students	Does not exist
Instance on 1st Floor - Staff	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor - Students	Inspected
Instance on 1st Floor - Staff	Does not exist
Pendant Mounted	
Instance on 1st Floor - Students	Does not exist
Surface Mounted	
Instance on 1st Floor - Students	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	
Instance on 1st Floor - Students	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	4 F. GY
Quantity Uom	EACH PERMACE LIBERADE
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - LED	
Instance on 1st Floor - Students	Does not exist
Instance on 1st Floor - Staff	Does not exist
Local Sound System	
Instance on 1st Floor - Students	Inspected

Building Condition Assessment Survey 2023-2024

cutcut Inspection		A205
Question	Response	
CAFETERIA		
Local Sound System		
Instance Condition	3- Fair	
Installation Year	2011	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance on 1st Floor - Staff	Does not exist	
Projection System		
Instance on 1st Floor - Students	Inspected	
Instance Condition	1- Good	
Is the projector on a cart or installed on the ceiling?	Ceiling	
Deficiency	No deficiencies recorded	
Instance on 1st Floor - Staff	Does not exist	
Theater Lighting System		
Instance on 1st Floor - Students	Inspected	
Instance on 1st Floor - Staff	Does not exist	
Dimming System		
Instance on 1st Floor - Students	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Theater Lighting		
Instance on 1st Floor - Students	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
COMPUTER LAB	Does not exist	
GYMNASIUM	Does not exist	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
Lighting	mspected	
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent	1	
Instance on 1st Floor	Inspected	
Pendant Mounted	map	
Instance on 1st Floor	Does not exist	
Surface Mounted	2 000 HOT WARM	
Instance on 1st Floor	Does not exist	
Recessed Mounted	2 000 HOT WARM	
Instance on 1st Floor	Inspected	
instance on 15t 1 1001	Inspected	

Building Condition Assessment Survey 2023-2024

neui mspeciion		A20.
Question	Response	
KITCHEN		
Lighting		
Lighting Fixture - Fluorescent		
Recessed Mounted		
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Does not exist	
LIBRARY	Inspected	
Instance on Room 216	Inspected	
Lighting	•	
Instance on Room 216	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 216	Inspected	
Pendant Mounted		
Instance on Room 216	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 216	Does not exist	
Recessed Mounted		
Instance on Room 216	Does not exist	
Lighting Fixture - HID		
Instance on Room 216	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 216	Does not exist	
Lighting Fixture - LED		
Instance on Room 216	Does not exist	
Raceway With Receptacles		
Instance on Room 216	Does not exist	
Projection System		
Instance on Room 216	Does not exist	
LOCKER ROOM	Does not exist	
MULTIPURPOSE ROOM	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SWIMMING POOL	Does not exist	
TOILET ROOM - STAFF	Inspected	
Lighting Lighting Fixture Fluorescent	Inspected Inspected	
Lighting Fixture - Fluorescent	Does not exist	
Pendant Mounted Surface Mounted	Inspected	
Condition	3- Fair	
-	No deficiencies recorded	
Deficiency		
Recessed Mounted	Inspected 3- Fair	
Condition		
Deficiency	No deficiencies recorded	

Building Condition Assessment Survey 2023-2024

icui Inspection		11203
Question	Response	
TOILET ROOM - STAFF		
Lighting		
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	
EMERGENCY GENERATOR SET	Does not exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EMERGENCY LIGHTING	Inspected	
Battery Pack	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Non Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EXIT LIGHT	Inspected	
Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	FIXTURE NOT OPERATIONAL	
Deficiency Location/Instance	Library, Stair B/Basement	
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Non Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EXIT/EMERGENCY LIGHT	Does not exist	
FIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Strobe	Inspected	

Building Condition Assessment Survey 2023-2024

cui inspection		212
estion	Response	
IRE ALARM SYSTEM		
Strobe		
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
CO Detector	Does not exist	
Heat Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Elevator Recall	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Magnetic Door Holder/Contactor	Does not exist	
Fused Cutout Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Inspected	
Bell At Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	General Electric	
Model	EST 2	
EquipmentId	Fire Alarm Control Panel	
Installation Year	2009	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel	Does not exist	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	2- Between Good and Fair	
Deficiency Punch Register	No deficiencies recorded Does not exist	

Building Condition Assessment Survey 2023-2024

irical inspection	A205
Question	Response
FIRE ALARM SYSTEM	
Sprinkler Flow/Air Pressure Switch	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
	Inspected
GROUNDING SYSTEM	3- Fair
Condition	
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Inspected
Elevator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Holding Area	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Does not exist
Main Equipment Rack (MDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<u> </u>	
LIGHTNING PROTECTION	Inspected
Condition	4- Between Fair and Poor
Deficiency	LIGHTNING PROTECTION CONDUCTOR CLAMPS NOT
	PROPERLY ATTACHED
Deficiency Location/Instance Deficiency Quantity	Chimney
	1
Quantity Uom	EACH PEN AGE
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3- Fair
	PANEL BOARD BEYOND USEFUL LIFE
Deficiency	
Deficiency Location/Instance Deficiency Quantity	Boiler Room, Kitchen
Quantity Uom	3 EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	DIVINI DO I DO DEVIOUS MARENT MARE
Deficiency Location/Instance	PANEL BOARD BEYOND USEFUL LIFE

Building Condition Assessment Survey 2023-2024

Question	Response
PANEL BOARD	
Fused Toggle Switch Type	
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Inspected
Condition	2- Between Good and Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Corridors Throughout the Building, Student Cafeteria, Electrical
Denoted Decimal Instance	Room
Deficiency Quantity	11
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	Room 116
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	N/A
Installation Year	1976
Source of Installation Year	Documented
Deficiency	SPEAKER NOT OPERATIONAL
Deficiency Location/Instance	Student Cafeteria
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE
	PRIORITY 5
Urgency of Action	LEVEL 6
Purpose of Action	
Violations	No violations recorded
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Room 116
Deficiency Quantity	55,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
SECURITY	Inspected
IPDVS/CCTV System	Does not exist
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
	Room 116B
Instance Instance Condition	3- Fair
Instance Condition	
Instance Quantity	1
T O TT	EACH
Instance Quantity Uom	
Instance Quantity Com Model	Vista - 128B
-	Vista - 128B 2009
Model	
Model Installation Year	2009

Building Condition Assessment Survey 2023-2024

Electrical Inspection	X205

Question	Response
SECURITY	
Intrusion Alarm System	
Infrared Sensor	
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
SERVICE SWITCH	Inspected
Instance	Electrical Room B3
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Federal Pacific Electric
EquipmentId	Main Dist. SWBD
Capacity/Size Quantity	2000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year Source of Installation Year	1976 Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B3
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room B3
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Federal Pacific Electric
EquipmentId	MSG-M2
Capacity/Size Quantity	400
Capacity/Size UOM Source of Capacity/Size	Amps Nameplate
Installation Year	1976
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B3
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2

Building Condition Assessment Survey 2023-2024

X205

ineal Inspection		71
Question	Response	
SERVICE SWITCH		
Violations	No violations recorded	
Instance	Electrical Room B3	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Federal Pacific Electric	
EquipmentId	PP-B	
Capacity/Size Quantity	200	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	1976	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room B3	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
SWITCHBOARD	Inspected	
Number of Spares	0	
Fused Disconnect Switch Type	Inspected	
Instance	Electrical Room B3	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Federal Pacific Electric	

Building Condition Assessment Survey 2023-2024

Question	Response	
SWITCHBOARD		
Fused Disconnect Switch Type		
Installation Year	2021	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fused Knife Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Does not exist	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
TD ANGEODMED	Door not avist	