Building Condition Assessment Survey 2023-2024

Asset:	P.S. 209 - BRON	X, 313 EAST 183 STREET	, BRONX, NY, 1	10458		
Inspecti	ion Id Inspection Type				Time In	Last Edited
	3978 ELECTRICAL				2024-03-13 11:22AM	2024-03-15 11:21AN
set Dat	^t a					
Questio	on			Answer		
Have ar	ny Systems/Major Building Co	omponents been upgraded?		Systems:	Most Lighting - Security	
				Years:	2022	
				Systems:	Intrusion Alarm System	
				Years:	2019	
				Systems:	Telephone System	
				Years:	2017	
				Systems:	LAN	
				Years:	2011	
				Systems:	Fire Alarm System Except (Sub	
					Annunciator, Sprinkler Flow/A	ir Pressure Switch,
				Voorse	Tamper Flow Switch/Chain) 2004	
				Years: Systems:	All Other Electrical Systems ar	id Components
				Years:	1994	ia Components
T	Campian			Helow Gro		
	Service ateractive Whiteboard (IWB) I	Evict?		Yes	unu	
	Penetration In Electrical Room			Yes No		
	CATED INTERCOMS IN			110		
Questio		TIKE RESCOE MIKERS		R	esponse	
		ce Areas, Fire Rescue Areas, ar	nd/or Holding Rooi		es	
	building?					
		e in all of these spaces for use of	during a fire?	Y	'es	
	re all dedicated intercoms ope			N		
	Which rooms or areas have no	on-operational dedicated interco	oms?	R	ooms 210, 313, 413	
riority C	Condition					
Exist	Priority	Condition	Component	Location	Person(s) Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified Title	Image
No cond	dition recorded					
nspectio	on					
Questic	on			Response		
Question Electric				Response		
Electric	cal				xist	
Electric ATH	cal LETIC FIELD			Does not e		
Electric ATHI	cal LETIC FIELD ITORIUM			Does not e		
Electric ATHI	cal LETIC FIELD ITORIUM ETERIA			Does not e Does not e Inspected		
ATHI AUD CAFI	CAI LETIC FIELD ITORIUM ETERIA Instance on 1st Floor			Does not e		
ATHI AUD CAFI	LETIC FIELD ITORIUM ETERIA Instance on 1st Floor			Does not e Does not e Inspected Inspected		
ATHI AUD CAFI	LETIC FIELD ITORIUM ETERIA Instance on 1st Floor thting Instance on 1st Floor			Does not e Does not e Inspected		
ATHI AUD CAFI	CAL LETIC FIELD ITORIUM ETERIA Instance on 1st Floor thing Instance on 1st Floor ighting Fixture - Fluorescen	t		Does not e Does not e Inspected Inspected Inspected		
Electric ATHI AUD CAFI Lig	LETIC FIELD ITORIUM ETERIA Instance on 1st Floor thting Instance on 1st Floor ighting Fixture - Fluorescen Instance on 1st Floor	t		Does not e Does not e Inspected Inspected		
Electric ATHI AUD CAFI Lig	LETIC FIELD ITORIUM ETERIA Instance on 1st Floor thting Instance on 1st Floor ighting Fixture - Fluorescen Instance on 1st Floor Pendant Mounted	t		Does not e Does not e Inspected Inspected Inspected Inspected	xist	
Electric ATHI AUD CAFI Lig	LETIC FIELD ITORIUM ETERIA Instance on 1st Floor hting Instance on 1st Floor ighting Fixture - Fluorescen Instance on 1st Floor Pendant Mounted Instance on 1st Floor	t		Does not e Does not e Inspected Inspected Inspected	xist	
Electric ATHI AUD CAFI Lig	LETIC FIELD ITORIUM ETERIA Instance on 1st Floor thing Instance on 1st Floor ighting Fixture - Fluorescen Instance on 1st Floor Pendant Mounted Instance on 1st Floor Surface Mounted	t		Does not e Does not e Inspected Inspected Inspected Does not e	xist	
Electric ATHI AUD CAFI Lig	LETIC FIELD ITORIUM ETERIA Instance on 1st Floor thting Instance on 1st Floor ighting Fixture - Fluorescen Instance on 1st Floor Pendant Mounted Instance on 1st Floor Surface Mounted Instance on 1st Floor	t		Does not e Does not e Inspected Inspected Inspected Inspected	xist	
Electric ATHI AUD CAFI Lig	LETIC FIELD ITORIUM ETERIA Instance on 1st Floor thing Instance on 1st Floor ighting Fixture - Fluorescen Instance on 1st Floor Pendant Mounted Instance on 1st Floor Surface Mounted Instance on 1st Floor Recessed Mounted	t		Does not e Does not e Inspected Inspected Inspected Does not e Does not e	xist	
Electric ATHI AUD CAFI Lig	LETIC FIELD ITORIUM ETERIA Instance on 1st Floor hting Instance on 1st Floor ighting Fixture - Fluorescen Instance on 1st Floor Pendant Mounted Instance on 1st Floor Surface Mounted Instance on 1st Floor Recessed Mounted Instance on 1st Floor	t		Does not e Does not e Inspected Inspected Inspected Does not e Does not e	xist	
Electric ATHI AUD CAFI Lig	Instance on 1st Floor Pendant Mounted Instance on 1st Floor Surface Mounted Instance on 1st Floor Recessed Mounted Instance on 1st Floor Instance on 1st Floor Instance Ondition	t		Does not e Does not e Inspected Inspected Inspected Does not e Does not e Inspected Joseph Does not e	xist	
Electric ATHI AUD CAFI Lig	ILETIC FIELD ITORIUM ETERIA Instance on 1st Floor hting Instance on 1st Floor ighting Fixture - Fluorescen Instance on 1st Floor Pendant Mounted Instance on 1st Floor Surface Mounted Instance on 1st Floor Recessed Mounted Instance on 1st Floor Instance on 1st Floor Deficiency	t		Does not e Does not e Inspected Inspected Inspected Does not e Does not e Inspected Lispected Lispected Lispected Lispected Lispected Lispected Lispected Lispected	xist	L LIFE
Electric ATHI AUD CAFI Lig	ILETIC FIELD ITORIUM ETERIA Instance on 1st Floor hting Instance on 1st Floor ighting Fixture - Fluorescen Instance on 1st Floor Pendant Mounted Instance on 1st Floor Surface Mounted Instance on 1st Floor Recessed Mounted Instance on 1st Floor Recessed Mounted Instance Onlist Floor Deficiency Deficiency Quantity	t		Does not e Does not e Inspected Inspected Inspected Does not e Does not e LIGHTING	xist	L LIFE
Electric ATHI AUD CAFI Lig	ILETIC FIELD ITORIUM ETERIA Instance on 1st Floor hting Instance on 1st Floor ighting Fixture - Fluorescen Instance on 1st Floor Pendant Mounted Instance on 1st Floor Surface Mounted Instance on 1st Floor Recessed Mounted Instance on 1st Floor Instance on 1st Floor Deficiency	t		Does not e Does not e Inspected Inspected Inspected Does not e Does not e LIGHTING 40 EACH	xist	L LIFE

Building Condition Assessment Survey 2023-2024

Duestion	Response
CAFETERIA	Response
Lighting Lighting Fixture - Fluorescent	
Recessed Mounted	
	DDIODITY 1
Urgency of Action	PRIORITY 1 LEVEL 2
Purpose of Action Violations	No violations recorded
	No violations recorded
Lighting Fixture - HID	D
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	5- Poor
Installation Year	1994
Source of Installation Year	Documented
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Projection System	
Instance on 1st Floor	Does not exist
Theater Lighting System	
Instance on 1st Floor	Does not exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier Exist?	Yes
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	30
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	752
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
	DD (OD MAY)

PRIORITY 1

No violations recorded

LIGHTING FIXTURE BEYOND USEFUL LIFE

LEVEL 2

Inspected

3- Fair

EACH

30

Potential Action Urgency of Action

Purpose of Action

Deficiency Quantity

Quantity Uom

Violations

Recessed Mounted
Condition

Deficiency

Building Condition Assessment Survey 2023-2024

iteu Inspection		1120)
Question	Response	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE		
Lighting		
Lighting Fixture - Fluorescent		
Recessed Mounted		
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Does not exist	
Recessed Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - LED	Does not exist	
COMPUTER LAB	Does not exist	
GYMNASIUM	Does not exist	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
Lighting	mspected	
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent	This provides	
Instance on 1st Floor	Inspected	
Pendant Mounted	Inspected	
Instance on 1st Floor	Does not exist	
Surface Mounted	DOES NOT CAIST	
Instance on 1st Floor	Does not exist	
Recessed Mounted	Does not exist	
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Deficiency Quantity	12	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Does not exist	
LIBRARY	Does not exist	
	Does not exist	
LOCKER ROOM		
MULTIPURPOSE ROOM	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SWIMMING POOL	Does not exist	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	

Building Condition Assessment Survey 2023-2024

ctrical inspection	X205
Question	Response
TOILET ROOM - STAFF	
Lighting	
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	Inspected
Condition	3- Fair
Deficiency Overtity	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	6 FACH
Quantity Uom Potential Action	EACH REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Does not exist
Recessed Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	26
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Inspected
Automatic Transfer Switch (ATS)	Inspected
Instance	Electrical Room C06
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Kohler Power Systems
EquipmentId	Fire Alarm Transfer Switch
Capacity/Size Quantity	70

Building Condition Assessment Survey 2023-2024

uestion		Response	
EMERGE	NCY GENERATOR SET	•	
	tic Transfer Switch (ATS)		
	Capacity/Size UOM	Amps	
	Source of Capacity/Size	Nameplate	
	Installation Year	1994	
	Source of Installation Year	Documented	
	Deficiency	No deficiencies recorded	
	Instance	Electrical Room C06	
	Instance Condition	3- Fair	
	Instance Quantity	1	
	Instance Quantity Uom	EACH	
		Kohler Power Systems	
	Manufacturer	Transfer Switch	
	EquipmentId Capacity/Size Quantity	400	
	Capacity/Size Quantity Capacity/Size UOM	Amps	
	Source of Capacity/Size	Nameplate	
	Installation Year	1994	
	Source of Installation Year	Documented	
	Deficiency	No deficiencies recorded	
Battery (Inspected	
-	Instance	Boiler Room	
	Instance Condition	3- Fair	
	Instance Quantity	1	
	Instance Quantity Uom	EACH	
	Manufacturer	Kohler Power Systems	
	EquipmentId	Battery Charger	
	Capacity/Size Quantity	10	
	Capacity/Size UOM	AmpsDC	
	Capacity/Size 2 Quantity	13	
	Capacity/Size 2 UOM	VDC	
	Source of Capacity/Size	Nameplate	
	Installation Year	1994	
	Source of Installation Year	Documented	
	Deficiency	No deficiencies recorded	
	ncy Distribution Board	Inspected	
	er of Spares	0	
Fused 1	Disconnect Switch Type	Inspected	
	Instance	Electrical Room C06	
	Instance Condition	3- Fair	
	Instance Quantity	1	
	Instance Quantity Uom	EACH	
	Manufacturer	All City Switchboard	
	EquipmentId	EDP	
	Capacity/Size Quantity	400	
	Capacity/Size UOM	Amps Total	
	Capacity/Size 2 Quantity	1	
	Capacity/Size 2 UOM	Section(s)	
	Source of Capacity/Size	Inspector Estimate	
	Installation Year	1994	
	Source of Installation Year	Documented	
	Deficiency	No deficiencies recorded	
	d Case Circuit Breaker Type	Does not exist	
Diesel	- VK-	Inspected	
	Instance	Boiler Room	
	Instance Condition	3- Fair	

Building Condition Assessment Survey 2023-2024

icui Inspection		AZUJ
uestion	Response	
EMERGENCY GENERATOR SET		
Diesel		
Instance Quantity Uom	EACH	
Manufacturer	Kohler Power Systems	
EquipmentId	Emergency Generator	
Capacity/Size Quantity	125	
Capacity/Size UOM	kVA	
Capacity/Size 2 Quantity	100	
Capacity/Size 2 UOM	kW	
Capacity/Size 3 Quantity	347	
Capacity/Size 3 UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	1994	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Natural Gas	Does not exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not exist	
EMERGENCY LIGHTING	Inspected	
Battery Pack	Does not exist	
Non Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EXIT LIGHT	Inspected	
	Inspected	
Battery Pack Condition	3- Fair	
Deficiency	No deficiencies recorded	
Non Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EXIT/EMERGENCY LIGHT	Does not exist	
FIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Inspected 3- Fair	
Condition		
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
CO Detector	Does not exist	
Heat Detector	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Elevator Recall	Inspected	

Building Condition Assessment Survey 2023-2024

Electrical Inspection	X209
Question	Response

estion	Response
IRE ALARM SYSTEM	
Elevator Recall	
Deficiency	No deficiencies recorded
Magnetic Door Holder/Contactor	Does not exist
Fused Cutout Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Custodian's Office - Room C16
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Gamewell
Model	IF610
EquipmentId	N/A
Installation Year	2004
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not exist
Sub-Panel	Inspected
Bell At Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Custodian's Office - Room C16
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Gamewell
Model	N/A
EquipmentId	Smoke Purge
Installation Year	1994
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not exist
Remote Annunciator	Inspected
Display Monitor	Does not exist
Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
	Does not exist
Printer	Does not exist Does not exist
Punch Register	Inspected
Sprinkler Flow/Air Pressure Switch Condition	3- Fair
	No deficiencies recorded
Deficiency	
Tamper Flow Switch/Chain	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
ROUNDING SYSTEM	Inspected

Building Condition Assessment Survey 2023-2024

X209

Question	Response	
GROUNDING SYSTEM		
Condition	3- Fair	
Deficiency	No deficiencies recorded	
INTERCOM SYSTEM	Inspected	
Elevator	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Holding Area	Does not exist	
LAN	Inspected	
Local Distribution Frame (I/LDF)	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	

Holding / Hea	Does not time.
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not exist
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Inspected
Instance	Room C18
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Siemens
EquipmentId	MCC-1
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	1994
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
DVIDV VO A DD DVIGO OVIGINA (Y 1

Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	Room 416

Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Dukane 250
Installation Year	1994
Source of Installation Year	Documented
Deficiency	CLOCK NOT OPERATIONAL

Building Condition Assessment Survey 2023-2024

Question	Response
PUBLIC ADDRESS SYSTEM	
Deficiency Location/Instance	Classrooms and Corridors
Deficiency Quantity	15
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
SECURITY	Inspected
IPDVS/CCTV System	Does not exist
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office - Room C16
Instance Condition	2- Between Good and Fair
Instance Quantity	1
	EACH
Instance Quantity Uom	
Model	Vista 128BPT
Installation Year	2019
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	2- Between Good and Fair
	No deficiencies recorded
Deficiency	
Siren/Strobe	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	1- Good
Deficiency	TIME CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Custodian's Office - Room C16
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Violations	No violations recorded
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Location/Instance	Roof, By Exit 3
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 3
Violations	No violations recorded
SERVICE SWITCH	Inspected
Instance	Electrical Room C06
Instance Condition	3- Fair
Instance Quantity	1

Building Condition Assessment Survey 2023-2024

Question	Response
SERVICE SWITCH	
Instance Quantity Uom	EACH
Manufacturer	All City Switchboard
EquipmentId	CON ED Building Disconnect
Capacity/Size Quantity	1600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1994
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	Inspected
Number of Spares	2
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room C06
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	All City Switchboard
EquipmentId	MDB
Capacity/Size Quantity	1600
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	3
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	1994
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not exist