Building Condition Assessment Survey 2023-2024

Electrical Inspection X229

Asset:	P.S. 230/I.S. 229 (UDC) - BRONX, 275 HARLEM RIVER PARK BRIDGE, BRONX, NY, 10453		
Inspection Id	Inspection Type	Time In	Last Edited
855	ELECTRICAL	2023-11-09 07:59AM	2023-12-05 10:26AM
and Data			

<u> Asset</u>	Data	
Q	uestion	

Have any Systems/Major Building Components been upgraded?

Answer Systems: Gymnasium LED Lighting Retrofitted

Years:

Exit Lights (Battery Pack), Emergency Lights (Battery Systems:

> Pack), Multipurpose Room LED Recessed (Retrofitted), Auditorium - House Lighting (LED Surface Mounted and Recessed - Retrofitted), LED Surface and Recessed Hallways and Some Classrooms and Offices (Retrofitted), Cafeterias - LED Lighting

(Retrofitted).

2022 Years:

Systems: Security Lighting 2020, 2010, 2000 Years:

Fire Alarm System, Most Motor Starters Systems:

2019 Years:

Partial Service Switch Systems:

Years:

Computer Lab - Room 144 (Raceway with Receptacles Systems:

2016 Years:

Systems: Elevator (Intercom System)

Years:

Systems: Exit/Emergency Light, Intrusion Alarm System (Panic

Switch, Central Control Panel)

Years: 2014

Telephone System, IPDVS/CCTV System, Lightning Systems:

Protection, Intrusion Alarm System (Remote

Annunciator Panel)

2012 Years:

Systems: Partial Molded Case Circuit Breaker Panel Boards

Years: 2011, 2000

Auditorium (Local Sound System, Theater Lighting Systems:

System)

2008 Years:

Public Address System (Amplifier) Systems:

Years:

Systems: Interior Fluorescent Lighting (Retrofitted)

Years:

Systems: Emergency Light/Exit Light Panel

2000 Years:

Below Ground

Yes

No

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Does Interactive Whiteboard (IWB) Exist?

Water Penetration In Electrical Room?

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in	No
your building?	

Priority Condition

Type of Service

riority co							
Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
Yes	Intercom - Not	Intercom in elevators are	Intercom	Elevator ID:	Michael	Custodian	No Photo Taken
	Operational	out of order.	System -	2P1131 and	Caputo		
			Elevator	2P1130			

Building Condition Assessment Survey 2023-2024

Electrical Inspection X229

Yes Fire Alarm System -Components Not Operational

cannot reach the doors.

Magnetic door contactors Fire Alarm

Corridor by System rooms: 222, Magnetic 231, 338, 440, Michael

Caputo

Custodian

No Photo Taken

444 Door Holder/Contac

ection	
uestion	Response
lectrical	
ATHLETIC FIELD	Does not exist
AUDITORIUM	Inspected
Instance on 2nd Floor	Inspected
House Lighting	
Instance on 2nd Floor	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	
Instance on 2nd Floor	Does not exist
Lighting Fixture - HID	
Instance on 2nd Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 2nd Floor	Does not exist
Lighting Fixture - LED	
Instance on 2nd Floor	Inspected
Pendant Mounted	*
Instance on 2nd Floor	Does not exist
Surface Mounted	
Instance on 2nd Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Local Sound System	The deficiences recorded
Instance on 2nd Floor	Inspected
Instance Condition	3- Fair
Installation Year	2008
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 2nd Floor	Does not exist
Theater Lighting System	
Instance on 2nd Floor	Inspected
Dimming System	
Instance on 2nd Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Theater Lighting	
Instance on 2nd Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
CAFETERIA	Inspected
Instance on 1st Floor, 2nd Floor	Inspected
Lighting	Inspected

Building Condition Assessment Survey 2023-2024

Question	Response	
CAFETERIA		
Lighting		
Lighting Fixture - Fluorescent		
Instance on 1st Floor, 2nd Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor, 2nd Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor, 2nd Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor, 2nd Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor, 2nd Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor, 2nd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor, 2nd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Local Sound System		
Instance on 1st Floor, 2nd Floor	Does not exist	
Projection System		
Instance on 1st Floor, 2nd Floor	Does not exist	
Theater Lighting System		
Instance on 1st Floor, 2nd Floor	Does not exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Inspected	
Pendant Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Does not exist	
Recessed Mounted	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected 2- Between Good and Fair	
Condition		
Deficiency	No deficiencies recorded	

Response Inspected
Inspected
No
Inspected
Inspected
Does not exist
Does not exist
Inspected
3- Fair
LIGHTING FIXTURE BALLAST DEFECTIVE
4
EACH
REPLACE BALLAST
PRIORITY 3
LEVEL 2
No violations recorded
Does not exist
Does not exist
Does not exist
Inspected
2- Between Good and Fair
No deficiencies recorded
Inspected
Inspected
Inspected
Does not exist
Does not exist
Does not exist
Inspected
Inspected
2- Between Good and Fair
No deficiencies recorded
Does not exist
Does not exist
Inspected

Building Condition Assessment Survey 2023-2024

uestion	Response	
GYMNASIUM		
Local Sound System		
Installation Year	1977	
Source of Installation Year	Documented	
Deficiency	AMPLIFIER NOT OPERATIONAL	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE SYSTEM	
Urgency of Action	PRIORITY 2	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Projection System		
Instance on 2nd Floor	Does not exist	
Scoreboard		
Instance on 2nd Floor	Does not exist	
Theater Lighting System		
Instance on 2nd Floor	Does not exist	
KITCHEN	Inspected	
Instance on Ground Floor	Inspected	
Lighting	mspected .	
Instance on Ground Floor	Inspected	
Lighting Fixture - Fluorescent	nispected	
Instance on Ground Floor	Lucrostad	
	Inspected	
Pendant Mounted		
Instance on Ground Floor	Does not exist	
Surface Mounted		
Instance on Ground Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Ground Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on Ground Floor	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Instance on Ground Floor	Description:	
	Does not exist	
Lighting Fixture - LED		
Instance on Ground Floor	Does not exist	
LIBRARY	Inspected	
Instance on Room 324	Inspected	
Lighting		
Instance on Room 324	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 324	Inspected	
Pendant Mounted	1	
Instance on Room 324	Does not exist	
Surface Mounted	2 See Hot Calif	
Instance on Room 324	Inconnected	
	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Room 324	Inspected	
Instance Condition	3- Fair	

Building Condition Assessment Survey 2023-2024

cirical Inspection		ALLY
Question	Response	
LIBRARY		
Lighting		
Lighting Fixture - Fluorescent		
Recessed Mounted		
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on Room 324	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 324	Does not exist	
Lighting Fixture - LED		
Instance on Room 324	Does not exist	
Raceway With Receptacles		
Instance on Room 324	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Room 324	Does not exist	
LOCKER ROOM	Inspected	
Instance on 3rd Floor - Boys	Inaccessible	
Instance on 3rd Floor - Girls	Inaccessible	
MULTIPURPOSE ROOM	Inspected	
Instance on 4th Floor	Inspected	
Lighting	1	
Instance on 4th Floor	Inspected	
Lighting Fixture - Fluorescent	A	
Instance on 4th Floor	Does not exist	
Lighting Fixture - HID		
Instance on 4th Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 4th Floor	Does not exist	
Lighting Fixture - LED		
Instance on 4th Floor	Inspected	
Pendant Mounted	•	
Instance on 4th Floor	Does not exist	
Surface Mounted		
Instance on 4th Floor	Does not exist	
Recessed Mounted		
Instance on 4th Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Local Sound System		
Instance on 4th Floor	Does not exist	
Projection System		
Instance on 4th Floor	Does not exist	
Theater Lighting System		
Instance on 4th Floor	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SWIMMING POOL	Does not exist	
TOILET ROOM - STAFF	Inspected	
Lighting Eightung Elyapagant	Inspected	
Lighting Fixture - Fluorescent	Inspected	

Building Condition Assessment Survey 2023-2024

neui inspection		122)
Question	Response	
TOILET ROOM - STAFF		
Lighting		
Lighting Fixture - Fluorescent		
Pendant Mounted	Does not exist	
Surface Mounted	Does not exist	
Recessed Mounted	Inspected	
Condition	3- Fair	
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE	
Deficiency Quantity	3	
Quantity Uom	EACH	
Potential Action	REPLACE BALLAST	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Does not exist	
Recessed Mounted	Inspected	
Condition	3- Fair	
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE	
Deficiency Quantity	8	
Quantity Uom	EACH	
Potential Action	REPLACE BALLAST	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	
EMERGENCY GENERATOR SET	Does not exist	
	Inspected	
EMERGENCY LIGHT/EXIT LIGHT PANEL	3- Fair	
Condition		
Deficiency	No deficiencies recorded	
EMERGENCY LIGHTING	Inspected	
Battery Pack	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Non Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EXIT LIGHT	Inspected	
Battery Pack	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Non Battery Pack	Does not exist	

Building Condition Assessment Survey 2023-2024

icai inspection	ALL
uestion	Response
EXIT/EMERGENCY LIGHT	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
FIRE ALARM SYSTEM	Inspected
Bell/Horn	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
CO Detector	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Heat Detector	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Elevator Recall	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Magnetic Door Holder/Contactor	Inspected
Condition	2- Between Good and Fair
Deficiency	CONTACTOR NOT OPERATIONAL
Deficiency Location/Instance	Corridor by Rooms: 222, 231, 338, 440, 444
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Fused Cutout Panel	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	2nd Floor by Exit 6
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH

Building Condition Assessment Survey 2023-2024

uestion	Response	
FIRE ALARM SYSTEM		
Main Panel		
Fire Alarm Control Panel (Electronic)		
Manufacturer	Edwards System Technology	
Model	EST3X	
EquipmentId	Fire Alarm Control Panel	
Installation Year	2019	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel	Does not exist	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Punch Register	Does not exist	
Sprinkler Flow/Air Pressure Switch	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Tamper Flow Switch/Chain	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
GROUNDING SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
INTERCOM SYSTEM	Inspected	_
Elevator	Inspected	
Condition	4- Between Fair and Poor	
Deficiency	INTERCOM CABINET NOT OPERATIONAL	
Deficiency Location/Instance	Elevator ID 2P1131 and 2P1130	
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	REPAIR	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Holding Area	Does not exist	-
LAN	Inspected	
Local Distribution Frame (I/LDF)	Inspected	_
Condition	3- Fair	_
Deficiency	No deficiencies recorded	
Main Equipment Rack (MDF)	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	_
LIGHTNING PROTECTION	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
MOTOR CONTROLLER	Inspected	
MOTOR CONTROL CENTER	Inspected	
Instance	Boiler Room	

Building Condition Assessment Survey 2023-2024

Duestion	Response
MOTOR CONTROLLER	
MOTOR CONTROLLER MOTOR CONTROL CENTER	
Instance Condition	3- Fair
	1
Instance Quantity	EACH
Instance Quantity Uom	
Manufacturer	Federal Pacific Electric
EquipmentId	N/A
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Capacity/Size 2 Quantity	3
Capacity/Size 2 UOM	Section(s) Switchboard Mains Size
Source of Capacity/Size Installation Year	1977
Installation Year Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance Deficiency Quantity	Boiler Room
	1 EACH
Quantity Uom	
Potential Action	REPLACE
Urgency of Action	PRIORITY 1 LEVEL 2
Purpose of Action	
Violations	No violations recorded
Instance	Room G31
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Federal Pacific Electric
EquipmentId	N/A
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Inspector Estimate
Installation Year	1977
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Room G31
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
MOTOR STARTER/CONTACTOR	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not exist
PANEL BOARD	Inspected
	<u> </u>
Fused Disconnect Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Rooms G02 and G18, Boiler Room
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
	DDIODITY 1

PRIORITY 1

Urgency of Action

uestion	Response
PANEL BOARD	
Fused Disconnect Switch Type	
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	39
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	Room 345
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	N/A
	1977
Installation Year Source of Installation Year	Documented
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Throughout the Building
Deficiency Execution Instance Deficiency Quantity	26
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Room 345
Deficiency Quantity	155,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action Purpose of Action	PRIORITY 1 LEVEL 2
Violations	No violations recorded
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Condition	2- Between Good and Fair
Installation Year	2012 Decemented
Source of Installation Year	Documented
Deficiency	No deficiencies recorded Inspected

Building Condition Assessment Survey 2023-2024

ineui Inspection		ALLI
Question	Response	
SECURITY		
Intrusion Alarm System		
Central Control Panel	Inspected	
Instance	Custodian's Office - Room 246	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Vista 128BPT	
Installation Year	2014	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Infrared Sensor	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Panic Switch	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Remote Annunciator	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Siren/Strobe	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting - Security	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
SERVICE SWITCH	Inspected	
Instance	Electrical Room	
Instance Condition	3- Fair	
Instance Condition Instance Quantity	1	
Instance Quantity Uom	EACH	
	Federal Pacific Electric	
Manufacturer EquipmentId	DP-A	
Equipmentid Capacity/Size Quantity	1600	
Capacity/Size Quantity Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	1977	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	Electrical Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Federal Pacific Electric	
EquipmentId	PDP 1&2, PDP AC1, PDP AC2 (Via XFMR)	
Capacity/Size Quantity	3000	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	

Building Condition Assessment Survey 2023-2024

n	Response	
TICE SWITCH		
Installation Year	1977	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	Electrical Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Federal Electric Panel	
EquipmentId	PDP-3	
Capacity/Size Quantity	1600	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	1977	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	Electrical Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
	Federal Pacific Electric	
Manufacturer		
EquipmentId Capacity/Size Quantity	SBAC	
Capacity/Size Quantity Capacity/Size UOM	4000 Amps	
Capacity/Size OOM Source of Capacity/Size	Amps Nameplate	
Installation Year	1977	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room	
Deficiency Quantity	l l	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
	Electrical Room	
Instance Instance Condition	3- Fair	
Instance Quantity	1 FACH	
Instance Quantity Uom	EACH	
Manufacturer	Federal Pacific Electric	
EquipmentId	Service Switch 2 Fire Pump	

Electrical Inspection	X229

Question	Response
SERVICE SWITCH	
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1977
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
SWITCHBOARD	Inspected
Number of Spares	0
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
<u>-</u>	EACH
Instance Quantity Uom	
Manufacturer	Federal Pacific Electric
EquipmentId	N/A
Capacity/Size Quantity	1600
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	•
Capacity/Size 2 UOM Source of Capacity/Size	Section(s) Nameplate
Installation Year	1977
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Deficiency Location/Instance	Electrical Room
Deficiency Quantity	
	1 FACH
Quantity Uom Potential Action	EACH REPLACE
Urgency of Action Purpose of Action	PRIORITY 1 LEVEL 2
Violations	No violations recorded
Instance	Electrical Room G02
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Federal Pacific Electric
EquipmentId	PNL PDP-1
Capacity/Size Quantity	800
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	1977
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room G02
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2

Duestion	Response
	response
SWITCHBOARD	
Fused Disconnect Switch Type	N 112 11
Violations	No violations recorded
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Federal Pacific Electric
EquipmentId	PDP-3
Capacity/Size Quantity	1600
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	3
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	1977
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Room G18
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
	Federal Pacific Electric
Manufacturer	
EquipmentId Capacity/Size Quantity	PNL PDP-2 3000
Capacity/Size Quantity Capacity/Size UOM	
Capacity/Size 2 Quantity	Amps Total 2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	1977
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Room G18
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
•	
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	4- Between Fair and Poor
Deficiency	TELEPHONE NOT OPERATIONAL
Deficiency Location/Instance	Classrooms
Deficiency Quantity	14
Quantity Uom	EACH
~ *	
Potential Action	REPLACE TELEPHONE

Electrical Inspection	X229

тсан інѕресион	XZ
Question	Response
TELEPHONE SYSTEM	
PBX/Intercom	
Purpose of Action	LEVEL 2
Violations	No violations recorded
Standard	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Inspected
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Federal Pacific
EquipmentId	N/A
Capacity/Size Quantity	1000
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	1977
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Room G02
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Federal Pacific
EquipmentId	N/A
Capacity/Size Quantity	300
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	1977
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Room G02
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Room G18
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Federal Pacific
EquipmentId	N/A
Capacity/Size Quantity	750
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	1977

Building Condition Assessment Survey 2023-2024

Question	Response	
TRANSFORMER		
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Room G18	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	