#### **Building Condition Assessment Survey 2023-2024**

Mechanical Inspection X229

Asset:	P.S. 230/I.S. 229 (UDC) - BRONX, 275 HARLEM RIV	ER PARK BRIDGE,	BRONX, NY, 10453	
Inspection Id	Inspection Type		Time In	Last Edited
871	MECHANICAL		2023-11-09 07:15PM	2024-06-10 11:12AM
set Data				
Question		Answer		
Have any Systems/Major Building Components been upgraded?		Systems:	Electric Domestic Water Heaters Remote Storage Tank	; Domestic Hot Water
		Years:	2021	
		Systems:	Climate Control System - Electr Service: Backflow Preventer (sp	•
		Years:	2019	
		Systems:	Sprinkler Heads; Sprinkler Pipin	ıg (~80%)
		Years:	2018	
		Systems:	MDF Room - Dedicated A/C Eq System)	uipment (DX Split
		Years:	2016	
		Systems:	Fire Booster Pump Assembly	
		Years:	2015	
		Systems:	Kitchen - Grease Trap	

2013

Years:

Are there fuel tanks? Yes

Total # of above ground tanks

Total capacity of all above ground tanks in gal.

15,000

Total # of below ground tanks 0
Total capacity of all below ground tanks in gal. 0
Total # of water main service entries to the asset 3

MERs/Fan Rooms Locations

Fire Booster Pump Room G32, 2nd Floor Hydronic Heating Hot Water Heat Exchanger Room; MERs G18, 103, 117, 159,
203, 215, 241, 303, 317, 341, 349, 403, 415, 445, 457

Are there any spaces with Missing or Defective CO Detectors?

No
Are there any Painted/Obstructed Sprinkler Heads?

No

Are there any Emergency Stop Switches with Missing Hammers? No components

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
Yes	Defective Boiler Safety Auxiliary	(6)	Boiler Safety Valve	Boiler Room @ Boilers #1, #2, #3	Jhanu Balkarran	Fireman	No Photo Taken
Yes	Other	Defective System	Refrigerant Leak Detection System	Boiler Room	Jhanu Balkarran	Fireman	CHILIGARD RI
Yes	Defective Boiler Safety Auxiliary	Boiler #2: Pump Control/Low Water Cut-off Combination piping leaking. Boiler #3: Defective Pump Control/Low Water Cut-off Combination	Steam Boiler	Boiler Room / Boilers #2, #3	Jhanu Balkavran	Fireman	
Yes	Defective Sprinkler/Standpipe System	Missing Valves handles (5)	Hose Valve Assembly	Stairs "A/G", "A/2", "A/1" "E2", "A/3"	Jhanu Balkavran	Fireman	A STANDING

## **Building Condition Assessment Survey 2023-2024**

nunteur Inspection		
pection		
Question	Response	
Mechanical	•	
AIR CONDITIONING	Inspected	
Chilled Water System	Inspected	
Absorption Chiller	Does not exist	
Air Cooled Chiller	Does not exist	
Air Cooled Condenser	Does not exist	
Chilled Water Distribution: Piping, Pumps and Auxiliaries	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Backflow Preventer	Does not exist	
Central Station Air Handler	Inspected	
Instance	MER G18	
Instance Condition	3- Fair	
Instance Condition  Instance Quantity		
	1 EACH	
Instance Quantity Uom		
Manufacturer	York	
EquipmentId	AHU-1	
Capacity/Size Quantity	10	
Capacity/Size UOM Source of Capacity/Size	Fan Motor HP Documented	
Installation Year	1977	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	MER 103	
Instance Condition	3- Fair	
Instance Quantity		
	1 EACH	
Instance Quantity Uom	York	
Manufacturer	AHU-2	
EquipmentId Capacity/Size Quantity	10	
Capacity/Size Quantity  Capacity/Size UOM	Fan Motor HP	
Source of Capacity/Size	Documented	
Installation Year	1977	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	MER 117	
Instance Condition	3- Fair	
Instance Quantity	1	-
Instance Quantity Uom	EACH	
Manufacturer	York	
	AHU-3	
EquipmentId Capacity/Size Quantity	20	
Capacity/Size Quantity  Capacity/Size UOM	Fan Motor HP	
Source of Capacity/Size	Inspector Estimate	
Installation Year	1977	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	MER 159	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
	York	
Manufacturer EquipmentId	AHU-4	
Equipmentia	Allo-T	

#### **Building Condition Assessment Survey 2023-2024**

unical Inspection	n
estion	Response
AIR CONDITIONING	
Chilled Water System	
Central Station Air Handler	
Capacity/Size UOM	Fan Motor HP
Source of Capacity/Size	Inspector Estimate 1977
Installation Year Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance Instance Condition	MER 203 3- Fair
Instance Quantity	1 FACIL
Instance Quantity Uom	EACH
Manufacturer	York
EquipmentId	AHU-5
Capacity/Size Quantity	15
Capacity/Size UOM	Fan Motor HP
Source of Capacity/Size	Inspector Estimate 1977
Installation Year Source of Installation Year	Documented
Deficiency	DEFECTIVE MOISTURE DRAINAGE (BASIN & TUBING)
Deficiency Location/Instance	MER 203
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	MER 215
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
	York
Manufacturer	AHU
EquipmentId Capacity/Size Quantity	10
Capacity/Size Quantity Capacity/Size UOM	Fan Motor HP
Source of Capacity/Size	Inspector Estimate
Installation Year	1977
Source of Installation Year	Documented
Deficiency	DEFECTIVE MOISTURE DRAINAGE (BASIN & TUBING)
Deficiency Location/Instance	MER 215
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	MER 241
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	York
EquipmentId	AHU-7
Capacity/Size Quantity	25
Capacity/Size Quantity  Capacity/Size UOM	Fan Motor HP
Source of Capacity/Size	Documented
	1077

Installation Year

1977

## **Building Condition Assessment Survey 2023-2024**

Question	Response	
AIR CONDITIONING	Короня	
Chilled Water System Central Station Air Handler		
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	MER 303	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	York	
EquipmentId	AHU-8	
Capacity/Size Quantity	20	
Capacity/Size UOM	Fan Motor HP	
Source of Capacity/Size	Documented	
Installation Year	1977	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	MER 317	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	York	
EquipmentId	AHU-9	
Capacity/Size Quantity	20	
Capacity/Size UOM	Fan Motor HP	
Source of Capacity/Size	Inspector Estimate	
Installation Year	1977	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	MER 341	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	York	
EquipmentId	AHU-10	
Capacity/Size Quantity	15	
Capacity/Size UOM	Fan Motor HP	
Source of Capacity/Size	Documented	
Installation Year	1977	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	MER 403	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	York	
EquipmentId	AHU-11	
Capacity/Size Quantity	15	
Capacity/Size UOM	Fan Motor HP	
Source of Capacity/Size	Documented	
Installation Year	1977	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	MER 415	

Instance Quantity

Response	
•	
EACH	
York	
20	
Fan Motor HP	
Documented	
1977	
Documented	
No deficiencies recorded	
MER 445	
3- Fair	
1	
EACH	
York	
AHU-13	
15	
Fan Motor HP	
Documented	
1977	
Documented	
No deficiencies recorded	
MER 457	
3- Fair	
1	
EACH	
York	
AHU-14	
15	
Fan Motor HP	
Documented	
<del>_</del>	
2- Between Good and Fair	
1	
EACH	
Trane	
Chiller #1	
Tons	
D 1 D	
Boiler Room  2- Between Good and Fair	
	EACH York AHU-12 20 Fan Motor HP Documented 1977 Documented No deficiencies recorded MER 445 3- Fair 1 EACH York AHU-13 15 Fan Motor HP Documented 1977 Documented No deficiencies recorded MER 457 3- Fair 1 EACH York AHU-13 15 Fan Motor HP Documented No deficiencies recorded MER 457 3- Fair 1 EACH York AHU-14 15 Fan Motor HP Documented 1977 Documented No deficiencies recorded Does not exist Inspected Boiler Room 2- Between Good and Fair 1 EACH Trane Chiller #1 360 Tons Inspector Estimate 1977 Documented R-11 No deficiencies recorded

Mechanical Inspection	X229
Question	Response

Question	Response
AIR CONDITIONING	
Chilled Water System	
Water Cooled Chiller	
Instance Quantity Uom	EACH
Manufacturer	Trane
EquipmentId	Chiller #2
Capacity/Size Quantity	360
Capacity/Size UOM	Tons
Source of Capacity/Size	Inspector Estimate
Installation Year	1977
Source of Installation Year	Documented
Refrigerant Type	R-11
Deficiency	No deficiencies recorded
Condenser Water Distribution: Piping, Pumps and Auxiliaries	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Cooling Coil in Ductwork	Does not exist
Cooling Tower	Inspected
Instance	4th Floor Roof
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Baltimore Air Coil (BAC)
EquipmentId	N/A
Capacity/Size Quantity	360
Capacity/Size UOM	Tons
Source of Capacity/Size	Inspector Estimate
Installation Year	2006
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Instance	4th Floor Roof
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Baltimore Air Coil (BAC)
EquipmentId	N/A
Capacity/Size Quantity	360
Capacity/Size UOM	Tons
Source of Capacity/Size	Inspector Estimate
Installation Year	2006
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
DX Split System	Inspected
Indoor Unit	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Outdoor Unit	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Dry Cooler	Does not exist
Packaged / Rooftop Unit	Does not exist
Packaged Terminal A/C	Does not exist
Refrigerant Leak Detection System	Inspected
Condition Condition	4- Between Fair and Poor
Deficiency	DEFECTIVE SYSTEM
Deficiency Location/Instance	Boiler Room

Mechanical Inspection	X229

Question	Response
AIR CONDITIONING	
Refrigerant Leak Detection System	
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Refrigerant Piping	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Return Fan	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
CENTRAL ACID WASTE NEUTRALIZING TANK	Does not exist
CLIMATE CONTROL SYSTEM	Inspected
BMS	Does not exist
Pneumat <u>ic System</u>	Inspected
Instance	Throughout
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Building Area Covered by Operational System	81-100%
Deficiency	DEFECTIVE DAMPER ACTUATOR
Deficiency Location/Instance	MER 117 @ AHU-3
Deficiency Quantity	1
Quantity Uom	EACH MAINTENANCE
Potential Action Urgency of Action	MAINTENANCE PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Hybrid System	Does not exist
Electric System	Inspected
Instance	Throughout (Heat Timer)
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Building Area Covered by Operational System	81-100%
Deficiency	No deficiencies recorded
COMPACTOR	Does not exist
CONVEYING	Inspected
Dumbwaiter	Does not exist
Elevator	Inspected
Condition	2- Between Good and Fair
Are all the existing elevators operable?	Yes
Deficiency	No deficiencies recorded
Escalator	Does not exist
Non-auditorium Handicap Lift - Vertical	Does not exist
Non-auditorium Handicap Lift - Stair	Does not exist
Ash Hoist	Does not exist
Sidewalk Elevator	Does not exist
DOMESTIC WATER SYSTEM	Inspected
Domestic Cold Water System	Inspected
Gravity System	Does not exist
Pressure Booster System	Inspected

#### **Building Condition Assessment Survey 2023-2024**

Question	Response	
DOMESTIC WATER SYSTEM		
Domestic Cold Water System		
Pressure Booster System		
Electric Pressure Booster System	Inspected	
Instance	Boiler Rooms	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	

Manufacturer	Systecon
EquipmentId	N/A
Capacity/Size Quantity	2
Capacity/Size UOM	Total # Pumps
Capacity/Size 2 Quantity	30

**Mechanical Inspection** 

Source of Installation Year

Capacity/Size 2 UOM Total Pumps HP
Source of Capacity/Size Documented
Installation Year 2011

Deficiency No deficiencies recorded

Hydraulic/Pneumatic Booster System Does not exist

Water Service	Inspected
Instance	Sprinkler/Domestic/Gas Meter Room G35
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH

Instance Quantity Uom

Deficiency

No deficiencies recorded

Instance

Sprinkler/Domestic/Gas Meter Room G35, Water Service Room inside Room 143

Instance Condition

3- Fair

Documented

 Instance Quantity
 2

 Instance Quantity Uom
 EACH

 Deficiency
 WATER MAIN:MISSING BACKFLOW PREVENTION

DEVICE

Deficiency Location/Instance

Sprinkler/Domestic/Gas Meter Room G35, Water Service Room inside Room 143

Deficiency Quantity 2
Quantity Uom EACH
Potential Action INSTALL
Urgency of Action PRIORITY 3
Purpose of Action LEVEL 2
Violations No violations recorded

 Domestic Hot Water System
 Inspected

 Domestic Hot Water Remote Storage Tank
 Inspected

 Condition
 1- Good

 Deficiency
 No deficiencies recorded

 Domestic Water Heat Exchanger
 Does not exist

 Electric Domestic Water Heater
 Inspected

 Condition
 1- Good

 Deficiency
 No deficiencies recorded

Gas Fired Domestic Water HeaterDoes not existOil Fired Domestic Water HeaterDoes not existHeat Pump Domestic Water HeaterDoes not exist

 Domestic Water Distribution Piping
 Inspected

 Condition
 3- Fair

 Deficiency
 No deficiencies recorded

DRAIN/WASTE/VENT AND STORM SYSTEM

BCAS Partners Version 2.0 (P) Page 8 of 15 Print Date: 8/8/2024

Inspected

X229

## **Building Condition Assessment Survey 2023-2024**

nunicui inspecuon		ALLY
Question	Response	
DRAIN/WASTE/VENT AND STORM SYSTEM		
Interior Storm Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Sewage/Waste/Vent Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Sewage Ejector Pump	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Sump Pump	Does not exist	
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist	
FIXTURES	Inspected	
Staff And Other	Inspected	
Janitor Sink	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lavatory/Sink	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Toilet	Inspected	
Condition	3- Fair	
	DEFECTIVE FLUSHOMETER VALVE	
Deficiency Deficiency Location/Instance	Staff Toilet Room 342	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Urinal	Inspected	
Condition	3- Fair	
	No deficiencies recorded	
Deficiency		
Student  Deigling Foundair	Inspected Inspected	
Drinking Fountain		
Condition	3- Fair	
Deficiency	CLOGGED/LEAKING	
Deficiency Location/Instance Deficiency Quantity	Corridor near Room 218, Stair "D/2"	
	2	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action Violations	LEVEL 2  No violations recorded	
Lavatory/Sink	Inspected	
Condition	2- Between Good and Fair	
Deficiency	CRACKED/PHYSICAL DAMAGE	
Deficiency Location/Instance	Girl's Toilet Room 173, 205	
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Locker Room Shower	Inspected	

## **Building Condition Assessment Survey 2023-2024**

inicui Inspection		
nestion	Response	
FIXTURES		
Student		
Locker Room Shower		
Instance on 3rd Floor - Boys	Inaccessible	
Instance on 3rd Floor - Girls	Inaccessible	
Sink And Fountain Combo Unit	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Toilet	Inspected	
Condition	2- Between Good and Fair	
Deficiency	DEFECTIVE FLUSHOMETER VALVE	
Deficiency Location/Instance	Girl's Toilet Room 447	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
	Inspected	
Urinal	•	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
GAS FIRED FURNACE	Does not exist	
GAS SERVICE	Inspected	
Gas Distribution Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Gas Meter Room Exhaust Fan	Does not exist	
Gas Meter Room Vent	Does not exist	
Gas Pressure Booster	Does not exist	
CO/Gas Leak Detection	Does not exist	
HEATING	Inspected	
	Does not exist	
Heating Coil In Ductwork Hydronic Heating	Inspected	
•	Inspected	
Hydronic Hot Water Distribution: Piping, Pumps and Auxiliaries		
Condition	3- Fair	
Deficiency	PIPING:DAMAGED/MISSING INSULATION	
Deficiency Location/Instance	MERs G18, 215, 203, 403	
Deficiency Quantity	60	
Quantity Uom	L.F.	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Backflow Preventer	Does not exist	
Hot Water Heat Exchanger	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Radiator/Convector/Fin Tube	Does not exist	
Steam Heating	Inspected	
F&T/Steam Drip Trap	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
MER Steam and Condensate Piping	Inspected	

Mechanical Inspection	X229	!

*		
estion	Response	
EATING		
Steam Heating		
MER Steam and Condensate Piping		
Deficiency	No deficiencies recorded	
Steam Condensate Return Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Steam Condensate Return Pumping System	Does not exist	
Steam Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Terminal Unit Thermostatic Trap	Does not exist	
Steam supplied by External Sources	Does not exist	
Unit Heater/Cabinet Heater	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
EATING PLANT	Inspected	
Instance on Ground Floor	Inspected	
Is there a water meter on the boiler make-up water piping?	Yes	
Observed Operational?	Yes	
Burner Manufacturer	Profire (Cleaver Brooks)	
Burner Model	4WI-101-125-015ST	
Burner Type	Oil	
Heating Plant Oil Number	2	
Boiler Auxiliaries		
Instance on Ground Floor	Inspected	
Boiler Auxiliary Piping		
Instance on Ground Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Boiler Emergency Stop Switch		
Instance on Ground Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Boiler Feedwater System		
Instance on Ground Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
<b>Boiler Feedwater Treatment(Automatic)</b>		
Instance on Ground Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Boiler Flue Exhaust		
Instance on Ground Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Boiler Make-up Water Backflow Preventer		
Instance on Ground Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Boiler Room Steam And Condensate Piping		
Instance on Ground Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	

Mechanical Inspection	X229
	_

Question	Response
HEATING PLANT	
Boiler Auxiliaries	
Boiler Safety Valve	
Instance on Ground Floor	Inspected
Instance Condition	5- Poor
Deficiency	DEFECTIVE
Deficiency Location/Instance	Boiler Room @ Boilers #1, #2, #3
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Boiler System	
Instance on Ground Floor	Inspected
Coal-fired Boiler	
Instance on Ground Floor	Does not exist
Hot Water Boiler	
Instance on Ground Floor	Does not exist
Modular Boiler	
Instance on Ground Floor	Does not exist
Steam Boiler	
Instance on Ground Floor	Inspected
Instance on Ground Floor	Inspected
Instance	Boiler Room
Instance Condition	2- Between Good and Fair
Instance Quantity	3,130
	MBH NET
Instance Quantity Uom  Cast Iron Boiler?	No
Manufacturer	Cleaver Brooks
EquipmentId	96061-1
Capacity/Size Quantity	36
Capacity/Size UOM	Burner GPH
Source of Capacity/Size	Documented
Installation Year	2012
Source of Installation Year	Documented
Deficiency	LEAKY/PLUGGED TUBES
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Boiler Room
Instance Condition	2- Between Good and Fair
Instance Quantity	3,130
Instance Quantity Uom	MBH NET
Cast Iron Boiler?	No
Manufacturer	Cleaver Brooks
EquipmentId	96061-2
Capacity/Size Quantity	36
Capacity/Size UOM	Burner GPH
Source of Capacity/Size	Documented
Installation Year	2012
Source of Installation Year	Documented

#### **Building Condition Assessment Survey 2023-2024**

uestion	Response
HEATING PLANT	
Boiler System	
Steam Boiler	
Deficiency	DEFECTIVE SAFETY AUXILIARY: LOW-WATER CUT-OFF, WATER COLUMN ASSEMBLY
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Instance	Boiler Room
Instance Condition	2- Between Good and Fair
Instance Quantity	3,130
Instance Quantity Uom	MBH NET
Cast Iron Boiler?	No
Manufacturer	Cleaver Brooks
EquipmentId	96061-03
Capacity/Size Quantity	36
Capacity/Size UOM	Burner GPH
Source of Capacity/Size	Documented
Installation Year	2012
Source of Installation Year	Documented
Deficiency	DEFECTIVE SAFETY AUXILIARY: LOW-WATER CUT-OFF, WATER COLUMN ASSEMBLY
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Fuel System	
Instance on Ground Floor	Inspected
Boiler Fresh Air Louver/Damper	
Instance on Ground Floor	Inspected
Instance Condition	2- Between Good and Fair
Туре	Automatic
Deficiency	No deficiencies recorded
Burner/Burner Control Panel	
Instance on Ground Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fuel Oil Storage/Supply System	
Instance on Ground Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
•	

BCAS Partners Version 2.0 (P)	Page 13 of 15	Print Date: 8/8/2024
-------------------------------	---------------	----------------------

Does not exist

Inspected

Inspected

Inspected

4- Between Fair and Poor

DOES NOT EXIST

Gas Trains And Vent At The Boiler
Instance on Ground Floor

Cafeteria - Room 414A

Cafeteria - Room 414A

Instance Condition
Deficiency

Instance on 1st Floor Cafeteria - Room 116A; Room 160; 4th Floor

Instance on 1st Floor Cafeteria - Room 116A; Room 160; 4th Floor

**Enclosed IDF Room** 

Dedicated A/C Equipment

## **Building Condition Assessment Survey 2023-2024**

iunicui Inspection	ALL)
Question	Response
Enclosed IDF Room	
Dedicated A/C Equipment	
Deficiency Location/Instance	1st Floor Cafeteria - Room 116A; Room 160; 4th Floor Cafeteria - Room 414A
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	INSTALL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
KITCHEN	Inspected
Instance on Ground Floor	Inspected
CO Detector	шерене
Instance on Ground Floor	Not required
Gas System	1.00.104
Instance on Ground Floor	Does not exist
Grease Trap	Does not exist
Instance on Ground Floor	Inspected
Instance Condition	2- Between Good and Fair
	No deficiencies recorded
Deficiency	No deficiencies recorded
Hood	Description of the second seco
Instance on Ground Floor	Does not exist
Hood Exhaust Ductwork	
Instance on Ground Floor	Does not exist
Hood Exhaust Fan	
Instance on Ground Floor	Does not exist
Hood Fire Suppression System	
Instance on Ground Floor	Does not exist
Hot Water Temperature Booster	
Instance on Ground Floor	Does not exist
Kitchen Sink	
Instance on Ground Floor	Inspected
Instance Condition	3- Fair
Deficiency	Missing Air Gap
Deficiency Location/Instance	Kitchen
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 4
Violations	SF93169
MDF Room	Inspected
Instance on Room 345A	Inspected
Dedicated A/C Equipment	
Instance on Room 345A	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Does not exist
SCIENCE PREP ROOM	Does not exist
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected
Dry Sprinkler Alarm Valve Assembly	Does not exist
Wet Sprinkler Alarm Valve Assembly	Does not exist
Fire Booster Pump Assembly	Inspected
Condition	2- Between Good and Fair

## **Building Condition Assessment Survey 2023-2024**

		ALL,
estion	Response	
SPRINKLERS, STANDPIPE, FIRE SYSTEM		
Fire Booster Pump Assembly		
Deficiency	No deficiencies recorded	
Roof Tank	Does not exist	
Siamese Connection	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Sprinkler Head	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Sprinkler Piping	Inspected	
Condition	1- Good	-
Deficiency	No deficiencies recorded	
Standpipe System	Inspected	
Hose Valve Assembly	Inspected	
Condition	3- Fair	
Deficiency	DEFECTIVE VALVE	
Deficiency Location/Instance	Stairs "A/G", "A/2", "A/1" "E2", "A/3"	
Deficiency Quantity	5	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Deficiency	DEFECTIVE FIRE HOSE CABINET	
Deficiency Location/Instance	Stairs "A/1", A/2", "C/3, "D/3" and other locations	
Deficiency Quantity	8	
Quantity Uom	EACH	
Potential Action	REPAIR	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Piping	Inspected	_
Condition	3- Fair	
Deficiency	No deficiencies recorded	
<u>-</u>	Does not exist	
Water Gong	Does not exist	
WIMMING POOL		
TENTILATION	Inspected	
Is the building Mechanically ventilated?	Yes	
Exhaust Fan	Inspected	
Condition	2- Between Good and Fair	
Approximate Total # of Fans	1-25	
Deficiency	No deficiencies recorded	
Heating And Ventilating Unit	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Metal Ductwork	Inspected	
Condition	3- Fair	
Are there any uninsulated ductwork by design in Mechanical rooms?	No	
Are there chain operated dampers?	No	
Deficiency	No deficiencies recorded	
Supply Fan Unit Ventilator	Does not exist  Does not exist	