Building Condition Assessment Survey 2023-2024

Asset:	P.S. 236 ANN	EX (P173 ECC) - BRONX, 499	EAST 175 STI	REET, BRONX,	NY, 10457	
Inspection	Id Inspection Type	e			Time In	Last Edited
	4379 MECHANICAI				2024-04-01 09:40AM	2024-04-11 08:31AN
sset Data						
Question				Answer		
Have any	Systems/Major Buildir	ng Components been upgraded?		Systems:	MDF Room - Dedicated A/C E	quipment (DX Split
•					System)	
				Years:	2013	
	fuel tanks?			No		
	water main service en	tries to the asset		1		
	n Rooms Locations			MER 111		
	any spaces with Missii any Painted/Obstructed	ng or Defective CO Detectors?		No No		
		witches with Missing Hammers?		No compo	onents	
		whenes with missing Hammers.		140 compe	monts	
riority Col		~				
Exist Last Year?	Priority	Condition	Component Affected	Location Description		Photo
	Category	Description	Affected	Description	Notified Title	Image
No conditi	ion recorded					
nspection						
Question				Response		
Mechanic	al					
AIR CO	ONDITIONING			Inspected		
Chille	d Water System			Does not	exist	
Conde	enser Water Distribut	ion: Piping, Pumps and Auxiliaries	5	Does not	exist	
Coolir	ng Coil in Ductwork			Does not	exist	
Coolir	ng Tower			Does not	exist	
DX SI	DX Split System			Inspected		
	oor Unit			Inspected		
Co	ondition			3- Fair		
	Deficiency				encies recorded	
	door Unit			Inspected		
Co	ondition				en Fair and Poor	
	Deficiency			UP TO 5 TONS:DEFECTIVE		
	Deficiency Locat			MER 111		
	Deficiency Quan	tity		1		
	Quantity Uom Potential Action			EACH REPAIR		
	Urgency of Actio	n		PRIORIT	Y 3	
	Purpose of Action			LEVEL 2		
	Violations				ions recorded	
Dry C	ooler			Does not	exist	
	ged / Rooftop Unit			Inspected		
	Instance			Roof		
	Instance Condition			4- Betwee	en Fair and Poor	
	Instance Quantity			1		
	Instance Quantity U	Jom		EACH		
	Manufacturer			Rheem		
	EquipmentId			N/A		
	Capacity/Size Quar	ntity		13		
	Capacity/Size UOM			Tons		
	Source of Capacity	/Size		Inspector	Estimate	
	Installation Year			2005		
	Source of Installation	on Year		Inspector	Estimate	
	Source of Heating Refrigerant Type			N/A		

Building Condition Assessment Survey 2023-2024

	1120
Response	
UP TO 20 TONS:DEFECTIVE CONTROLS	
Roof	
1	
EACH	
REPLACE	
PRIORITY 3	
LEVEL 2	
No violations recorded	
Inspected	
3- Fair	
DEFECTIVE	
Does not exist	
Inspected	
Inspected	
Throughout	
5- Poor	
1	
EACH	
0-20%	
*	
•	
Does not exist	
Inspected	
Inspected	
Does not exist	
Does not exist Does not exist	
Does not exist	
	UP TO 20 TONS:DEFECTIVE CONTROLS Roof 1 EACH REPLACE PRIORITY 3 LEVEL 2 No violations recorded Inspected 3- Fair DEFECTIVE Rooms 108, 109, 116 (3 of 8) 3 EACH REPAIR PRIORITY 3 LEVEL 2 No violations recorded Does not exist Inspected 3- Fair No deficiencies recorded Does not exist Inspected Inspected Inspected Inspected Inspected Throughout 5- Poor 1 EACH 0-20% 2000 Inspector Estimate DEFECTIVE SYSTEM Throughout 1 EACH REPLACE PRIORITY 3 LEVEL 2 No violations recorded Does not exist

Building Condition Assessment Survey 2023-2024

tanical Inspection	X23
Question	Response
DOMESTIC WATER SYSTEM	
Domestic Cold Water System	
Water Service	
Instance Quantity	1
Instance Quantity Uom	EACH
Deficiency	WATER MAIN:MISSING BACKFLOW PREVENTION
	DEVICE
Deficiency Location/Instance	Water Heater/Meter Room 115
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action Urgency of Action	INSTALL PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Domestic Hot Water System	Inspected
Domestic Hot Water System Domestic Hot Water Remote Storage Tank	Does not exist
Domestic Water Heat Exchanger	Does not exist
Electric Domestic Water Heater	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
	Does not exist
Gas Fired Domestic Water Heater	Does not exist Does not exist
Oil Fired Domestic Water Heater	Does not exist
Heat Pump Domestic Water Heater	
Domestic Water Distribution Piping	Inspected 3- Fair
Condition	No deficiencies recorded
Deficiency	
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected
Interior Storm Piping	Inspected 3- Fair
Condition	
Deficiency	No deficiencies recorded
Sewage/Waste/Vent Piping	Inspected 3- Fair
Condition	
Deficiency	No deficiencies recorded
Sewage Ejector Pump	Does not exist
Sump Pump	Does not exist
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist
FIXTURES	Inspected
Staff And Other	Inspected
Janitor Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Urinal	Does not exist
Student	Inspected
Drinking Fountain	Does not exist
Lavatory/Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Locker Room Shower	Does not exist

Building Condition Assessment Survey 2023-2024

anical inspection		X236
uestion	Response	
FIXTURES		
Student		
Sink And Fountain Combo Unit	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Toilet	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Urinal	Does not exist	
GAS FIRED FURNACE	Does not exist	
GAS SERVICE	Does not exist	
HEATING	Inspected	
Heating Coil In Ductwork	Inspected 3- Fair	
Condition	No deficiencies recorded	
Deficiency	Does not exist	
Hydronic Heating Radiator/Convector/Fin Tube	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
	Does not exist	
Steam Heating Steam supplied by External Sources	Does not exist Does not exist	
Unit Heater/Cabinet Heater	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
·		
HEATING PLANT	Does not exist	
Enclosed IDF Room	Does not exist	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
CO Detector		
Instance on 1st Floor	Not required	
Gas System		
Instance on 1st Floor	Does not exist	
Grease Trap		
Instance on 1st Floor	Does not exist	
Hood		
Instance on 1st Floor	Does not exist	
Hood Exhaust Ductwork		
Instance on 1st Floor	Does not exist	
Hood Exhaust Fan		
Instance on 1st Floor	Does not exist	
Hood Fire Suppression System	December 11	
Instance on 1st Floor	Does not exist	
Hot Water Temperature Booster	December 11 to 12	
Instance on 1st Floor	Does not exist	
Kitchen Sink		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	MISSING INDIRECT WASTE	
Deficiency Location/Instance	Kitchen	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	INSTALL	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	

Building Condition Assessment Survey 2023-2024

uestion	Response		
KITCHEN			
Kitchen Sink			
Violations	No violations recorded		
MDF Room	Inspected		
Instance on Room 110	Inspected		
Dedicated A/C Equipment			
Instance on Room 110	Inspected		
Instance Condition	2- Between Good and Fair		
Deficiency	No deficiencies recorded		
SCIENCE DEMO ROOM	Does not exist		
SCIENCE LAB	Does not exist		
SCIENCE PREP ROOM	Does not exist		
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Does not exist		
SWIMMING POOL	Does not exist		
VENTILATION	Inspected		
Is the building Mechanically ventilated?	Partial		
Exhaust Fan	Inspected		
Condition	3- Fair		
Approximate Total # of Fans	1-25		
Deficiency	No deficiencies recorded		
Heating And Ventilating Unit	Does not exist		
Metal Ductwork	Inspected		
Condition	3- Fair		
Are there any uninsulated ductwork by design in Mechanical rooms?	Yes		
Are there chain operated dampers?	No		
Deficiency	No deficiencies recorded		
Supply Fan	Does not exist		
Unit Ventilator	Does not exist		