

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X338

Asset: MORRIS HEIGHTS EDUCATIONAL COMPLEX - BRONX, 1780 DR MARTIN LUTHER KING JR BOULEVARD, BRONX, NY, 10453

Inspection Id	Inspection Type	Time In	Last Edited
1094	ELECTRICAL	2023-11-17 08:02AM	2023-12-11 02:03PM




Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: All Electrical Systems and Components Years: 2010
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration In Electrical Room?	No

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	Yes
Are dedicated intercoms available in all of these spaces for use during a fire?	No
Which spaces do not have dedicated intercoms?	Room 102

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No	Fire Alarm System - Defective	Mapping Fault	Fire Alarm System - Main Panel	Main Entrance Lobby	Christian Perez	Fireman	
No	Exit Light - Not Operational	All Exit lights out of order in Gymnasium (two) and Kitchen (one).	Exit Light	Gymnasium, Kitchen	Christian Perez	Fireman	
Yes	Lightning Protection - Defective	Some Lightning protection rods are defective.	Lightning Protection	Main Roof - RTUs: 1, 3, 4, 5, 6	Christian Perez	Fireman	
Yes	Fire Alarm System - Components Not Operational	Magnetic Door Holders are out of order	Fire Alarm System - Magnetic Door Holder/Contact	Corridor by Rooms: 112, 222, 312, 322	Christian Perez	Fireman	No Photo Taken

Inspection

Question	Response
Electrical	
ATHLETIC FIELD	Does not exist
AUDITORIUM	Inspected
Instance on 1st Floor	Inspected
House Lighting	
Instance on 1st Floor	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X338

Question	Response
AUDITORIUM	
House Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	11
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Is the projector on a cart or installed on the ceiling?	Ceiling
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Inspected
Instance Condition	4- Between Fair and Poor
Deficiency	DIMMING RACK/LIGHT CONSOLE NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X338

Question	Response
AUDITORIUM	
Theater Lighting System	
Dimming System	
Violations	No violations recorded
Theater Lighting	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
CAFETERIA	
Instance on Basement	Inspected
Lighting	
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	
Instance on Basement	Does not exist
Surface Mounted	
Instance on Basement	Does not exist
Recessed Mounted	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Basement	Does not exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not exist
Lighting Fixture - LED	
Instance on Basement	Does not exist
Local Sound System	
Instance on Basement	Inspected
Instance Condition	3- Fair
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on Basement	Does not exist
Theater Lighting System	
Instance on Basement	Does not exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	
Pendant Mounted	
Does not exist	
Surface Mounted	
Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Does not exist	
Lighting Fixture - Incandescent	
Does not exist	
Lighting Fixture - LED	
Does not exist	
COMPUTER LAB	
Does not exist	
GYMNASIUM	
Inspected	

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X338

Question	Response
GYMNASIUM	
Instance on 3rd Floor	Inspected
Lighting	
Instance on 3rd Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 3rd Floor	Inspected
Pendant Mounted	
Instance on 3rd Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 3rd Floor	Does not exist
Recessed Mounted	
Instance on 3rd Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 3rd Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 3rd Floor	Does not exist
Lighting Fixture - LED	
Instance on 3rd Floor	Does not exist
Local Sound System	
Instance on 3rd Floor	Inspected
Instance Condition	3- Fair
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 3rd Floor	Does not exist
Scoreboard	
Instance on 3rd Floor	Does not exist
Theater Lighting System	
Instance on 3rd Floor	Does not exist
KITCHEN	Inspected
Instance on Basement	Inspected
Lighting	
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	
Instance on Basement	Does not exist
Surface Mounted	
Instance on Basement	Does not exist
Recessed Mounted	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Basement	Does not exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not exist
Lighting Fixture - LED	
Instance on Basement	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X338

Question	Response
LIBRARY	Inspected
Instance on Room 426	Inspected
Lighting	
Instance on Room 426	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 426	Inspected
Pendant Mounted	
Instance on Room 426	Does not exist
Surface Mounted	
Instance on Room 426	Does not exist
Recessed Mounted	
Instance on Room 426	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Room 426	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 426	Does not exist
Lighting Fixture - LED	
Instance on Room 426	Does not exist
Raceway With Receptacles	
Instance on Room 426	Does not exist
Projection System	
Instance on Room 426	Does not exist
LOCKER ROOM	Inspected
Instance on Room 327 - Boys	Inspected
Alternative Use	Yes
Lighting	
Instance on Room 327 - Boys	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 327 - Boys	Inspected
Pendant Mounted	
Instance on Room 327 - Boys	Does not exist
Surface Mounted	
Instance on Room 327 - Boys	Does not exist
Recessed Mounted	
Instance on Room 327 - Boys	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Room 327 - Boys	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 327 - Boys	Does not exist
Lighting Fixture - LED	
Instance on Room 327 - Boys	Does not exist
MULTIPURPOSE ROOM	Does not exist
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Inspected
Instance on Room 405	Inspected
Power Panel?	Yes
Alternative Use	No
Instance on Room 401	Inspected
Power Panel?	Yes

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X338

Question	Response
SCIENCE LAB	
Alternative Use	No
Lighting	
Instance on Room 405	Inspected
Instance on Room 401	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 405	Inspected
Instance on Room 401	Inspected
Pendant Mounted	
Instance on Room 405	Does not exist
Instance on Room 401	Does not exist
Surface Mounted	
Instance on Room 405	Does not exist
Instance on Room 401	Does not exist
Recessed Mounted	
Instance on Room 405	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 401	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Room 405	Does not exist
Instance on Room 401	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 405	Does not exist
Instance on Room 401	Does not exist
Lighting Fixture - LED	
Instance on Room 405	Does not exist
Instance on Room 401	Does not exist
Emergency Gas Shut-Off Valve	
Instance on Room 405	Does not exist
Instance on Room 401	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 405	Does not exist
Instance on Room 401	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Power Supply	
Instance on Room 405	Does not exist
Instance on Room 401	Inspected
Instructor Unit	
Instance on Room 401	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Room 401	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Student Unit	
Instance on Room 401	Does not exist
Projection System	

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X338

Question	Response
SCIENCE LAB	
Projection System	
Instance on Room 405	Does not exist
Instance on Room 401	Does not exist
SCIENCE PREP ROOM	
Instance on Room 407	Inspected
Power Panel?	No
Alternative Use	No
Instance on Room 403	Inspected
Power Panel?	No
Alternative Use	Yes
Lighting	
Instance on Room 407	Inspected
Instance on Room 403	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 407	Inspected
Instance on Room 403	Inspected
Pendant Mounted	
Instance on Room 407	Does not exist
Instance on Room 403	Does not exist
Surface Mounted	
Instance on Room 407	Does not exist
Instance on Room 403	Does not exist
Recessed Mounted	
Instance on Room 407	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 403	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Room 407	Does not exist
Instance on Room 403	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 407	Does not exist
Instance on Room 403	Does not exist
Lighting Fixture - LED	
Instance on Room 407	Does not exist
Instance on Room 403	Does not exist
Emergency Gas Shut-Off Valve	
Instance on Room 407	Does not exist
Instance on Room 403	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 407	Does not exist
Instance on Room 403	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Power Supply	
Instance on Room 407	Does not exist
Instance on Room 403	Does not exist
SWIMMING POOL	
	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X338

Question	Response
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Does not exist
Recessed Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Does not exist
Recessed Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Inspected
Automatic Transfer Switch (ATS)	Inspected
Instance	Room B14A
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ASCO
EquipmentId	ATS#1 - EMDB
Capacity/Size Quantity	800
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Room B14A
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ASCO
EquipmentId	ATS#2 - Sprinkler Control Panel
Capacity/Size Quantity	20
Capacity/Size UOM	HP
Source of Capacity/Size	Nameplate
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Battery Charger	Inspected
Instance	Emergency Generator Outdoor Enclosure

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X338

Question	Response
EMERGENCY GENERATOR SET	
Battery Charger	
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Cummins Onan
EquipmentId	Battery Charger
Capacity/Size Quantity	10
Capacity/Size UOM	AmpsDC
Capacity/Size 2 Quantity	24
Capacity/Size 2 UOM	VDC
Source of Capacity/Size	Nameplate
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Emergency Distribution Board	Inspected
Number of Spares	3
Fused Disconnect Switch Type	Inspected
Instance	Room B14A
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Cutler Hammer
EquipmentId	EMDB
Capacity/Size Quantity	600
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Molded Case Circuit Breaker Type	Does not exist
Diesel	Inspected
Instance	Emergency Generator Outdoor Enclosure
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Cummins Onan
EquipmentId	Emergency Generator
Capacity/Size Quantity	312
Capacity/Size UOM	kVA
Capacity/Size 2 Quantity	250
Capacity/Size 2 UOM	kW
Capacity/Size 3 Quantity	867
Capacity/Size 3 UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Natural Gas	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not exist
EMERGENCY LIGHTING	Inspected
Battery Pack	Does not exist
Non Battery Pack	Inspected
Condition	3- Fair

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X338

Question	Response
EMERGENCY LIGHTING	
Non Battery Pack	
Deficiency	No deficiencies recorded
EXIT LIGHT	
	Inspected
Battery Pack	
Condition	3- Fair
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Gymnasium, Kitchen
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Non Battery Pack	
	Does not exist
EXIT/EMERGENCY LIGHT	
	Does not exist
FIRE ALARM SYSTEM	
	Inspected
Bell/Horn	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Strobe	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Manual Pull Station	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
CO Detector	
	Does not exist
Heat Detector	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Elevator Recall	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Magnetic Door Holder/Contactor	
Condition	4- Between Fair and Poor
Deficiency	CONTACTOR NOT OPERATIONAL
Deficiency Location/Instance	Corridor by Rooms: 112, 222, 312, 322
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Fused Cutout Panel	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded

NYC Department of Education
Building Condition Assessment Survey 2023-2024

Electrical Inspection

X338

Question	Response
FIRE ALARM SYSTEM	
Fire Alarm Digital Communicator	Inspected
Instance	MDF Room 109A
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Silent Knight
EquipmentId	N/A
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Main Panel	Inspected
Bell At Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	4- Between Fair and Poor
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	General Electric
Model	EST 2
EquipmentId	Fire Alarm Control Panel
Installation Year	2010
Source of Installation Year	Documented
Deficiency	PANEL DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	E623912
Fire Alarm Control Panel (Standard)	Does not exist
Sub-Panel	Does not exist
Remote Annunciator	Inspected
Display Monitor	Does not exist
Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Punch Register	Does not exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Inspected
Elevator	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X338

Question	Response
INTERCOM SYSTEM	
Elevator	
Condition	3- Fair
Deficiency	No deficiencies recorded
Holding Area	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Inspected
Condition	3- Fair
Deficiency	LIGHTNING AIR TERMINAL (ROD) DEFECTIVE
Deficiency Location/Instance	Main Roof - RTUs: 1, 3, 4, 5, 6
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	MDF Room 109A
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Bogen Multicom - 2000
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Condition	3- Fair
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X338

Question	Response
SECURITY	
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office - Room 107A
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128BP
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
SERVICE SWITCH	Inspected
Instance	Room B14B
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Cutler Hammer
EquipmentId	Fire Pump
Capacity/Size Quantity	400
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Room B14B
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Cutler Hammer
EquipmentId	SS#1
Capacity/Size Quantity	3000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Room B14B
Instance Condition	2- Between Good and Fair
Instance Quantity	1

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X338

Question	Response
SERVICE SWITCH	
Instance Quantity Uom	EACH
Manufacturer	Cutler Hammer
EquipmentId	SS#2
Capacity/Size Quantity	1600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Room B14B
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Cutler Hammer
EquipmentId	SS#3
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	Inspected
Number of Spares	8
Fused Disconnect Switch Type	Inspected
Instance	Room B14B
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Cutler Hammer
EquipmentId	HDB
Capacity/Size Quantity	4000
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Room B14B
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Cutler Hammer
EquipmentId	MDB Section #1, #2
Capacity/Size Quantity	1600
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Room B14B
Instance Condition	2- Between Good and Fair
Instance Quantity	1

NYC Department of Education
Building Condition Assessment Survey 2023-2024

Electrical Inspection

X338

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Instance Quantity Uom	EACH
Manufacturer	East Coast
EquipmentId	N/A
Capacity/Size Quantity	3000
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	
PBX/Intercom	
Condition	Inspected
Deficiency	3- Fair
Deficiency	No deficiencies recorded
Standard	
Condition	Inspected
Deficiency	3- Fair
Deficiency	No deficiencies recorded
TRANSFORMER	
	Does not exist