## **Building Condition Assessment Survey 2023-2024**

Electrical Inspection	X340
-----------------------	------

Electrical I	nspection						<b>X3</b> 4
Asset:	P.S. 340 - BRON	X, 25 WEST 195 STREET,	BRONX, NY, 1	0468			
Inspection	Id Inspection Type				Time	In	Last Edited
	1131 ELECTRICAL				2023-	-11-20 08:04A	M 2024-04-05 01:02PM
sset Data							
Question				Answer			
Have any	Systems/Major Building C	Components been upgraded?		Systems:	Telephone Sy	stem	
,	, , ,	1 10		Years:	2021		
				Systems:	Intrusion Alar	m System (Par	tial Remote Annunciator,
				•	Most Infrared		
				Years:	2020		
				Systems:	Exit Lights (E	Battery Pack)	
				Years:	2018		
				Systems:	All Other Elec	ctrical Systems	and Components
				Years:	1999		
Type of Se	ervice			Below Gr	ound		
Does Inter	ractive Whiteboard (IWB)	Exist?		Yes			
Water Pen	etration In Electrical Roor	n?		No			
DEDICA	TED INTERCOMS I	N FIRE RESCUE AREAS					
Question					Response		
	•	nce Areas, Fire Rescue Areas, a	nd/or Holding Roo	ms in	Yes		
your bui		1 : 11 C.4	1		37		
		ole in all of these spaces for use	during a fire?		Yes Yes		
	all dedicated intercoms op	erational?			Yes		
Priority Con		G W.			<b></b>	<b>.</b>	
Exist Last Year?	Priority Category	Condition  Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
Yes	Water Leaks onto Electrical Equipment	Water leaks onto light fixtures through the roof.	Lighting Fixture	Canopy, Corridor by Room 324, Room 324	Louis Gonzalez	Fireman	No Photo Taken
No	Fire Alarm System -	It is out of order and	Fire Alarm	Basement -	Louis	Fireman	No Photo Taken
110	Components Not Operational	blocking AC unit in room C14A	System - Fan Shutdown Control	Mechanical Room C14A	Gonzales	THEMAN	THE FAMOUR PARCE
No	Emergency Generator	Generator Batteries are	Emergency	Roof	Louis	Fireman	No Photo Taken
	Components - Not Operational	not Operational	Generator	Generator Enclosure	Gonzalez		
Inspection							
Question				Response	2		
Electrical							
	CTIC FIELD			Does not			
	ORIUM			Does not			
CAFET				Inspected			
	Instance on 1st Floor			Inspected			
Lighti				Inconst-1			
<u>, , , , , , , , , , , , , , , , , , , </u>	Instance on 1st Floor			Inspected			
Ligh	Iting Fixture - Fluoresce	nt		T			
_	Instance on 1st Floor			Inspected	1		
Pe	endant Mounted			ъ .	:-4		
	Instance on 1st Floor			Does not	exist		
Su	urface Mounted				• ,		
_	Instance on 1st Floor			Does not	exist		
Re	ecessed Mounted						
	Instance on 1st Floor			Inspected			
	Instance Condition			3- Fair			

## **Building Condition Assessment Survey 2023-2024**

Question	Response
CAFETERIA	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Installation Year	1999
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Cafeteria-1st Floor
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Projection System	
Instance on 1st Floor	Does not exist
Theater Lighting System	
Instance on 1st Floor	Does not exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	17
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
COMPUTER LAB	Inspected
Instance on Room 325	Inspected
Power Panel?	Yes
Lighting	
Instance on Room 325	Inspected
	-

## **Building Condition Assessment Survey 2023-2024**

Electrical Inspection	X340
Question	Response

Question	Response
COMPUTER LAB	
Lighting	
Lighting Fixture - Fluorescent	
Instance on Room 325	Inspected
Pendant Mounted	
Instance on Room 325	Does not exist
Surface Mounted	
Instance on Room 325	Does not exist
Recessed Mounted	
Instance on Room 325	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Room 325	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 325	Does not exist
Lighting Fixture - LED	
Instance on Room 325	Does not exist
Raceway With Receptacles	
Instance on Room 325	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
GYMNASIUM	Does not exist
KITCHEN	Inspected
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID  Instance on 1st Floor	Description of society
	Does not exist
Lighting Fixture - Incandescent  Instance on 1st Floor	Does not exist
Lighting Fixture - LED	Does not exist
Instance on 1st Floor	Does not exist
LIBRARY	Inspected
Instance on Room 322	Inspected
	inspected
Lighting Instance on Room 322	Inspected
Lighting Fixture - Fluorescent	r
Instance on Room 322	Inspected
Pendant Mounted	1 -
Instance on Room 322	Does not exist
Surface Mounted	
Instance on Room 322	Does not exist

## **Building Condition Assessment Survey 2023-2024**

4*	n	
uestion	Response	
LIBRARY		
Lighting		
Lighting Fixture - Fluorescent		
Recessed Mounted		
Instance on Room 322	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on Room 322	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 322	Does not exist	
Lighting Fixture - LED		
Instance on Room 322	Does not exist	
Raceway With Receptacles		
Instance on Room 322	Does not exist	
Projection System		
Instance on Room 322	Does not exist	
LOCKER ROOM	Does not exist	
MULTIPURPOSE ROOM	Inspected	
Instance on 1st Floor	Inspected	
Lighting		
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Does not exist	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	1999	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Multipurpose Room-1st Floor	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Projection System		
Instance on 1st Floor	Does not exist	

## **Building Condition Assessment Survey 2023-2024**

uestion	Response	
MULTIPURPOSE ROOM		
Theater Lighting System		
Instance on 1st Floor	Does not exist	
SCIENCE DEMO ROOM	Inspected	
Instance on Room 318	Inspected	
Power Panel?	Yes	
Alternative Use	No	
Lighting		
Instance on Room 318	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 318	Inspected	
Pendant Mounted		
Instance on Room 318	Does not exist	
Surface Mounted		
Instance on Room 318	Does not exist	
Recessed Mounted		
Instance on Room 318	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on Room 318	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 318	Does not exist	
Lighting Fixture - LED		
Instance on Room 318	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Room 318	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power		
Instance on Room 318	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Power Supply		
Instance on Room 318	Inspected	
Instructor Unit		
Instance on Room 318	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Meter Demonstration Unit		
Instance on Room 318	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Room 318	Does not exist	
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Inspected	
Instance on Room 318A	Inaccessible	
SWIMMING POOL	Does not exist	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent Pendant Mounted	Inspected  Does not exist	

## **Building Condition Assessment Survey 2023-2024**

ircui Inspection	Дот
Question	Response
TOILET ROOM - STAFF	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	5- Poor
Deficiency	BELL TRANSFORMER PANEL NOT OPERATIONAL
Deficiency Location/Instance	Custodian's Office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE PANEL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Inspected
Automatic Transfer Switch (ATS)	Inspected
Instance	Electrical Room C03
Instance Condition	3- Fair
Instance Quantity	1
	EACH
Instance Quantity Uom	ASCO
Manufacturer	Transfer Switch
EquipmentId Capacity/Size Quantity	800
Capacity/Size Quantity  Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1999
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room C03
Instance Condition	3- Fair
Instance Quantity	1
	EACH
Instance Quantity Uom	
Manufacturer	ASCO
EquipmentId	Fire Alarm Transfer Switch
Capacity/Size Quantity	70
Capacity/Size UOM Source of Capacity/Size	Amps
Source of Capacity/Size	Nameplate

## **Building Condition Assessment Survey 2023-2024**

uestion		Response
	GENCY GENERATOR SET	•
	natic Transfer Switch (ATS)	
Auton	Installation Year	1999
	Source of Installation Year	Documented
	Deficiency	No deficiencies recorded
Ratter	y Charger	Inspected
Datter	Instance	Roof - Generator Enclosure
	Instance Condition	3- Fair
	Instance Quantity	1
		EACH
	Instance Quantity Uom	
	Manufacturer	SENS
	EquipmentId	Battery Charger
	Capacity/Size Quantity	10
	Capacity/Size UOM	AmpsDC
	Capacity/Size 2 Quantity	24
	Capacity/Size 2 UOM	VDC
	Source of Capacity/Size	Nameplate
	Installation Year	1999
	Source of Installation Year	Documented
	Deficiency	No deficiencies recorded
	gency Distribution Board	Inspected
	ber of Spares	0
Fuse	d Disconnect Switch Type	Inspected
	Instance	Electrical Room C03
	Instance Condition	3- Fair
	Instance Quantity	1
	Instance Quantity Uom	EACH
	Manufacturer	Siemens
	EquipmentId	Emergency Distribution Panel
	Capacity/Size Quantity	800
	Capacity/Size UOM	Amps Total
	Capacity/Size 2 Quantity	1
	Capacity/Size 2 UOM	Section(s)
	Source of Capacity/Size	Nameplate
	Installation Year	1999
	Source of Installation Year	Documented
	Deficiency	No deficiencies recorded
Mole	ded Case Circuit Breaker Type	Does not exist
	**	
Diesel		Inspected  Roof - Generator Enclosure
	Instance	
	Instance Condition	3- Fair
	Instance Quantity	1
	Instance Quantity Uom	EACH
	Manufacturer	Detroit Diesel Spectrum
	EquipmentId	Emergency Generator
	Capacity/Size Quantity	265
	Capacity/Size UOM	kVA
	Capacity/Size 2 Quantity	205
	Capacity/Size 2 UOM	kW
	Capacity/Size 3 Quantity	711
	Capacity/Size 3 UOM	Amps
	Source of Capacity/Size	Nameplate
	Installation Year	1999
	Source of Installation Year	Documented
	Deficiency	BATTERY NOT OPERATIONAL
	Deficiency Quantity	3
	Quantity Uom	EACH

## **Building Condition Assessment Survey 2023-2024**

trical Inspection	X340
Question	Response
EMERGENCY GENERATOR SET	
Diesel	
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Natural Gas	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not exist
EMERGENCY LIGHTING	Inspected
Battery Pack	Does not exist
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Non Battery Pack	Does not exist
•	Does not exist
EXIT/EMERGENCY LIGHT	
FIRE ALARM SYSTEM	Inspected
Bell/Horn	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	3- Fair
Deficiency	CONTROL NOT OPERATIONAL
Deficiency Location/Instance	Basement - Mechanical Room C14A
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Duct Smoke Detector	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
CO Detector	Does not exist
Heat Detector	Does not exist
Elevator Recall	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Magnetic Door Holder/Contactor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fused Cutout Panel	Inspected

## **Building Condition Assessment Survey 2023-2024**

estion	Response	
RE ALARM SYSTEM		
Fused Cutout Panel		
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Inspected	
Bell At Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Notifier	
Model	AFP - 300	
EquipmentId	Interior Code Fire Alarm	
Installation Year	1999	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel	Does not exist	
Remote Annunciator	Inspected	
Display Monitor	Inspected	
Condition	5- Poor	
Deficiency	MONITOR NOT OPERATIONAL	
Deficiency Location/Instance	Custodian's Office	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Panel	Inspected	
Condition	5- Poor	
Deficiency	PANEL NOT OPERATIONAL	
Deficiency Location/Instance Deficiency Quantity	Main Office - Room 118	
Quantity Uom	1 EACH	
Potential Action	EACH REPLACE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Printer	Inspected	
Condition	5- Poor	
Deficiency	PRINTER NOT OPERATIONAL	
Deficiency Location/Instance	Custodian's Office	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Punch Register	Does not exist	
Sprinkler Flow/Air Pressure Switch	Inspected	

## **Building Condition Assessment Survey 2023-2024**

псан інгрестон		X340
duestion	Response	
FIRE ALARM SYSTEM		
Sprinkler Flow/Air Pressure Switch		
Deficiency	No deficiencies recorded	
Tamper Flow Switch/Chain	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
GROUNDING SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
INTERCOM SYSTEM	Inspected	
Elevator	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Holding Area	Does not exist	
LAN	Inspected	
Local Distribution Frame (I/LDF)	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Main Equipment Rack (MDF)	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
LIGHTNING PROTECTION	Does not exist	
MOTOR CONTROLLER	Inspected	
MOTOR CONTROL CENTER	Does not exist	
MOTOR STARTER/CONTACTOR	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Variable Frequency Drive	Does not exist	
PANEL BOARD	Inspected	
Fused Disconnect Switch Type	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fused Knife Switch Type	Does not exist	
Fused Toggle Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
PUBLIC ADDRESS SYSTEM	Inspected	
Instance	MDF Room 205	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Bogen Multicom - 2000	
Installation Year	1999	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
SECURITY	Inspected	
IPDVS/CCTV System	Does not exist	
Intrusion Alarm System	Inspected	
Central Control Panel	Inspected	
Instance	Custodian's Office - Room 107	
Instance Condition	3- Fair	
Instance Quantity	1	

## **Building Condition Assessment Survey 2023-2024**

icai inspection	A)4
uestion	Response
SECURITY	
Intrusion Alarm System	
Central Control Panel	
Instance Quantity Uom	EACH
Model	Vista - 50P
Installation Year	1999
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	4- Between Fair and Poor
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Location/Instance	Roof, Building Perimeter
Deficiency Quantity	16
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action Purpose of Action	PRIORITY 3 LEVEL 3
Violations	No violations recorded
	LIGHTING FIXTURE PHOTOCELL NOT OPERATIONAL
Deficiency Deficiency Location/Instance	
Deficiency Quantity	Roof, Building Perimeter 7
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Violations	No violations recorded
Deficiency	TIME CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Room 311
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Violations	No violations recorded
SERVICE SWITCH	Inspected
Instance	Electrical Room C03
Instance Condition	3- Fair
Instance Quantity	1
	EACH
Instance Quantity Uom	
Manufacturer	All City Switchboard  Main Disconnect
EquipmentId Capacity/Size Quantity	2500
Capacity/Size Quantity	2300

## **Building Condition Assessment Survey 2023-2024**

Question	Response
SERVICE SWITCH	
Source of Capacity/Size	Nameplate
Installation Year	1999
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	Inspected
Number of Spares	0
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room C03
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	All City Switchboard
EquipmentId	N/A
Capacity/Size Quantity	2500
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	1999
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
TRANSFORMER	Does not exist