Electrical Inspection	X362
-----------------------	------

Electrical I	nspection						X362
Asset:	I.S./H.S. 362 - BI	RONX, 921 EAST 228 STR	EET, BRONX, N	Y, 10466			
Inspection	Id Inspection Type				Time	In	Last Edited
1	249 ELECTRICAL				2023-	-11-27 07:58AM	1 2024-03-18 02:00PM
Asset Data							
Question				Answer			
Have any	Systems/Major Building C	Components been upgraded?		Systems:		ting, LED Lighti and Gymnasium	ing in Auditorium
				Years:	2022	•	
				Systems:		b - Rooms: 227,	236, 243 (Raceway with
				Years:	Receptacles) 2019		
				Systems:	LED Lighting	ř	
				Years:	2018	•	
				Systems:	IPDVS/CCTV	/ System	
				Years:	2010	. System	
				Systems:		ctrical Systems a	and Components
				Years:	2008	ouriour systems o	and components
Type of Se	ervice			Below Gr			
	active Whiteboard (IWB)	Exist?		Yes			
	etration In Electrical Room			No			
DEDICA	TED INTERCOMS II	N FIRE RESCUE AREAS					
Question]	Response		
		nce Areas, Fire Rescue Areas, a	nd/or Holding Roon	ns in	Yes		
your bui							
		ole in all of these spaces for use	during a fire?		Yes		
	all dedicated intercoms op	erational?			Yes		
Priority Co							
Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
Yes	Lightning Protection - Defective	Rods missing or poorly installed	Lightning Protection	Roof and RTUs: 4, 5, 6, 7, 8 and 9	Frank Atkins	Fireman	
Yes	Fire Alarm System - Components Not Operational	Fire Alarm Magnetic Door Holders are out of order	Fire Alarm System - Magnetic Door Holder/Contac tor	4th, 3rd, 2nd, 1st Floor	Frank Atkinson	Fireman	No Photo Taken
Inspection							
Question				Response	:		
Electrical							
-	TIC FIELD			Does not			
AUDIT				Inspected			
	Instance on 1st Floor			Inspected			
House	Instance on 1st Floor			Inamant- 1			
	Does a Chandelier Exis	st?		Inspected No			
Liab	ting Fixture - Fluorescei			TNO			
Ligh	Instance on 1st Floor	ш		Does not	evist		
Ligh	ting Fixture - HID			Does not	-Albt		
Ligh	Instance on 1st Floor			Does not	exist		
Ligh	ting Fixture - Incandesc	ent		Does not			
Ligh	Instance on 1st Floor	CIII		Inspected			
	mstance on 18t F100f			пърсски			

Electrical Inspection	X362
0 4:	D.

-		
uestion	Response	
AUDITORIUM		
House Lighting		
Lighting Fixture - Incandescent		
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	140 deficiences recorded	
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
	No deficiencies recorded	
Recessed Mounted	T 1	
Instance on 1st Floor	Inspected 2- Between Good and Fair	
Instance Condition		
Deficiency Deficiency Quantity	LIGHTING FIXTURE NOT OPERATIONAL	
	1 EACH	
Quantity Uom Potential Action		
	REPLACE	
Urgency of Action	PRIORITY 3 LEVEL 2	
Purpose of Action Violations	No violations recorded	
	No violations recorded	
Local Sound System Instance on 1st Floor	Inspected	
	3- Fair	
Installation Year	2008	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System	To deficiencies recorded	
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Is the projector on a cart or installed on the ceiling?	Cart	
Deficiency	No deficiencies recorded	
Theater Lighting System	No deficiences recorded	
Instance on 1st Floor	Inspected	
Dimming System	порессей	
Instance on 1st Floor	Inspected	
	3- Fair	
Instance Condition		
Deficiency The start Linkship	No deficiencies recorded	
Theater Lighting	T 1	
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
CAFETERIA	Inspected	
Instance on 1st Floor - Students	Inspected	

Building Condition Assessment Survey 2023-2024

ricai Inspection	A302
Question	Response
CAFETERIA	
Instance on 1st Floor - Staff	Inspected
Lighting	
Instance on 1st Floor - Students	Inspected
Instance on 1st Floor - Staff	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor - Students	Inspected
Instance on 1st Floor - Staff	Inspected
Pendant Mounted	
Instance on 1st Floor - Students	Does not exist
Instance on 1st Floor - Staff	Does not exist
Surface Mounted	
Instance on 1st Floor - Students	Does not exist
Instance on 1st Floor - Staff	Does not exist
Recessed Mounted	
Instance on 1st Floor - Students	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on 1st Floor - Staff	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor - Students	Does not exist
Instance on 1st Floor - Staff	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor - Students	Does not exist
Instance on 1st Floor - Staff	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor - Students	Does not exist
Instance on 1st Floor - Staff	Does not exist
Local Sound System	
Instance on 1st Floor - Students	Inspected
Instance Condition	3- Fair
Installation Year	2008
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance on 1st Floor - Staff	Does not exist
Projection System	
Instance on 1st Floor - Students	Does not exist
Instance on 1st Floor - Staff	Does not exist
Theater Lighting System	
Instance on 1st Floor - Students	Does not exist
Instance on 1st Floor - Staff	Does not exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected

Building Condition Assessment Survey 2023-2024

Question	Response	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE		
Lighting		
Lighting Fixture - Fluorescent		
Pendant Mounted		
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Does not exist	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
COMPUTER LAB	Inspected	
Instance on Room 243	Inspected	
Power Panel?	Yes	
Instance on Rooms: 227, 236	Inspected	
Power Panel?	No	
Lighting	1.0	
Instance on Room 243	Inspected	
Instance on Rooms: 227, 236	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 243	Inspected	
Instance on Rooms: 227, 236	Inspected	
Pendant Mounted	<u> </u>	
Instance on Room 243	Does not exist	
Instance on Rooms: 227, 236	Does not exist	
Surface Mounted		
Instance on Room 243	Does not exist	
Instance on Rooms: 227, 236	Does not exist	
Recessed Mounted		
Instance on Room 243	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms: 227, 236	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on Room 243	Does not exist	
Instance on Rooms: 227, 236	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 243	Does not exist	
Instance on Rooms: 227, 236	Does not exist	
Lighting Fixture - LED		
Instance on Room 243	Does not exist	
Instance on Rooms: 227, 236	Does not exist	

Question	Response	
COMPUTER LAB		
Raceway With Receptacles		
Instance on Room 243	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Instance on Rooms: 227, 236	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
GYMNASIUM	Inspected	
Instance on 1st Floor	Inspected	
Lighting		
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent	1	
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted	•	
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	2008	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 1st Floor	Does not exist	
Scoreboard		
Instance on 1st Floor	Inspected	
Instance Condition	4- Between Fair and Poor	
Deficiency	DAMAGED	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action Violations	LEVEL 2 No violations recorded	
	No violations recorded	
Theater Lighting System	Door mot aviet	
Instance on 1st Floor	Does not exist	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	

Building Condition Assessment Survey 2023-2024

X362

uestion	Response	
KITCHEN		
Lighting		
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		

Building Condition Assessment Survey 2023-2024

cai Inspection		
estion	Response	
OCKER ROOM		
Alternative Use	No	
Instance on Rooms: 116C, 116D, 342B	Inspected	
Alternative Use	Yes	
Instance on Room 116N	Inaccessible	
Lighting		
Instance on Rooms: 116I, 116J, 130H, 130K, 342A, 440A, 440B	Inspected	
Instance on Rooms: 116C, 116D, 342B	Inspected	
Lighting Fixture - Fluorescent		
Instance on Rooms: 116I, 116J, 130H, 130K, 342A, 440A, 440B	Inspected	
Instance on Rooms: 116C, 116D, 342B	Inspected	
Pendant Mounted	Inspected	
Instance on Rooms: 116I, 116J, 130H, 130K, 342A, 440A, 440B	Does not exist	
Instance on Rooms: 116C, 116D, 342B	Does not exist	
Surface Mounted	Does not exist	
Instance on Rooms: 116I, 116J, 130H, 130K, 342A, 440A, 440B	Does not exist	
Instance on Rooms: 1161, 1163, 13611, 1368, 342A, 446A, 446B	Does not exist Does not exist	
Recessed Mounted	Does not exist	
	Turning and d	
Instance on Rooms: 116I, 116J, 130H, 130K, 342A, 440A, 440B	Inspected 3- Fair	
Instance Condition		
Deficiency	No deficiencies recorded	
Instance on Rooms: 116C, 116D, 342B	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on Rooms: 116I, 116J, 130H, 130K, 342A, 440A, 440B	Does not exist	
Instance on Rooms: 116C, 116D, 342B	Does not exist	
Lighting Fixture - Incandescent		
Instance on Rooms: 116I, 116J, 130H, 130K, 342A, 440A, 440B	Does not exist	
Instance on Rooms: 116C, 116D, 342B	Does not exist	
Lighting Fixture - LED		
Instance on Rooms: 116I, 116J, 130H, 130K, 342A, 440A, 440B	Does not exist	
Instance on Rooms: 116C, 116D, 342B	Does not exist	
IULTIPURPOSE ROOM	Inspected	
Instance on Room 440	Inspected	
Lighting		
Instance on Room 440	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 440	Inspected	
Pendant Mounted		
Instance on Room 440	Does not exist	
Surface Mounted		
Instance on Room 440	Does not exist	
Recessed Mounted		
Instance on Room 440	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on Room 440	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Instance on Room 440	Does not exist	
	Does not exist	
Lighting Fixture - LED Instance on Room 440	Does not exist	

Electrical Inspection	X362

uestion	Response
MULTIPURPOSE ROOM	
Local Sound System	
Instance on Room 440	Inspected
Instance Condition	3- Fair
Installation Year	2008
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on Room 440	Does not exist
Theater Lighting System	
Instance on Room 440	Does not exist
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Inspected
Instance on Rooms: 241, 331, 335, 431, 435, 439	Inspected
Power Panel?	Yes
Alternative Use	No
Instance on Room 339	Inspected
Power Panel?	Yes
Alternative Use	No
Instance on Room 237	Inspected
Power Panel?	Yes
Alternative Use	No
Lighting	110
Instance on Rooms: 241, 331, 335, 431, 435, 439	Inspected
Instance on Room 339	Inspected
Instance on Room 237	Inspected
Lighting Fixture - Fluorescent	
Instance on Rooms: 241, 331, 335, 431, 435, 439	Inspected
Instance on Room 339	Inspected
Instance on Room 237	Inspected
Pendant Mounted	
Instance on Rooms: 241, 331, 335, 431, 435, 439	Does not exist
Instance on Room 339	Does not exist
Instance on Room 237	Does not exist
Surface Mounted	2000 100 01100
Instance on Rooms: 241, 331, 335, 431, 435, 439	Does not exist
Instance on Room 339	Does not exist
Instance on Room 237	Does not exist
Recessed Mounted	2000 100 01100
Instance on Rooms: 241, 331, 335, 431, 435, 439	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 339	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 237 Instance Condition	Inspected 3- Fair
Deficiency	No deficiencies recorded
	INO deficiencies recorded
Lighting Fixture - HID	Door not aviet
Instance on Rooms: 241, 331, 335, 431, 435, 439	Does not exist
Instance on Room 339	Does not exist
Instance on Room 237	Does not exist
Lighting Fixture - Incandescent	

Building Condition Assessment Survey 2023-2024

rical Inspection	_	<u> </u>
uestion	Response	
SCIENCE LAB		
Lighting		
Lighting Fixture - Incandescent		
Instance on Rooms: 241, 331, 335, 431, 435, 439	Does not exist	
Instance on Room 339	Does not exist	
Instance on Room 237	Does not exist	
Lighting Fixture - LED		
Instance on Rooms: 241, 331, 335, 431, 435, 439	Does not exist	
Instance on Room 339	Does not exist	
Instance on Room 237	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Rooms: 241, 331, 335, 431, 435, 439	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 339	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 237	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power		
Instance on Rooms: 241, 331, 335, 431, 435, 439	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 339	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 237	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Power Supply		
Instance on Rooms: 241, 331, 335, 431, 435, 439	Inspected	
Instance on Room 339	Inspected	
Instance on Room 237	Inspected	
Instructor Unit		
Instance on Rooms: 241, 331, 335, 431, 435, 439	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 339	Inspected	
Instance Condition	3- Fair	
D c :	NT 1 C ' ' 1 1	

	Deficiency	No deficiencies recorded	
Meter	Demonstration Unit		
	Instance on Rooms: 241, 331, 335, 431, 435, 439	Inspected	
	Instance Condition	3- Fair	
	Deficiency	No deficiencies recorded	
	Instance on Room 339	Inspected	
	Instance Condition	3- Fair	
	Deficiency	No deficiencies recorded	
	Instance on Room 237	Inspected	
	Instance Condition	3- Fair	
tners Ve	rsion 2.0 (P)	Page 9 of 20	Print Date: 8/8/202

No deficiencies recorded

Inspected 3- Fair

Deficiency

Instance on Room 237

Instance Condition

Electrical Inspection	X362

· · · · · · · · · · · · · · · · · · ·		
Question	Response	
SCIENCE LAB		
Power Supply		
Meter Demonstration Unit		
Deficiency	No deficiencies recorded	
Student Unit		
Instance on Rooms: 241, 331, 335, 431, 435, 439	Does not exist	
Instance on Room 339	Does not exist	
Instance on Room 237	Does not exist	
Projection System		
Instance on Rooms: 241, 331, 335, 431, 435, 439	Does not exist	
Instance on Room 339	Does not exist	
Instance on Room 237	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
SCIENCE PREP ROOM	Inspected	
Instance on Rooms: 333, 337, 433, 437	Inspected	
Power Panel?	No	
Alternative Use	No	
Instance on Room 239	Inaccessible	
Lighting	maccessione	
Instance on Rooms: 333, 337, 433, 437	Inspected	
Lighting Fixture - Fluorescent	mspecied	
Instance on Rooms: 333, 337, 433, 437	Inspected	
Pendant Mounted	mspecied	
Instance on Rooms: 333, 337, 433, 437	Does not exist	
Surface Mounted	Does not exist	
Instance on Rooms: 333, 337, 433, 437	Does not exist	
Recessed Mounted	Does not exist	
Instance on Rooms: 333, 337, 433, 437	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	No deficiences recorded	
Instance on Rooms: 333, 337, 433, 437	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
	Does not exist	
Instance on Rooms: 333, 337, 433, 437	Does not exist	
Lighting Fixture - LED	Does not exist	
Instance on Rooms: 333, 337, 433, 437	Does not exist	
Emergency Gas Shut-Off Valve Instance on Rooms: 333, 337, 433, 437	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
	No deficiencies recorded	
Emergency Shut-Off Power Instance on Rooms: 333, 337, 433, 437	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
	no deficiencies recorded	
Power Supply Instance on Rooms: 333, 337, 433, 437	Does not exist	
SWIMMING POOL	Does not exist	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Lighting Fixture - Fluorescent Pendant Mounted	Inspected Inspected Does not exist	

Building Condition Assessment Survey 2023-2024

iricai Inspection		A302
Question	Response	
TOILET ROOM - STAFF		
Lighting		
Lighting Fixture - Fluorescent		
Recessed Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Does not exist	
Recessed Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Condition	3- Fair	
	No deficiencies recorded	
Deficiency		
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	
EMERGENCY GENERATOR SET	Inspected	
Automatic Transfer Switch (ATS)	Inspected	
Instance	Water Meter/Fire Pump Room 116B	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	ASCO	
EquipmentId	Fire Pump Power Transfer Switch	
Capacity/Size Quantity	20	
Capacity/Size UOM	HP	
Source of Capacity/Size	Nameplate	
Installation Year	2008	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	ATS Room 118	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	ASCO	
EquipmentId	Fire Alarm Automatic Transfer Switch	
Capacity/Size Quantity	30	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	2008	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	ATS Room 118	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	

Electrical Inspection	A302

uestion		Response
EMERG	ENCY GENERATOR SET	
Autom	atic Transfer Switch (ATS)	
	Manufacturer	ASCO
	EquipmentId	N/A
	Capacity/Size Quantity	400
	Capacity/Size UOM	Amps
	Source of Capacity/Size	Nameplate
	Installation Year	2008
	Source of Installation Year	Documented
	Deficiency	No deficiencies recorded
Battery	y Charger	Inspected
	Instance	Lower Roof - Emergency Generator Enclosure
	Instance Condition	2- Between Good and Fair
	Instance Quantity	1
	Instance Quantity Uom	EACH
	Manufacturer	SENS
	EquipmentId	Battery Charge
	Capacity/Size Quantity	20
	Capacity/Size UOM	AmpsDC
	Capacity/Size 2 Quantity	24
	Capacity/Size 2 UOM	VDC
	Source of Capacity/Size	Nameplate
	Installation Year	2008
	Source of Installation Year	Documented
	Deficiency	No deficiencies recorded
	ency Distribution Board	Inspected
	ber of Spares	2
Fused	d Disconnect Switch Type	Inspected
	Instance	ATS Room 118
	Instance Condition	2- Between Good and Fair
	Instance Quantity	1
	Instance Quantity Uom	EACH
	Manufacturer	Electrotech
	EquipmentId	N/A
	Capacity/Size Quantity	400
	Capacity/Size UOM	Amps Total
	Capacity/Size 2 Quantity	1
	Capacity/Size 2 UOM	Section(s)
	Source of Capacity/Size	Inspector Estimate
	Installation Year	2008
	Source of Installation Year	Documented
	Deficiency	No deficiencies recorded
Mold	led Case Circuit Breaker Type	Does not exist
Diesel		Inspected
	Instance	Lower Roof - Emergency Generator Enclosure
	Instance Condition	2- Between Good and Fair
	Instance Quantity	1
	Instance Quantity Uom	EACH
		Caterpillar
	Manufacturer	
	Manufacturer EquipmentId	Emergency Generator
		Emergency Generator 438
	EquipmentId	
	EquipmentId Capacity/Size Quantity Capacity/Size UOM	438
	EquipmentId Capacity/Size Quantity Capacity/Size UOM Capacity/Size 2 Quantity	438 kVA
	EquipmentId Capacity/Size Quantity Capacity/Size UOM	438 kVA 350
	EquipmentId Capacity/Size Quantity Capacity/Size UOM Capacity/Size 2 Quantity Capacity/Size 2 UOM	438 kVA 350 kW

Building Condition Assessment Survey 2023-2024

icui Inspection		21302
estion	Response	
EMERGENCY GENERATOR SET		
Diesel		
Installation Year	2008	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Natural Gas	Does not exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not exist	
EMERGENCY LIGHTING	Inspected	
Battery Pack	Does not exist	
Non Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EXIT LIGHT	Inspected	
Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	FIXTURE NOT OPERATIONAL	
Deficiency Location/Instance	4th Floor by Exit 6	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
	Does not exist	
Non Battery Pack	Does not exist	
EXIT/EMERGENCY LIGHT		
FIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected 2- Between Good and Fair	
Condition		
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
CO Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Heat Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Elevator Recall	Inspected	
Condition	2- Between Good and Fair	
	No deficiencies recorded	
Deficiency	No deliciencies recorded	

Building Condition Assessment Survey 2023-2024

cui inspection		71302
estion	Response	
TRE ALARM SYSTEM		
Magnetic Door Holder/Contactor		
Condition	3- Fair	
Deficiency	CONTACTOR NOT OPERATIONAL	
Deficiency Location/Instance	1st, 2nd, 3rd and 4th Floor	
Deficiency Quantity	7	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Fused Cutout Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Inspected	
Instance	Water Meter/Fire Pump Room 116B	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Ademco	
EquipmentId	Fire Alarm Communicator	
Installation Year	2008	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Main Panel	Inspected	
Bell At Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
	Inspected	
Fire Alarm Control Panel (Electronic)	-	
Instance	Main Entrance Lobby 2- Between Good and Fair	
Instance Condition		
Instance Quantity	1	
Instance Quantity Uom	ЕАСН	
Manufacturer	Siemens	
Model	MXL	
EquipmentId	Fire Alarm Control Panel	
Installation Year	2008	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel Sub-Panel	Does not exist	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Punch Register	Does not exist	
Sprinkler Flow/Air Pressure Switch	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Deficiency Tamper Flow Switch/Chain	No deficiencies recorded Inspected	

Building Condition Assessment Survey 2023-2024

cutcui inspection	AJ	002
Question	Response	
FIRE ALARM SYSTEM		
Tamper Flow Switch/Chain		
Deficiency	No deficiencies recorded	
GROUNDING SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
INTERCOM SYSTEM	Inspected	-
Elevator	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Holding Area	Does not exist	
LAN	Inspected	
Local Distribution Frame (I/LDF)	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	-
Main Equipment Rack (MDF)	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
LIGHTNING PROTECTION	Inspected	
Condition	3- Fair	
Deficiency	LIGHTNING AIR TERMINAL (ROD) DEFECTIVE	
Deficiency Location/Instance Deficiency Quantity	Roof, RTUs: 4, 5, 6, 7, 8 and 9	
	1 EACH	
Quantity Uom	EACH	
Potential Action	REPAIR PRIORITY 5	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
MOTOR CONTROLLER	Inspected	
MOTOR CONTROL CENTER	Does not exist	
MOTOR STARTER/CONTACTOR	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Variable Frequency Drive	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
PANEL BOARD	Inspected	
Fused Disconnect Switch Type	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fused Knife Switch Type	Does not exist	
Fused Toggle Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
PUBLIC ADDRESS SYSTEM	Inspected	
Instance	Room 124	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Telecor II	
Installation Year	2008	
Installation Year Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
	No deficiences recorded	

Building Condition Assessment Survey 2023-2024

icui inspection		ЛЭО
uestion	Response	
SECURITY	Inspected	
IPDVS/CCTV System	Under construction	
Intrusion Alarm System	Inspected	
Central Control Panel	Inspected	
Instance	Custodian's Office - Room 210	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Vista 128P	
Installation Year	2008	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Infrared Sensor	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Panic Switch	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Remote Annunciator	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Siren/Strobe	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting - Security Condition	Inspected 1- Good	
Deficiency	No deficiencies recorded	
·		
SERVICE SWITCH	Inspected	
Instance	Electrical Room 120	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Electrotech	
EquipmentId	ATS EMDBH	
Capacity/Size Quantity	400	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year Source of Installation Year	2008 Documented	
Deficiency	No deficiencies recorded	
	Electrical Room 120	
Instance	2- Between Good and Fair	
Instance Condition		
Instance Quantity	1 FACU	
Instance Quantity Uom	EACH	
Manufacturer	Electrotech	
EquipmentId	DBH	
Capacity/Size Quantity	600	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	2008	
Source of Installation Year	Documented No deficiencies recorded	
Deficiency Instance	No deficiencies recorded Electrical Room 120	
	1/141 D 120	

Electrical Inspection		X362
Question	Response	

Question		Response		
SERVICE SWITCH				
Instance Quantity		1		
Instance Quantity Uon	1	EACH		
Manufacturer		Electrotech		
EquipmentId		DBL		
Capacity/Size Quantity	T.	1200		
Capacity/Size UOM		Amps		
Source of Capacity/Siz	ze e	Nameplate		
Installation Year	_	2008		
Source of Installation	Year	Documented		
Deficiency		No deficiencies recorded		
Instance		Electrical Room 120		
Instance Condition		2- Between Good and Fair		
Instance Quantity		1		
Instance Quantity Uon	1	EACH		
Manufacturer		Electrotech		
EquipmentId		HDBH-A		
Capacity/Size Quantity	1	1200		
Capacity/Size UOM		Amps		
Source of Capacity/Siz	de .	Nameplate 2008		
Installation Year Source of Installation	Voor	Documented		
Deficiency	i cai	No deficiencies recorded		
Instance Instance Condition		Electrical Room 120 2- Between Good and Fair		
Instance Quantity		EACH		
Instance Quantity Uon	1			
Manufacturer		Electrotech		
EquipmentId		HDBH-B 2500		
Capacity/Size Quantity Capacity/Size UOM		Amps		
Source of Capacity/Siz	re	Nameplate		
Installation Year		2008		
Source of Installation	Year	Documented		
Deficiency		No deficiencies recorded		
SWITCHBOARD		Inspected		
Number of Spares		24		
Fused Disconnect Switch Type		Inspected		
Instance		Electrical Room 120		
Instance Condition		2- Between Good and Fair		
Instance Quantity		1		
Instance Quantity Uon	1	EACH		
Manufacturer		Electrotech		
EquipmentId		CDB Section 1, 2		
Capacity/Size Quantity	7	800		
Capacity/Size UOM		Amps Total		
Capacity/Size 2 Quant	ity	2		
Capacity/Size 2 UOM		Section(s)		
Source of Capacity/Siz	ze e	Nameplate		
Installation Year	_	2008		
Source of Installation	Year	Documented		
Deficiency		No deficiencies recorded		
Instance		Electrical Room 120		
Instance Condition		2- Between Good and Fair		
Instance Quantity		1		
Instance Quantity Uon	1	EACH		

Building Condition Assessment Survey 2023-2024

ieur inspection		1100
estion	Response	
SWITCHBOARD		
Fused Disconnect Switch Type		
Manufacturer	Electrotech	
EquipmentId	DBH	
Capacity/Size Quantity	1000	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	1	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Nameplate	
Installation Year	2008	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Electrical Room 120	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Electrotech	
EquipmentId	DBL	
Capacity/Size Quantity	1000	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	3	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Nameplate	
Installation Year	2008	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Electrical Room 120	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Electrotech	
EquipmentId	HDBH-A	
Capacity/Size Quantity	1000	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	1	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Nameplate	
Installation Year	2008	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Electrical Room 120	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Electrotech	
EquipmentId	HDBH-B	
Capacity/Size Quantity	1200	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	2	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Nameplate	
Installation Year	2008	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fused Knife Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Does not exist	
FELEPHONE SYSTEM	Inspected	

Electrical Inspection	X362

trical Inspection		X362	
Question	Response		
TELEPHONE SYSTEM			
PBX/Intercom	Inspected		
Condition	3- Fair		
Deficiency	No deficiencies recorded		
Standard	Inspected		
Condition	3- Fair		
Deficiency	No deficiencies recorded		
TRANSFORMER	Inspected		
Instance	Electrical Room		
Instance Condition	2- Between Good and Fair		
Instance Quantity	1		
Instance Quantity Uom	EACH		
Manufacturer	Rex Power Magnetics		
EquipmentId	N/A		
Capacity/Size Quantity	300		
Capacity/Size UOM	kVA		
Source of Capacity/Size	Nameplate		
Installation Year	2008		
Source of Installation Year	Documented		
Deficiency	No deficiencies recorded		
Instance	ATS Room 118		
Instance Condition	2- Between Good and Fair		
Instance Quantity	1		
Instance Quantity Uom	EACH		
Manufacturer	Rex Power Magnetics		
EquipmentId	Fire Alarm Transformer		
Capacity/Size Quantity	30		
Capacity/Size UOM	kVA		
Source of Capacity/Size	Nameplate		
Installation Year	2008		
Source of Installation Year	Documented		
Deficiency	No deficiencies recorded		
Instance	ATS Room 118		
Instance Condition	2- Between Good and Fair		
Instance Quantity	1		
Instance Quantity Uom	EACH		
Manufacturer	Rex Power Magnetics		
EquipmentId	N/A		
Capacity/Size Quantity	150		
Capacity/Size UOM	kVA		
Source of Capacity/Size	Nameplate		
Installation Year	2008		
Source of Installation Year	Documented		
Deficiency	No deficiencies recorded		
Instance	Electrical Room 120		
Instance Condition	2- Between Good and Fair		
Instance Quantity	1		
Instance Quantity Uom	EACH		
Manufacturer	Rex Power Magnetics		
EquipmentId	N/A		
Capacity/Size Quantity	750		
Capacity/Size UOM	kVA		
Source of Capacity/Size	Nameplate		
Installation Year	2008		
Source of Installation Year	Documented		

Building Condition Assessment Survey 2023-2024

Electrical Inspection X362

tion		Response
ANSFO	DRMER	
	Deficiency	No deficiencies recorded
	Instance	Electrical Room 120
	Instance Condition	2- Between Good and Fair
	Instance Quantity	1
	Instance Quantity Uom	EACH
	Manufacturer	Rex Power Magnetics
	EquipmentId	N/A
	Capacity/Size Quantity	45
	Capacity/Size UOM	kVA
	Source of Capacity/Size	Nameplate
	Installation Year	2008
	Source of Installation Year	Documented
	Deficiency	No deficiencies recorded
	Instance	Elevator Machine Room 121
	Instance Condition	2- Between Good and Fair
	Instance Quantity	1
	Instance Quantity Uom	EACH
	Manufacturer	Rex Power Magnetics
	EquipmentId	N/A
	Capacity/Size Quantity	113
	Capacity/Size UOM	kVA
	Source of Capacity/Size	Nameplate
	Installation Year	2008
	Source of Installation Year	Documented
	Deficiency	No deficiencies recorded
	Instance	Penthouse - Mechanical Room
	Instance Condition	2- Between Good and Fair
	Instance Quantity	1
	Instance Quantity Uom	EACH
	Manufacturer	Rex Power Magnetics
	EquipmentId	N/A
	Capacity/Size Quantity	300
	Capacity/Size UOM	kVA
	Source of Capacity/Size	Nameplate
	Installation Year	2008
	Source of Installation Year	Documented
	Deficiency	No deficiencies recorded