Building Condition Assessment Survey 2023-2024

Architectural Inspection X387

Asset:	PRE-K CENTER @ 5500 BROADWAY - BRONX, 5500 BROADWAY, BRONX, NY, 10463					
Inspection Id	Inspection Type	Time In	Last Edited			
3638	ARCHITECTURAL - SENIOR	2024-03-01 08:58AM	2024-04-08 07:25PM			
3652	ARCHITECTURAL - ASSOCIATE	2024-03-01 12:42PM	2024-04-07 04:33PM			
Isset Data			·			

As

Set Data Question		Answer		
Was the Building Fully Accessibl	e for Inspection?	Yes		
Principal(s) Information				
	Principal Name	Jacqueline Baker		
	Principal Organization	Pre - K Center @ 5500 Broadway - Bronx		
	Meeting with Principal?	Yes		
	Principal Feedback	The Principal had no comments about the condition of the building at this time.		
Custodian		Christopher Worrell		
Was the Custodian Present?		Yes		
Fireman		Robert Cantine		
Was the Fireman Present?		No		
Building Square Footage		6,000		
Comments on the Area (for Athle	tic Field, Playing Surfaces, Leased Spaces)	None		
Comments on the Stories (Floors)) plus Basements	2+B (Leased part of 1st Floor)		
Comments on the Year Built		1921		
Student Population		44		
Staff Population		9		
Comments on the Number of Cla	ssrooms	3		

Comments on the Number of Classrooms Weather

Facade Photo



Corner of Broadway and West 230th Street - South View

Building Condition Assessment Survey 2023-2024

Architectural Inspection

Main Entrance Photo

X387



Facade A - West 230th Street

Not taken

No

No Storm Water Management Type Selected

Systems: Complete interior renovation of the leased space

occupying a portion of the 1st Floor.

Years: 2017

Systems: Complete interior renovation of the leased space

occupying a portion of the 1st Floor.

Years: 2017 No New Construction

No Tandem Yes

2016

Partial Inspection

Priority Condition

Leased Space?

Year Leased

Inspection Type

Tandem

Roof Photo

Do Stormwater Management/Green Infrastructure systems exist?

Have any Systems/Major Building Components been upgraded?

Have there been any New Building Additions?

Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
Yes	Broken Glass	Broken panes of interior glass located at a low height in pre-k classrooms are a safety hazard.	Windows	Classrooms 104, 107 and 110	Robert Cantine	Fireman	

Structural Engineer Required

Structural	Condition	Component	Location	Person(s)	Person(s)	Photo
Condition Type	Description	Affected	Description	Notified	Title	Image

No condition recorded

Programmatic Accessibility

Programmatic Accessibility Status Question	Response
Is the Primary or secondary entrance on an accessible route?	Yes
Is the building a multi-story building?	No
Do any of the following spaces exist? Classroom, Art Room, Auditorium, Cafeteria,	Yes
Computer, Gymnasiums, Library, Multipurpose Room, Science Labs	
For the spaces that do exist, are they ALL accessible?	Yes
Is there at least one Boys and Girls or Unisex toilet accessible In the building?	Yes

					System	Strobe
Physical Breakdown Structure	Exists	Complies	Required	Deficiency	Listening	Alarm
					Assistive	Fire

PROGRAMMATIC ACCESSIBILITY

Exterior Routes

Building Condition Assessment Survey 2023-2024

Architectural Inspection X387


hysical Breakdown Structure	Exists	Complies	Required	Deficiency	Assistive Listening System	Fire Alarm Strobe
Exterior Entrances & Exits		Yes			System	50.000
Exterior H/C Lifts	No		No			
Exterior Ramps and Railings	No		No			
Interior Routes						
Corridor and Lobby H/C Lifts	No		No			
Interior Corridor Doors And Hardware	Yes	Yes				
Interior Corridors & Lobbies		Yes				
Interior Elevators	No					
Interior Lobby Doors And Hardware		Yes				
Interior Ramps	Yes	Yes				
Rooms & Spaces						
Art Rooms	No					
Auditorium	No					
Cafeteria	No					
Classrooms 1st Floor	37					
	Yes	Yes				
Computer Rooms	No					
Gymnasium	No					
Library	No					
Main Office						
Room 105	Yes	Yes				
Multi-purpose Room						
1st Floor	Yes	Yes			No	Yes
Nurse's Office						
1st Floor	Yes	Yes				
Pool	No					
Science Lab	No					
Toilet Rooms (boys)						
1st Floor - (Unisex inside Classroom)	Yes	Yes				
Toilet Rooms (girls)						
1st Floor - (Unisex inside Classroom)	Yes	Yes				
Toilet Rooms (staff)						
1st Floor	Yes	Yes				

Building Condition Assessment Survey 2023-2024

Architectural Inspection

X387

Building Template



pection	
Question	Response
Architectural	
EXTERIOR	Inspected
AREAWAY	Does not exist
AWNINGS AND CANOPIES	Does not exist
CHIMNEY	Does not exist
COPING	Not required
CORNICE	Does not exist
DOORS	Inspected
DOORS AND FRAMES	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
DOOR HARDWARE	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
LINTELS	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
TRANSOM/SIDE LIGHT	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EXTERIOR WALLS	Inspected
Material Type(s)	Masonry
Replacement Quantity	3,000
Replacement Uom	S.F.
Instance on All Facades	Inspected
Instance Condition	3- Fair
Instance Quantity	3,000
Instance Quantity Uom	S.F.
Deficiency	BRICK:DETERIORATED JOINTS

Building Condition Assessment Survey 2023-2024

Architectural Inspection X387 Question Response **EXTERIOR** EXTERIOR WALLS Roof Plan Reference Elevation Elevation Reference Facade A and B Deficiency Quantity Quantity Uom S.F. Potential Action REPOINT PRIORITY 3 Urgency of Action Purpose of Action LEVEL 2 Deficiency Photo 1 Facade B Deficiency Photo 2 No photo recorded Violations No violations recorded Deficiency BRICK: DETERIORATED MASONRY SILLS - MINOR Roof Plan Reference Elevation Elevation Reference Facade A Deficiency Quantity 12 Quantity Uom L.F. Potential Action REPAIR

PRIORITY 3

LEVEL 2

Urgency of Action

Purpose of Action

Building Condition Assessment Survey 2023-2024

Architectural Inspection X387

Question EXTERIOR

EXTERIOR WALLS

Deficiency Photo 1



Response

	Facade A and B
Deficiency Photo 2	No photo recorded
Violations	No violations recorded
EXTERIOR SOFFITS	Does not exist
LOADING DOCK	Does not exist
LOUVER	Does not exist
PARAPETS	Not required
PLAZA DECK	Does not exist
ROOF	Inspected
ROOFING	Inspected
ROOF HATCH/SMOKE HATCH	Does not exist
LEADERS, GUTTERS, DOWNSPOUTS, SCUPPERS	Not required
ROOF BARRIER/FENCE	Does not exist
ROOF CAGE	Does not exist
ROOFING	Not required
ROOFING DRAINS	Not required
SPECIALTIES	Inspected
BULKHEAD/PENTHOUSE	Not required
CUPOLA/ SPIRES/ TOWERS	Does not exist
DORMER	Does not exist
DUNNAGE STEEL	Not required
SKYLIGHT/ROOF VENT	Does not exist
ROOF/GRAVITY TANK	Does not exist
STAIRS/RAMPS: EXTERIOR	Inspected
BUILDING CHEEK/FLANK WALLS	Does not exist
RAILINGS	Does not exist
STAIRS/RAMPS	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
WINDOWS	Inspected
Replacement Quantity	200
Replacement Uom	S.F.
EXTERIOR GUARDS	Does not exist
LINTELS	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
WINDOWS	Inspected
Material Type(s)	Aluminum
Instance on Aluminum - Other:Facade A and B	Inspected
Instance Condition	1- Good
Instance Quantity	200
Instance Quantity Instance Quantity Uom	S.F.
Installation Year	2016
Source of Installation Year	Custodial Staff
Are these windows insulated?	Yes
diese masmo monarea.	

Building Condition Assessment Survey 2023-2024

ectural Inspection			
estion	Response		
EXTERIOR			
WINDOWS			
WINDOWS			
Deficiency	ALUMINUM - OTHER:BROKEN PANE		
Roof Plan Reference	X387 B O D A Exterior Street		
Elevation			
Elevation Reference	Facade A and B		
Deficiency Quantity	15		
Quantity Uom	S.F.		
Potential Action	MAINTENANCE		
Urgency of Action	PRIORITY 5		
Purpose of Action	LEVEL 6		
Deficiency Photo 1			
	Classroom 104 shown, also Rooms 107 and 110 similar		
Deficiency Photo 2	No photo recorded		
Violations	No violations recorded		
NTERIOR	Inspected		
POOLS	Does not exist		
STRUCTURAL	Inspected		
COLUMNS/BEAMS/BEARING WALLS	Inspected		
Condition	2- Between Good and Fair		
Deficiency	No deficiencies recorded		
FLOOR STRUCTURE	Inspected		
Condition	2- Between Good and Fair		
Deficiency	No deficiencies recorded		
FOUNDATION WALLS	Inaccessible		
DOOF CTDUCTURE	Inaccessible		
ROOF STRUCTURE	N-4 4		
VAULTS-BUNKERS	Not required		
	Does not exist		
VAULTS-BUNKERS AUDITORIUM CAFETERIA	Does not exist Does not exist		
VAULTS-BUNKERS AUDITORIUM CAFETERIA CLASSROOMS/CORRIDORS/ADMIN SPACES	Does not exist Does not exist Inspected		
VAULTS-BUNKERS AUDITORIUM CAFETERIA CLASSROOMS/CORRIDORS/ADMIN SPACES Ceiling	Does not exist Does not exist Inspected Inspected		
VAULTS-BUNKERS AUDITORIUM CAFETERIA CLASSROOMS/CORRIDORS/ADMIN SPACES Ceiling Condition	Does not exist Does not exist Inspected Inspected 2- Between Good and Fair		
VAULTS-BUNKERS AUDITORIUM CAFETERIA CLASSROOMS/CORRIDORS/ADMIN SPACES Ceiling	Does not exist Does not exist Inspected Inspected		

2- Between Good and Fair

No deficiencies recorded

 $\frac{\textbf{Door(s)}}{\text{Condition}}$

Deficiency

Building Condition Assessment Survey 2023-2024

estion	Response	
NTERIOR		
CLASSROOMS/CORRIDORS/ADMIN SPACES		
Floor Finish	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Walls	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Specialties	Does not exist	
GYMNASIUM	Does not exist	
INTERIOR DOOR HARDWARE	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
INTERIOR GUARDS	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
Ceiling		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
	no deficieles recolded	
Door(s) Instance on 1st Floor	Increated	
	Inspected 2- Between Good and Fair	
Instance Condition	No deficiencies recorded	
Deficiency	No deficiencies recorded	
Floor Finish		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Walls		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
LIBRARY	Does not exist	
LOCKER ROOM	Does not exist	
MULTI-PURPOSE ROOM	Inspected	
Instance on 1st Floor	Inspected	
Ceiling		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Door(s)		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fixed Equipment		
Instance on 1st Floor	Does not exist	
Floor Finish		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
	ino deliciencies recorded	
Sliding-folding Partition		

Building Condition Assessment Survey 2023-2024

nitectural Inspection	X38
Question	Response
INTERIOR	
MULTI-PURPOSE ROOM	
Stage	
Instance on 1st Floor	Does not exist
Walls	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Window Curtains/Shades/Blinds	
Instance on 1st Floor	Does not exist
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Does not exist
SCIENCE PREP ROOM	Does not exist
SHOWER ROOM	Does not exist
STAIRS/RAMPS: INTERIOR	Inspected
Do Letter Stair Signs Exist?	Yes
Ceiling	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Door(s)	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Partition	Does not exist
Railings	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Stairs and Landings	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Walls	Inspected
Condition	2 Retween Good and Fair

Building Condition Assessment Survey 2023-2024

Question	Response
INTERIOR	
TOILET ROOMS - STUDENTS	
Floor Finish	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Stalls	Does not exist
Walls	Inspected
Condition	
	2- Between Good and Fair
Deficiency	No deficiencies recorded
LIFE SAFETY	Inspected
F.D. HOLDING AREA	Does not exist
STEEL STAIRS	Does not exist
SITE	Inspected
CONTAINERIZATION	Does not exist
DRAINAGE SYSTEM FOR ASPHALT	Does not exist
DRAINAGE SYSTEM FOR CONCRETE	Does not exist
DRAINAGE SYSTEM FOR SOIL	Does not exist
DRINKING FOUNTAINS	Does not exist
FENCES	Does not exist
IRRIGATION SYSTEM	Does not exist
PAVING	Inspected
Student Non-Use	Does not exist
Student Use	Does not exist
Site Sidewalks & Walkways	Does not exist
DOT Sidewalk	Inspected
Asphalt	Does not exist
Concrete	Inspected
Condition	3- Fair
Deficiency	DAMAGED/DETERIORATED/MISSING SECTIONS
Deficiency Location/Instance	West 230th Street, Exterior Street
Deficiency Quantity	350
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo 1	West 230th Street
	West 230th Street
Deficiency Photo 2	No photo recorded
Violations	No violations recorded

Deficiency Photo 2	No photo recorded
Violations	No violations recorded
Pavers	Does not exist
PLAYGROUNDS	Does not exist
PLAYING SURFACE	Does not exist
RETAINING WALLS	Does not exist
SEATING	Does not exist
SITE WALLS (NOT RETAINING WALLS)	Does not exist
STAIRS/RAMPS: EXTERIOR	Does not exist

NYC Department of Education Building Condition Assessment Survey 2023-2024

Architectural Inspection X387

Does the SCA expect asset to have artwork?

No