Building Condition Assessment Survey 2023-2024

Electrical Inspection	X392
-----------------------	------

	Asset:	THE CASITA MARIA CENTER FOR ARTS AND EDUCATION - BRONA, 928 SIMPSON STREET, BRONA,		
		NY, 10459		
	Inspection Id	Inspection Type	Time In	Last Edited
	4072	ELECTRICAL	2024-03-19 07:52AM	2024-05-22 02:31PM
c	ot Data			

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Intrusion Alarm System (Panic Switches), Fire Alar System (Partial Smoke Detector)
	Years: 2023
	Systems: Gymnasium - LED Lighting
	Years: 2022
	Systems: LED Lighting, Security Lighting
	Years: 2021
	Systems: All Other Electrical Systems and Components
	Years: 2009
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes

Water Penetration In Electrical Room?

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

DEDICATED INTERCOMS IN TIRE RESCUE AREAS	
Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in	Yes
your building?	
Are dedicated intercoms available in all of these spaces for use during a fire?	Yes
Are all dedicated intercoms operational?	Yes

No

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
Yes	Fire Alarm System - Not Connected to Central Station	N/A	Fire Alarm System - Digital Communicator	Room 112 (Inside Room 106)	Daniel Peña	Fireman	No Photo Taken
No	Water Leaks onto Electrical Equipment	Water Dripping from above slab to Ceiling damaging Light Fixture	Lighting Fixture	Weight Room Inside Gymnasium	Daniel Peña	Fireman	Light Late

Inspection

estion	Response	
etrical		
THLETIC FIELD	Does not exist	
UDITORIUM	Does not exist	
AFETERIA	Inspected	
Instance on Basement	Inspected	
Lighting		
Instance on Basement	Inspected	
Lighting Fixture - Fluorescent		
Instance on Basement	Inspected	
Pendant Mounted		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Basement	Does not exist	

Building Condition Assessment Survey 2023-2024

neu Inspection		ASI
Question	Response	
CAFETERIA		
Lighting		
Lighting Fixture - Fluorescent		
Recessed Mounted		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on Basement	Does not exist	
Lighting Fixture - Incandescent		
Instance on Basement	Does not exist	
Lighting Fixture - LED		
Instance on Basement	Does not exist	
Local Sound System	Does not exist	
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Installation Year	2009	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System	To deficiencies recorded	
Instance on Basement	Does not exist	
	Does not exist	
Theater Lighting System Instance on Basement	Does not exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting Deve of Chemistry Francists	Inspected	
Does a Chandelier Exist?	No Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected 3- Fair	
Condition		
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Does not exist	
Recessed Mounted	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
COMPUTER LAB	Does not exist	
GYMNASIUM	Inspected	
	-	
Instance on 1st Floor	Inspected	
Lighting	Inches 1	
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		

Building Condition Assessment Survey 2023-2024

	710
Response	
Inspected	
3- Fair	
No deficiencies recorded	
Does not exist	
Does not exist	
Does not exist	
Inspected	
•	
Inspected	
1- Good	
No deficiencies recorded	
1.0 40110101010100	
Does not exist	
Ingnastad	
Tto deficiences recorded	
Increated	
No deficiencies recorded	
Inchested	
No deficiencies recorded	
Y 1	
Inspected	
No deficiencies recorded	
3- Fair	
No deficiencies recorded	
Inspected	
Inspected	
	Inspected 3 - Fair No deficiencies recorded Does not exist Does not exist Inspected Inspected Inspected 1 - Good No deficiencies recorded Does not exist Does not exist Inspected 3 - Fair 2009 Documented No deficiencies recorded Inspected 3 - Fair Ceiling No deficiencies recorded Inspected 3 - Fair No deficiencies recorded Inspected 3 - Fair No deficiencies recorded

Building Condition Assessment Survey 2023-2024

iricai Inspection		ASJE
Question	Response	
KITCHEN		
Lighting		
Lighting Fixture - Fluorescent		
Pendant Mounted		
Instance on Basement	Does not exist	
Surface Mounted		
Instance on Basement	Does not exist	
Recessed Mounted		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on Basement	Does not exist	
Lighting Fixture - Incandescent		
Instance on Basement	Does not exist	
Lighting Fixture - LED		
Instance on Basement	Does not exist	
LIBRARY	Inspected	
Instance on Room 314	Inspected	
Lighting		
Instance on Room 314	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 314	Inspected	
Pendant Mounted		
Instance on Room 314	Does not exist	
Surface Mounted		
Instance on Room 314	Does not exist	
Recessed Mounted		
Instance on Room 314	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on Room 314	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 314	Does not exist	
Lighting Fixture - LED		
Instance on Room 314	Does not exist	
Raceway With Receptacles		
Instance on Room 314	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Room 314	Does not exist	
LOCKER ROOM	Inspected	
Instance on 1st Floor - Boys	Inaccessible	
Instance on 1st Floor - Girls	Inaccessible	
MULTIPURPOSE ROOM	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Inspected	
Instance on Rooms 401, 501	Inspected	
Power Panel?	Yes	
Alternative Use	No	
American ve Obe	INU	

Building Condition Assessment Survey 2023-2024

Electrical Inspection X	392	2
-------------------------	-----	---

estion	Response	
CIENCE LAB		
Power Panel?	Yes	
Alternative Use	No	
Lighting	110	
Instance on Rooms 401, 501	Inspected	
Instance on Room 505-1	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Instance on Rooms 401, 501	Inspected	
Instance on Room 505-1	Inspected	
Pendant Mounted	Inspected	
	Does not exist	
Instance on Rooms 401, 501 Instance on Room 505-1	Does not exist	
-	Does not exist	
Surface Mounted	D	
Instance on Rooms 401, 501 Instance on Room 505-1	Does not exist	
	Does not exist	
Recessed Mounted	Y 1	
Instance on Rooms 401, 501	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 505-1	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on Rooms 401, 501	Does not exist	
Instance on Room 505-1	Does not exist	
Lighting Fixture - Incandescent		
Instance on Rooms 401, 501	Does not exist	
Instance on Room 505-1	Does not exist	
Lighting Fixture - LED		
Instance on Rooms 401, 501	Does not exist	
Instance on Room 505-1	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Rooms 401, 501	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 505-1	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power		
Instance on Rooms 401, 501	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 505-1	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Power Supply		
Instance on Rooms 401, 501	Inspected	
Instance on Room 505-1	Inspected	
Instructor Unit	•	
Instance on Rooms 401, 501	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 505-1	Inspected	

Building Condition Assessment Survey 2023-2024

Electrical Inspection		392
0	D	

icai Inspection		
uestion	Response	
SCIENCE LAB		
Power Supply		
Instructor Unit		
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Meter Demonstration Unit		
Instance on Rooms 401, 501	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 505-1	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Student Unit		
Instance on Rooms 401, 501	Does not exist	
Instance on Room 505-1	Does not exist	
Projection System		
Instance on Rooms 401, 501	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 505-1	Does not exist	
SCIENCE PREP ROOM	Inspected	
Instance on Room 403, 503	Inspected	
Power Panel?	No	
Alternative Use		
	Yes	
Lighting Instance on Room 403, 503	Inspected	
Lighting Fixture - Fluorescent	nispected	
Instance on Room 403, 503	Inspected	
Pendant Mounted	nispected	
Instance on Room 403, 503	Does not exist	
Surface Mounted	DOCS HOT CAIST	
	Does not exist	
Instance on Room 403, 503	Does not exist	
Recessed Mounted	Towns and d	
Instance on Room 403, 503	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on Room 403, 503	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 403, 503	Does not exist	
Lighting Fixture - LED		
Instance on Room 403, 503	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Room 403, 503	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power		
Instance on Room 403, 503	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Power Supply		
Instance on Room 403, 503	Does not exist	

Building Condition Assessment Survey 2023-2024

rical Inspection		X392
Question	Response	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	
EMERGENCY GENERATOR SET	Does not exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not exist	
EMERGENCY LIGHTING	Inspected	
Battery Pack	Does not exist Inspected	
Non Battery Pack Condition	3- Fair	
Deficiency	No deficiencies recorded	
· · · · · · · · · · · · · · · · · · ·		
EXIT LIGHT	Inspected	
Battery Pack Condition	Inspected 3- Fair	
Deficiency	No deficiencies recorded	
· 	Does not exist	
Non Battery Pack	Does not exist Does not exist	
EXIT/EMERGENCY LIGHT		
FIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Manual Pull Station Condition	Inspected 2- Between Good and Fair	

Building Condition Assessment Survey 2023-2024

icai Inspection	ASS
uestion	Response
FIRE ALARM SYSTEM	
Fan Shutdown Control	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
CO Detector	Does not exist
Heat Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Elevator Recall	Does not exist
	Does not exist
Magnetic Door Holder/Contactor Fused Cutout Panel	Inspected
Condition Condition	2- Between Good and Fair
	No deficiencies recorded
Deficiency	
Fire Alarm Digital Communicator	Inspected 110 G 111 P 100
Instance	Room 112 (Inside Room 106)
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Silent Knight
EquipmentId	N/A
Installation Year	2009
Source of Installation Year	Documented
Deficiency	NOT CONNECTED TO CENTRAL STATION
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL CONNECTION
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Main Panel	Does not exist
Sub-Panel Sub-Panel	Does not exist
Remote Annunciator	Inspected
Display Monitor	Does not exist
Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Printer	Does not exist
Punch Register	Does not exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Does not exist
NTERCOM SYSTEM	Does not exist
AN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	3- Fair

Building Condition Assessment Survey 2023-2024

neui Inspection		ASJE
Question	Response	
LAN		
Local Distribution Frame (I/LDF)		
Deficiency	No deficiencies recorded	
Main Equipment Rack (MDF)	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
LIGHTNING PROTECTION	Does not exist	
MOTOR CONTROLLER	Inspected	
MOTOR CONTROL CENTER	Does not exist	
MOTOR STARTER/CONTACTOR	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Variable Frequency Drive	Does not exist	
PANEL BOARD	Inspected	
Fused Disconnect Switch Type	Does not exist	
Fused Knife Switch Type	Does not exist	
Fused Toggle Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
PUBLIC ADDRESS SYSTEM	Inspected	
Instance	MDF Room 201-2	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Telecor 250	
Installation Year	2009	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
SECURITY	Inspected	
IPDVS/CCTV System	Inspected	
Condition	3- Fair	
Installation Year	2009	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Intrusion Alarm System	Inspected	
Central Control Panel	Inspected	
Instance	Custodian's Office - Room B15	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Vista - 128B	
Installation Year	2009	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Infrared Sensor	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Panic Switch	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Remote Annunciator	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	

Building Condition Assessment Survey 2023-2024

Question	Response	
SECURITY		
Intrusion Alarm System		
Siren/Strobe	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting - Security	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
SERVICE SWITCH	Does not exist	
SWITCHBOARD	Does not exist	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
TRANSFORMER	Does not exist	