Building Condition Assessment Survey 2023-2024

Electrical Inspection

Asset:	WALTON HS - BRONX, 2780 RESERVOIR AVENUE	, BRONX, NY, 10468		
Inspection Id	Inspection Type		Time In	Last Edited
4990	ELECTRICAL		2024-04-25 09:24AM	2024-06-17 10:54AM
Asset Data				
Question		Answer		
Have any Syste	ms/Major Building Components been upgraded?	Systems:	Fire Alarm System (Partial Manu	ual Pull Station).
		Years:	2023	
		Systems:	Gymnasium 1 Scoreboard	
		Years:	2022	

	rears.	2022
	Systems:	Molded Case Circuit Breaker Type Panel Board
	Years:	2021, 2020, 2009, 2008, 2005, 2004, 1996
	Systems:	LAN
	Years:	2021
	Systems:	Emergency Generator Set (Battery Charger).
	Years:	2019
	Systems:	Security Lights
	Years:	2018, 1996
	Systems:	IPDVS/CCTV System, Telephone System, Intrusion Alarm System (Central Control Panel, Infrared Sensor, Partial Remote Annunciator)
	Years:	2018
	Systems:	Partial Intercom System (Elevator), Fire Alarm System (Sprinkler Flow/ Air Pressure Switch)
	Years:	2017
	Systems:	Swimming Pool, Exit Lights (Battery Pack), Exit/Emergency Lights
	Years:	2011
	Systems:	Science Lab - Room 231, Science Prep Room 231A
	Years:	2010
	Systems:	Public Address System, Local Sound System, Auditorium (Theater Lighting System)
	Years:	2009
	Systems:	Intrusion Alarm System (Except Central Control Panel, Infrared Sensor, Partial Remote Annunciator).
	Years:	2005
	Systems:	Fire Alarm System.
	Years:	1999
	Systems:	Service Switch, Switchboard, Emergency Generator Set, Motor Starters
	Years:	1996
Type of Service	Below Gr	ound
Does Interactive Whiteboard (IWB) Exist?	Yes	
Vater Penetration In Electrical Room?	No	
DEDICATED INTERCOMS IN FIRE RESCUE AREAS		
Question]	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?		Yes
Are dedicated intercoms available in all of these spaces for use during a fire?		Yes
A 11 1 1 4 1 4 1 4 1 1 4 1 1 4 1 1 4 1		

Priority Condition

Are all dedicated intercoms operational?

Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
No	Water Leaks onto Electrical Equipment	N/A	Area Smoke Detector, Public Address System - Speaker	Cafeteria	Pedro Batista	Fireman	No Photo Taken

Yes

Building Condition Assessment Survey 2023-2024

Electrical Inspection

inca	a inspection							A4J
	Fire Alarm System - Defective	N/A	Fire Alarm System - Sub Panel	Auditorium Stage	Pedro Batista	Fireman	No Photo Taken	
	Exposed Electrical Wires	N/A	Raceway With Receptacles	Computer Lab Room 348 A/B	Pedro Batista	Fireman	No Photo Taken	
	Other	Not Operational	Emergency Gas Shut-Off Valve, Emergency Shut-Off Power	Science Lab Room 378	Pedro Batista	Fireman	No Photo Taken	
pecti	on							
Questi	ion			Response				
Electri	ical			-				
ATH	ILETIC FIELD			Does not e	exist			
	DITORIUM			Inspected				
neb	Instance on 1st Floor			Inspected				
Ho	ouse Lighting			moperied				
110	Instance on 1st Floor			Under con	struction			
Lo	ocal Sound System							
	Instance on 1st Floor			Inspected				
	Instance Condition			3- Fair				
	Installation Year			2009				
	Source of Installation	Year		Document				
	Deficiency			No deficie	encies recorde	d		
Pro	ojectio <u>n System</u>							
	Instance on 1st Floor			Does not e	exist			
Th	neater Lighting System			T . 1				
_	Instance on 1st Floor			Inspected				
Ľ	Dimming System			T . 1				
	Instance on 1st Floor			Inspected				
	Instance Condition			3- Fair				
_	Deficiency			No deficie	ncies recorde	d		
Т	Theater Lighting							
	Instance on 1st Floor			Inspected				
	Instance Condition			3- Fair				
	Deficiency				encies recorde	d		
CAF	FETERIA			Inspected				
	Instance on Basement			Inspected				
Lig	ghting							
-	Instance on Basement			Under con	struction			
Lo	ocal So <u>und System</u>			T				
	Instance on Basement			Inspected 3- Fair				
	Instance Condition Installation Year			2009				
	Source of Installation	Year		2009 Document	ed			
	Deficiency				encies recorde	d		
Pro	ojection System							
	Instance on Basement			Inspected				
	Instance Condition			3- Fair				
		art or installed on the ceiling?		Ceiling				
	Deficiency				ncies recorde	d		
ТЬ	neater Lighting System							
1.0								
11	Instance on Basement	;		Does not e	exist			

Building Condition Assessment Survey 2023-2024

Electrical Inspection

		А43
estion	Response	
LASSROOM/CORRIDOR/ADMINISTRATIVE SPACE		
Lighting	Under construction	
OMPUTER LAB	Inspected	
Instance on Room 348A/B	Inspected	
Power Panel?	No	
Instance on Rooms 139	Inspected	
Power Panel?	No	
Lighting		
Instance on Room 348A/B	Under construction	
Instance on Rooms 139	Under construction	
Raceway With Receptacles		
Instance on Room 348A/B	Inspected	
Instance Condition	3- Fair	
Deficiency	RECEPTACLES NOT OPERATIONAL	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance on Rooms 139	Does not exist	
YMNASIUM	Inspected	
Instance on 1st Floor - Gymnasium 1	Inspected	
Instance on 1st Floor - Gymnasium 2, 1st Floor - Gymnasium 3	Inspected	
Lighting	The day as we take the set	
Instance on 1st Floor - Gymnasium 1	Under construction	
Instance on 1st Floor - Gymnasium 2, 1st Floor - Gymnasium 3	Under construction	
Local Sound System	×	
Instance on 1st Floor - Gymnasium 1	Inspected	
Instance Condition	3- Fair	
Installation Year	2009	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance on 1st Floor - Gymnasium 2, 1st Floor - Gymnasium 3	Inspected	
Instance Condition	3- Fair	
Installation Year	2009	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 1st Floor - Gymnasium 1	Does not exist	
Instance on 1st Floor - Gymnasium 2, 1st Floor - Gymnasium 3	Does not exist	
Scoreboard		
Instance on 1st Floor - Gymnasium 1	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Instance on 1st Floor - Gymnasium 2, 1st Floor - Gymnasium 3	Does not exist	
Theater Lighting System		
Instance on 1st Floor - Gymnasium 1	Does not exist	
Instance on 1st Floor - Gymnasium 2, 1st Floor - Gymnasium 3	Does not exist	
ITCHEN	Inspected	
Instance on Basement	Inspected	
	mspeccu	
Lighting Instance on Basement	Under construction	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

rical Inspection	X43(
uestion	Response
LIBRARY	
Instance on 1st Floor	Under construction
LOCKER ROOM	Inspected
Instance on Basement - Boys, Basement - Girls	Inspected
Alternative Use	No
Instance on Basement - Visitors	Inspected
Alternative Use	Yes
Instance on Basement Pool - Boys, Basement Poo	I - Girls Inspected
Alternative Use	No
Lighting	
Instance on Basement - Boys, Basement - Girls	Under construction
Instance on Basement - Visitors	Under construction
Instance on Basement Pool - Boys, Basement Poo	I - Girls Under construction
MULTIPURPOSE ROOM	Does not exist
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Inspected
Instance on Room 178	Inspected
Power Panel?	
Alternative Use	No
	No
Instance on Room 218, 231	Inspected
Power Panel?	Yes
Alternative Use	No
Instance on Room 327	Inspected
Power Panel?	No
Alternative Use	No
Instance on Room 378	Inspected
Power Panel?	Yes
Alternative Use	No
Instance on Room 386	Inspected
Power Panel?	Yes
Alternative Use	No
Instance on Room 182, 379	Inspected
Power Panel?	Yes
Alternative Use	No
Lighting	
Instance on Room 178	Under construction
Instance on Room 218, 231	Under construction
Instance on Room 327	Under construction
Instance on Room 378	Under construction
Instance on Room 386	Under construction
Instance on Room 182, 379	Under construction
Emergency Gas Shut-Off Valve	
Instance on Room 178	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 218, 231	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 327	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 378	Inspected

Building Condition Assessment Survey 2023-2024

Electrical Inspection

estion		Response
	CE LAB	1
	gency Gas Shut-Off Valve	
	Instance Condition	4- Between Fair and Poor
	Deficiency	NOT OPERATIONAL
	Deficiency Quantity	1
	Quantity Uom	EACH
	Potential Action	REPLACE
	Urgency of Action	PRIORITY 5
	Purpose of Action	LEVEL 6
	Violations	No violations recorded
	Instance on Room 386	Inspected
	Instance Condition	3- Fair
	Deficiency	No deficiencies recorded
	Instance on Room 182, 379	Inspected
	Instance Condition	3- Fair
	Deficiency	No deficiencies recorded
Emerg	gency Shut-Off Power	
	Instance on Room 178	Inspected
	Instance Condition	3- Fair
	Deficiency	No deficiencies recorded
	Instance on Room 218, 231	Inspected
	Instance Condition	3- Fair
	Deficiency	No deficiencies recorded
	Instance on Room 327	Does not exist
	Instance on Room 378	Inspected
	Instance Condition	4- Between Fair and Poor
	Deficiency	NOT OPERATIONAL
	Deficiency Quantity	1
	Quantity Uom	EACH
	Potential Action	REPLACE
	Urgency of Action Purpose of Action	PRIORITY 5 LEVEL 6
	Violations	No violations recorded
	Instance on Room 386	
		Inspected 3- Fair
	Instance Condition	
	Deficiency	No deficiencies recorded
	Instance on Room 182, 379	Inspected 3- Fair
	Instance Condition	
	Deficiency	No deficiencies recorded
Power	Supply Instance on Room 178	Does not exist
	Instance on Room 218, 231	Inspected
	Instance on Room 327	Does not exist
	Instance on Room 378	Inspected
	Instance on Room 386	Does not exist
	Instance on Room 182, 379	Inspected
Insti	ructor Unit	To prove the d
	Instance on Room 218, 231	Inspected
	Instance Condition	3- Fair
	Deficiency	No deficiencies recorded
	Instance on Room 378	Inspected
	Instance Condition	3- Fair
	Deficiency	No deficiencies recorded
	Instance on Room 182, 379	Inspected

Building Condition Assessment Survey 2023-2024

Electrical Inspection

estion		Response	
CIENCE LAP	3		
Power Supply	7		
Instructor U			
Insta	nce Condition	3- Fair	
Defie	ciency	No deficiencies recorded	
Meter Dem	onstration Unit		
Insta	nce on Room 218, 231	Inspected	
Insta	nce Condition	3- Fair	
Defie	ciency	No deficiencies recorded	
Insta	nce on Room 378	Inspected	
Insta	nce Condition	3- Fair	
Defie	ciency	No deficiencies recorded	
	nce on Room 182, 379	Inspected	
	nce Condition	3- Fair	
Defie	ciency	No deficiencies recorded	
Student Uni			
Insta	nce on Room 218, 231	Does not exist	
	nce on Room 378	Does not exist	
Insta	nce on Room 182, 379	Does not exist	
Projection Sy			
	nce on Room 178	Does not exist	
Insta	nce on Room 218, 231	Inspected	
Insta	nce Condition	3- Fair	
	ciency	No deficiencies recorded	
	nce on Room 327	Does not exist	
Insta	nce on Room 378	Does not exist	
Insta	nce on Room 386	Does not exist	
Insta	nce on Room 182, 379	Does not exist	
CIENCE PRE		Inspected	
	nce on Room 231A	Inspected	
	er Panel?	Yes	
	native Use	No	
	nce on Room 186, 385	Inspected	
	er Panel?	No	
	native Use	No	
Lighting		INO	
	nce on Room 231A	Under construction	
	nce on Room 186, 385	Under construction	
	as Shut-Off Valve		
	nce on Room 231A	Inspected	
	nce Condition	3- Fair	
	ciency	No deficiencies recorded	
	nce on Room 186, 385	Inspected	
	nce Condition	3- Fair	
	ziency	No deficiencies recorded	
	hut-Off Power		
	nce on Room 231A	Inspected	
	nce Condition	3- Fair	
	ziency	No deficiencies recorded	
	nce on Room 186, 385	Inspected	
	nce Condition	3- Fair	
	ziency	No deficiencies recorded	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

	Λ4
uestion	Response
SCIENCE PREP ROOM	
Power Supply	
Instance on Room 231A	Does not exist
Instance on Room 186, 385	Does not exist
SWIMMING POOL	Inspected
Instance on Basement	Inspected
Lighting	^
Instance on Basement	Under construction
Local Sound System	
Instance on Basement	Inspected
Instance Condition	3- Fair
Installation Year	2011
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Scoreboard	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
FOILET ROOM - STAFF	Inspected
Lighting	Under construction
FOILET ROOM - STUDENT	Inspected
Lighting	Under construction
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Inspected
	Inspected
Automatic Transfer Switch (ATS) Instance	Electrical Room B37
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ASCO
EquipmentId	ATS-1
Capacity/Size Quantity	1200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1996
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room B37
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ASCO
EquipmentId	ATS-2 F.A Transfer Switch
Capacity/Size Quantity	100
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1996
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Battery Charger	Inspected
Instance	Roof - Emergency Generator Enclosure
Instance Condition	1- Good

Building Condition Assessment Survey 2023-2024

Electrical Inspection

1		
estion		Response
EMERGENC	Y GENERATOR SET	
Battery Cha	arger	
	tance Quantity	1
Ins	tance Quantity Uom	EACH
	nufacturer	La Marche
	uipmentId	Battery Charger
1	pacity/Size Quantity	10
	pacity/Size UOM	AmpsDC
	pacity/Size 2 Quantity	24
	pacity/Size 2 UOM	VDC
So	urce of Capacity/Size	Nameplate
Ins	tallation Year	2019
So	urce of Installation Year	Documented
De	ficiency	No deficiencies recorded
Emergency	Distribution Board	Inspected
Number of	f Spares	13
Fused Dis	connect Switch Type	Inspected
Ins	tance	Electrical Room B37
Ins	tance Condition	3- Fair
Ins	tance Quantity	1
Ins	tance Quantity Uom	EACH
	nufacturer	Square D
	uipmentId	Emergency Side Addition
	pacity/Size Quantity	1200
	pacity/Size UOM	Amps Total
	pacity/Size 2 Quantity	2
	pacity/Size 2 UOM	Section(s)
	urce of Capacity/Size	Nameplate
	tallation Year	1996
	urce of Installation Year	Documented
	ficiency	No deficiencies recorded
	ase Circuit Breaker Type	Does not exist
Diesel	ase Circuit Breaker Type	Inspected
	tance	Roof - Emergency Generator Enclosure
	tance Condition	3- Fair
	tance Quantity	1 EACH
	tance Quantity Uom	
	nufacturer	Caterpillar
1	uipmentId	Emergency Generator
	pacity/Size Quantity	438
	pacity/Size UOM	kVA
	pacity/Size 2 Quantity	350
	pacity/Size 2 UOM	kW
	pacity/Size 3 Quantity	1,214
	pacity/Size 3 UOM	Amps
	urce of Capacity/Size	Nameplate
	tallation Year	1996
	urce of Installation Year	Documented
	ficiency	DEFECTIVE FUEL SUPPLY/DELIVERY SYSTEM
	Deficiency Quantity	1
	Quantity Uom	EACH
F	Potential Action	REPAIR
τ	Jrgency of Action	PRIORITY 5
	Purpose of Action	LEVEL 2
	Violations	No violations recorded
Natural Ga	8	Does not exist

Building Condition Assessment Survey 2023-2024

Electrical Inspection

		A4 J
uestion	Response	
EMERGENCY LIGHTING	Inspected	
Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Non Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	FIXTURE NOT OPERATIONAL	
Deficiency Location/Instance	Cafeteria	
Deficiency Quantity	l	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 2	
Violations		
	No violations recorded	
XIT LIGHT	Inspected	
Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	BATTERY NOT OPERATIONAL	
Deficiency Location/Instance	Throughout the Building	
Deficiency Quantity	18	
Quantity Uom	EACH	
Potential Action	REPLACE BATTERY	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 4	
Violations	35657904R	
Non Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
XIT/EMERGENCY LIGHT	Inspected 3- Fair	
Condition		
Deficiency	No deficiencies recorded	
TRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Inspected	
Condition	3- Fair	
	No deficiencies recorded	
Deficiency		
Duct Smoke Detector	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
CO Detector	Does not exist	
Heat Detector	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Elevator Recall	Inspected	
	Inspected	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

cui Inspection		А4Ј
estion	Response	
IRE ALARM SYSTEM		
Elevator Recall		
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Magnetic Door Holder/Contactor	Does not exist	
Fused Cutout Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Inspected	
Bell At Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	1st Floor Corridor by Stair G	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Edwards System Technology	
Model	EST 3	
EquipmentId	Fire Alarm Control Panel	
Installation Year	1999	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel	Inspected	
Bell At Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Auditorium Stage	
Instance Condition	4- Between Fair and Poor	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Notifier	
Model	RP - 1001	
EquipmentId	Stage Deluge Panel	
Installation Year	1999	
Source of Installation Year	Documented	
Deficiency	PANEL DEFECTIVE	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPAIR	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	12127296J	
Instance	Auditorium Stage	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Notifier	
Model	System 5000	
EquipmentId	N/A	
Installation Year	1999	
Source of Installation Year	Documented	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

rical Inspection		A43 0
Question	Response	
FIRE ALARM SYSTEM		
Sub-Panel		
Fire Alarm Control Panel (Electronic)		
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Punch Register	Does not exist	
Sprinkler Flow/Air Pressure Switch	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Tamper Flow Switch/Chain	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
GROUNDING SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
INTERCOM SYSTEM	Inspected	
	Inspected	
Elevator Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Holding Area	Does not exist	
LAN	Inspected	
LAIN Local Distribution Frame (I/LDF)	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
	Inspected	
Main Equipment Rack (MDF) Condition	1- Good	
Deficiency	No deficiencies recorded	
LIGHTNING PROTECTION	Does not exist	
MOTOR CONTROLLER	Inspected	
MOTOR CONTROL CENTER	Does not exist	
MOTOR STARTER/CONTACTOR	Inspected 3- Fair	
Condition		
Deficiency	No deficiencies recorded	
Variable Frequency Drive	Inspected 3- Fair	
Condition Deficiency		
	No deficiencies recorded	
PANEL BOARD	Inspected	
Fused Disconnect Switch Type	Does not exist	
Fused Knife Switch Type	Does not exist	
Fused Toggle Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
PUBLIC ADDRESS SYSTEM	Inspected	
Instance	Room 137	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

uestion	Response	
PUBLIC ADDRESS SYSTEM		
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Rauland TC2100	
Installation Year	2009	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
SECURITY	Inspected	
IPDVS/CCTV System	Inspected	
Condition	2- Between Good and Fair	
Installation Year	2018	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Intrusion Alarm System	Inspected	
Central Control Panel	Inspected	
Instance	Custodian's Office	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Vista 128BPT	
Installation Year	2018	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Infrared Sensor	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Panic Switch	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Remote Annunciator	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Siren/Strobe	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting - Security	Inaccessible	
SERVICE SWITCH	Inspected	
Instance	Electrical Room B37	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	General Electric	
EquipmentId	Emergency Transfer Switch ATS#1	
Capacity/Size Quantity	1600	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	1996 De annue 1	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Electrical Room B37	
Instance Condition	3- Fair	
Instance Quantity	1	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

Building Condition Assessment Survey 2023-2024

Electrical Inspection

	X430
Response	
1- Good	
No deficiencies recorded	
Inspected	
1- Good	
No deficiencies recorded	
Does not exist	
-	1- Good No deficiencies recorded Inspected 1- Good No deficiencies recorded