Building Condition Assessment Survey 2023-2024

Electrical Inspection X441

Asset:	CLINTON HS AF - BRONX, 100 WEST MOSHOLU PARKWAY	SOUTH,	BRONX, NY, 10468	
Inspection Id	Inspection Type		Time In	Last Edited
5177	ELECTRICAL		2024-05-01 08:47AM	2024-05-06 08:32PM
lsset Data				
Question		Answer		
Have any Systems/Major Building Components been upgraded?		Systems:	Intrusion Alarm System (Central Control Panel, Remote Annunciator, Partial Infrared Sensor)	
		Years:	2011	
		Systems:	IPDVS/CCTV System, Softball I	Field (Scoreboard)
		Years:	2007	
		Systems:	Interior Fluorescent Lighting	
		Years:	2004	
		Systems:	Switchboard, Motor Starter, Part Circuit Breaker Type Panel Boar System, Local Sound System, Ex	d, Public Address
		Years:	1991	
Type of Service	;	Below Gr	ound	
Does Interactiv	e Whiteboard (IWB) Exist?	Yes		
Water Penetrati	on In Electrical Room?	No		
DEDICATEI	O INTERCOMS IN FIRE RESCUE AREAS			
Question]	Response	
Are there any	Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in	1	No	

Priority Condition

your building?

Purpose of Action

Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
Yes	Water Leaks onto Electrical Equipment	N/A	Lighting Fixture	Locker Room South - Storage Room	Danilo Cepeda	Fireman	

pection			
Question	Response		
Electrical			
ATHLETIC FIELD	Inspected		
Exterior Lighting	Inspected		
Condition	3- Fair		
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE		
Deficiency Quantity	61		
Quantity Uom	EACH		
Potential Action	REPLACE-UPGRADE		
Urgency of Action	PRIORITY 1		
Purpose of Action	LEVEL 2		
Violations	No violations recorded		
Local Sound System	Inspected		
Condition	3- Fair		
Installation Year	1991		
Source of Installation Year	Documented		
Deficiency	BEYOND USEFUL LIFE		
Deficiency Location/Instance	ATHLETIC FIELD		
Deficiency Quantity	1		
Quantity Uom	EACH		
Potential Action	REPLACE		
Urgency of Action	PRIORITY 1		

LEVEL 2

Building Condition Assessment Survey 2023-2024

Electrical Inspection X441

incui mspeciion		23771
Question	Response	
ATHLETIC FIELD		
Local Sound System		
Violations	No violations recorded	
Scoreboard	Inspected	
Instance	Football Field	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Deficiency	No deficiencies recorded	
Instance	Softball Field	
Instance Condition	5- Poor	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Deficiency	NOT OPERATIONAL	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
AUDITORIUM	Does not exist	
CAFETERIA	Does not exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
COMPUTER LAB	Does not exist	
GYMNASIUM	Does not exist	
	Does not exist	
KITCHEN		
LIBRARY	Does not exist	
LOCKER ROOM	Inspected	
Instance on 1st Floor - South, 1st Floor - North	Inspected	
Alternative Use	No	
Lighting		
Instance on 1st Floor - South, 1st Floor - North	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor - South, 1st Floor - North	Inspected	
Pendant Mounted		
Instance on 1st Floor - South, 1st Floor - North	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on 1st Floor - South, 1st Floor - North	Inspected	

Building Condition Assessment Survey 2023-2024

Electrical Inspection X441

iricai Inspection		A441
Question	Response	
LOCKER ROOM		
Lighting		
Lighting Fixture - Fluorescent		
Surface Mounted		
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor - South, 1st Floor - North	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor - South, 1st Floor - North	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor - South, 1st Floor - North	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor - South, 1st Floor - North	Does not exist	
MULTIPURPOSE ROOM	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SWIMMING POOL	Does not exist	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Does not exist	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Does not exist	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
AUXILIARY SIGNAL/BELL SYSTEM	Does not exist	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	
EMERGENCY GENERATOR SET	Does not exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not exist	
	Does not exist	
EMERGENCY LIGHTING		
EXIT LIGHT	Does not exist	
EXIT/EMERGENCY LIGHT	Does not exist	
FIRE ALARM SYSTEM	Does not exist	
GROUNDING SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Deliciency	ino deficiencies recorded	

Building Condition Assessment Survey 2023-2024

D
Response
Does not exist
Does not exist
Does not exist
Inspected
Does not exist
Inspected
3- Fair
No deficiencies recorded
Does not exist
Inspected
Does not exist
Does not exist
Does not exist
Inspected
3- Fair
No deficiencies recorded
Inspected
Coach's Office (Inside Locker Room South)
3- Fair
1
EACH
Dukane 250
1991
Documented
BEYOND USEFUL LIFE
Coach's Office (Inside Locker Room South)
2,825
S.F.
REPLACE
PRIORITY 1
LEVEL 2
No violations recorded
Inspected
Inspected
3- Fair
2007
Documented
No deficiencies recorded
Inspected
Inspected
Coach's Office (Inside Locker Room South)
3- Fair
1
EACH
Vista - 128BP
2011
Documented
PANEL NOT CONNECTED TO EMERGENCY POWER SOURCE
1
EACH
INSTALL CONNECTION

PRIORITY 4

No violations recorded

LEVEL 3

Urgency of Action

Purpose of Action

Violations

Building Condition Assessment Survey 2023-2024

Electrical Inspection X441

ricui Inspection	ATT
Question	Response
SECURITY	
Intrusion Alarm System	
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Does not exist
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
	No deficiencies recorded
Deficiency	
Lighting - Security	Does not exist
SERVICE SWITCH	Does not exist
SWITCHBOARD	Inspected
Number of Spares	3
Fused Disconnect Switch Type	Does not exist
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Instance	Outdoor Electrical Enclosure
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Atlas Switch
EquipmentId	Main Distribution
Capacity/Size Quantity	400
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	1991
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Does not exist
Standard	Inspected
Condition	5- Poor
Deficiency	SYSTEM NOT OPERATIONAL
Deficiency Location/Instance	Field House
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
TRANSFORMER	Does not exist