Building Condition Assessment Survey 2023-2024


Architectural Inspection X456

Asset:	TRUMAN HS AF - BRONX, 750 BAYCHESTER AVENUE, BRONX, NY, 10475		
Inspection Id	Inspection Type	Time In	Last Edited
1542	ARCHITECTURAL - SENIOR	2023-12-08 07:00AM	2024-01-24 12:55PM
1549	ARCHITECTURAL - ASSOCIATE	2023-12-08 01:27PM	2024-05-06 04:06PM
seet Data			

Asset Data

Weather Facade Photo

Question		Answer		
Was the Building Fully Acc	essible for Inspection?	Yes		
Principal(s) Information				
	Principal Name	Keri Alfaro		
	Principal Organization	Harry S. Truman HS - Bronx		
	Meeting with Principal?	Yes		
	Principal Feedback	The Principal had no comments about the condition of the building at this time.		
Custodian		David Dottavino		
Was the Custodian Present?		Yes		
Fireman		Roy Paolucci		
Was the Fireman Present?		Yes		
Building Square Footage		0		
Comments on the Area (for	Athletic Field, Playing Surfaces, Leased Spaces)	Total Site Area: 283327 SF; Playing Surface Area: 242900 SF		
Comments on the Stories (F	loors) plus Basements	N/A		
Comments on the Year Buil	t	1973		
Student Population		2444		
Staff Population		3		
Comments on the Number of	of Classrooms	0		



Athletic Field - North View

Building Condition Assessment Survey 2023-2024

Architectural Inspection

Main Entrance Photo

X456

Athletic Field - North Entrance



Athletic Field - Southeast View from Main Asset X455

No

No Storm Water Management Type Selected

No System Upgraded

No New Construction

No Tandem

No

Roof Photo

Do Stormwater Management/Green Infrastructure systems exist?

Type

Have any Systems/Major Building Components been upgraded?

Have there been any New Building Additions?

Tandem

Leased Space?

Priority Condition

Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
No cond	ition recorded						

Structural Engineer Required

Structural	Condition	Component	Location	Person(s)	Person(s)	Photo
Condition Type	Description	Affected	Description	Notified	Title	Image


No condition recorded

Programmatic Accessibility

Programmatic Accessibility Status Question			Resp	onse		
Physical Breakdown Structure	Exists	Complies	Required	Deficiency	Assistive Listening System	Fire Alarm Strobe

Architectural Inspection X456

Building Template



Inspection

Question	Response
Architectural	
EXTERIOR	Does not exist
INTERIOR	Does not exist
ATHLETIC FIELDS	Inspected
PLAYING SURFACE	Inspected
Replacement Quantity	242,900
Replacement Uom	S.F.
Synthetic Turf Field exists?	No
Instance on Baseball, Football and Soccer Field	Inspected
Instance Condition	5- Poor
Instance Quantity	165,000
Instance Quantity Uom	S.F.


Deficiency

Deficiency Location/Instance

Deficiency Location/Instance

NATURAL TURF:DAMAGED/WORN OUT

Football and Soccer Field



Deficiency Quantity

Quantity Uom

Potential Action

Urgency of Action

Purpose of Action Deficiency Photo 1 S.F. REPLACE PRIORITY 4

20,000

LEVEL 2



Building Condition Assessment Survey 2023-2024

uestion	Response
ATHLETIC FIELDS	
PLAYING SURFACE	
TEATING SUMACE	Middle of field
Deficiency Photo 2	No photo recorded
Violations	No violations recorded
Instance on Basketball Court	Inspected
Instance Condition	4- Between Fair and Poor
Instance Quantity	
Instance Quantity Instance Quantity Uom	7,300 S.F.
-	
Deficiency	ASPHALT:DAMAGED/DETERIORATED
Deficiency Location/Instance Deficiency Location/Instance	Basketball Court X456 Tall to the sine, 333,337 Ell Projection Ann. 32(3) Ell Projection Ann.
Deficielcy Education Histarice	Transfer dama and an
Deficiency Quantity	500
Quantity Uom	S.F.
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo 1	
	Center of Court
Deficiency Photo 2	No photo recorded
Violations	No violations recorded
Instance on Running Track	Inspected
Instance Condition	3- Fair
Instance Quantity	36,000
Instance Quantity Uom	S.F.
Deficiency	ATHLETIC WEARING SURFACE:DAMAGED/DETERIORATED
Deficiency Location/Instance	Running Track
Deficiency Location/Instance	NASS Test all share a 301,277 EF Terrang further does NACOS DE S Auto Naco Naco Naco Naco Naco Naco Naco Nac
Deficiency Quantity	350
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

Building Condition Assessment Survey 2023-2024

Architectural Inspection X456

Question Response

ATHLETIC FIELDS

PLAYING SURFACE

Deficiency Photo 1



North end of Oval

Deficiency Photo 2



West side of Oval

No violations recorded

Instance on Tennis and Handball Courts	Inspected
Instance Condition	4- Between Fair and Poor

Instance Quantity 34,600
Instance Quantity Uom S.F.


Deficiency

Deficiency Location/Instance

Deficiency Location/Instance

ASPHALT:DAMAGED/DETERIORATED

Tennis and Handball Courts



Deficiency Quantity

Quantity Uom

Potential Action

Urgency of Action

Purpose of Action

Deficiency Photo 1

3,700 S.F. REPLACE

PRIORITY 4

LEVEL 2



Tennis Courts

Deficiency Photo 2



Building Condition Assessment Survey 2023-2024

	D
nestion	Response
ATHLETIC FIELDS	
PLAYING SURFACE	II. II. II.O.
	Handball Courts
Violations	No violations recorded
FIXED EQUIPMENT	Inspected
Basketball Backboard	Inspected
Condition	5- Poor
Deficiency	DAMAGED/MISSING
Deficiency Location/Instance	Basketball Court
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo 1	
	Basketball Court
Deficiency Photo 2	No photo recorded
Violations	No violations recorded
Basketball Hoops	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Basketball Posts	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Football Goal Posts	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Tennis Net Posts	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
	Inspected
SEATING P. J.	Does not exist
Benches	
Bleachers	Inspected
Concrete	Inspected
Condition	4- Between Fair and Poor
Deficiency	CRACKS/SPALLING - MAJOR
Deficiency Location/Instance	Along West Side Field
Deficiency Quantity	400
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action Purpose of Action	PRIORITY 3 LEVEL 2

Building Condition Assessment Survey 2023-2024

itectural Inspection	X45
uestion	Response
ATHLETIC FIELDS	
SEATING	
Bleachers	
Concrete	
Deficiency Photo 1	
	Along West Side Field
Deficiency Photo 2	No photo recorded
Violations	No violations recorded
Metal/Wood/Plastic	Inspected
Condition	2- Between Good and Fair
Deficiency	DAMAGED
Deficiency Location/Instance Deficiency Quantity	Along West Side Field 30
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
	Along West Side Field
Deficiency Photo 2	No photo recorded
Violations	No violations recorded
SITE	Inspected
CONTAINERIZATION	Does not exist
DRAINAGE SYSTEM FOR ASPHALT	Inspected
Catch Basins/Manhole - Surrounded by Asphalt	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Culverts - Asphalt Covering	Does not exist
DRAINAGE SYSTEM FOR CONCRETE	Does not exist Inspected
DRAINAGE SYSTEM FOR SOIL Catch Basins/Manhole - Surrounded by Soil	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Culverts - Soil Covering	Does not exist
DRINKING FOUNTAINS	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
FENCES	Inspected
Condition	4- Between Fair and Poor
Deficiency	CHAIN LINK:DAMAGED POST/RAIL
Deficiency I costion/Instance	Hondhall Count North Couth Fact West Side

Handball Court, North, South, East, West Side

Deficiency Location/Instance

Building Condition Assessment Survey 2023-2024

uestion	Response
SITE	•
FENCES	
Deficiency Quantity	100
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo 1	LEVEL 2
	Handball Court
Deficiency Photo 2	No photo recorded
Violations	No violations recorded
Deficiency	CHAIN LINK:DAMAGED/DETERIORATED
Deficiency Location/Instance	Along West, East Side, Handball Court, Near Bleachers, Tennis
,	Court
Deficiency Quantity	700
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo 1	
	Handball Court
Deficiency Photo 2	No photo recorded
Violations	No violations recorded
IRRIGATION SYSTEM	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
PAVING	Inspected
Student Non-Use	Inspected
Gravel Exists?	No
Asphalt	Inspected
Condition	4- Between Fair and Poor
Deficiency	CRACKS - MAJOR
Deficiency Location/Instance	Open Storage
Deficiency Quantity	1,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Dymass of Action	LEVEL 2

LEVEL 2

Purpose of Action

Building Condition Assessment Survey 2023-2024

eld

PRIORITY 3

LEVEL 2

Urgency of Action

Purpose of Action

Building Condition Assessment Survey 2023-2024

uestion	Response
SITE	
PAVING	
Site Sidewalks & Walkways	
Concrete	
Deficiency Photo 1	
	Along West Side Field
Deficiency Photo 2	No photo recorded
Violations	No violations recorded
Pavers	Does not exist
DOT Sidewalk	Does not exist
PLAYGROUNDS	Does not exist
PLAYING SURFACE	Does not exist
RETAINING WALLS	Inspected
Condition	3- Fair
Are there any Retaining Walls 6' OR higher facing public street/sidewalk?	No
Deficiency	CAST IN PLACE CONCRETE:CRACKS/SPALLING - MAJOR
Deficiency Location/Instance	Near Tennis Court, Along West Side Field
Deficiency Quantity	75
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action Deficiency Photo 1	LEVEL 2
	Along West Side Field
Deficiency Photo 2	No photo recorded
Violations	No violations recorded
SEATING	Does not exist
SITE WALLS (NOT RETAINING WALLS)	Inspected
Condition	3- Fair
Deficiency	CAST IN PLACE CONCRETE: CRACKS/SPALLING - MAJOR
Deficiency Location/Instance	Handball Court
Deficiency Quantity	35
Quantity Uom	S.F.
Potential Action	REPLACE

PRIORITY 3

LEVEL 2

Urgency of Action

Purpose of Action

Building Condition Assessment Survey 2023-2024

Architectural Inspection X456

Question Response SITE SITE WALLS (NOT RETAINING WALLS) Deficiency Photo 1 Handball Court Deficiency Photo 2 No photo recorded Violations No violations recorded STAIRS/RAMPS: EXTERIOR Inspected Site Cheek/flank Walls Inspected Condition 2- Between Good and Fair Deficiency No deficiencies recorded Inspected Railings Condition 2- Between Good and Fair Deficiency No deficiencies recorded Inspected Stairs/ramps Condition 3- Fair CAST IN PLACE CONCRETE: CRACKS/SPALLING - MAJOR Deficiency West Side Field Deficiency Location/Instance Deficiency Quantity 75 S.F. Quantity Uom Potential Action REPLACE Urgency of Action PRIORITY 3 Purpose of Action LEVEL 2 Deficiency Photo 1 West Side Field

No photo recorded

No violations recorded

Deficiency Photo 2

Violations

NYC Department of Education Building Condition Assessment Survey 2023-2024

Architectural Inspection X456

Does the SCA expect asset to have artwork?

No