Building Condition Assessment Survey 2023-2024

Electrical Insp	ection						X49
Asset:	3K CENTER @ 2	020 WHITE PLAINS R	OAD - BRONX, 2	020 WHITE PLA	AINS ROAD, I	BRONX, NY,	, 10462
Inspection Id	Inspection Type				Time I	n	Last Edited
196	ELECTRICAL				2023-1	0-16 09:20AM	1 2023-11-07 08:48AM
Asset Data							
Question				Answer			
Have any Syste	ems/Major Building Co	omponents been upgraded?		Systems:	All Electrical S	Systems and Co	mponents.
				Years:	2023		
Type of Servic	e			Below Gro	ound		
Does Interactiv	ve Whiteboard (IWB) I	Exist?		Yes			
	tion In Electrical Room			No			
	D INTERCOMS IN	FIRE RESCUE AREAS	<u>s</u>				
Question	y Life Passue Assistan	ce Areas, Fire Rescue Areas	and/or Holding Door		Yes		
your building		ce Areas, Fire Rescue Areas	, and/or notding Roof	IIIS III I	es		
		e in all of these spaces for us	se during a fire?	Y	/es		
	edicated intercoms ope			Y	'es		
Priority Condi	tion						
<u>`</u>	iority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year? Car	tegory	Description	Affected	Description	Notified	Title	Image
No condition r	recorded						
Inspection							
Question				Response			
Electrical				тегропзе			
ATHLETIC	FIFI D			Does not e	exist		
AUDITORI				Does not e			
				Does not e			
CAFETERI		MANAGED ATTICE OD A CIT.			XISt		
-	OM/CORRIDOR/ADI	MINISTRATIVE SPACE		Inspected			
Lighting Does a C	Chandelier Exist?			Inspected No			
	Fixture - Fluorescent	<u> </u>		Does not e	exist		
	g Fixture - HID	•		Does not e	exist		
	Fixture - Incandesce	nt		Does not e	exist		
	g Fixture - LED			Inspected			
	nt Mounted			Does not e	exist		
Surfac	ce Mounted			Inspected			
Cond	lition			1- Good			
	Deficiency			No deficie	ncies recorded		
Recess	sed Mounted			Inspected			
Cond	lition			1- Good			
	Deficiency			No deficie	ncies recorded		
COMPUTE	CR LAB			Does not e	exist		
GYMNASII	UM			Does not e	exist		
KITCHEN				Inspected			
Iı	nstance on 1st Floor			Inspected			
Lighting_							
I1	nstance on 1st Floor			Inspected			
_	g Fixture - Fluorescent	t					
-	nstance on 1st Floor			Does not e	exist		
_	g Fixture - HID						
	nstance on 1st Floor			Does not e	exist		
_	g Fixture - Incandesce	nt			• .		
	nstance on 1st Floor			Does not e	exist		
_	g Fixture - LED			т . •			
lı	nstance on 1st Floor			Inspected			

Building Condition Assessment Survey 2023-2024

Electrical Inspection		X492
Question	Response	

Question	Response
KITCHEN	•
Lighting	
Lighting Fixture - LED	
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
LIBRARY	Does not exist
LOCKER ROOM	Does not exist
MULTIPURPOSE ROOM	Inspected
Instance on Room 122	Inspected
Lighting	Inspected
Instance on Room 122	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 122	Does not exist
Lighting Fixture - HID	
Instance on Room 122	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 122	Does not exist
Lighting Fixture - LED	
Instance on Room 122	Inspected
Pendant Mounted	
Instance on Room 122	Does not exist
Surface Mounted	
Instance on Room 122	Does not exist
Recessed Mounted	
Instance on Room 122	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Local Sound System	
Instance on Room 122	Does not exist
Projection System	
Instance on Room 122	Does not exist
Theater Lighting System	D
Instance on Room 122	Does not exist
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Does not exist
SCIENCE PREP ROOM	Does not exist
SWIMMING POOL	Does not exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Does not exist
Recessed Mounted	Inspected
Condition	1- Good

Building Condition Assessment Survey 2023-2024

Electrical Inspection X492

Question	Response	
TOILET ROOM - STAFF		
Lighting		
Lighting Fixture - LED		
Recessed Mounted		
Deficiency	No deficiencies recorded	
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Does not exist	
Recessed Mounted	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	
EMERGENCY GENERATOR SET	Does not exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not exist	
EMERGENCY LIGHTING	Inspected	
Battery Pack Condition	Inspected 1- Good	
Deficiency	No deficiencies recorded	
	Does not exist	
Non Battery Pack		
EXIT LIGHT	Inspected	
Battery Pack Condition	Inspected 1- Good	
Deficiency	No deficiencies recorded	
<u></u>	Does not exist	
Non Battery Pack		
EXIT/EMERGENCY LIGHT	Does not exist	
FIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected 1- Good	
Condition		
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Inspected 1- Good	
Condition		
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected 1- Good	
Condition		
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected 1- Good	
Condition	No deficiencies recorded	
Deficiency	No deficiencies recorded	

Building Condition Assessment Survey 2023-2024

Electrical Inspection X492

ісаі Іпѕреспоп		X49
estion	Response	
FIRE ALARM SYSTEM		
Heat Detector	Does not exist	
Elevator Recall	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Magnetic Door Holder/Contactor	Does not exist	
Fused Cutout Panel	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Inspected	
Bell At Panel	Does not exist	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	1- Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Mircom	
Model	FX - 2000	
EquipmentId	Fire Alarm Control Panel	
Installation Year	2023	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel	Does not exist	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	-
Punch Register	Does not exist	
Sprinkler Flow/Air Pressure Switch	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Tamper Flow Switch/Chain	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
ROUNDING SYSTEM	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
NTERCOM SYSTEM	Inspected	
Elevator	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Holding Area	Does not exist	
AN	Inspected	
Local Distribution Frame (I/LDF)	Does not exist	
Main Equipment Rack (MDF)	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	

Building Condition Assessment Survey 2023-2024

Electrical Inspection	X4	192
Ouestion	Response	

Question	Response
MOTOR CONTROLLER	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Does not exist
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	MDF Room 113
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Bogen Multicom - 2000
Installation Year	2023
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Condition	1- Good
Installation Year	2023
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office - 121
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista 128BPT
Installation Year	2023
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
SERVICE SWITCH	Inspected
Instance	Electrical Room 125
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	All City Switchboard
Dautuous Vousion 2 0 (D)	Page 5 of 6 Print Data: 9/9/2024

Building Condition Assessment Survey 2023-2024

Electrical Inspection X492

Question	Response
SERVICE SWITCH	
EquipmentId	1200A Service Switch
Capacity/Size Quantity	1200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2023
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	Inspected
Number of Spares	3
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room 125
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	All City Switchboard
EquipmentId	N/A
Capacity/Size Quantity	1200
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	2023
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
TRANSFORMER	Does not exist