
Building Condition Assessment Survey 2023-2024

Architectural Inspection

Asset:	3K CENTER @ 1107 EAST GUN HILL ROAD - BRONX,	1107 EAST GUN HILL ROAD, BRONX, N	Y, 10469
Inspection Id	Inspection Type	Time In	Last Edited
201	ARCHITECTURAL - ASSOCIATE	2023-10-16 12:00PM	A 2023-11-19 11:56PM
203	ARCHITECTURAL - SENIOR	2023-10-16 11:46A	M 2024-06-12 09:41PM
set Data			
Question		Answer	
Was the Buildin	ng Fully Accessible for Inspection?	Yes	
Principal(s) Inf	ormation		
	Principal Name	None	
	Principal Organization	N/A	
	Meeting with Principal?	No	
	Principal Feedback	No Feedback from Principal	
Custodian		Carlos Carrera	
Was the Custod	lian Present?	Yes	
Fireman		None	
Was the Firema	n Present?	No	
Building Squar	e Footage	9,000	
Comments on t	he Area (for Athletic Field, Playing Surfaces, Leased Spaces)	None	
Comments on t	he Stories (Floors) plus Basements	1 Floor (no basement)	
Comments on t	he Year Built	2023	
Student Popula	tion	0	
Staff Population	n	0	
Comments on t	he Number of Classrooms	4	
Weather		Fair	
Facade Photo			






East Gun Hill Road - Northeast View



Facade A - East Gun Hill Road

Architectural Inspection

Roof Photo



Full Inspection

Priority Condition

Leased Space?

Year Leased Inspection Type

Tandem

Do Stormwater Management/Green Infrastructure systems exist?

Have any Systems/Major Building Components been upgraded?

Have there been any New Building Additions?

Type


Exist	Priority	Condition	Con	nponent	Location	Person(s) Person(s)	Photo	
Last Year?	Category	Description	Affe	ected	Description	Notified	Title	Image	
No condi	tion recorded								
tructural	Engineer Requi	ired							
Structural	Condition	n Compone	ent	Location		Person(s)	Person(s)	Photo	
Condition T	ype Descripti	on Affected		Descriptio	n	Notified	Title	Image	
No condi	tion recorded								
Programm	atic Accessibilit	<i>y</i>							
Program	matic Accessibility S	tatus Question				Response			
Is the Pri	mary or secondary ent	trance on an accessible route?	1			Yes			
Is the b	uilding a multi-story	building?				No			
		aces exist? Classroom, Art Ro		n, Cafeteria,		Yes			
		ibrary, Multipurpose Room, S	Science Labs						
		st, are they ALL accessible?				Yes			
Is	there at least one Boy	ys and Girls or Unisex toilet a	ccessible In the	building?		Yes			
Physical	Breakdown Structur	re	Exists	Complies	Requ	ired Defi	ciency	Assistive Listening Svstem	Fire Alarn Strob
PROGR	AMMATIC ACCESS	SIBILITY						System	51100
Exte	rior Routes								
_	Exterior Entrances &	& Exits		Yes					
_	Exterior H/C Lifts		No		Ν	0			
_	Exterior Ramps and	Railings	Yes	Yes					
Inter	ior Routes								
_	Corridor and Lobby	H/C Lifts	No		N	0			
_	Interior Corridor Do	oors And	Yes	Yes					
_	Hardware								
_	Interior Corridors &	k Lobbies		Yes					
	Interior Elevators		No						

Building Condition Assessment Survey 2023-2024

Architectural Inspection

ectural Inspection					· · ··	X50
ysical Breakdown Structure	Exists	Complies	Required	Deficiency	Assistive Listening System	Fire Alarn Strob
Interior Ramps	Yes	Yes			2	
Rooms & Spaces						
Art Rooms	No					
Auditorium	No					
Cafeteria	No					
Classrooms						
1st Floor	Yes	Yes				
Computer Rooms	No					
Gymnasium	No					
Library	No					
Main Office						
Room 103	Yes	Yes				
Multi-purpose Room	No					
Nurse's Office						
Room 113	Yes	Yes				
Pool	No					
Science Lab	No					
Toilet Rooms (boys)						
1st Floor (unisex)	Yes	Yes				
Toilet Rooms (girls)						
1st Floor (unisex)	Yes	Yes				
Toilet Rooms (staff)						
1st Floor	Yes	Yes				

Building Template



EAST GUN HILL ROAD

nspection		
Question	Response	
Architectural		
EXTERIOR	Inspected	
AREAWAY	Does not exist	
AWNINGS AND CANOPIES	Does not exist	
CHIMNEY	Does not exist	

Architectural Inspection

ecturut Inspection		A30
lestion	Response	
EXTERIOR		
COPING	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
CORNICE	Does not exist	
DOORS	Inspected	
DOORS AND FRAMES	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
DOOR HARDWARE	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
LINTELS	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
TRANSOM/SIDE LIGHT	Inspected	
Condition	1- Good	
	No deficiencies recorded	
Deficiency	Inspected	
EXTERIOR WALLS Material Type(s)	Masonry, Other	
Replacement Quantity	8,500	
Replacement Uom	S.F.	
Instance on All Facades	Inspected	
Instance Condition	1- Good	
Instance Quantity	8,500	
Instance Quantity Uom	8,500 S.F.	
Deficiency	No deficiencies recorded	
EXTERIOR SOFFITS	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
LOADING DOCK	Does not exist	
LOADING DOCK	Does not exist	
PARAPETS	Inspected	
Material Type(s)	Masonry	
Replacement Quantity	1,200	
Replacement Uom	C.F.	
Instance on All Facades	Inspected	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1,200	
Instance Quantity Uom	CF	
Deficiency	No deficiencies recorded	
PLAZA DECK	Does not exist	
ROOF	Inspected	
ROOFING	Inspected	
ROOF HATCH/SMOKE HATCH	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
LEADERS, GUTTERS, DOWNSPOUTS, SCUPPERS	Does not exist	
LEADERS, GUITERS, DOWNSPOUTS, SCUPPERS ROOF BARRIER/FENCE	Inspected	
Condition	2- Between Good and Fair	
	No deficiencies recorded	
Deficiency		
ROOF CAGE	Does not exist	
ROOFING Replacement Quantity	Inspected 9,000	

Building Condition Assessment Survey 2023-2024

Architectural Inspection

estion	Response	
XTERIOR	*	
ROOF		
ROOFING		
ROOFING		
Replacement Uom	S.F.	
Instance on Single Ply, Fully Adhered Roof:Roof 1	Inspected	
Instance Roof Photo		
	Roof 1	
Instance Condition	1- Good	
Instance Quantity	9,000	
Instance Quantity Uom	S.F.	
Does the roof have major mechanical equipment sitting on Dunnage Steel less than 18" above the Roofing?	No	
Does this Roof Instance have a Sustainable Roof System?	Yes	
Sustainable Roof System Type	White Roof	
Sustainable Roof System Location (Roof Number)	Roof 1	
Do solar panels exist on these roofs?	No	
Is/Are the roof(s) suitable for Solar Panel installation?	<u>No</u> 2023	
Source of Installation Year	Custodial Staff	
Deficiency	No deficiencies recorded	
ROOFING DRAINS	Inspected	
	2- Between Good and Fair	
Condition	No deficiencies recorded	
Deficiency		
SPECIALTIES	Inspected	
BULKHEAD/PENTHOUSE	Does not exist	
CUPOLA/ SPIRES/ TOWERS	Does not exist	
DORMER	Does not exist	
DUNNAGE STEEL	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
SKYLIGHT/ROOF VENT	Does not exist	
ROOF/GRAVITY TANK	Does not exist	
STAIRS/RAMPS: EXTERIOR	Inspected Does not exist	
BUILDING CHEEK/FLANK WALLS	Inspected	
RAILINGS		
Condition	1- Good	
Deficiency	No deficiencies recorded	
STAIRS/RAMPS	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
WINDOWS	Inspected	
Replacement Quantity	296	
Replacement Uom	S.F.	
EXTERIOR GUARDS	Does not exist	
LINTELS	Inspected	
Condition	2- Between Good and Fair	

Building Condition Assessment Survey 2023-2024

Architectural Inspection

ectural Inspection		ЛЭ
lestion	Response	
EXTERIOR		
WINDOWS		
WINDOWS	Inspected	
Material Type(s)	Aluminum	
Instance on Aluminum - Other:Facades A and C	Inspected	
Instance Condition	1- Good	
Instance Quantity	296	
Instance Quantity Uom	S.F.	
Installation Year	2023	
Source of Installation Year	Custodial Staff	
Are these windows insulated?	Yes	
Deficiency	No deficiencies recorded	
NTERIOR	Inspected	
POOLS	Does not exist	
STRUCTURAL	Inspected	
COLUMNS/BEAMS/BEARING WALLS	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
FLOOR STRUCTURE	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
FOUNDATION WALLS	Inspected	
Material Type(s)	Concrete	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
ROOF STRUCTURE	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
VAULTS-BUNKERS	Does not exist	
AUDITORIUM	Does not exist	
CAFETERIA	Does not exist	
CLASSROOMS/CORRIDORS/ADMIN SPACES	Inspected	
Ceiling	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Door(s)	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Floor Finish	Inspected	
Condition	1- Good	
Deficiency	I- Good No deficiencies recorded	
Walls	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Specialties	Does not exist	
GYMNASIUM	Does not exist	
INTERIOR DOOR HARDWARE	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
INTERIOR GUARDS	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
KITCHEN	Does not exist	
LIBRARY	Does not exist	

Architectural Inspection

	A302
Response	
Does not exist	
Inspected	
Inspected	
1- Good	
No deficiencies recorded	
Inspected	
-	
*	
1- Good	
No deficiencies recorded	
Inspected	
1- Good	
No deficiencies recorded	
-	
Inspected	
1- Good	
No deficiencies recorded	
Inspected	
1- Good	
No deficiencies recorded	
Inspected	
Inspected	
1- Good	
-	
1- Good	
1- Good No deficiencies recorded	
1- Good No deficiencies recorded Does not exist	
	Does not exist Does not exist Does not exist Does not exist Does not exist Does not exist Does not exist Inspected I

Building Condition Assessment Survey 2023-2024

Architectural Inspection

ectural Inspection		A30
estion	Response	
ITE		
FENCES		
Condition	1- Good	
Deficiency	No deficiencies recorded	
IRRIGATION SYSTEM	Does not exist	
PAVING	Inspected	
Student Non-Use	Does not exist	
Student Use	Inspected	
Gravel Exists?	No	
Asphalt	Does not exist	
Concrete	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Pavers	Does not exist	
Site Sidewalks & Walkways	Inspected	
Asphalt	Does not exist	
Concrete	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Pavers	Does not exist	
DOT Sidewalk	Inspected	
Asphalt	Does not exist	
Concrete	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Pavers	Does not exist	
PLAYGROUNDS	Inspected	
Instance on Back Yard Playground	Inspected	
Benches	1 I	
Instance on Back Yard Playground	Does not exist	
Fence		
Instance on Back Yard Playground	Does not exist	
Pavement		
Instance on Back Yard Playground	Does not exist	
Play Equipment		
Instance on Back Yard Playground	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Safety Surfacing		
Instance on Back Yard Playground	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Unpaved Area	D	
Instance on Back Yard Playground	Does not exist	
PLAYING SURFACE	Does not exist	
RETAINING WALLS	Does not exist	
SEATING Develop	Inspected Does not exist	
Benches	Does not exist Does not exist	
Bleachers		
SITE WALLS (NOT RETAINING WALLS)	Inspected	
Condition	1-Good	
Deficiency	No deficiencies recorded	
STAIRS/RAMPS: EXTERIOR	Inspected	

Building Condition Assessment Survey 2023-2024

Architectural Inspection

Question	Response	
SITE		
STAIRS/RAMPS: EXTERIOR		
Railings	Does not exist	
Stairs/ramps	Does not exist	

Architectural Inspection

Does the SCA expect asset to have artwork?

No