Building Condition Assessment Survey 2023-2024

		7023-		Last Edited	02·45PM
		2023-	10-10 07.37AN	2023-10-10	02.731 IV
	Answer				
		All Flectrical	Systems and Co	omnonents	
	•		Systems and Co	mponents	
	Yes				
	No				
Holding Rooms is		-			
omponent I	Location	Person(s)	Person(s)	Photo	
-	Description	Notified	Title	Image	
	Resnonse				
	Response				
	Does not a	viet			
		AISt			
	No				
	Does not e	exist			
	Does not e	exist			
Does not exist					
Inspected					
		XIST			
		ncies recorded			
	Does not e	exist			
	Does not e	exist			
	Does not e	exist			
	Does not e	exist			
Inspected					
	Inspected				
)	omponent I	Response Does not et al. Cood in spected in	Answer Systems: All Electrical Years: 2023 Below Ground Yes No Response Holding Rooms in No Response Does not exist	Answer Systems: All Electrical Systems and Coryears: 2023 Below Ground Yes No Response Holding Rooms in No Response Holding Rooms in No Response Does not exist Does not exist Does not exist Inspected	Systems: All Electrical Systems and Components Years: 2023 Below Ground Yes No Response Floiding Rooms in No Response Floiding Rooms in No Response Response Does not exist Does not exist Does not exist Inspected Inspect

Building Condition Assessment Survey 2023-2024

rical inspection		X502
Question	Response	
TOILET ROOM - STAFF		
Lighting		
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Does not exist	
Recessed Mounted	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Does not exist	
Recessed Mounted	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	
EMERGENCY GENERATOR SET	Does not exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
EMERGENCY LIGHTING	Inspected	
Battery Pack	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Non Battery Pack	Does not exist	
EXIT LIGHT	Inspected	
Battery Pack	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Non Battery Pack	Does not exist	
EXIT/EMERGENCY LIGHT	Does not exist	
FIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	

Building Condition Assessment Survey 2023-2024

нсш інгресион		ASU
Question	Response	
FIRE ALARM SYSTEM		
Duct Smoke Detector		
Condition	1- Good	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
CO Detector	Does not exist	
Heat Detector	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Elevator Recall	Does not exist	-
Magnetic Door Holder/Contactor	Does not exist	
Fused Cutout Panel	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Inspected	
Bell At Panel	Does not exist	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	1- Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer Model	Edwards System Technology EST3X	
EquipmentId	Fire Alarm Control Panel	
Installation Year	2023	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	-
Sub-Panel	Does not exist	
Remote Annunciator	Does not exist	
Sprinkler Flow/Air Pressure Switch	Does not exist	
Tamper Flow Switch/Chain	Does not exist	
GROUNDING SYSTEM	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
INTERCOM SYSTEM	Does not exist	
LAN	Inspected	
Local Distribution Frame (I/LDF)	Does not exist	
Main Equipment Rack (MDF)	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
LIGHTNING PROTECTION	Does not exist	
MOTOR CONTROLLER	Inspected	
MOTOR CONTROL CENTER	Does not exist	
MOTOR STARTER/CONTACTOR Condition	Inspected 1- Good	
Deficiency	No deficiencies recorded	
Variable Frequency Drive	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	

Building Condition Assessment Survey 2023-2024

ricai Inspection	X502
Question	Response
PANEL BOARD	
Fused Disconnect Switch Type	Does not exist
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	Telecommunication Room 122
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Bogen Multicom - 2000
Installation Year	2023
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Condition	1- Good
Installation Year	2023
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian Office 111
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista 128BPT
Installation Year	2023
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
SERVICE SWITCH	Inspected
Instance	Electrical Closet inside Room 128
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
	Electric Switchboard
Manufacturer	Electric Switchboard

Building Condition Assessment Survey 2023-2024

Question	Response
SERVICE SWITCH	
Capacity/Size Quantity	1200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2023
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	Inspected
Number of Spares	7
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room 115
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Raycap
EquipmentId	MSWB
Capacity/Size Quantity	1200
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	2023
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
TRANSFORMER	Does not exist