

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**X600**

**Asset:** ALFRED E. SMITH HS - BRONX, 333 EAST 151 STREET, BRONX, NY, 10451

Inspection Id	Inspection Type	Time In	Last Edited
4783	ELECTRICAL	2024-04-15 08:50AM	2024-05-22 08:56AM

**Asset Data**

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Fire Alarm System (Most Area Smoke Detectors), Retrofitted LED Lighting except (Auditorium, Library, Room 356, Gymnasium). Years: 2023 Systems: Most Molded Case Circuit Breaker Panel Board Years: 2022, 2007, 2001, 1990 Systems: LAN, Partial Fused Disconnect Switch Type Panel Board Years: 2022 Systems: Emergency Lighting, Exit Lights (Battery Packs) Years: 2017 Systems: Public Address System, Local Sound System, Intrusion Alarm System (Partial Panic Switches) Years: 2015 Systems: Computer Lab B38 Years: 2013 Systems: Computer Lab B42 (Raceways with Receptacles) Years: 2012 Systems: Library Years: 2008 Systems: Emergency Light/Exit Light Panel Years: 2007 Systems: Fire Alarm System Except (Sprinkler Flow/Air Pressure Switch, Tamper Flow Switch/Chain) Years: 2006 Systems: Interior Fluorescent Lighting, Security Lights, HID Lighting Years: 2003 Systems: Intrusion Alarm System Years: 1996
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration In Electrical Room?	Yes

**DEDICATED INTERCOMS IN FIRE RESCUE AREAS**

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

**Priority Condition**

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
Yes	Water Penetration in Electrical Room	N/A	Electrical Equipment	Electrical Room B29	Augustin Palau	Fireman	No Photo Taken
No	Water Leaks onto Electrical Equipment	Water Leaks on Electrical Light Fixture outside Mechanical Room	Lighting Fixture	Basement near Room B3	Augustine Palau	Fireman	No Photo Taken
Yes	Exposed Electrical Wires	N/A	Raceway With Receptacles	Room 201	Augustin Palau	Fireman	No Photo Taken

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**X600**

Yes	Other	Not Operational	Fire Alarm System (Area Smoke Detector, Manual Pull Station)	Area Smoke Detector in Room 160, Manual Pull Station at Basement Corridor Nearby Room B39.	Augustine Palau	Fireman	No Photo Taken
-----	-------	-----------------	--	--	-----------------	---------	----------------

**Inspection**

Question	Response
<b>Electrical</b>	
<b>ATHLETIC FIELD</b>	Does not exist
<b>AUDITORIUM</b>	Inspected
Instance on 1st Floor	Inspected
<b>House Lighting</b>	
Instance on 1st Floor	Inspected
Does a Chandelier Exist?	No
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	
Instance on 1st Floor	Does not exist
<b>Surface Mounted</b>	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on 1st Floor	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on 1st Floor	Does not exist
<b>Recessed Mounted</b>	
Instance on 1st Floor	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor	Does not exist
<b>Local Sound System</b>	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Projection System</b>	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Is the projector on a cart or installed on the ceiling?	Ceiling
Deficiency	No deficiencies recorded
<b>Theater Lighting System</b>	
Instance on 1st Floor	Inspected
<b>Dimming System</b>	

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**X600**

Question	Response
<b>AUDITORIUM</b>	
<b>Theater Lighting System</b>	
<b>Dimming System</b>	
Instance on 1st Floor	Does not exist
<b>Theater Lighting</b>	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	21
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>CAFETERIA</b>	
Instance on 2nd Floor	Inspected
Instance on 2nd Floor	Inspected
<b>Lighting</b>	
Instance on 2nd Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 2nd Floor	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on 2nd Floor	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 2nd Floor	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on 2nd Floor	Inspected
<b>Pendant Mounted</b>	
Instance on 2nd Floor	Does not exist
<b>Surface Mounted</b>	
Instance on 2nd Floor	Does not exist
<b>Recessed Mounted</b>	
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Local Sound System</b>	
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Projection System</b>	
Instance on 2nd Floor	Does not exist
<b>Theater Lighting System</b>	
Instance on 2nd Floor	Does not exist
<b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b>	
<b>Lighting</b>	
Does a Chandelier Exist?	No
<b>Lighting Fixture - Fluorescent</b>	
Instance on 2nd Floor	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on 2nd Floor	Inspected
<b>Pendant Mounted</b>	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on 2nd Floor	Does not exist
<b>Recessed Mounted</b>	
Instance on 2nd Floor	Does not exist

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**X600**

Question	Response
<b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Incandescent</b>	Does not exist
<b>Lighting Fixture - LED</b>	Inspected
<b>Pendant Mounted</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>COMPUTER LAB</b>	
	Inspected
Instance on Room B38	Inspected
Power Panel?	No
Instance on Room B42	Inspected
Power Panel?	Yes
Instance on Room 144/146, 257	Inspected
Power Panel?	Yes
<b>Lighting</b>	
Instance on Room B38	Inspected
Instance on Room B42	Inspected
Instance on Room 144/146, 257	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room B38	Does not exist
Instance on Room B42	Does not exist
Instance on Room 144/146, 257	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on Room B38	Does not exist
Instance on Room B42	Does not exist
Instance on Room 144/146, 257	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room B38	Does not exist
Instance on Room B42	Does not exist
Instance on Room 144/146, 257	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on Room B38	Inspected
Instance on Room B42	Inspected
Instance on Room 144/146, 257	Inspected
<b>Pendant Mounted</b>	
Instance on Room B38	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room B42	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 144/146, 257	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on Room B38	Does not exist
Instance on Room B42	Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**X600**

Question	Response
<b>COMPUTER LAB</b>	
<b>Lighting</b>	
<b>Lighting Fixture - LED</b>	
<b>Surface Mounted</b>	
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 144/146, 257	Does not exist
<b>Recessed Mounted</b>	
Instance on Room B38	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room B42	Does not exist
Instance on Room 144/146, 257	Does not exist
<b>Raceway With Receptacles</b>	
Instance on Room B38	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room B42	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 144/146, 257	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>GYMNASIUM</b>	Inspected
Instance on 3rd Floor	Inspected
<b>Lighting</b>	
Instance on 3rd Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 3rd Floor	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on 3rd Floor	Inspected
<b>Pendant Mounted</b>	
Instance on 3rd Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on 3rd Floor	Does not exist
<b>Recessed Mounted</b>	
Instance on 3rd Floor	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 3rd Floor	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on 3rd Floor	Does not exist
<b>Local Sound System</b>	
Instance on 3rd Floor	Inspected
Instance Condition	2- Between Good and Fair
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Projection System</b>	
Instance on 3rd Floor	Does not exist
<b>Scoreboard</b>	
Instance on 3rd Floor	Inspected
Instance Condition	5- Poor

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**X600**

Question	Response
<b>GYMNASIUM</b>	
<b>Scoreboard</b>	
Deficiency	NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Theater Lighting System</b>	
Instance on 3rd Floor	Does not exist
<b>KITCHEN</b>	
Instance on Building Addition - 2nd Floor	Inspected
<b>Lighting</b>	
Instance on Building Addition - 2nd Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Building Addition - 2nd Floor	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on Building Addition - 2nd Floor	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Building Addition - 2nd Floor	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on Building Addition - 2nd Floor	Inspected
<b>Pendant Mounted</b>	
Instance on Building Addition - 2nd Floor	Does not exist
<b>Surface Mounted</b>	
Instance on Building Addition - 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on Building Addition - 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>LIBRARY</b>	
Instance on Room 260	Inspected
<b>Lighting</b>	
Instance on Room 260	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 260	Inspected
<b>Pendant Mounted</b>	
Instance on Room 260	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on Room 260	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on Room 260	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Instance on Room 260	Does not exist
<b>Lighting Fixture - Incandescent</b>	

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**X600**

Question	Response
<b>LIBRARY</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 260	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on Room 260	Does not exist
<b>Raceway With Receptacles</b>	
Instance on Room 260	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Projection System</b>	
Instance on Room 260	Does not exist
<b>LOCKER ROOM</b>	Inspected
Instance on 3rd Floor - Boys, 3rd Floor - Girls	Inspected
Alternative Use	No
<b>Lighting</b>	
Instance on 3rd Floor - Boys, 3rd Floor - Girls	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 3rd Floor - Boys, 3rd Floor - Girls	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on 3rd Floor - Boys, 3rd Floor - Girls	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 3rd Floor - Boys, 3rd Floor - Girls	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on 3rd Floor - Boys, 3rd Floor - Girls	Inspected
<b>Pendant Mounted</b>	
Instance on 3rd Floor - Boys, 3rd Floor - Girls	Does not exist
<b>Surface Mounted</b>	
Instance on 3rd Floor - Boys, 3rd Floor - Girls	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on 3rd Floor - Boys, 3rd Floor - Girls	Does not exist
<b>MULTIPURPOSE ROOM</b>	Does not exist
<b>SCIENCE DEMO ROOM</b>	Inspected
Instance on Room 357	Inspected
Power Panel?	No
Alternative Use	Yes
Instance on Room 364	Inspected
Power Panel?	No
Alternative Use	No
Instance on Room 366	Inspected
Power Panel?	No
Alternative Use	No
<b>Lighting</b>	
Instance on Room 357	Inspected
Instance on Room 364	Inspected
Instance on Room 366	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 357	Does not exist
Instance on Room 364	Does not exist
Instance on Room 366	Does not exist
<b>Lighting Fixture - HID</b>	

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**X600**

Question	Response
<b>SCIENCE DEMO ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - HID</b>	
Instance on Room 357	Does not exist
Instance on Room 364	Does not exist
Instance on Room 366	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 357	Does not exist
Instance on Room 364	Does not exist
Instance on Room 366	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on Room 357	Inspected
Instance on Room 364	Inspected
Instance on Room 366	Inspected
<b>Pendant Mounted</b>	
Instance on Room 357	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 364	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 366	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on Room 357	Does not exist
Instance on Room 364	Does not exist
Instance on Room 366	Does not exist
<b>Recessed Mounted</b>	
Instance on Room 357	Does not exist
Instance on Room 364	Does not exist
Instance on Room 366	Does not exist
<b>Emergency Gas Shut-Off Valve</b>	
Instance on Room 357	Does not exist
Instance on Room 364	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 366	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Emergency Shut-Off Power</b>	
Instance on Room 357	Does not exist
Instance on Room 364	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 366	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Power Supply</b>	
Instance on Room 357	Inspected
Instance on Room 364	Inspected
Instance on Room 366	Inspected
<b>Instructor Unit</b>	
Instance on Room 357	Inspected



**NYC Department of Education**  
**Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**X600**

Question	Response
<b>SCIENCE DEMO ROOM</b>	
<b>Power Supply</b>	
<b>Instructor Unit</b>	
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 364	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 366	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Meter Demonstration Unit</b>	
Instance on Room 357	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 364	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 366	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Projection System</b>	
Instance on Room 357	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 364	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 366	Does not exist
<b>SCIENCE LAB</b>	
Instance on Room 452	Inspected
Power Panel?	Yes
Alternative Use	No
Instance on Room 313, 323, 460	Inspected
Power Panel?	Yes
Alternative Use	Yes
<b>Lighting</b>	
Instance on Room 452	Inspected
Instance on Room 313, 323, 460	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 452	Does not exist
Instance on Room 313, 323, 460	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on Room 452	Does not exist
Instance on Room 313, 323, 460	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 452	Does not exist
Instance on Room 313, 323, 460	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on Room 452	Inspected
Instance on Room 313, 323, 460	Inspected
<b>Pendant Mounted</b>	
Instance on Room 452	Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**X600**

Question	Response
<b>SCIENCE LAB</b>	
<b>Lighting</b>	
<b>Lighting Fixture - LED</b>	
<b>Pendant Mounted</b>	
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 313, 323, 460	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on Room 452	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 313, 323, 460	Does not exist
<b>Recessed Mounted</b>	
Instance on Room 452	Does not exist
Instance on Room 313, 323, 460	Does not exist
<b>Emergency Gas Shut-Off Valve</b>	
Instance on Room 452	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 313, 323, 460	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Emergency Shut-Off Power</b>	
Instance on Room 452	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 313, 323, 460	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Power Supply</b>	
Instance on Room 452	Inspected
Instance on Room 313, 323, 460	Inspected
<b>Instructor Unit</b>	
Instance on Room 452	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 313, 323, 460	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Meter Demonstration Unit</b>	
Instance on Room 452	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 313, 323, 460	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Student Unit</b>	
Instance on Room 452	Does not exist
Instance on Room 313, 323, 460	Does not exist
<b>Projection System</b>	
Instance on Room 452	Does not exist

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**X600**

Question	Response
<b>SCIENCE LAB</b>	
<b>Projection System</b>	
Instance on Room 313, 323, 460	Does not exist
<b>SCIENCE PREP ROOM</b>	
Instance on Room 317	Inspected
Power Panel?	No
Alternative Use	Yes
Instance on Room 456	Inspected
Power Panel?	Yes
Alternative Use	Yes
<b>Lighting</b>	
Instance on Room 317	Inspected
Instance on Room 456	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 317	Does not exist
Instance on Room 456	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on Room 317	Does not exist
Instance on Room 456	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 317	Does not exist
Instance on Room 456	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on Room 317	Inspected
Instance on Room 456	Inspected
<b>Pendant Mounted</b>	
Instance on Room 317	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 456	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on Room 317	Does not exist
Instance on Room 456	Does not exist
<b>Recessed Mounted</b>	
Instance on Room 317	Does not exist
Instance on Room 456	Does not exist
<b>Emergency Gas Shut-Off Valve</b>	
Instance on Room 317	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 456	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Emergency Shut-Off Power</b>	
Instance on Room 317	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 456	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Power Supply</b>	

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**X600**

Question	Response
<b>SCIENCE PREP ROOM</b>	
<b>Power Supply</b>	
Instance on Room 317	Inspected
Instance on Room 456	Does not exist
<b>Instructor Unit</b>	
Instance on Room 317	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>SWIMMING POOL</b>	Does not exist
<b>TOILET ROOM - STAFF</b>	Inspected
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Does not exist
<b>Lighting Fixture - HID</b>	Does not exist
<b>Lighting Fixture - Incandescent</b>	Does not exist
<b>Lighting Fixture - LED</b>	Inspected
<b>Pendant Mounted</b>	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>TOILET ROOM - STUDENT</b>	Inspected
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Does not exist
<b>Lighting Fixture - HID</b>	Does not exist
<b>Lighting Fixture - Incandescent</b>	Does not exist
<b>Lighting Fixture - LED</b>	Inspected
<b>Pendant Mounted</b>	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>AUXILIARY SIGNAL/BELL SYSTEM</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>EMERGENCY DC STANDBY BATTERY POWER</b>	Does not exist
<b>EMERGENCY GENERATOR SET</b>	Does not exist
<b>EMERGENCY LIGHT/EXIT LIGHT PANEL</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>EMERGENCY LIGHTING</b>	Inspected
<b>Battery Pack</b>	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Non Battery Pack</b>	
Condition	2- Between Good and Fair

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**X600**

<b>Question</b>	<b>Response</b>
<b>EMERGENCY LIGHTING</b>	
<b>Non Battery Pack</b>	
Deficiency	No deficiencies recorded
<b>EXIT LIGHT</b>	Inspected
<b>Battery Pack</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Non Battery Pack</b>	Does not exist
<b>EXIT/EMERGENCY LIGHT</b>	Does not exist
<b>FIRE ALARM SYSTEM</b>	Inspected
<b>Bell/Horn</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Strobe</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Manual Pull Station</b>	Inspected
Condition	3- Fair
Deficiency	PULL STATION NOT OPERATIONAL
Deficiency Location/Instance	Basement Corridor near B39
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
<b>Fan Shutdown Control</b>	Does not exist
<b>Duct Smoke Detector</b>	Does not exist
<b>Area Smoke Detector</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	DETECTOR NOT OPERATIONAL
Deficiency Location/Instance	Room 160
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
<b>CO Detector</b>	Under construction
<b>Heat Detector</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Elevator Recall</b>	Does not exist
<b>Magnetic Door Holder/Contactor</b>	Does not exist
<b>Fused Cutout Panel</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Fire Alarm Digital Communicator</b>	Does not exist
<b>Main Panel</b>	Inspected
<b>Bell At Panel</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Fire Alarm Control Panel (Electronic)</b>	Inspected
Instance	Main Entrance Lobby
Instance Condition	3- Fair

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**X600**

Question	Response
<b>FIRE ALARM SYSTEM</b>	
<b>Main Panel</b>	
<b>Fire Alarm Control Panel (Electronic)</b>	
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Mircom
Model	FX - 2000
EquipmentId	Fire Alarm Control Panel
Installation Year	2006
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Fire Alarm Control Panel (Standard)</b>	Does not exist
<b>Sub-Panel</b>	Does not exist
<b>Remote Annunciator</b>	Inspected
<b>Display Monitor</b>	Does not exist
<b>Panel</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Printer</b>	Does not exist
<b>Punch Register</b>	Does not exist
<b>Sprinkler Flow/Air Pressure Switch</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Tamper Flow Switch/Chain</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>GROUNDING SYSTEM</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>INTERCOM SYSTEM</b>	Does not exist
<b>LAN</b>	Inspected
<b>Local Distribution Frame (I/LDF)</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Main Equipment Rack (MDF)</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>LIGHTNING PROTECTION</b>	Does not exist
<b>MOTOR CONTROLLER</b>	Inspected
<b>MOTOR CONTROL CENTER</b>	Does not exist
<b>MOTOR STARTER/CONTACTOR</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Variable Frequency Drive</b>	Does not exist
<b>PANEL BOARD</b>	Inspected
<b>Fused Disconnect Switch Type</b>	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Mechanical Equipment Room 439, B3, B46, B49, B65, Boiler Room
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**X600**

<b>Question</b>	<b>Response</b>
<b>PANEL BOARD</b>	
<b>Fused Disconnect Switch Type</b>	
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Fused Knife Switch Type</b>	Does not exist
<b>Fused Toggle Switch Type</b>	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B29
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Molded Case Circuit Breaker Type</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	4th Floor Corridor, Kitchen, Computer Lab Room 257, 1st and 2nd Floor Corridors
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>PUBLIC ADDRESS SYSTEM</b>	Inspected
Instance	Room 116B
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Bogen Quantum Multicom IP
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>SECURITY</b>	Inspected
<b>IPDVS/CCTV System</b>	Under construction
<b>Intrusion Alarm System</b>	Inspected
<b>Central Control Panel</b>	Inspected
Instance	Custodian's Office
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	4140 XMPT
Installation Year	1996
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Custodian's Office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 3
Violations	No violations recorded
<b>Infrared Sensor</b>	Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**X600**

Question	Response
<b>SECURITY</b>	
<b>Intrusion Alarm System</b>	
<b>Infrared Sensor</b>	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Panic Switch</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Remote Annunciator</b>	
Condition	Inspected
Deficiency	3- Fair
Deficiency	No deficiencies recorded
<b>Siren/Strobe</b>	
Condition	Inspected
Deficiency	3- Fair
Deficiency	No deficiencies recorded
<b>Lighting - Security</b>	
Condition	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE PHOTOCELL NOT OPERATIONAL
Deficiency Location/Instance	Nearby Exit 1
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Violations	No violations recorded
<b>SERVICE SWITCH</b>	
Instance	Inspected
Instance	Electrical Room B29
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Metropolitan
EquipmentId	Freight Passenger Elev. Control PNL.
Capacity/Size Quantity	400
Capacity/Size UOM	Amps
Source of Capacity/Size	Fuse Size
Installation Year	1966
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B29
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room B29
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Metropolitan
EquipmentId	Heating Equip. Power Panel
Capacity/Size Quantity	500
Capacity/Size UOM	Amps
Source of Capacity/Size	Fuse Size
Installation Year	1966
Source of Installation Year	Documented



**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**X600**

Question	Response
<b>SERVICE SWITCH</b>	
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B29
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room B29
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Metropolitan
EquipmentId	Main Distribution Center No.1
Capacity/Size Quantity	3000
Capacity/Size UOM	Amps
Source of Capacity/Size	Fuse Size
Installation Year	1966
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B29
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room B29
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Metropolitan
EquipmentId	Main Distribution Center No. 2
Capacity/Size Quantity	3000
Capacity/Size UOM	Amps
Source of Capacity/Size	Fuse Size
Installation Year	1966
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B29
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room B29
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Metropolitan
EquipmentId	Service Switch for Welding Shop Panel
Capacity/Size Quantity	800
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**X600**

Question	Response
<b>SERVICE SWITCH</b>	
Installation Year	1966
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B29
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>SWITCHBOARD</b>	Inspected
Number of Spares	4
<b>Fused Disconnect Switch Type</b>	Inspected
Instance	Electrical Room B29
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Metropolitan Electric
EquipmentId	N/A
Capacity/Size Quantity	3000
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	6
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Fuse Size
Installation Year	1966
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B29
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room B44
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Metropolitan Electric
EquipmentId	N/A
Capacity/Size Quantity	3000
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	6
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Fuse Size
Installation Year	1966
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B44
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Fused Knife Switch Type</b>	Does not exist

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

***Electrical Inspection***

**X600**

<b>Question</b>	<b>Response</b>
<b>SWITCHBOARD</b>	
Molded Case Circuit Breaker Type	Does not exist
<b>TELEPHONE SYSTEM</b>	
PBX/Intercom	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	5- Poor
Deficiency	SYSTEM NOT OPERATIONAL
Deficiency Location/Instance	Telephone Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>TRANSFORMER</b>	
	Does not exist