Electrical Inspection	X650
-----------------------	------

Asset:	JANE ADDAMS	S HS - BRONX, 900 T	INTON AVENUE, BRO	ONX, NY, 10456	5		
Inspection	n Id Inspection Type				Time	In	Last Edited
	4886 ELECTRICAL				2024	-04-22 09:19Al	M 2024-05-24 09:41AN
set Data							
Question	l			Answer			
Have any	Systems/Major Building (Components been upgrad	ed?	Systems:	LAN		
				Years:	2022		
				Systems:	Molded Case	Circuit Breaker	Panel Board
				Years:	2019, 1997		
				Systems:	Intercom Sys	tem (Elevator)	
				Years:	2019		
				Systems:	Emergency L	ighting (Battery	Pack)
				Years:	2017		
				Systems:	Security Ligh	its	
				Years:	2015, 1997		
				Systems:	LED Lighting	ss System, Exit i g (Gymnasium,	Lights (Battery Pack), Auditorium)
				Years:	2015		
				Systems:	Telephone Sy	rstem	
				Years:	2012		
				Systems:	Alarm System Fluorescent L	n, Local Sound Lighting, Audito	trusion Alarm System, Fire System, Interior rium (Theatre Lighting h, Most Switchboard
				Years:	1997	st service switc.	ii, Most Switchooard
				Systems:		nect Switch Typ	e Panel Board
				Years:	1995	71	
Type of S	Service			Below Gro	ound		
	eractive Whiteboard (IWB)	Exist?		Yes			
	netration In Electrical Room			Yes			
DEDICA	ATED INTERCOMS I	N FIRE RESCUE AR	REAS				
Question					Response		
	•	nce Areas, Fire Rescue A	reas, and/or Holding Roon	ns in Y	'es		
your bu	iliding? ledicated intercoms availab	ale in all of these spaces t	For use during a fire?		/es		
	all dedicated intercoms op		or use during a rice.		lo Io		
	hich rooms or areas have i		d intercoms?		Rooms 301, 201		
iority Co		•					
Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
ast Year?	Category	Description	Affected	Description	Notified	Title	Image
0	Water Penetration in Electrical Room	N/A	Electrical Equipment	Electrical Room B36	John Anglero	Handyman	No Photo Taken
es	Intercom - Not	N/A	Intercom	Elevator	John	Handyman	No Photo Taken
	Connected to Remote		System -	Device IDs:	Anglero		
	Monitoring Station		Elevator	2P1807, 2P10101			
es	Fire Alarm System -	N/A	Fire Alarm	Corridor near	John	Handyman	No Photo Taken
0.5	Components Missing	- W. A. B.	System -	Stairs C/3, C/2	Anglero	Tanayman	1.5 I How Turon
2011	. 8		Magnetic	-	S		
			Door				
			Holder/Contac				
spection			tor				
speciion				Response			
Question	-			response			
Question	1						
Electrica	al ETIC FIELD			Does not e	wist		

Building Condition Assessment Survey 2023-2024

Electrical InspectionX650QuestionResponse

Question	Response
AUDITORIUM	
Instance on 1st Floor	Inspected
House Lighting	
Instance on 1st Floor	Inspected
Does a Chandelier Exist?	Yes
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	5- Poor
Installation Year	1997
Source of Installation Year	Documented
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded

Building Condition Assessment Survey 2023-2024

estion	Response
UDITORIUM	
Projection System	
Instance on 1st Floor	Does not exist
Theater Lighting System	
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	DIMMING RACK/LIGHT CONSOLE BEYOND USEFUL LIFE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Theater Lighting	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	162
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
AFETERIA	Inspected
Instance on 3rd Floor - Staff	Inspected
Instance on 3rd Floor - Students	Inspected
Lighting	1
Instance on 3rd Floor - Staff	Inspected
Instance on 3rd Floor - Students	Inspected
Lighting Fixture - Fluorescent	
Instance on 3rd Floor - Staff	Inspected
Instance on 3rd Floor - Students	Inspected
Pendant Mounted	mspecceu
	Years and d
Instance on 3rd Floor - Staff	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on 3rd Floor - Students	Does not exist
Surface Mounted	
Instance on 3rd Floor - Staff	Does not exist
Instance on 3rd Floor - Students	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	16
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2

uestion	Response
CAFETERIA	response
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Violations	No violations recorded
Recessed Mounted	1.0 Violations recorded
Instance on 3rd Floor - Staff	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on 3rd Floor - Students	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	30
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - HID	
Instance on 3rd Floor - Staff	Does not exist
Instance on 3rd Floor - Students	Does not exist
Lighting Fixture - Incandescent	
Instance on 3rd Floor - Staff	Does not exist
Instance on 3rd Floor - Students	Does not exist
Lighting Fixture - LED	
Instance on 3rd Floor - Staff	Does not exist
Instance on 3rd Floor - Students	Does not exist
Local Sound System	
Instance on 3rd Floor - Staff	Does not exist
Instance on 3rd Floor - Students	Inspected
Instance Condition	5- Poor
Installation Year	1997
Source of Installation Year	Documented
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Projection System	
Instance on 3rd Floor - Staff	Does not exist
Instance on 3rd Floor - Students	Does not exist
Theater Lighting System	
Instance on 3rd Floor - Staff	Does not exist
Instance on 3rd Floor - Students	Does not exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected

Building Condition Assessment Survey 2023-2024

incui Inspection		11030
Question	Response	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE		
Lighting		
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	3- Fair	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Deficiency Quantity	920	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Surface Mounted	Inspected	
Condition	3- Fair	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Deficiency Quantity	420	
Quantity Uom	EACH DEDLACE LIBORADE	
Potential Action Urgency of Action	REPLACE-UPGRADE PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Recessed Mounted	Inspected	
Condition	3- Fair	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Deficiency Quantity	120	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Inspected	
Pendant Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - LED	Does not exist	
COMPUTER LAB	Does not exist	
GYMNASIUM GYMNASIUM	Inspected	
Instance on 4th Floor	Inspected	
Lighting	inspected	
Instance on 4th Floor	Inspected	
Lighting Fixture - Fluorescent	пърсски	
Instance on 4th Floor	Does not exist	
Lighting Fixture - HID	DOGS HOLCAIST	
Instance on 4th Floor	Does not exist	
	DOCS HOT CYIST	
Lighting Fixture - Incandescent	Door not avist	
Instance on 4th Floor	Does not exist	
Lighting Fixture - LED	Turneretad	
Instance on 4th Floor	Inspected	
Pendant Mounted	December 1997	
Instance on 4th Floor	Does not exist	

Question	Response
GYMNASIUM	·
Lighting	
Lighting Fixture - LED	
Surface Mounted	
Instance on 4th Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 4th Floor	Does not exist
Local Sound System	
Instance on 4th Floor	Inspected
Instance Condition	5- Poor
Installation Year	1997
Source of Installation Year	Documented
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Projection System	
Instance on 4th Floor	Does not exist
Scoreboard	
Instance on 4th Floor	Inspected
Instance Condition	5- Poor
Deficiency	NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Theater Lighting System	
Instance on 4th Floor	Does not exist
KITCHEN	Inspected
Instance on 3rd Floor	Inspected
Lighting	
Instance on 3rd Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 3rd Floor	Inspected
Pendant Mounted	
Instance on 3rd Floor	Does not exist
Surface Mounted	
Instance on 3rd Floor	Does not exist
Recessed Mounted	
Instance on 3rd Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	80
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded

D	X65
Kesponse	
Dona and smirt	
Does not exist	
Does not exist	
Does not exist	
Door not exist	
Inspected	
Inspected	
*	
Inspected	
ivo violations recorded	
Inchected	
LEVEL 2	
No violations recorded	
Inspected	
3- Fair	
LIGHTING FIXTURE BEYOND USEFUL LIFE	
EACH	
REPLACE-UPGRADE	
PRIORITY 1	
LEVEL 2	
No violations recorded	
Does not exist	
Does not exist	
Does not exist	
Inspected	
3- Fair	
No deficiencies recorded	_
	Inspected 3- Fair LIGHTING FIXTURE BEYOND USEFUL LIFE 52 EACH REPLACE-UPGRADE PRIORITY 1 LEVEL 2 No violations recorded Does not exist Does not exist Inspected 3- Fair

Building Condition Assessment Survey 2023-2024

not exist ted
ted
ted
ted
ted
ted
ted
ted
ted
ted
:
TING FIXTURE BEYOND USEFUL LIFE
[
ACE-UPGRADE
RITY 1
L 2
plations recorded
ted
;
TING FIXTURE BEYOND USEFUL LIFE
I
ACE-UPGRADE
RITY 1
L 2
plations recorded
not exist
ted
:
ΓING FIXTURE BEYOND USEFUL LIFE
ACE-UPGRADE
RITY 1
L2
plations recorded
not exist
not exist
not exist
not exist not exist
not exist

Does not exist

Instance on 4th Floor - Boys

Electrical Inspection	X650

Does not exist	
Does not exist	
Inspected	
Yes	
Increasted	
Inspected	
Inspected	
<u> </u>	
<u> </u>	
REPLACE-UPGRADE	
LEVEL 2	
No violations recorded	
Does not exist	
Does not exist	
Does not exist	
Does not exist	
DOCS HOT CAIST	
Does not exist	
DOG NOT CAST	
Does not exist	
Does not exist	
	Inspected Inspected Inspected No No No Inspected No Yes Inspected 3- Fair LIGHTING FIXTURE BEYOND USEFUL LIFE 45 EACH REPLACE-UPGRADE PRIORITY 1 LEVEL 2 No violations recorded Inspected 3- Fair LIGHTING FIXTURE BEYOND USEFUL LIFE 56 EACH REPLACE-UPGRADE PRIORITY 1 LEVEL 2 No violations recorded Inspected J- Fair LIGHTING FIXTURE BEYOND USEFUL LIFE 56 EACH REPLACE-UPGRADE PRIORITY 1 LEVEL 2 No violations recorded

Electrical Inspection	A030

estion	Response
	response
CCIENCE DEMO ROOM Emergency Coa Shut Off Value	
Emergency Gas Shut-Off Valve Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Rooms 135, 136, 137	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<u> </u>	ino deficiencies recorded
Emergency Shut-Off Power Instance on Rooms 117, 225, 227	Does not exist
Instance on Rooms 117, 223, 227 Instance on Rooms 135, 136, 137	Inspected
Instance Condition	3- Fair
	No deficiencies recorded
Deficiency	No deliciencies recorded
Power Supply	To an art of
Instance on Rooms 117, 225, 227	Inspected
Instance on Rooms 135, 136, 137	Inspected
Instructor Unit	
Instance on Rooms 117, 225, 227	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Rooms 135, 136, 137	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Rooms 117, 225, 227	Does not exist
Instance on Rooms 135, 136, 137	Does not exist
Projection System	
Instance on Rooms 117, 225, 227	Does not exist
Instance on Rooms 135, 136, 137	Does not exist
CIENCE LAB	Inspected
Instance on Rooms 118, 120	Inspected
Power Panel?	No
Alternative Use	No
Lighting	
Instance on Rooms 118, 120	Inspected
Lighting Fixture - Fluorescent	
Instance on Rooms 118, 120	Inspected
Pendant Mounted	
Instance on Rooms 118, 120	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	60
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	
Instance on Rooms 118, 120	Does not exist
Recessed Mounted	
Instance on Rooms 118, 120	Does not exist
Lighting Fixture - HID	
Instance on Rooms 118, 120	Does not exist
Lighting Fixture - Incandescent	

Question	Response
SCIENCE LAB	
Lighting	
Lighting Fixture - LED	
Instance on Rooms 118, 120	Does not exist
Emergency Gas Shut-Off Valve	
Instance on Rooms 118, 120	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Rooms 118, 120	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Power Supply	
Instance on Rooms 118, 120	Inspected
Instructor Unit	
Instance on Rooms 118, 120	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Rooms 118, 120	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Student Unit	
Instance on Rooms 118, 120	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Projection System	
Instance on Rooms 118, 120	Does not exist
SCIENCE PREP ROOM	Inspected
Instance on Room 115	Inaccessible
SWIMMING POOL	Does not exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	18
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	Does not exist

Building Condition Assessment Survey 2023-2024

Question	Response
TOILET ROOM - STAFF	
Lighting	
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	25
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Inspected
Automatic Transfer Switch (ATS)	Inspected
Instance	Auditorium Stage (By Exit 5)
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ASCO
EquipmentId	N/A (Dimmer Transfer Switch)
Capacity/Size Quantity	30
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1997
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Room B40A
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Master Control Systems
1.100100100100101	Automatic Transfer Switch
EquipmentId	Automatic Transfer Switch
EquipmentId Capacity/Size Quantity	Automatic Transfer Switch

Question		Response	
EMERGEN	NCY GENERATOR SET	•	
	c Transfer Switch (ATS)		
	Source of Capacity/Size	Nameplate	
_	Installation Year	1997	
	Source of Installation Year	Documented	
Ī	Deficiency	No deficiencies recorded	
-	Instance	Electrical Room B37	
Ī	Instance Condition	3- Fair	
-	Instance Quantity	1	
-	Instance Quantity Uom	EACH	
-		Cummins Onan	
	Manufacturer	ATS-1	
	EquipmentId	600	
	Capacity/Size Quantity		
	Capacity/Size UOM	Amps	
_	Source of Capacity/Size	Nameplate 1997	
	Installation Year	1997 Documented	
_	Source of Installation Year	No deficiencies recorded	
-	Deficiency		
_	Instance	Generator Room B36	
Ī	Instance Condition	3- Fair	
I	Instance Quantity	1	
I	Instance Quantity Uom	EACH	
- N	Manufacturer	Cummins Onan	
I	EquipmentId	Fire Alarm ATS-2	
	Capacity/Size Quantity	40	
	Capacity/Size UOM	Amps	
	Source of Capacity/Size	Nameplate	
_	Installation Year	1997	
	Source of Installation Year	Documented	
-	Deficiency	No deficiencies recorded	
Battery C		Inspected	
_	Instance	Generator Room B36	
	Instance Condition	3- Fair	
_	Instance Quantity		
-		1 EACH	
_	Instance Quantity Uom		
	Manufacturer	SENS	
	EquipmentId	Battery Charger	
	Capacity/Size Quantity	10	
	Capacity/Size UOM	AmpsDC	
	Capacity/Size 2 Quantity	24	
	Capacity/Size 2 UOM	VDC	
_	Source of Capacity/Size	Nameplate	
	Installation Year	1997	
_	Source of Installation Year	Documented	
I	Deficiency	No deficiencies recorded	
	cy Distribution Board	Inspected	
Number	of Spares	5	
Fused D	Disconnect Switch Type	Inspected	
Ī	Instance	Generator Room B36	
Ī	Instance Condition	3- Fair	
_	Instance Quantity	1	
_	Instance Quantity Uom	EACH	
-	<u> </u>	Siemens	
1	Manufacturer	Gen Dist BD	
	EquipmentId Capacity/Size Quantity	800	

Electrical Inspection	A050

	·· X · · · · · · ·		
Question		Response	
EMERG	ENCY GENERATOR SET		
Emerge	ency Distribution Board		
Fused	d Disconnect Switch Type		
	Capacity/Size 2 Quantity	1	
	Capacity/Size 2 UOM	Section(s)	
	Source of Capacity/Size	Nameplate	
	Installation Year	1997	
	Source of Installation Year	Documented	
	Deficiency	No deficiencies recorded	
Mold	ed Case Circuit Breaker Type	Does not exist	
Diesel		Inspected	
	Instance	Generator Room B36	
	Instance Condition	3- Fair	
	Instance Quantity	1	
	Instance Quantity Uom	EACH	
	Manufacturer	Cummins Onan	
	EquipmentId	Emergency Generator	
	Capacity/Size Quantity	313	
	Capacity/Size UOM	kVA	
	Capacity/Size 2 Quantity	250	
	Capacity/Size 2 UOM	kW	
	Capacity/Size 3 Quantity	867	
	Capacity/Size 3 UOM	Amps	
	Source of Capacity/Size	Nameplate	
	Installation Year	1997	
	Source of Installation Year	Documented	
	Deficiency	No deficiencies recorded	
Natura		Does not exist	
	ENCY LIGHT/EXIT LIGHT PANEL	Does not exist	
-	ENCY LIGHTING	Inspected	
Battery Condi		Inspected 2- Between Good and Fair	
Condi			
	Deficiency	No deficiencies recorded	
Non Ba	attery Pack	Inspected	
Condi	ition	3- Fair	
	Deficiency	No deficiencies recorded	
EXIT LI	GHT	Inspected	
Battery	y Pack	Inspected	
Condi		2- Between Good and Fair	
	Deficiency	FIXTURE NOT OPERATIONAL	
	Deficiency Location/Instance	Kitchen	
	Deficiency Quantity	1	
	Quantity Uom	EACH	
	Potential Action	REPLACE	
	Urgency of Action	PRIORITY 5	
	Purpose of Action	LEVEL 2	
	Violations	No violations recorded	
	attery Pack	Inspected	
Condi		3- Fair	
	Deficiency	No deficiencies recorded	
EXIT/EN	MERGENCY LIGHT	Does not exist	
	ARM SYSTEM	Inspected	
FIRE AI	termination and the second	_	
	nrn	Inspected	
FIRE AL Bell/Ho		Inspected 3- Fair	

Building Condition Assessment Survey 2023-2024

cui inspection		AUS
estion	Response	
IRE ALARM SYSTEM		
Strobe	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
CO Detector	Does not exist	
Heat Detector	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Elevator Recall	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Magnetic Door Holder/Contactor	Inspected	
Condition	4- Between Fair and Poor	
Deficiency	CONTACTOR MISSING	
Deficiency Location/Instance	Corridor near Stair C/3, C/2	
Deficiency Quantity	4	
Quantity Uom	EACH	
Potential Action	INSTALL CONTACTOR	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Fused Cutout Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Inspected	
Instance	Room B40A	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Ademco	
EquipmentId	Fire Alarm Communicator	
Installation Year	1997	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Main Panel	Inspected	
Bell At Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	

Electrical Inspection	A030

uestion	Response
FIRE ALARM SYSTEM	
Main Panel	
Fire Alarm Control Panel (Electronic)	
Manufacturer	Edwards System Technology
Model	RMDP-1N
EquipmentId	Fire Alarm Control Panel
Installation Year	1997
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not exist
Sub-Panel	Does not exist
Remote Annunciator	Inspected
Display Monitor	Does not exist
Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
	Does not exist
Printer	
Punch Register	Does not exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Inspected
Elevator	Inspected 1- Good
Condition	
Deficiency	NOT CONNECTED TO REMOTE MONITORING STATION
Deficiency Location/Instance	Elevator Device IDs: 2P1807, 2P10101
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	INSTALL CONNECTION
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Holding Area	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	1- Good
	No deficiencies recorded
Deficiency	
LIGHTNING PROTECTION	Does not exist
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not exist
variable Picquency Drive	DOG NOT CAST

Building Condition Assessment Survey 2023-2024

ctrical inspection	X650
Question	Response
PANEL BOARD	
Fused Disconnect Switch Type	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B37
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	CIRCUIT BREAKER NOT OPERATIONAL
Deficiency Location/Instance	Corridor near Rooms 101, 318
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE CIRCUIT BREAKER
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	Room 320B
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Dukane 250
Installation Year	2015
Source of Installation Year	Documented
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Classrooms and Corridors
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
SECURITY	Inspected
IPDVS/CCTV System	Under construction
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office - Room 129
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128BP
	1997
Installation Year Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Deficiency Location/Instance	Custodian's Office - Room 129
Deficiency Quantity	Custodian's Office - Room 129
Quantity Uom	EACH
Quality Oolii	EACH

Response	
DEDLACE	
Inspected	
3- Fair	
No deficiencies recorded	
Inspected	
3- Fair	
No deficiencies recorded	
<u> </u>	
-	
-	
3- Fair	
1	
EACH	
Square D	
Fire Pump	
600	
Amps	
Nameplate	
1997	
Documented	
No deficiencies recorded	
Electrical Room B37	
3- Fair	
•	
No deficiencies recorded	
	No deficiencies recorded Inspected 3- Fair No deficiencies recorded Inspected 3- Fair No deficiencies recorded Inspected 2- Between Good and Fair TIME CLOCK NOT OPERATIONAL Electrical Room 1 EACH REPLACE PRIORITY 3 LEVEL 3 No violations recorded Inspected Electrical Room B37 3- Fair 1 EACH Square D Fire Pump 600 Amps Nameplate 1997 Documented No deficiencies recorded Electrical Room B37

Building Condition Assessment Survey 2023-2024

X650

Response
3- Fair
1
EACH
Standard Switchboard
Main Switch
3000
Amps
Nameplate
1970
Documented
BEYOND USEFUL LIFE
Electrical Room B37
1
EACH
REPLACE
PRIORITY 1
LEVEL 2
No violations recorded
Inspected
7
Inspected

Capacity/Size Quantity	3000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1970
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B37
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
SWITCHBOARD	Inspected
Number of Spares	7
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room B37
	3- Fair
Instance Condition	
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Standard Switchboard
EquipmentId	N/A
Capacity/Size Quantity	3000
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	3
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	1970
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B37
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room B37
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	N/A
Capacity/Size Quantity	1600
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	3
Capacity/Size 2 UOM	Section(s)
	Service Switch Size
Source of Capacity/Size Installation Year	Service Switch Size 1997

Building Condition Assessment Survey 2023-2024

uestion	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Instance	Electrical Room B37
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Siemens
EquipmentId	Electrical Distribution Panel (Old TCUs)
Capacity/Size Quantity	600
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	1997
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not exist