### **Building Condition Assessment Survey 2023-2024**

#### Mechanical Inspection

Asset:	P.S. 723 - BRO	ONX, 3540 BIVONA STREE	T, BRONX, NY, 1	10475			
Inspection Id	I Inspection Type				Time	(n	Last Edited
213	33 MECHANICAL				2024-	01-04 07:42Al	M 2024-02-13 11:46AN
lsset Data							
Question				Answer			
Have any Sys	stems/Major Building		Systems:	Electric Dome	stic Water Hea	ter	
				Years:	2023		
				Systems:			; Student Toilet Room
						Toilet Room F	Fixtures (~50%)
				Years:	2022		
				Systems:	DX Split Syste	ems	
Are there fuel	1 toplas			Years:	2017		
		• • • •		No			
	ter main service entr	ies to the asset		l Let Elsen N	(ED		
	ooms Locations	g or Defective CO Detectors?		1st Floor M No	MER		
•	y Painted/Obstructed	•		No			
		vitches with Missing Hammers?		No compo	nents		
Priority Condi				po			
	riority	Condition	Component	Location	Person(s)	Person(s)	Photo
	ategory	Description	Affected	Description	Notified	Title	Image
No condition							
Inspection							
Question				Response			
Mechanical							
AIR CONI	DITIONING			Inspected			
	Water System			Does not e			
Condenser Water Distribution: Piping, Pumps and Auxiliaries			ies	Does not e			
Cooling Cooling T	Coil in Ductwork			Does not e			
DX Split				Inspected	Alst		
Indoor				Inspected			
Condi				1- Good			
-	Deficiency				ncies recorded		
Outdoo	2			Inspected			
Condi				1- Good			
-	Deficiency				ncies recorded		
Dry Cool				Does not e			
	d / Rooftop Unit			Does not e			
	d Terminal A/C			Does not e	exist		
	ant Leak Detection	System		Does not e	exist		
Refrigera	ant Piping	-		Inspected			
Conditio	on			1- Good			
1	Deficiency			No deficie	encies recorded		
Return F	lan			Does not e	exist		
CENTRAL	LACID WASTE NE	EUTRALIZING TANK		Does not e	exist	_	
CLIMATE	E CONTROL SYST	EM		Does not e	exist		
	TOR			Does not e	exist		
COMPAC	ING			Does not e	exist		
COMPACT CONVEYI							
CONVEYI	IC WATER SYSTE	М		Inspected			
CONVEYI DOMESTI	IC WATER SYSTE			Inspected Inspected			
CONVEYI DOMESTI Domestic	IC WATER SYSTE c Cold Water Systen			Inspected Inspected Does not e	exist		
CONVEYI DOMESTI Domestic Gravity	IC WATER SYSTE			Inspected			

### **Building Condition Assessment Survey 2023-2024**

#### **Mechanical Inspection**

unicui Inspecuon	Δ/
uestion	Response
DOMESTIC WATER SYSTEM	
Domestic Cold Water System	
Water Service	
Instance	1st Floor MER
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Deficiency	WATER MAIN:MISSING BACKFLOW PREVENTION DEVICE
Deficiency Location/Instance	1st Floor MER
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Domestic Hot Water System	Inspected
Domestic Hot Water Remote Storage Tank	Does not exist
Domestic Water Heat Exchanger	Does not exist
Electric Domestic Water Heater	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Gas Fired Domestic Water Heater	Does not exist
Oil Fired Domestic Water Heater	Does not exist
Heat Pump Domestic Water Heater	Does not exist
Domestic Water Distribution Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected
Interior Storm Piping	Does not exist
Sewage/Waste/Vent Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sewage Ejector Pump	Does not exist
Sump Pump	Does not exist
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist
FIXTURES	Inspected
Staff And Other	Inspected
Janitor Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	2- Between Good and Fair
Deficiency	CRACKED/PHYSICAL DAMAGE
Deficiency Location/Instance	Mans Toilet Room
Deficiency Quantity	
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Toilet	Inspected
	2- Between Good and Fair
Condition	
Condition Deficiency	No deficiencies recorded

## **Building Condition Assessment Survey 2023-2024**

#### **Mechanical Inspection**

	ΛΛ
Response	
Inspected	
Inspected	
1- Good	
No deficiencies recorded	
Inspected	
1- Good	
CLOGGED/LEAKING	
Girls Toilet Room	
1	
EACH	
MAINTENANCE	
PRIORITY 3	
Inspected	
1- Good	
No deficiencies recorded	
Inspected	
1- Good	
No deficiencies recorded	
Does not exist	
Does not exist	
Inspected	
3- Fair	
Does not exist	
inspected	
Inspected	
*	
Does not exist	
Does not exist	
Does not exist	
Inspected	
Yes	
Inspected	
	Inspected Inspec

### **Building Condition Assessment Survey 2023-2024**

#### **Mechanical Inspection**

estion	Response				
TENTILATION					
Exhaust Fan					
Deficiency	No deficiencies recorded				
Heating And Ventilating Unit	Does not exist				
Metal Ductwork	Inspected				
Condition	3- Fair				
Are there any uninsulated ductwork by design in Mechanical rooms?	No				
Are there chain operated dampers?	No				
Deficiency	DEFECTIVE REGISTER/DIFFUSER				
Deficiency Location/Instance	Exit-1				
Deficiency Quantity	1				
Quantity Uom	EACH				
Potential Action	MAINTENANCE				
Urgency of Action	PRIORITY 3				
Purpose of Action	LEVEL 2				
Violations	No violations recorded				
Supply Fan	Does not exist				
Unit Ventilator	Does not exist				