Building Condition Assessment Survey 2023-2024

Mechanical Inspection

Asset: JEROME PAR	K EDUCATIONAL BUILD	ING, 2865 CLAI	LIN AVENUE,	BRONX, NY,	10468	
Inspection Id Inspection Type				Time	In	Last Edited
1167 MECHANICAL				2023-	-11-20 08:30PM	1 2024-06-21 01:47PM
lsset Data						
Question			Answer			
Have any Systems/Major Building	Components been upgraded?		Systems:	Exhaust Fans	(~50%)	
			Years:	2020		
Are there fuel tanks?			No			
Total # of water main service entrie	es to the asset		1			
MERs/Fan Rooms Locations			None			
Are there any spaces with Missing			No			
Are there any Painted/Obstructed S			No			
Are there any Emergency Stop Swi	tches with Missing Hammers?		No compo	onents		
riority Condition						
Exist Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year? Category	Description	Affected	Description	Notified	Title	Image
No condition recorded						
Inspection						
Question			Response			
Mechanical			•			
AIR CONDITIONING			Inspected			
			Does not			
Chilled Water System			Does not			
Condenser Water Distribution: Piping, Pumps and Auxiliaries Cooling Coil in Ductwork			Does not			
Cooling Tower			Does not			
DX Split System			Inspected			
Indoor Unit			Inspected			
Condition			1- Good			
Deficiency			No deficie	encies recorded		
Outdoor Unit			Inspected			
Condition			1- Good			
Deficiency			No deficie	encies recorded		
Dry Cooler			Does not	exist		
Packaged / Rooftop Unit			Inspected			
Instance			Roof			
Instance Condition			2- Betwee	en Good and Fai	r	
Instance Quantity			1			
Instance Quantity Uor	n		EACH			
Manufacturer			Coolbreez	ze		
EquipmentId			RTU-1			
Capacity/Size Quantit	у		20			
Capacity/Size UOM			Tons			
Source of Capacity/Si	ze		Documen	ted		
Installation Year			2017			
Source of Installation	Year		Documen	ted		
Source of Heating			Gas			
Refrigerant Type			R-410A	TONGOREEC	TIVE COMPT	ESSOD
Deficiency Deficiency Location/Instance				TONS:DEFEC	TIVE COMPRI	ESSOR
Deficiency Location Deficiency Quantity			Roof 1			
Quantity Uom			I EACH			
Potential Action			REPLAC	E		
			PRIORIT			
Urgency of Action			1100001			
Purpose of Action			LEVEL 2			

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

	$\mathbf{A} \mathbf{D}$
Response	
Does not exist	
Does not exist	
Inspected	
1- Good	
No deficiencies recorded	
Does not exist	
Does not exist	
Inspected	
Does not exist	
Does not exist	
Does not exist	
Inspected	
Throughout	
2- Between Good and Fair	
1	
EACH	
81-100%	
No deficiencies recorded	
Does not exist	
Inspected	
•	
3- Fair	
Yes	
No deficiencies recorded	
Does not exist	
Inspected	
Inspected	
Does not exist	
Inspected	
Inspected	
Boiler Room	
1- Good	
1	
EACH	
Federal Pump	
N/A	
2	
Total # Pumps	
15	
Boiler Room 1- Good	
	Does not exist Inspected 1 - Good No deficiencies recorded Does not exist Inspected Throughout 2 - Between Good and Fair 1 EACH 81-100% No deficiencies recorded Does not exist Inspected Does not exist Inspected 3 - Fair Yes No deficiencies recorded Does not exist Inspected Inspected Doe

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

lestion	Response	
DOMESTIC WATER SYSTEM		
Domestic Cold Water System		
Water Service		
Instance Quantity Uom	EACH	
Deficiency	No deficiencies recorded	
Domestic Hot Water System	Inspected	
Domestic Hot Water Remote Storage Tank	Does not exist	
Domestic Water Heat Exchanger	Does not exist	
Electric Domestic Water Heater	Does not exist	
Gas Fired Domestic Water Heater	Inspected	
Instance	Boiler Room	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Lochinvar	
EquipmentId	N/A	
Capacity/Size Quantity	200	
Capacity/Size UOM	MBH Input	
Capacity/Size 2 Quantity	91	
Capacity/Size 2 UOM	Gallons	
Source of Capacity/Size	Documented	
Installation Year	2017 Decomposited	
Source of Installation Year	Documented No deficiencies recorded	
Deficiency	Does not exist	
Oil Fired Domestic Water Heater	Does not exist	
Heat Pump Domestic Water Heater		
Domestic Water Distribution Piping Condition	Inspected 2- Between Good and Fair	
Deficiency	No deficiencies recorded	
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected	
Interior Storm Piping	Inspected 3- Fair	
Condition		
Deficiency	No deficiencies recorded	
Sewage/Waste/Vent Piping	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Sewage Ejector Pump	Does not exist	
Sump Pump Condition	Inspected 2- Between Good and Fair	
	No deficiencies recorded	
Deficiency		
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist	
TATURES	Inspected	
Staff And Other	Inspected	
Janitor Sink	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Lavatory/Sink	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Toilet	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Urinal	Does not exist	

NYC Department of Education Building Condition Assessment Survey 2023-2024

Mechanical Inspection

anical Inspection	Δ/
uestion	Response
FIXTURES	
Student	
Drinking Fountain	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Locker Room Shower	Does not exist
Sink And Fountain Combo Unit	Inspected
Condition	1- Good
	No deficiencies recorded
Deficiency	
Toilet	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Urinal	Inspected
Condition	2- Between Good and Fair
Deficiency	CRACKED/PHYSICAL DAMAGE
Deficiency Location/Instance	Boy's Toilet Room 317
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
GAS FIRED FURNACE	Does not exist
GAS SERVICE	Inspected
Gas Distribution Piping	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Gas Meter Room Exhaust Fan	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Gas Meter Room Vent	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Gas Pressure Booster	Inspected
Instance	Gas Meter Room B07
Instance Condition	1- Good
Instance Quantity	2
Instance Quantity Uom	EACH
Manufacturer	Etter
EquipmentId	N/A
Capacity/Size Quantity	1
Capacity/Size UOM	HP
Source of Capacity/Size	Documented
Installation Year	2017
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
CO/Gas Leak Detection	Inspected
Instance	Boiler Room, Gas Meter Room
mountee	
Instance Condition	2- Between Good and Fair
Instance Condition Instance Quantity	2- Between Good and Fair 1

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

estion	Response
AS SERVICE	
CO/Gas Leak Detection	
Installation Year	2017
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
EATING	Inspected
Heating Coil In Ductwork	Does not exist
Hydronic Heating	Inspected
Hydronic Heating Hydronic Hot Water Distribution: Piping, Pumps and Auxiliaries	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Backflow Preventer	Does not exist
Hot Water Heat Exchanger	Does not exist
Radiator/Convector/Fin Tube	Inspected
Condition	1- Good
Deficiency	RADIATOR/CONVECTOR:DAMAGED GUARD/SHIELD
Deficiency Location/Instance	Gymnasium
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Heating	Does not exist
Steam supplied by External Sources	Does not exist
Unit Heater/Cabinet Heater	Inspected
Condition	1- Good
Deficiency	DEFECTIVE
Deficiency Location/Instance	Gas Meter Room B07
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
EATING PLANT	Inspected
Instance on Basement	Inspected
Is there a water meter on the boiler make-up water piping?	No
Burner Manufacturer	N/A
Burner Model	N/A
Burner Type	Gas
Heating Plant Oil Number	N/A
Boiler Auxiliaries	
Instance on Basement	Inspected
Boiler Auxiliary Piping	
Instance on Basement	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Boiler Emergency Stop Switch	
Instance on Basement	Inspected
	1- Good
Instance Condition	
Deficiency	No deficiencies recorded
Boiler Feedwater System	
Instance on Basement	Does not exist

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

nicui Inspection		ΛΙ
estion	Response	
EATING PLANT		
Boiler Auxiliaries		
Boiler Feedwater Treatment(Automatic		
Instance on Basement	Does not exist	
Boiler Flue Exhaust		
Instance on Basement	Does not exist	
Boiler Make-up Water Backflow Preven	er	
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Boiler Room Steam And Condensate Pi	ing	
Instance on Basement	Does not exist	
Boiler Safety Valve		
Instance on Basement	Does not exist	
Boiler System		
Instance on Basement	Inspected	
Coal-fired Boiler		
Instance on Basement	Does not exist	
Hot Water Boiler		
Instance on Basement	Does not exist	
Modular Boiler		
Instance on Basement	Inspected	
Instance on Basement	Inspected	
Instance	Boiler Room	
Instance Condition	1- Good	
Instance Quantity	2.000	
Instance Quantity Uom	MBH NET	
Manufacturer	Lochinvar	
EquipmentId	171033-01	
Capacity/Size Quantity	2300	
Capacity/Size UOM	MBH Gross	
Source of Capacity/Size	Documented	
Installation Year	2017	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Boiler Room	
Instance Condition	1- Good	
Instance Quantity	2,000	
Instance Quantity Uom	MBH NET	
Manufacturer	Lochinvar	
EquipmentId	171033-02	
Capacity/Size Quantity	2300	
Capacity/Size UOM	MBH Gross	
Source of Capacity/Size	Documented	
Installation Year	2017	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Steam Boiler		
Instance on Basement	Does not exist	
Fuel System		
Instance on Basement	Inspected	
Boiler Fresh Air Louver/Damper		
Instance on Basement	Inspected	
Instance Condition	1- Good	
Туре	Automatic	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

	11	A //:
uestion	Response	
HEATING PLANT		-
Fuel System		
Boiler Fresh Air Louver/Damper		
Deficiency	No deficiencies recorded	
Burner/Burner Control Panel		
Instance on Basement	Does not exist	
Fuel Oil Storage/Supply System		
Instance on Basement	Does not exist	
Gas Trains And Vent At The Boiler		
Instance on Basement	Does not exist	
Enclosed IDF Room	Does not exist	
KITCHEN	Inspected	
Instance on Basement	Inspected	
CO Detector	1	
Instance on Basement	Not required	
Gas System		
Instance on Basement	Does not exist	
Grease Trap		
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Hood		
Instance on Basement	Does not exist	
Hood Exhaust Ductwork		
Instance on Basement	Does not exist	
Hood Exhaust Fan		-
Instance on Basement	Does not exist	
Hood Fire Suppression System		
Instance on Basement	Does not exist	
Hot Water Temperature Booster		
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Kitchen Sink		
Instance on Basement	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
MDF Room	Inspected	
Instance on Room 306B	Inspected	
Dedicated A/C Equipment		
Instance on Room 306B	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Inspected	
Instance on Room 301	Inspected	
Alternative Use	Yes	
Acid Waste Neutralizing Tank	100	
Instance on Room 301	Does not exist	
CO Detector		
Instance on Room 301	Not required	
Emergency Shower		
Instance on Room 301	Does not exist	
Eye Wash		

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

Response	
Inspected	
1- Good	
No deficiencies recorded	
Does not exist	
Does not exist	
Does not exist	
Inspected	
1- Good	
No deficiencies recorded	
Does not exist	
Inspected	
Partial	
Inspected	
1- Good	
1-25	
No deficiencies recorded	
Does not exist	
Inspected	
1- Good	
No	
No	
No deficiencies recorded	
Does not exist	
	1- Good No deficiencies recorded Does not exist Does not exist Does not exist Inspected 1- Good No deficiencies recorded Does not exist Inspected 1- Good 1-25 No deficiencies recorded Does not exist Inspected 1-Good No No No No No No No No No No deficiencies recorded