# **Building Condition Assessment Survey 2023-2024**

ectrical Inspe	ection					X78
Asset:	P.S. 51 - BRONX	K, 695 EAST 182 STREET,	, BRONX, NY, 10	0457		
Inspection Id	Inspection Type				Time In	Last Edited
1244	ELECTRICAL				2023-11-28 08:58AN	1 2023-11-29 09:00AM
sset Data						
Question				Answer		
Have any Syste	ms/Major Building C	Components been upgraded?		Systems:	Panel Boards	Case Circuit Breaker
				Years:	2021	
				Systems:		Pack)
				Years:	2018, 2011	
				Systems:		
				Years:	2018	
				Systems:	All Other Electrical Systems a	and Components
				Years:	2014	
				Systems:	Exit Lights (Battery Pack)	
				Years:	2011	
Type of Service	2			Below G	round	
Does Interactive	e Whiteboard (IWB)	Exist?		Yes		
Water Penetrati	on In Electrical Roor	n?		No		
DEDICATEI	) INTERCOMS I	N FIRE RESCUE AREAS				
Question					Response	
Are there any your building		nce Areas, Fire Rescue Areas, a	ınd/or Holding Rooi	ms in	No	
iority Condit						
Exist Prio	-	Condition	Component	Location	Person(s) Person(s)	Photo
	egory	Description	Affected	Description	Notified Title	Image
No condition re	ecorded					
nspection						
Question				Respons	e	
Electrical						
ATHLETIC	FIELD			Does not	exist	
AUDITORIU	U <b>M</b>			Does not	exist	
CAFETERIA	A			Inspected	d	
In	stance on Basement			Inspected	d	
Lighting						
In	stance on Basement			Inspected	d	
Lighting	Fixture - Fluorescer	nt				
In	stance on Basement			Inspected	d	
Pendan	t Mounted					
In	stance on Basement			Does not	exist	
Surface	e Mounted					
In	stance on Basement			Does not	exist	
Recesse	ed Mounted					
In	stance on Basement			Inspected	d	
In	stance Condition			•	een Good and Fair	
-	eficiency			No defic	iencies recorded	
	Fixture - HID			110 45110		
_	stance on Basement			Does not	exist	
		ont .		DOES HOL	, CAIST	
	Fixture - Incandesc	ent		D	aviet	
-	stance on Basement			Does not	exist	
	Fixture - LED				• ,	
	stance on Basement			Does not	exist	
Local Soun	nd System					
_	stance on Basement			Inspected		

# **Building Condition Assessment Survey 2023-2024**

Electrical Inspection	X781

Question	Response
CAFETERIA	•
Local Sound System	
Instance Condition	3- Fair
Installation Year	2014
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on Basement	Does not exist
Theater Lighting System	
Instance on Basement	Does not exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Surface Mounted	Does not exist
Recessed Mounted	Does not exist
COMPUTER LAB	Does not exist
GYMNASIUM	Inspected
Instance on 1st Floor	Inspected
Lighting	1
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	•
Instance on 1st Floor	Inspected
Pendant Mounted	•
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Inspected
Pendant Mounted	nspected
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	no deficiencies recorded
Instance on 1st Floor	Does not exist
HISTAIRCE OIL 18t L.1001	DOCS HOL CVIST

## **Building Condition Assessment Survey 2023-2024**

Electrical Inspection	X781
Question	Response

incui Inspection		14701
Question	Response	
GYMNASIUM		
Lighting		
Lighting Fixture - HID		
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Does not exist	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	2014	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Is the projector on a cart or installed on the ceiling?	Ceiling	
Deficiency	No deficiencies recorded	
Scoreboard		
Instance on 1st Floor	Does not exist	
Theater Lighting System		
Instance on 1st Floor	Inspected	
Dimming System		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Theater Lighting		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
KITCHEN	Inspected	
Instance on Basement	Inspected	
Lighting		
Instance on Basement	Inspected	
Lighting Fixture - Fluorescent	<u> </u>	
Instance on Basement	Inspected	
Pendant Mounted	·	
Instance on Basement	Does not exist	
Surface Mounted		
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Two deficiences recorded	
Instance on Basement	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Instance on Basement	Does not exist	
Lighting Fixture - LED	Does not exist	
Instance on Basement	Does not exist	
nistance on Daschicht	Does not exist	

## **Building Condition Assessment Survey 2023-2024**

incui inspection		21701
Question	Response	
LIBRARY	Does not exist	
LOCKER ROOM	Does not exist	
MULTIPURPOSE ROOM	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	
SCIENCE LAB SCIENCE PREP ROOM	Does not exist	
	Does not exist	
SWIMMING POOL		
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected Inspected	
Lighting Fixture - Fluorescent	Does not exist	
Pendant Mounted Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
	No deficiencies recorded	
Deficiency	Does not exist	
Recessed Mounted	Does not exist  Does not exist	
Lighting Fixture - HID		
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Surface Mounted	Does not exist	
Recessed Mounted	Does not exist	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	
EMERGENCY GENERATOR SET	Does not exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not exist	
EMERGENCY LIGHTING	Inspected	
	Inspected	
Battery Pack Condition	1- Good	
Deficiency	No deficiencies recorded	
Non Battery Pack	Does not exist	
EXIT LIGHT	Inspected	
	Inspected	
Battery Pack Condition	3- Fair	
Condition	J- 1 all	
Deficiency	No deficiencies recorded	

## **Building Condition Assessment Survey 2023-2024**

		<b>X</b> /0
estion	Response	
EXIT/EMERGENCY LIGHT	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
TIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	2- Between Good and Fair	_
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	_
Fan Shutdown Control	Inspected  2- Between Good and Fair	
Condition	No deficiencies recorded	
Deficiency		_
Duct Smoke Detector	Inspected  2- Between Good and Fair	_
Condition		
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected  2- Between Good and Fair	_
Condition	2 2 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3	
Deficiency	No deficiencies recorded	
CO Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Heat Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Elevator Recall	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Magnetic Door Holder/Contactor	Does not exist	
Fused Cutout Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Inspected	
Bell At Panel	Does not exist	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Edwards	
Model	EST3X	
EquipmentId	Fire Alarm Control Panel	
Installation Year	2014	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel	Does not exist	_
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	

## **Building Condition Assessment Survey 2023-2024**

aricai inspection		A/01
Question	Response	
FIRE ALARM SYSTEM		
Remote Annunciator		
Panel		
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Punch Register	Does not exist	
Sprinkler Flow/Air Pressure Switch	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Tamper Flow Switch/Chain	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
GROUNDING SYSTEM	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
- <u> </u>	Inspected	
INTERCOM SYSTEM	Inspected	
Elevator  Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
•	Does not exist	
Holding Area		
LAN	Inspected	
Local Distribution Frame (I/LDF)  Condition	Inspected  2- Between Good and Fair	
Deficiency	No deficiencies recorded	
	Inspected	
Main Equipment Rack (MDF)  Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
	Does not exist	
LIGHTNING PROTECTION		
MOTOR CONTROLLER	Inspected	
MOTOR CONTROL CENTER	Does not exist	
MOTOR STARTER/CONTACTOR	Inspected	
Condition Deficiency	2- Between Good and Fair No deficiencies recorded	
Variable Frequency Drive	Does not exist	
PANEL BOARD	Inspected	
Fused Disconnect Switch Type	Does not exist  Does not exist	
Fused Knife Switch Type	Does not exist  Does not exist	
Fused Toggle Switch Type  Moddod Cons Circuit Breaker Type	Inspected	
Molded Case Circuit Breaker Type  Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
PUBLIC ADDRESS SYSTEM	Inspected	
Instance	MDF Room 310	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1 EACH	
Instance Quantity Uom	EACH	
Model	Dukane 250	
Installation Year	2014	
Source of Installation Year	Documented  GDE A KED NOT OBER ATIONAL	
Deficiency	SPEAKER NOT OPERATIONAL	
Deficiency Location/Instance	Outside Play Area	

## **Building Condition Assessment Survey 2023-2024**

	A/61
Response	
1	
EACH	
REPAIR	
PRIORITY 5	
LEVEL 2	
No violations recorded	
Inspected	
Inspected	
2- Between Good and Fair	
2014	
Documented	
No deficiencies recorded	
Inspected	
Inspected	
Old Locker Room	
2- Between Good and Fair	
1	
EACH	
Vista - 128BP	
2014	
Documented	
No deficiencies recorded	
Inspected	
2- Between Good and Fair	
No deficiencies recorded	
Inspected	
2- Between Good and Fair	
No deficiencies recorded	
Inspected	
2- Between Good and Fair	
No deficiencies recorded	
Inspected	
<u> </u>	
*	
mspected	
1	
	1 EACH REPAIR PRIORITY 5 LEVEL 2 No violations recorded Inspected Inspected 2- Between Good and Fair 2014 Documented No deficiencies recorded Inspected Inspected Inspected Old Locker Room 2- Between Good and Fair 1 EACH Vista - 128BP 2014 Documented No deficiencies recorded Inspected Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair

## **Building Condition Assessment Survey 2023-2024**

Question	Response	
SWITCHBOARD		
Fused Disconnect Switch Type		
Instance	Electrical Room C01	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	All City Switchboard	
EquipmentId	N/A	
Capacity/Size Quantity	1200	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	2	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Service Switch Size	
Installation Year	2014	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fused Knife Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Does not exist	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
TRANSFORMER	Does not exist	