# **Building Condition Assessment Survey 2023-2024**

Mechanical Inspection	X817
-----------------------	------

Inspection	n Id Inspection Ty	/ne			Time	In	Last Edited
	3751 MECHANICA					-03-07 10:13AN	
		AL .			2024	-03-07 10.13AW	1 2024-03-10 03.43FWI
Asset Data Question				Answer			
		ding Components been upgraded	19	Systems:	MDF Room -	- Dedicated A/C.)	Equipment (DX Split
Have ally	Systems/Major Bund	anig Components been upgraded	11	Systems.	System)	Dedicated 71 C	Equipment (DA Spire
				Years:	2022		
				Systems:	Exhaust Fans	(~60%)	
				Years:	2020	,	
				Systems:	Electric Dom	estic Water Heat	er
				Years:	2014		
Are there	fuel tanks?			No			
	f water main service e	entries to the asset		1			
	an Rooms Locations	entries to the asset		MER 110			
		sing or Defective CO Detectors	)	No No			
	e any Painted/Obstruc	_	•	No			
	•	Switches with Missing Hamme	arc?	No compo	ments		
		Switches with Missing Hailing	40.	140 compe	,1101110		
Priority Co							
Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
No condi	tion recorded						
Inspection	ı						
Question	1			Response	,		
Mechani	ical						
AIR C	ONDITIONING			Inspected			
	ed Water System			Does not			
Condenser Water Distribution: Piping, Pumps and Auxiliaries			Does not exist				
	ing Coil in Ductwork		inaries	Does not			
	ing Tower	<u> </u>		Does not			
	Split System			Inspected			
	loor Unit			Inspected			
$\overline{c}$	ondition			3- Fair			
	Deficiency			No defici	encies recorded		
	tdoor Unit			Inspected			
	ondition			4- Between Fair and Poor			
C				4- Between Fair and Poor OVER 5 TONS:DEFECTIVE			
	Deficiency	· /r				IIVE	
	Deficiency Loc Deficiency Qua			MER 110			
		antity		1 EACH			
	Quantity Uom	_		REPAIR			
	Potential Action				37.2		
	Urgency of Act			PRIORIT			
	Purpose of Acti	ion		LEVEL 2			
	Violations				ions recorded		
	Cooler			Does not			
	aged / Rooftop Unit			Does not			
	aged Terminal A/C			Inspected			
Cor	ndition			3- Fair			
	Deficiency	. ~		DEFECT			
	Deficiency Loc				oose Room 113		
	Deficiency Qua	antity		1			
	Quantity Uom			EACH			
	Potential Action			REPAIR			
	Urgency of Act			PRIORIT			
	Purpose of Acti	ion		LEVEL 2			

# **Building Condition Assessment Survey 2023-2024**

Mechanical Inspection X817

unicui inspeciion	Λ
uestion	Response
AIR CONDITIONING	
Packaged Terminal A/C	
Violations	No violations recorded
Refrigerant Leak Detection System	Does not exist
Refrigerant Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Return Fan	Does not exist
CENTRAL ACID WASTE NEUTRALIZING TANK	Does not exist
CLIMATE CONTROL SYSTEM	Does not exist
COMPACTOR	Does not exist
CONVEYING	Does not exist
DOMESTIC WATER SYSTEM	Inspected
Domestic Cold Water System	Inspected
Gravity System	Does not exist
Pressure Booster System	Does not exist
Water Service	Inspected
Instance	Water Service Room 114
Instance Condition	3- Fair
Instance Quantity	1
	EACH
Instance Quantity Uom	
Deficiency	WATER MAIN:MISSING BACKFLOW PREVENTION DEVICE
Deficiency Location/Instance	Water Service Room 114
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Domestic Hot Water System	Inspected
Domestic Hot Water Remote Storage Tank	Does not exist
Domestic Water Heat Exchanger	Does not exist
Electric Domestic Water Heater	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Gas Fired Domestic Water Heater	Does not exist
Oil Fired Domestic Water Heater	Does not exist
Heat Pump Domestic Water Heater	Does not exist
Domestic Water Distribution Piping	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE DOMESTIC HOT WATER CIRCULATING PUMP
Deficiency Location/Instance	Water Service Room 114
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected
Interior Storm Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sewage/Waste/Vent Piping	Inspected

# **Building Condition Assessment Survey 2023-2024**

Mechanical Inspection X817

nunicui Inspection		AOI
Question	Response	
DRAIN/WASTE/VENT AND STORM SYSTEM		
Sewage/Waste/Vent Piping		
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Sewage Ejector Pump	Does not exist	
Sump Pump	Does not exist	
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist	
FIXTURES	Inspected	
Staff And Other	Inspected	
Janitor Sink	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lavatory/Sink	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Toilet	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Urinal	Does not exist	
Student	Inspected	
Drinking Fountain	Does not exist	
Lavatory/Sink	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Locker Room Shower	Does not exist	
Sink And Fountain Combo Unit	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Toilet	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Urinal	Does not exist	
GAS FIRED FURNACE	Does not exist	
	Does not exist	
GAS SERVICE		
HEATING	Inspected	
Heating Coil In Ductwork	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hydronic Heating	Does not exist  Inspected	
Radiator/Convector/Fin Tube Condition	3- Fair	
Deficiency	No deficiencies recorded	
	Does not exist	
Steam Heating Steam supplied by External Sources	Does not exist  Does not exist	
Unit Heater/Cabinet Heater	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
HEATING PLANT	Does not exist	
	Does not exist  Does not exist	
Enclosed IDF Room		
KITCHEN	Does not exist	
MDF Room	Inspected	
Instance on Room 108	Inspected	
Dedicated A/C Equipment		

# **Building Condition Assessment Survey 2023-2024**

Mechanical Inspection X817

Inspected
Inspected
Inspected
1- Good
No deficiencies recorded
Does not exist
Inspected
Yes
Inspected
2- Between Good and Fair
1-25
No deficiencies recorded
Does not exist
Inspected
3- Fair
No
No
DEFECTIVE DUCTWORK
MER 110
10
L.F.
MAINTENANCE
PRIORITY 3
LEVEL 2
No violations recorded
DAMAGED/MISSING INSULATION
MER 110
20
L.F.
MAINTENANCE
PRIORITY 3
LEVEL 2
No violations recorded
Does not exist
Does not exist